Chapter Eleven

DEFECT DIAGNOSIS

Contents

| | Conte | nts | | | | |
|--|------------------|---|--|--------------------------------|----------------------|---------------------------|
| Defect diagnosis, Ghost 53 Mk. 1 Checks, check records, and interpretation D.C. Check Gain Check Negative Rate Check Governor adjustments Miscellaneous adjustments Test equipment Defect diagnosis table, Ghost 48 Mk. 1 Defect diagnosis table, Ghost 48 Mk. 2 | 32 (34 32 | General How to use Tools and e Assembly Ghost : D.C. To | the tables equipment and calibration 53 Mk, 1 est Set tion of Routine the Test Set | of equipm | 1 | Page 36 1 2 3 50 52 51 50 |
| Defect Sym | ptom | | | 8 M k. 2 Fer to page | | |
| Accelerate after light-up, failure to Acceleration of engine, fast Acceleration of engine, slow, or no | | | 8 | 20 26 26 | 8 | |
| Datum (electric max. r.p.m. control) of | difficult t | o set | _ | _ | 46 | |
| Fuel pressure warning light coming of Full throttle does not give maximum Full throttle r.p.m. exceeds permitted Full throttle r.p.m., unstable | r.p.m. | | 14 10 8 2, 12 | 14 22 22 | 14 42 40 | |
| Govern, failure to Governed r.p.m. too high Governed r.p.m. too low Governing, inconsistent | | | 8 | 22 22 22 28 | 36 40 42 | |
| Idling speed, incorrect Isolating switch, operation causes too | great a | variation | 3, 8 | 20 | 8 | |
| of r.p.m. | great a | variation | - | _ | 46 | |
| Jet pipe temperature, incorrect | | | 12 | 26 | 12 | |
| Oil consumption, high Oil leakage, suspected Oil pressure, incorrect | | | 12 12 12 | 12 12 12 | 12 12 12 | |
| R.P.M. decrease (governed) starts at v R.P.M. (governed) falls excessively wi R.P.M. fluctuation, continuous R.P.M. (governed) increases with forw | ith forwa | ird speed | = | | 38 46 38 46 | |
| Starting, engine does not rotate at Starting, faulty, juddering Starting, no light-up at | | | 4 8 4 | 4 8 16 | 4 8 4 | |
| Vibration, abnormal | | | 14 | 14 | 14 | |

Illustrations

| | Fig. | | | Fig. |
|--|------|---------------------------------|-----------|------|
| Pictorial diagram of Ghost 48 Mk. 1 fuel | | Negative Rate Check | ¥:* | 4 |
| system and test gauges | 1 | Routine Test Set | | 5 |
| Gain Check | 2 | Calibration of Routine Test Set | | 6 |
| Direct Current (D.C.) Check | 3 | D.C. Test Set | * (*) | 7 |




Fig. 1. Pictorial diagram of Ghost 48 Mk. 1 fuel system showing use of test gauges for defect diagnosis.

If the engine is conscientiously serviced and maintained, and it is operated correctly, running defects will be reduced to a minimum. When a running defect is encountered, systematic investigation may save much unnecessary work and pages 4 to 49 of this chapter contain Defect Diagnosis Tables which should assist the operator to diagnose, and to rectify, a defect quickly; although it is inevitable that on occasions some temporarily baffling defect will be encountered. Pages 4 to 15 cover the Ghost 48 Mk. 1, pages 16 to 29 the Ghost 48 Mk. 2, and pages 32 to 52 the Ghost 53 Mk. 1.

In compiling these tables it has been assumed that the engine has been operated and serviced correctly, and that the airframe equipment associated with the engine is serviceable. For these reasons factors such as visible leakages, insufficient or incorrect grades of fuel or oil, defective aircraft components such as tank booster pumps and instruments, closed cocks and incorrectly set switches and controls, and incorrect operating sequences have not been considered. If incorrect operation or inefficient servicing is suspected, these matters should be checked before investigating further. Similarly, before commencing to investigate any apparent defect based on an abnormal instrument indication ensure that the instrument itself is functioning correctly; possibly by changing the instrument for one which is known to be serviceable. When investigating electrical defects, the cause of any blown fuses should be discovered and rectified before any further action is taken.

In these defect diagnosis tables, it has been assumed generally that the fault under investigation has a single cause, for instance under "No light-up at starting" secondary Cause d.iii it has been assumed that either the pumps are faulty, or the barometric pressure control, or the air-fuel ratio control, and not two or all three of these components. If, however, the trouble persists after locating and rectifying one faulty component, it will be obvious that one or more of the remaining components is probably faulty also.

A thorough knowledge of the starting cycle and equipment will assist in the elimination and rectification of starting troubles, and reference to the text and illustrations in chapters 2 and 3 will assist when investigating lubrication and fuel system defects.

Although an attempt has been made to list all known and possible defects which may affect the running of the engine, it must not be assumed that all these defects are likely to occur; many of them may never be encountered. It is, of course, impossible to forecast the particular defects which may

occur in individual engines, and, therefore, this table is not intended to supersede the knowledge of an experienced engineer but to assist those who are unfamiliar with these engines.

The actual method of rectifying defects is considered as coming within the category of servicing, maintenance, or repair, and, where a chapter reference is given in the right-hand column of the tables, the necessary information will be found in that chapter. Additional information may be found also in other chapters in this handbook, in the relevant aircraft handbook, and in the accessory manufacturers' publications, and reference should be made to these as necessary. Where the method of rectifying a defect is self-evident no entry has been made in the 'Refer to' column of the tables.

HOW TO USE THE DEFECTS DIAGNOSIS TABLE

To locate and rectify a defect it is not necessary to make all the investigations tabulated, as the tables are designed to lead the investigator from the known symptom, column by column, to the remedial action with the minimum of work.

If the engine is not functioning correctly the probable defect will be indicated by certain symptoms and these symptoms are the only point from which any investigation can commence. The first step, therefore, is to locate the observed symptom in the first (left-hand) column of the tables.

In practice it is found that more than one defect can produce the same symptoms, and, therefore, each probable defect with the method of investigaton is listed in the columns headed 'Primary cause' and 'Primary investigation'. The probable defects are listed so that either the most probable are investigated first or the first invesigations lead on to the others in a logical sequence. Therefore, the primary causes should be investigated in the order given. Once the primary cause has been identified it is unnecessary to proceed with any further primary investigation and attention should be transferred to the next two columns and any secondary cause identified in a similar manner. In each instance, the immediate remedial action is suggested in column six of the tables, and where appropriate, further instructions can be located from the cross references given in the last (righthand) column.

UNSTABLE R.P.M. AT FULL THROTTLE, Ghost 48 Mk. 1.

If the H.P. fuel cock control is not rigged correctly, movement of the H.P. cock lever within its gate may cause a variation of up to 100 r.p.m. at full throttle. Where this trouble is experienced,

make a check to ensure that the H.P. fuel cock control is functioning correctly within its gate, and recheck by ground running that the full throttle r.p.m. does not fluctuate. If the r.p.m. still fluctuates, the aircraft control linkage should be shortened slightly. To do this, slacken the lock nuts at each end of the control rod which is adjacent to the fuel control valve assembly on the engine, and turn the rod the required amount to ensure that the fuel cut-off valve is in the fully open position when the lever in the cockpit is through the gate. Retighten the lock nuts.

INCORRECT IDLING SPEED, Ghost 48, Mk. 1

Should the idling speed deviate from the normal for no apparent reason, before re-adjusting the slow-running needle, make the following checks.

- (1) Remove the slow-running needle and flush out the orifice, by switching ON the fuel tank booster pump. Hold a clean sheet of white blotting paper in front of the orifice in the fuel control valve assembly, so that the fuel issuing from the orifice passes through the blotting paper, which will trap any sediment or dirt, and so confirm, or disprove, its presence.
- (2) Remove the low pressure fuel filter element, and check that it is clean and undamaged.
- (3) Check the aircraft engine controls thus:—
 Place the throttle lever, in the cockpit, in the fully SHUT position. Remove the bolt which couples the throttle rod end to the throttle lever on the control valve assembly, as described in chapter 14, page 6. Check whether the bolt holes in the two components align correctly when both the cockpit lever and the lever on the control valve assembly are in the slow-running position.

A further check can be made, whilst the controls are disconnected, by holding the lever on the control valve assembly in the slow-running position, and starting the engine. Observe the r.p.m. and if it is incorrect, still holding the lever on the control valve in the slow-running position, re-adjust the slow-running needle as necessary.

When the results of these checks are satisfactory, refit the bolt, adjusting the aircraft control rod if necessary to align the bolt holes.

The first two checks apply mainly if the idling speed is too low; the third applies if the speed is too high. Refer also to Symptom 5 on page 8.

TOOLS AND EQUIPMENT

In addition to the normal tool kit, spanners, etc., the defect investigation equipment should include the following.

A 0-24 voltmeter, and insulation and continuity testing equipment.

Pressure gauge assembly T.75051 i.e. 0-200 lb. per sq. in. pressure gauge.

Pressure gauge assembly T.75050 i.e. 0-2500 lb. per sq. in pressure gauge. Pressure gauge and pipe assembly T.75050 is filled with kerosene and, therefore, when connecting this gauge into the fuel system, it is important to remember that both ends of the T-piece must not be opened simultaneously; i.e. having removed one hand nut to connect one branch of the T-piece to the system, do not remove the second hand nut until the first branch of the T-piece has been connected up.

Male and female adapters T.77097 and T.77098 which are required to convert $\frac{1}{8}$ in. B.S.P. gauges to $\frac{1}{4}$ in. B.S.P. when tapping into the B.P.C. pressure pipe.

If the pressure gauges T.75051 and T.75050 are not available a T-piece $\frac{1}{8}$ in. B.S.P. $\times \frac{1}{8}$ in. B.S.P. to connect a locally provided pressure gauge into B.P.C. delivery pressure or servo line will be required.

A slave distributor-to-burner pipe connection Part No. 29761 to enable a burner pressure gauge to be connected to any burner; there is a permanent burner pressure gauge connection on No. 2 burner pipe.

Equipment for very accurate measurement of engine speed, such as a hand stroboscope, or hand tachometer, or a revolution counter and a stop watch.

To use a hand tachometer, such as Smiths A.T.H.7, remove the tachometer generator and apply the hand tachometer direct to the normal tachometer generator drive.

It is essential when using locally made equipment that the transmitting pipes are kept as short as possible.

GHOST 48 Mk. 2

The foregoing tools and equipment were originally provided for use on the Ghost 48 Mk. 1. Although they can be adapted for use on the Ghost 48 Mk. 2, additional gauges are required for use on the Dowty spill-burner fuel system which is fitted to the latter and, to meet this, a special portable test rig is being developed.

The table has been compiled on the assumption that the Dowty portable test rig will be available. This rig consists of a box containing the necessary gauges, hand pumps, connecting pipes, adapters and blanks. Where this equipment is not available, suitable gauges and pumps must be obtained locally, having regard to the pressures specified in the table; and standard pipes, adapters and blanks utilized to connect the gauges and pumps to the system, and to blank off orifices as specified.

| Symptom | Primary Cause | Primary Investigation |
|---|---|--|
| 1. ENGINE DOES NOT ROTATE AT STARTING (TURBO STARTER FAILURE) | a. Cartridge does not fire | Wait at least 15 seconds, select and fire second cartridge, or wait one minute and change cartridge |
| (See also table in chapter 50, page 14) | | |
| | b. Tripping of overspeed cut- | Possibility of products of combustion, gritty in nature, lodging between cut-off plate and turbine; this might cause excessive friction and trip cut-off |
| | c. Safety disc blown | This will be indicated by a heavy discharge of yellow smoke for an eleven second period |
| | d. Cut-off plate not reset | |
| 2. NO LIGHT-UP AT STARTING | a. Faulty or discharged aircraft batteries | Check the aircraft batteries and electric circuit |
| | b. (High energy ignition) Faulty surface discharge igniter plug | The simplest way to check this is to fit two surface discharge igniter plugs which are known to be serviceable and to make another attempt to start |
| | c. (High energy ignition) Faulty igniter circuit | Check igniter cable for continuity, insulation and good contact at each end |
| - | | |
| | | |
| | | |
| | d. Inadequate fuel supply to burners | Connect pressure gauge T.75051 to the union on No. 2 burner distributor pipe connection. Attempt to start the engine; a build-up of pressure of at least 50 lb. per sq. in. should be observed |
| | - Ea x | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|--|--|---|---------------------------|
| i. Electrical fault | Breech cap not correctly fitted | Wait 1 full minute and screw cap fully home | _ |
| NOTE.—It has been considered that two defective cartridges will not occur together | Test the circuit at the firing pin, this can be done by removing both cartridges and replacing one breech cap. Check continuity by means of a 30 v. voltmeter, across the exposed pin and the barrel assembly. Replace other breech cap and repeat check, removing the first breech cap. It is essential to place the selector switch in the respective firing position | Locate defect and rectify or change defective component | |
| ii. Starter drive failure | | Change starter | Chap. 19 |
| | | | _ |
| | | Fit a new safety disc | Chap. 50 |
| | | Re-set cut-off plate | Chap. 50 |
| | | Change the batteries for ones known to be fully charged and without fault, or correct the defect in the electric circuit | Aircraft hand- book |
| | | Fit two serviceable surface discharge igniter plugs | Chap. 15 |
| | | Change defective ignition cable | Chap. 15 |
| i. Fault in L.T. supply to H.E. condenser unit | Check circuit for continuity and insulation | Rectify defect or change defective component | Aircraft hand- book |
| ii. Faulty high energy con- denser unit | If the condenser unit can be heard operating but there is no high energy discharge, which is indicated by the discharge noise at the igniter plug, check the circuit from the battery to the condenser unit for an incorrect connection, i.e. the positive lead connected to a negative terminal or vice versa. If the wiring is correct, the serviceability of a suspect condenser may be checked by changing over the port and starboard units | | Chap. 15 |
| i. H.P. cut-off valve not opening fully | Ensure that the H.P. fuel cut-off valve lever, in the cockpit, is in the fully open position. Disconnect the control from the lever on the fuel control valve assembly, and check whether the H.P. cut-off valve can be moved any further towards the open position | Adjust the aircraft portion of the control circuit until full movement is obtained, and check also that, with the cockpit lever in the closed position, the H.P. cut-off valve closes fully | Aircraft hand- book |
| ii. Distributor sticking | | Change defective distributor | Chap. 14 |

DEFECT DIAGNOSIS TABLE Ghost 48 Mk. 1

| Symptom | Primary Cause | Primary Investigation |
|---|---|-----------------------|
| 2. NO LIGHT-UP AT STARTING (contd.) | d. Inadequate fuel supply to burners (contd.) | Trimary Investigation |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|--|--|---|----------|
| iii. Faulty B.P.C., A-F ratio control, or fuel pumps | Check 1. To prove that the fault is as under iii. Disconnect the delivery pressure pipe from the fuel pump to the B.P.C. at the connection of the fuel pump and connect adapter T.77098 and pressure gauge T.75050 to the fuel pump and reconnect the delivery pipe to the T-piece. Repeat the attempt to start but keep the H.P. fuel cut-off valve lever in the CLOSED position to avoid flooding the engine. If there is a build-up of pressure of approximately 1350 lb. per sq. in., there is nothing wrong with the fuel system as under iii. Proceed to secondary cause iv. | | |
| | Check 2. To decide whether the fault is in the B.P.C. or A-F ratio control, or in the pumps. Disconnect and blank off the servo lines to the B.P.C. and A-F ratio control. Attempt to start the engine with the fuel pump isolating switch OFF. | | |
| | If the start is successful, the fault is in either the B.P.C. or the A-F ratio control. If the check 1 pressure gauge is still connected, a build-up of pressure of approximately 2000 lb. per sq. in. should be obtained NOTE.—If the engine starts under these conditions, a high idling speed is to be expected and the adjustment must not be altered | As it is more likely for the B.P.C. to be at fault, change the B.P.C., reconnect the servo lines, and repeat the attempt to start. If the engine still fails to start change the A-F ratio control | Chap. 14 |
| | If the start is unsuccessful, either or both pumps may be faulty. In practice this trouble seldom occurs | To avoid lengthy investigation as to which pump is faulty, change both pumps. Alternatively, change the pumps one at a time, making a further attempt to start after each change | Chap. 14 |
| iv. Incorrect slow-running adjustment | Open the throttle slightly and repeat the attempts to start the engine. If the engine starts but will not idle with the throttle fully closed, it suggests that the slow-running bleed has become blocked, or has been screwed in inadvertently | Carefully noting the number of complete turns the slow-running needle is unscrewed, remove the needle and examine for dirt on needle or in orifice. Screw in needle the same number of complete turns as it was unscrewed. If start is still unsuccessful, or if no blockage was discovered set needle one turn further open. When a successful start is made readjust the slow-running speed. Keep a note of all alterations made. | Chap. 14 |
| v. Faulty burners in igniter combustion chambers | If all others checks are satisfactory, the difficulty may be due to faulty burners in combustion chambers No. 3 and 10 | Change these burners | Chap. 14 |

| Symptom | Primary Cause | Primary Investigation |
|--|--|---|
| 3. FAILURE TO ACCELERATE AFTER LIGHT-UP | a. Internal resistance in engine | This would probably have revealed itself during the free running check when the engine was stopped previously |
| | b. Faulty starter | Low cranking r.p.m. by starter due to long service life of starter. Check starter log book for number of shots fired |
| | c. Inadequate fuel supply | Proceed as described under 2.c. in this table |
| 4. FAULTY START- ING, JUDDERING | Insufficient or incorrect oil in starter gearbox | |
| 5. INCORRECT IDLING SPEED | a. Engine not warmed up | Run up slowly to maximum r.p.m., and return to idling; idling speed may then be correct |
| NOTE.—Idling speed varies slightly with atmospheric pressure and temperature. | b. Faulty B.P.C., or faulty A-F ratio control over-riding the B.P.C. incorrectly | Connect adapter T.77098 and pressure gauge T.75050 to the delivery pressure pipe from the pump to the B.P.C. as described under 2.c.iii in this table. When the engine is idling, a pressure of 1350±100 lb. per sq. in. should be registered. If the pressure is outside this range the B.P.C. may be faulty |
| | | If, after changing the B.P.C., the engine still does not run correctly and the pressure is still outside the range given, the A-F ratio control is probably faulty |
| | c. Incorrect adjustment of the slow-running bleed | Alter the adjustment of the slow-running needle as little as possible; keeping a careful roord of all alterations made |
| | d. Faulty fuel pump | Proceed as described under 2.c.iii in this table |
| 6. FULL THROTTLE R.P.M. EXCEEDS THE PERMITTED MAXIMUM | a. Governor mechanism in- correctly adjusted | |
| NOTE.—One of the fuel pumps is set to govern at 50 r.p.m. more than the other pump and therefore, when the fuel pump isolating switch is ON the higher r.p.m. may be attained. | | |
| | burner pressure to fall as lov | stood that there is a tendency for the governed r.p.m. to was 500 lb. per sq. in., the governed speed will increase governed speed will be approximately 10200 r.p.m. Providence |
| | b. Faulty fuel pump (i.e. governor mechanism) | Engine r.p.m. will not respond to any amount of governor adjustment |

FAILURE TO ACCELERATE AFTER LIGHT-UP Ghost 48 Mk. 1

Chapter 11 Page 9

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|--|--|--|----------|
| | | | Chap. 9 |
| Slipping clutch | | Change starter | Chap. 19 |
| | | | _ |
| | | Prime starter gearbox, if in- correct oil is suspected, re- move starter, drain, and refill | |
| Cold oil in engine-driven aircraft accessories | Run engine until all gas and oil tem- peratures have stabilized | | _ |
| | | Change B.P.C. | Chap. 14 |
| | | | 1 |
| | | Change A-F ratio control | Chap. 14 |
| | Annual Colonia | | Chap. 14 |
| | | | Chap. 14 |
| | | Readjust the governor mechanism. Before deciding that either of the fuel pumps is faulty, ensure that you are adjusting the governor which is controlling the r.p.m. and that neither governor will respond to adjustment. Turn the adjusting screw, on the fuel pumps, anti-clockwise to decrease the governed r.p.m. | Chap. 14 |

change with burner pressure (i.e., fuel flow). For instance, if the ambient temperature is high and causes the to approximately 10300 r.p.m., and if the ambient temperature is low, causing the burner pressure to be as high as ed that the variation of governed r.p.m. with burner pressure is within these limits, it is unnecessary to reset the

| | Change defective fuel pump | Chap. 14 |
|------|----------------------------|----------|
| | | |

| | Symptom | Primary Cause | Primary Investigation |
|----|---|--|---|
| 7. | FULL THROTTLE DOES NOT GIVE MAXIMUM PER- MITTED R.P.M. | a. Throatle or H.P. fuel cut- off valve not opening fully | Check controls as described for H.P. fuel cut-off valve under 2.c.i in this table |
| | (refer also to note under 6 in this table and to cold weather operation in chapter 10). | b. Governor mechanism in fuel pumps incorrectly set or faulty, or faulty B.P.C. or A-F ratio control | Disconnect the servo pipe from the front fuel pump to the B.P.C. and connect pressure gauge T.75050 to the servo outlet on the front pump, and blank off the third leg of the pressure gauge T-piece. Having thus blanked off the servo side of both pumps from both the B.P.C. and the A-F ratio control. Run the engine up to the maximum r.p.m. obtainable. If when this r.p.m. is reached, there is an appreciable drop in the pump delivery pressure (from about 2000 to about 1000 lb. per sq. in.) the governor mechanism in one of the fuel pumps is operating at too low an r.p.m. |
| | | c. Inadequate fuel supply reaching burners | Connect pressure gauge T.75050 as above |
| | | | |
| | | | |
| | | | |
| | , | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------------------------------------|---|---|---------------------------|
| | | Adjust aircraft portion of control circuit | Aircraft hand- book |
| | | Readjust the governor mechanism. Before deciding that either of the pumps is faulty, ensure that you are adjusting the governor which is controlling the r.p.m. and that neither governor will respond to adjustment. Turn the adjusting screw on the fuel pump clockwise to increase the governed r.p.m. If either pump will not respond to adjustment (below the setting of the other pump governor), change that fuel pump | Chap. 14 |
| i. Faulty fuel pumps | If, although both pumps appear to respond to governor adjustment, maximum r.p.m. is still unobtainable and delivery pressure drops as the throttle is opened, both pumps are probably faulty. | Change both pumps | Chap. 14 |
| ii. Faulty B.P.C. | Having obtained the required r.p.m. with the servo system blanked off (i.e. on pump stall pressure of 2000 lb. per sq. in.), connect the servo pipe to the third leg of the pressure gauge T-piece and disconnect the servo pipe from the B.P.C. to the A-F ratio control and blank off the connection on the B.P.C. If a delivery pressure of 1350±100 lb. per sq. in. (since the gauge will be recording servo pressure, the actual reading will be proportionally lower than the actual delivery pressure) is NOT maintained, at all except governing r.p.m., the B.P.C. is faulty; refer also to note below | Change B.P.C. | Chap. 14 |
| iii. Faulty A-F ratio con- trol | Reconnect the servo pipe from the B.P.C. to the A-F ratio control. If a delivery pressure of 1350±100 lb. per sq. in. is NOT maintained, at all except governing r.p.m., the A-F ratio control is faulty | Change A-F ratio control | Chap. 14 |

NOTE.—If the stipulated delivery pressure is maintained at all except governing r.p.m., neither the fuel pumps, nor the B.P.C. or the A-F ratio control is faulty. It should be noted that low temperature conditions can make this pressure inadequate for reaching maximum r.p.m.; this condition is best investigated in terms of burner pressure. For instance, if full throttle does not give maximum r.p.m., connect a pressure gauge to the union on No. 1 burner distribution pipe connection and check that the maximum burner pressure, for cold weather conditions (1050—1100 lb. per sq. in.), is being obtained. If this is correct, nothing more can be done.

| iv. Faulty burners | Exceptionally high burner pressure, registered when pressure gauge is connected to pipes between distributor and burners | dismantling of the burners is | Chap. 14 |
|-----------------------|--|-------------------------------|----------|
| v. Faulty distributor | If the results of the foregoing investiga- tions are unsuccessful, the distributor is probably faulty | Change distributor | Chap. 14 |

| Symptom | Primary Cause | Primary Investigation |
|---|--|---|
| 8. UNSTABLE R.P.M. AT FULL THROTTLE | Incorrect rigging of high pressure fuel cut-off valve control linkage may cause a variation of up to 100 r.p.m. at full throttle | Ensure that the H.P. fuel cock lever is functioning correctly within its gate, and re-check by ground running that the full throttle r.p.m. does not fluctuate |
| 9. INCORRECT OIL PRESSURE | a. Insufficient oil | Check level of oil |
| NOTE.—It has been assumed that the correct grade of oil is in use. | b. High or low ambient temperature | This will cause either low or high pressure respectively |
| | c. Faulty relief valve | Remove pressure relief valve, without altering its set- ting, and examine condition of valve and seat |
| | d. Incorrectly set relief valve | If other checks are satisfactory, setting of valve is faulty |
| O. SUSPECTED OIL LEAKAGE OR HIGH OIL CON- SUMPTION | Check by grownerely be the Front Bearing. The Rockhard | etimes carbonised, condition of the rear bearing housing, and running to ascertain whether the oil consumption is result of over priming. I lacquer applied to the impeller gives the impression, and an engine for oil leakage from the front bearing |
| II. INCORRECT JET PIPE TEMPERA- TURE | a. Faulty thermocouple leads and connections | This is usually shown by erratic temperature readings. Remove leads and check for continuity and insulation |
| NOTE.—The engine should be run for as short a time as possible to carry out these investigations. | b. Faulty thermocouple c. Uneven burning | Fit new thermocouple and recheck |
| | | |
| | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|--|-------------------------|---|---------------------------|
| If r.p.m. still fluctuates, the aircraft control linkage requires adjustment | | Adjust cut-off valve control rod sufficiently to ensure that the fuel cut-off valve is fully open when the lever in the cockpit is through the gate | Aircraft hand- book |
| | | Refill as necessary. Check | Chap. 9 |
| | | again after running when oil temperature has settled down | Chap. 7 |
| | 4 | Check again after running when oil temperature has settled down to normal | _ |
| | | Renew faulty part and readjust | Chap. 13 |
| | | Readjust | Chap. 13 |
| | | | |

insulating plate, and front face of the turbine disc is normal and of itself does not justify rejection of an engine. normal or is excessive. Also check the delivery of the rear bearing metering pump. Some of the oiliness may

particularly when the engine is new, or has been newly overhauled, of a thick film of fresh oil. Therefore, ensure that the apparent oil film is actually oil.

| | | Fit new leads | Aircraft hand- book |
|--|---|---|---------------------------|
| | | | Chap. 18 |
| Burners not functioning correctly due to dam- aged burners or clogged burner filters | Remove burners and examine without dismantling | Change burners as necessary | Chap. 14 |
| ii. Cracked or damaged combustion chambers | If condition is not cured, combustion chambers may have been damaged by the excessive temperatures. Remove and examine for cracks, distortion, etc. | Change combustion chambers as necessary | Chap. 16 |
| iii. Faulty distributor | | Change distributor | Chap. 14 |

| | Symptom | Primary Cause | Primary Investigation |
|-----|--|---|---|
| 12. | ABNORMAL VIBRATION | a. Unstable combustion at starting due to over-rich mixtures | This will die out as engine speed increases to idling |
| | | b. Damaged impeller or tur- bine blades | Examine in situ for damage |
| | | c. Defective engine-driven aircraft accessory | This type of vibration will become familiar to the operator, with engine running experience |
| | | d. Contact between engine and airframe structure | This may occur only when the engine is running, or when it is hot, carefully examine all likely points for evidence of rubbing or contact |
| | | | |
| | | | |
| | | e. Engine faulty | If vibration persists after removal of all accessories, or is encountered at other speeds, engine is faulty. |
| | FUEL PRESSURE WARNING LIGHT COMING ON AT ALTI- TUDE FOR NO APPARENT REASON | The bore of the pressure union in the side of the switch body blocked with shellac or dirt | Examine the bore of the union for blockage |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|---|--|--|--------------------------|
| | | No action required | |
| | | Remove engine and return for overhaul | Chap. 6 |
| | | Determine cause and rectify | _ |
| evealing no engine defect but omponents is the real cause of contact are:—Diffuser casin repection doors, pre-mod. 70 No. 8 burner shims on aircraft hamber castings on high-rate asing, No. 9 deflector cover ins on cable cover attached of the fireproof bulkhead and bolt one to rear bearing on fuel in | , unnecessarily, on grounds of vibration rub marks indicating that contact bet of the vibration. In Venom aircraft, ng and rear cover on cowlings and reta 4 and 914. No. 3 and 9 burner feed to main fuel pipe, pre-mod. 983. Combedischarge fire extinguisher pipes. Ca stud. Turbo-starter fins on fireproof to fireproof bulkhead. Drain pipes gots adjacent to air-intake front. Ghost manifold feed pipe bracket, pre-mod. | tween engine and airframe the most common points aining buckles for cowling pipes on aileron controls. Soustion chamber expansion bin air supply on diffuser bulkhead. Turbo-starter enerally. Engine controls 48 Mk. 2, metering pump 1117. Tungum pipe spill | Aircraf hand- book |
| | | Remove engine and return for overhaul | Chap. 6 |
| | | Remove shellac or dirt | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

DEFECT DIAGNOSIS TABLE
Ghost 48 Mk. 2
Based on Dowly Fuel Systems Ltd., table ENG. 220 Mk.2, issue 5, dated September 1955.

| Check the aircraft batteries and electric circuit Check ignition cable for continuity, insulation, and good contact at each end Fit two torch igniters which are known to be serviceable and attempt another start, or investigate as |
|---|
| Check ignition cable for continuity, insulation, and good contact at each end Fit two torch igniters which are known to be service- |
| Fit two torch igniters which are known to be service |
| Fit two torch igniters which are known to be service |
| |
| suggested in secondary cause iic |
| Remove the plug from the low pressure tapping of the valve head of the supply pump, insert adapter union S.T.5068-31 with the existing bonded seal and connect a 0-30 lb. per sq. in. pressure gauge to the union. Switch on the fuel tank booster pump and check that the static pressure is not less than 10 lb per sq. in. If the static pressure is satisfactory, attempt to start the engine. If during this attempt the pressure does not fall below 6 lb. per sq. in. failure to start may have been due to low r.p.m. A pressure of less than 6 lb. per sq. in. is probably due to a dirty filter or a faul upstream of the filter. If the engine still does not start, remove the blank from the manifold feed pipe elbow on the valve group unit. Connect a 0-100 lb. per sq. in. pressure gauge to the elbow. |
| per sq. in. should be observed. If the pressure i 10 lb. per sq. in. or greater, either the torch ignite or the torch igniter valve in the valve group unit, o both, are not operating correctly. |
| |

| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|-----|---|---|--|---------------------------|
| | | | | |
| | | | Change the batteries for ones known to be fully charged and without fault, or correct the defect in the electric circuit | |
| | | | Change defective ignition cable | Chap. 15 |
| i. | Fault in L.T. supply to high energy ignition unit | Check circuit for continuity and insulation | Rectify defect | Aircraft hand- book |
| ii. | Faulty high energy ignition unit | If the ignition unit can be heard operating but there is no high energy discharge, which is indicated by the discharge noise at the igniter plug, check the circuit from the battery to the ignition unit for an incorrect connection; i.e. the positive lead connected to a negative terminal or vice versa. As a quick check, the serviceability of a suspect unit may be checked by changing over the port and starboard units | Change faulty ignition unit for one known to be serviceable | Chap. 15 |
| | | | Fit two serviceable torch igniters | Chap. 15 |
| i. | Faulty fuel tanks booster pump | If the static pressure is below the figure specified the booster pump is faulty | Change the booster pump | Aircraft hand- book |
| ii. | Faulty valve group unit | Disconnect L.T. supply from ignition unit. Remove the torch igniter assembly from the combustion chamber, but still keep the pipe to the torch igniter connected. Simulate a start and ensure that a spray of fuel issues from the torch. | | |

DEFECT DIAGNOSIS TABLE Ghost 48 Mk. 2

| Symptom | Primary Cause | Primary Investigation |
|---|--|---|
| 2. NO LIGHT-UP AT STARTING (contd.) | d. Insufficient pressure at the supply pump inlet (contd.) | |
| | | |
| | | |
| | | |
| | | A pressure below 10 lb. per sq. in. on the 0-100 ll per sq. in. pressure gauge could possibly mean that there is no priming flow in the spill line which is due to a faulty priming valve. Also if the circuit control valve is stuck in the running position there will be no pressur (refer to secondary cause iib) |
| | | |

| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------|---|---|--|------------------------|
| ia. | Faulty isolating valve or torch igniter valve | lowing investigation:—Ensure that the booster pump is switched off. Remove the plug from the end of the banjo bolt at the downstream throttle connection on the valve group unit. Insert adapter union AGS.1105-A with the existing bonded seal and connect the hand pump to it. Turn on the H.P. cock. Disconnect the pipe leading from the torch igniter valve to the igniters, apply a pressure up to 50 lb. per sq. in. to open the isolating valve; fuel should flow from the torch igniter valve connection. If there is no flow at this pressure, either the torch igniter valve or isolating valve is faulty. | | Dowty hand- book |
| | | If there is a flow the torch igniter is faulty | Refer to secondary cause iic | |
| iib. | Faulty circuit control valve | If no pressure is created, the circuit control valve is stuck in the running position Disconnect the drain connection and attempt to release the valve. If this is unsuccessful remove the valve group unit and renew the complete circuit control valve group | | Dowty hand- book |
| ic. | Faulty torch igniter assemblies | Connect the hand pump to the pipe leading to the igniters at the torch igniter valve end and apply a pressure. If there is no spray at the torches either the pipe is blocked or the torch igniters are faulty | Disconnect the pipes at the torch igniter end and check that the pipes are not obstructed. If there is no obstruction renew the torch igniters | Chap. 1 |
| iid. | Faulty priming valve | The cause of not starting may be due to lack of priming, in which case the priming valve may be faulty To check this, disconnect the manifold feed and spill pipes at the valve group unit. With the ignition off simulate a start. Fuel should discharge from both pipes. If no flow is observed from the burner spill pipe, the priming valve is faulty | | Dowty hand- book |
| iie. | Faulty No. 4 non-return valve | If there is still no flow after testing the priming valve again, No. 4 non-return valve group valve is faulty | | Dowty hand- book |
| iif. | Faulty No. 1 non- return valve | If no flow is observed from the feed to manifold, No. 1 non-return valve is faulty | Remove the valve group unit and renew the complete No. 1 non-return valve group | Dowty hand- book |

| Primary Cause | Primary Investigation |
|--|--|
| d. Insufficient pressure at the supply pump inlet (contd.) | |
| a. Internal resistance in engine | This should have revealed itself during the running down check at previous shut-down; listen for undurinoise and check the rotor swing back during the run down as it is undesirable to continue to attempt to star the engine if some mechanical failure has occurred |
| b. Faulty starter | Low cranking r.p.m. caused by starter approaching encorporate of permitted service life. Check total number of shots fired |
| c. Inadequate fuel supply | |
| See page 8 | |
| Engine not warmed up | Run the engine above the idling speed for a shorperiod and then return to the idling speed |
| | |
| | d. Insufficient pressure at the supply pump inlet (contd.) a. Internal resistance in engine b. Faulty starter c. Inadequate fuel supply See page 8 |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|--|--|--|----------------------|
| iig. Faulty supply pump | Remove the plug from the high pressure tapping on the supply pump, insert adapter union S.T.5068-31 with the existing bonded seal, connect a 0-360 lb. per sq. in. pressure gauge to the union. With the ignition off and the throttle fully open simulate a start; check that the pressure on the 0-360 lb. per sq. in. pressure gauge is not less than 100 lb. per sq. in. at peak cranking speed. If it is less than 100 lb. per sq. in. the supply pump is faulty | Change the supply pump | Chap. 14 |
| | | | |
| | | Change starter Remove inspection plate and check cut-off | Chap. 19 Chap. 50 |
| | | Refer to Symptom 2 Primary Cause d | |
| | | | |
| Incorrect setting of the idling adjuster | Check the idling adjustment If the idling speed is high, and the effect of screwing in the idling adjuster fails to reduce the engine r.p.m., remove the plug from the high pressure tapping on the supply pump and insert adapter union S.T.5068-31, using the existing bonded seal. Connect a 0-1000 lb. per sq. in. pressure gauge in the union. Check that the pressure is 280 to 330 lb. per sq. in. WARNING: If the idling adjuster is screwed in too far, excessive pressure in the system will result. This may damage the flow control diaphragm and the | | |
| i. Faulty supply pump | If the pressure is above 330 lb. per sq. in. the minimum flow valve or the flow control unit is faulty To isolate the defective unit proceed as follows:—Remove the plug in the end of the servo pipe banjo bolt on the supply pump. Fit adapter union AGS.1105.A with the existing bonded seal in the banjo bolt and connect a 0-1000 lb. per sq. in. pressure gauge to the union If the servo pressure is virtually zero, the minimum flow device is faulty If the servo pressure is between 180 and 220 lb. per sq. in. the minimum flow device is satisfactory | Change the supply pump | Chap. 14 |

| | Symptom | Primary Cause | Primary Investigation |
|----|---|---|---|
| 5. | INCORRECT IDLING SPEED (contd.) | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | FULL THROTTLE R.P.M. EXCEEDS MAXIMUM | Governor mechanism on supply pump incorrectly adjusted | |
| | FULL THROTTLE DOES NOT GIVE | a. The governor mechanism on the supply pump in- correctly adjusted | Refer to symptom 13—Primary Investigation |
| | MAXIMUM PERMITTED R.P.M. | b. H.P. fuel shut-off and throttle not opening fully | Move H.P. fuel shut-off and throttle levers in cockpi to fully open position. Disconnect the control fron each lever on the valve group unit and check whethe the shut-off valves or the throttle can be moved furthe towards the open position |
| | | | |

| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------|-------------------------------------|---|--|---------------------------|
| ii. | Faulty flow control (F.C.) unit | If the pump pressure is 330 lb. per sq. in. or over, and idling r.p.m. and the servo pressure are high, the filter in the F.C. unit may be blocked | Remove the filter from the F.C. unit, clean, replace and test again | Dowty hand- book |
| | | If idling r.p.m. is high but with normal servo and supply pump delivery pressure the flow control unit diaphragm may be ruptured, proceed as follows:— Remove the banjo bolt from the upstream banjo connection at the valve group unit and fit adapter union S.T.5068-32. Connect the hand pump to the adapter union. Remove the banjo bolt from the downstream connection at the valve group unit and connect special banjo bolt S.T.5068-77. Attach a length of P.R. hose to this connection. Apply a pressure of 150 lb. per sq. in. with the hand pump and check for any leakage from the downstream connection. If there is any leakage the F.C. unit is faulty | Change the F.C. unit | Chap. 14 |
| iii. | Faulty circulating pump | If idling speed is in excess of 5000 r.p.m. and the pressures are normal, the circulating pump is faulty. Check as follows. Disconnect the return to tank fuel connection on the valve group unit and leave it open. Close the shut-off valves and check the quantity of fuel discharged from this connection. This should be at least $1\frac{1}{2}$ pints. If less than $1\frac{1}{2}$ pints is observed the circulating pump is faulty | Remove the valve group unit and renew the circulating pump complete | Dowty hand- book |
| | | If the pump delivery pressure is above 330 lb. per sq. in. and the idling speed is below 2800 r.p.m. the idling adjuster is faulty If the pressures are normal and the idling r.p.m. are low, screw out the idling adjuster and if the r.p.m. do not increase refer to Symptom 12 Primary Cause | Renew the idling adjuster assembly Ensure that the valve seat is not blown out when renewing the idling adjuster | Dowty hand- book |
| 4 | | | Adjust governor | Chap. 14 |
| | | | | |
| | | | Adjust aircraft portion of control until full movement is obtained and then check that when the lever closes in the cockpit, the H.P. shut-off and the throttle fully closes in the valve group unit | Aircraft hand- book |
| i. | Faulty A-F ratio control (A-F.R.C.) | Refer to Symptom 12 Primary Investigation. Open the throttle slowly during this operation. If maximum r.p.m. are obtained the A-F.R.C. is faulty | Change the A-F.R.C. | Chap. 14 |

DEFECT DIAGNOSIS TABLE Ghost 48 Mk. 2

| Symptom | Primary Cause | Primary Investigation |
|--|---------------|-----------------------|
| 7. FULL THROTTLE DOES NOT GIVE MAXIMUM PERMITTED R.P.M. (contd.) | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| INCORRECT OIL PRESSURE | | |
| ote.—It is assumed at the correct grade oil is in use. | See page 12 | |

| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------|-------------------------|---|--|------------------------|
| ii. | Faulty F.C. unit | With the servo pipes connected together as in Symptom 12 Primary Investigation, proceed as follows: Disconnect the spill pipe at the valve group unit and blank the connection on the valve group unit using outer sleeve A.G.S.904-BB, cone cap A.G.S.1159-BB and split pin A.G.S.166/2. Remove the plug from the downstream banjo connection on the valve group unit and insert adapter union A.G.S.1105-A with the existing bonded seal. Remove the plug from the upstream banjo connection, insert adapter union A.G.S.1105-A and connect a differential pressure gauge (250 lb. per sq. in.) to the unions. Start the engine and open the throttle fully | | |
| | | If fuel flows from the low pressure connection of the F.C. unit when there is a pressure differential of less than 80 lb. per sq. in. on the differential pressure gauge, the F.C. unit is faulty | Proceed as in Symptom 12 Secondary Investigation F.C. unit | |
| | | Retest and if still unsatisfactory the F.C. unit is faulty | Change the F.C. unit | Chap. 14 |
| iii. | Faulty supply pump | If no flow is observed from the low pressure connection of the F.C. unit and there is a pressure drop of less than 80 lb. per sq. in. the supply pump is faulty | Remove the supply pump restrictor and filter. Clean the filter. Re-assemble the filter only at this stage | Dowty hand- book |
| | | Insert plug assembly S.T.5068-36. Connect the hand pump, with a 0-2000 lb. per sq. in. pressure gauge in the circuit, remove the servo connector from the by-pass valve cover and replace with blank connector S.T.5068-38. Replace the by-pass valve cover. Apply a pressure of 1000-1200 lb. per sq. in. to the half-ball valve. The re-seat pressure must not be less than 800 lb. per sq. in. Disconnect the hand pump, re-assemble the restrictor plug and restrictor, replace the servo connector and retest. If there is still no flow from the low pressure connection of the F.C. unit, the supply pump is faulty | Change the supply pump | Chap. 14 |
| iv. | Faulty circulating pump | If fuel flows from the spill pipe connection at the F.C. unit and the difference is 95 lb. per sq. in. or above the circulating pump is faulty NOTE If the pressure lies between 80 and 95 lb. per sq. in. the F.C. unit, valve group unit, and supply pump are satisfactory | Remove the valve group unit and renew the circulat- ing pump complete | Dowty hand- book |

| Symptom | Primary Cause | Primary Investigation |
|---|--|--|
| 9. INCORRECT JET PIPE TEMPERATURE | a. Faulty thermocouple leads and connections | This is usually indicated by erratic temperature readings. Remove leads and check for continuity and insulation |
| Note.—The engine should be run for as | b. Faulty thermocouple | |
| short a time as possible to carry out these in- vestigations. | c. Burners not functioning correctly | Examine engine for possible local hot spots at root o combustion chambers, and check for correct position of biased burners |
| | | E |
| 10. ABNORMAL VIBRATION | See page 12 | |
| 11. FAST (i.e., less than 4 sec.) ACCELERATION OF ENGINE FROM 5000 to | Faulty A-F.R.C. | Fast acceleration may be due to a collection of foreign matter in the external servo filter in the A-F.R.C. |
| 10100 ENGINE R.P.M. | | Test again and if this test is unsatisfactory the A-F.R.C. is faulty |
| 12. SLOW OR NO ACCELERATION, (i.e., more than 8 secs.) TO | Faulty A-F.R.C. | Disconnect and remove the two servo connections from the A-F.R.C. and connect the two servo pipes together using elbow union S.T.5068-28 Disconnect the spill pipe at the valve group unit and |
| ACCELERATE THE ENGINE from 5000 to 10100 R.P.M. WHEN OPENING THE THROTTLE | | blank off the banjo union using outer sleeve AGS 904-BB, cone cap AGS.1159-BB and split pin AGS.166/2 Start the engine. Accelerate through the range quoted If the acceleration time is less than 5 seconds the A-F.R.C. is at fault, which may be due to an obstructed filter |
| RAPIDLY | | After replacing the filter and restrictor connect the A-F.R.C. to the system and accelerate the engine. |
| | | If the engine again fails to accelerate repeat the above investigation and if the engine then accelerates the A-F.R.C. is faulty |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|--------------------------|---|---|------------------------|
| | | Fit new leads | |
| | | Fit new thermocouple and recheck | |
| Faulty A-F ratio control | Disconnect air pressure pipe from A-F.R.C. Start booster pump. If fuel drips or flows from air pressure connection A-F.R.C. is faulty The above only applies if overheating takes place in No. 5 combustion chamber at idling speed | Change the A-F.R.C. | Chap. 14 |
| II. | | | |
| | | Remove and clean the exter- nal servo filter. Renew the 'O' ring seal in the filter | Dowty hand- book |
| | | Change the A-F.R.C. | Chap. 14 |
| | | Remove the restrictor and filter of the internal servo circuit. Clean the filter. Renew the 'O' ring seal on the restrictor. Replace the assembly | Dowty hand- book |
| | | Change the A-F.R.C. | Chap. 14 |
| i. Faulty F.C. unit | If, with the A-F.R.C. isolated, the acceleration takes more than 5 secs., with fuel flowing freely from the spill connection of the F.C. unit during acceleration and below 10000 r.p.m., the F.C. unit is faulty. Proceed as follows: Disconnect the servo connection at the F.C. unit, fit adapter union S.T.5068-33 to the servo connection and connect the hand pump, with a 0-2000 lb. per sq. in. pressure gauge in the circuit, to the union adapter Apply a pressure of 1500 lb. per sq. in. to the half-ball servo valve. This pressure must be maintained. Check for leakage, which will be indicated by a loss of pressure shown on the 2000 lb. per sq. in. pressure gauge. If 1500 lb. per sq. in. is not maintained the F.C. unit is faulty. If there is a leakage, connect the hand pump and up stream and servo connections of the F.C. unit | Change the F.C. unit | Chap. 14 |

| | Symptom | Primary Cause | Primary Investigation |
|-----|---|----------------------------|--|
| 12. | SLOW OR NO ACCELERATION (i.e., more than 8 secs.) TO ACCELERATE THE ENGINE from 5000 to 10100 R.P.M. WHEN OPENING THE THROTTLE RAPIDLY (contd.) | Faulty A-F.R.C. (cont.) | |
| | | | |
| | | | |
| | | | |
| | | | |
| | , | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| 12 | INCONSISTENT | Ambient temperature condi- | Variations between plus 30 and minus 50 r.p.m. from |
| 13. | GOVERNING | tions | the normal governed speed may be ignored unless they are habitual, in which instance adjust the governor mechanism to meet the different operating conditions. Variations greater than this must be investigated and remedied. Refer to Symptoms 6 and 7 |
| 14. | FUEL PRESSURE WARNING LIGHT COMING ON AT ALTITUDE FOR NO APPARENT REASON | See page 12 | |

| Faulty F.C. unit (cont.) | Remove the banjo belt from the upstream banjo connection on the valve group unit and insert special banjo bolt ST. 5068-32. Disconnect the servo pipe from the F.C. unit and fit adapter union assembly ST.5068-33. Connect flexible hose assembly ST.5068-78 to the special banjo bolt and adapter union, and the hand pump to the remaining connection on the hose assembly. Apply a pressure of approximately 100 lb. per sq. in. which will lift the diaphragm and allow a flow of fuel to clear any obstruction under the half-ball servo valve. Repeat the previous test by running the engine. If there is virtually no flow, i.e. a drip rather than a steady flow, from the spill connection when running at idling speed, and acceleration is still slow, the supply pump or circulating pump is faulty | | |
|-----------------------------|---|--|------------------------|
| ii. Faulty circulating pump | Reconnect the servo pipe to, and disconnect the compressor pressure pipe from the A-F.R.C. Blank the compressor pressure pipe using cone plug A.G.S.1143B. The A-F.R.C. will then limit the flow to 300 gall. per hr. With the throttle fully open the r.p.m. should be above 7000 If it does not reach 7000 r.p.m. fuel is being lost downstream of the unit and | Remove the valve group unit and renew the circulating pump complete | Dowty hand- book |
| ii. Faulty supply pump | If the speed is 7000 r.p.m. or greater the supply pump is not performing correctly at maximum r.p.m. | Remove the supply pump restrictor and filter. Clean the filter; re-assemble the filter only at this stage | |
| | Insert the plug assembly S.T.5068-36. Connect up the hand pump, with a 0-2000 lb. per sq. in. pressure gauge in the circuit. Remove the servo connector from the by-pass valve cover and replace with blank connector S.T.5068-38. Replace the by-pass cover. Apply a pressure of 1000-1200 lb. per sq. in. to the half-ball valve. The re-seat pressure must not be less than 800 lb. per sq. in. Disconnect the hand-pump and re-assemble the restrictor plug, restrictor, servo connector and test again for acceleration. If this is still unsatisfactory, the supply pump is faulty | Change the supply pump | Chap. 1 |
| | | | |
| | | | |

DEFECT DIAGNOSIS, GHOST FIFTY-THREE Mk. 1

Defect investigation in respect of the Ghost 53 Mk. 1 follows the same pattern, and uses the same test equipment, as for the Ghost 48 Mk. 1 in so far as it concerns the mechanical aspects of the basic fuel system components which are common to both Marks. The electric max. r.p.m. control fitted to the Ghost 53 Mk. 1 is separate from the basic system; it obtains its controlling data from sources outside the fuel system, and only enters directly into the system at the servo throttle by which it exercises the master control of the flow of fuel to the burners. The Ghost 53 Mk. 1 system components can be divided into three groups:—

- The electric, "sensing", group of the electric max. r.p.m. control; consisting of the altitude compensating unit, and the magnetic amplifier unit which receives its operative signal from the engine-driven tachometer generator; and its power supply from the aircraft flight instruments' inverters.
- 2. The electro-mechanical, "action", group of the electric max. r.p.m. control which links the purely electrical (1) with the purely mechanical (3) groups, and varies the fuel flow independently of the pilot's throttle setting; thus performing the actual control of maximum engine r.p.m. This group consists of the line pressure control unit, and the servo throttle.
- 3. The basic fuel system.

The approach to defect investigation differs in each of these groups. In the first group the electric current output from the magnetic amplifier to the line pressure control unit is measured and recorded at various engine r.p.m., and the readings are plotted as a graph. In the second, a known, controllable and independent D.C. electric current is applied to the line pressure control unit and the consequent effect on engine r.p.m. is recorded and plotted. In the third group it is the hydraulic pressures within the basic fuel system which are measured and recorded. In each case it is the characteristics of the results so obtained which lead to diagnosis of the defect and its correction.

TEST EQUIPMENT FOR DEFECT DIAGNOSIS

Two sets of electric test equipment are required for the diagnosis of defects in the electric max. r.p.m. control equipment. These are:—

- That required to measure the output of control current from the magnetic amplifier to the line pressure control unit. This equipment is known as the Routine Test Set, and is described on page 50. The test which it is used to apply is called the Gain Check.
- That required to apply a known, controllable, and independent D.C. current to the line pres-

sure control unit. This equipment also is described on page 52. For the purposes of this Table it is known as the D.C. Test Set, and the test for which it is used is called the D.C. Check.

Equipment required for carrying out pressure and other checks of the basic fuel system is that listed on page 3 with the addition of three special adapters T.79447, T.79450, and T.79474 which enable the existing pressure test equipment to be connected into the Ghost 53 Mk. 1 fuel system. Instructions for the use of these adapters are given in the table where appropriate. It should be noted that in the case of the Ghost 53 Mk. 1 whilst the hand-held tachometer-Smiths A.T.H.7-can be used for accurate measurement of r.p.m. for setting the hydraulic governor mechanism or for calibrating the cockpit engine r.p.m. indicator, this can be done only when the electric max. r.p.m. control equipment is inoperative, because this control operates upon a continuous electric signal from the tachometer generator the drive for which, therefore, cannot be made available to operate the hand-held tachometer.

DEFECT DIAGNOSIS CHECKS, CHECK RECORDS, AND THEIR INTERPRETATION

Gain check

The Gain Check is carried out as follows:-

- Ensure that the controlled max. r.p.m. is set correctly at 10350 r.p.m.
- 2. Plug the Routine Test Set into the test socket in the electric max. r.p.m. control system, and turn the Test Set control switch to No. 1 position. The test socket which is provided in the aircraft cockpit taps into the circuit between the magnetic amplifier unit and the line pressure control unit.
- Open the throttle slowly and record the current indicated by the Test Set microammeter at idling, at about 10000 r.p.m., at 10300 r.p.m., and at full throttle. Observe particularly the r.p.m. at which the indicated current starts to increase; this will normally become clearly perceptible over a range of 10 r.p.m. Close the throttle. The current flowing in the circuit between the magnetic amplifier unit and the line pressure control unit is in milliamps; that indicated by the Test Set meter is in microamps; but if the Test Set has been calibrated correctly the numerical values of both currents will be the same. Thus, 20 microamps indicated by the Test Set meter will indicate that 20 milliamps is the actual current flow in the circuit between the magnetic amplifier unit and the line pressure control unit.
- Plot the readings obtained as a graph—Fig. 2 is a typical example.




Fig. 2. Gain Check. Magnetic amplifier gain, typical curve.

Fig. 2 illustrates a typical curve obtained by applying the Gain Check. The interpretation of the various aspects of the curve are as follows:—

- Datum. The line BD represents the maximum full throttle r.p.m. attained by the engine when under the control of the electric max. r.p.m. control equipment. This r.p.m. is adjustable by means provided within the electric control equipment, and the correct pre-setting of this adjustment, so that the maximum controlled r.p.m. of engine does not exceed the permissible limit for the engine type, is essential to the correct functioning of the engine. The r.p.m. to which the engine is so controlled is known as the "datum", and for the Ghost 53 Mk. 1 this datum is 10350 r.p.m. Adjustments to the datum r.p.m. are made on the Datum control, marked 'D' on the magnetic amplifier unit; adjustments so made have the effect of moving the line BD bodily along the horizontal scale.
- 2. Standing current. The steady line pressure control controlling current depicted by the line CA is called the "standing current". This should be approximately 75 milliamps but may vary up to approximately 100 milliamps when the engine is first started and until the system has warmed up. The standing current is adjusted by the Bias control, marked 'B' on the magnetic amplifier unit, this adjustment being permissible only when the magnetic amplifier unit is being bench calibrated prior to issue for service. No adjustment of the Bias control is permissible during routine servicing.
- 3. Magnetic amplifier gain. The increase in con-

- trolling current output of the magnetic amplifier unit from the "standing current" at point A, the beginning of operation of the electric max. r.p.m. control, to the maximum at point B, the point of maximum controlled engine r.p.m., is called the magnetic amplifier gain. The value of the gain is given by the line BD.
- 4. Take-over range. The line AD represents the range of engine r.p.m. over which the electric max. r.p.m. control operates to assume full control of the maximum engine r.p.m. This is known as the "take-over range".
- Rate of gain. The efficiency of the electric max, r.p.m. control system is directly affected by the rate of gain of the magnetic amplifier output of controlling current, that is to say the variation of the line BD relative to the line AD, or, the variation of the angle BAD. Provided that the line BD is fixed correctly by the pre-setting of datum before the Gain Check is carried out, then the position of the point A along the line CD provides a direct indication of the value of the magnetic amplifier gain. For correct functioning of the system, the point A should be between 10000 and 10100 r.p.m. and be as near 10000 r.p.m. as possible. Adjustment of the position of point A is made on the Gain control, marked 'G' on the magnetic amplifier unit, this adjustment being permissible only when the magnetic amplifier is bench calibrated prior to issue for service. Any adjustment of the gain setting will alter the amplifier datum setting, which will require re-adjustment accordingly. No adjustment of the amplifier gain is permissible during routine servicing.




Fig. 3. Direct Current (D.C.) Check. Line pressure control/servo throttle group characteristic, typical curve.

D.C. Check

The D.C. Check is carried out as follows:-

- Disconnect the Breeze connector from the line pressure control unit, and connect in its place the connector of the D.C. Test Set.
- 2. Taking care not to overspeed the engine, and with the test set applied current at zero, open the throttle to 10350 r.p.m. Do not forget that there is no governor to control the max. r.p.m. attainable and that control relies solely on the operator's manipulation of the throttle lever.
- With the throttle locked in this position, increase the applied current in 25 milliamp stages to a maximum of 450 milliamps, recording at each stage the indicated engine r.p.m. Close the throttle.
- 4. Plot the readings obtained as a graph—Fig. 3 is a typical example.

Fig. 3 illustrates a typical curve obtained by applying the D.C. Check. The interpretation of the various aspects of the curve is as follows:—

- The curve depicts the actual effectiveness of the line pressure control unit in conjunction with the servo throttle in controlling the flow of fuel to the burners and, therefore, the engine r.p.m. The whole curve is called the characteristic of the line pressure control/servo throttle group.
- The slope of the curve between the points P and Q, that is over an applied current range

- of 200 to 350 milliamps, is particularly important and should be not less than 150 r.p.m. and not more than 350 r.p.m. per 25 milliamp applied current. There is no direct adjustment provided for varying the slope of the curve.
- 3. The curve should be smooth, and free from "steps".

Negative Rate Check

The Negative Rate Check is made during a full throttle climb to altitude, readings of engine r.p.m. being recorded at intervals of about 3000 ft. altitude from about 7000 ft., these being plotted as a curve on return to base.

Fig. 4 illustrates a typical curve obtained by a Negative Rate Check. It is interpreted as follows:—

- The curve records the actual effectiveness of the whole electric max. r.p.m. equipment in controlling the maximum engine r.p.m. at all heights.
- From L to M the basic datum setting of the electric equipment is operative and the maximum r.p.m. is controlled to a steady 10350. The curve should be level, free from irregularities, and within ± 50 r.p.m. of the datum—see also page 33, sub-para. 1.
- At point M the altitude compensating unit comes into operation and from then the maximum engine r.p.m. is controlled to a value decreasing progressively with increasing altitude.

Issued by Amendment No. 132 April, 1957




Fig. 4. Negative Rate Check. Full throttle climb to height, typical curve.

This negative acceleration of engine r.p.m. is called the "negative rate". The point M should occur at about 23000 ft. At point N, 40000 ft., the controlled max. r.p.m. should be approximately 10200 r.p.m.

4. The curve from M to N should be smooth and free from steps and irregularities. There is no adjustment provided for varying the position of point M, this being governed by the setting of the altitude compensating unit aneroid capsule during manufacture. The angle of the curve MN, that is the negative rate, is adjusted on the Negative Rate control spindle, marked "N.R.", on the magnetic amplifier unit.

MISCELLANEOUS ADJUSTMENTS

The following adjustments are provided in the magnetic amplifier unit in addition to those already described:—

- Anticipation. This term is applied to that aspect of the magnetic amplifier electrical design whereby the tendency for engine r.p.m. to mount rapidly to overspeeding during rapid accelerations is anticipated and corrected. A direct adjustment of Anticipation is provided, marked 'A' on the magnetic amplifier unit, and this should be set to give the minimum overshoot of r.p.m. when the throttle is opened rapidly from 9800 r.p.m. to full throttle: clockwise rotation of the spindle increases the effect. This adjustment is set correctly when the magnetic amplifier is bench calibrated prior to issue for service, and no adjustment is permitted during routine servicing-see Velocity Feed Back, below.
- Velocity Feed Back. This term describes the rate of response of the magnetic amplifier control current to an overspeed signal from the tachometer generator. Direct adjustment of this rate of response is provided at spindle "V.F.B." on the magnetic amplifier unit; clockwise rotation of this spindle slows the magnetic amplifier response, gives greater stability under steady running conditions, but reduces the response of the system to momentary changes in r.p.m. and thus tends to result in overshooting of r.p.m. during accelerations. This control should, therefore, be set as far anti-clockwise as is consistent with steady running stability. This adjustment is set correctly prior to the issue of the magnetic amplifier unit for service, and no adjustment is permitted during routine servicing. The Anticipation and Velocity Feed-Back controls have a slightly inter-related effect, and adjustments should be made conjointly.
- 3. Isolating Compensation. This term describes the adjustment provided in later design magnetic amplifiers,—Type 390/1—by which the normal variation in engine r.p.m. resulting from the operation of the fuel pump isolating switch can be reduced to a minimum.

GOVERNOR ADJUSTMENTS

Whenever it is necessary to change the magnetic amplifier unit in the electric max. r.p.m. control equipment it is important to remember that the datum, isolating compensation, and negative rate adjustments must be checked and, if necessary, corrected.

DEFECT DIAGNOSIS TABLE Ghost 53 Mk. 1

| rage 50 | Gliost 3. | onost Torty-cight |
|---|--|---|
| Symptom | Primary Cause | Primary Investigation |
| 1. ENGINE DOES NOT ROTATE AT STARTING (TURBO STARTER FAILURE) | | er to Symptom 1 on page 4 |
| 2. NO LIGHT-UP AT STARTING | Ref | er to Symptom 2 on page 4 |
| 3. FAILURE TO ACCELERATE AFTER LIGHT-UP | Ref | er to Symptom 3 on page 8 |
| 4. FAULTY STARTING, JUDDERING | Ref | er to Symptom 4 on page 8 |
| 5. INCORRECT IDLING SPEED | Ref | er to Symptom 5 on page 8 |
| 6. FAILURE TO GOVERN | a. Electric max. r.p.m. con- trol datum setting too high | Check datum adjustment, marked 'D', in magnetic amplifier |
| | b. No L.P.C. controlling current | Apply Gain Check (refer to page 32) and record L.P.C. control current at idling and 10350 r.p.m. Current at idling should be about 75 m.A. |
| | | If current at 10350 r.p.m. is adequate, i.e., exceeds about 200 m.A., refer to Primary Cause c. |
| | c. Failure of L.P.C./servo throttle group | Apply D.C. Check (refer to page 34). This should result in a reduction of engine speed to about 7000 r.p.m. at 450 m.A. applied current. If the r.p.m. does not fall below 8000 proceed as described in col. 4, 5, and 6. |
| | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|---|---|---|---------------------------|
| | | | |
| | | | |
| | | | |
| | · | Deduce deturn cetting Apri | |
| | | Reduce datum setting. Anti- clockwise rotation of spindle reduces governing r.p.m | |
| i. No such standing cur- rent indicates failure of power supply, or circuits from aircraft inverter to magnetic amplifier, or magnetic amplifier to L.P.C. | Check inverter output. Test electric circuits | Change inverter Rectify wiring defects | Aircraft hand- book |
| i. Presence of standing current but failure of cur- rent to increase with r.p.m. indicates failure of electric circuit within magnetic amplifier, or of output from tachometer generator | Test electric circuit Check tachometer generator output | Rectify wiring Change tachometer generator | Aircraft hand- book |
| iii. Faulty magnetic am- plifier | | Change magnetic amplifier | Aircraft hand- book |
| | | Change the L.P.C./servo throttle group, and repeat the D.C. Check. | |

IMPORTANT

If either the line pressure control (L.P.C.) or the servo throttle is to bé changed, or renewed, BOTH units must be removed and a MATCHED PAIR of units fitted.

This instruction affects those given on pages 39, 41, 43, 45, 47, and 49, and in each instance the instructions in the "Remedial Action" column "change L.P.C.", "change servo throttle", must be regarded as being instructions to **change the L.P.C./servo throttle group**, and to apply the D.C. Check after the replacement matched pair of units has been fitted.

| Symptom | Primary Cause | Primary Investigation |
|--|--|---|
| 7. CONTINUOUS R.P.M. FLUCTUATION i.e., ELECTRIC MAXIMUM R.P.M. CONTROL IS UNSTABLE | incorrect rigging of control cir. H.P. fuel cut-off valve in the c throttle" on page 12. | following checks, ensure that the trouble is not caused by reuit between the H.P. cock lever in the cockpit and the ontrol valve assembly. Refer to "Unstable r.p.m. at full Check hydraulic governor adjustment |
| | max. r.p.m. control | |
| | b. Too high a magnetic amplifier gain | Apply Gain Check (refer to page 32) |
| | c. Insufficient rate in the L.P.C./servo throttle group | Apply D.C. Check (refer to page 34). The curve should show a minimum slope of 6 r.p.m. per milliamp between 250 and 350 m.A. applied current |
| | d. Unstable current supply to magnetic amplifier | |
| | e. Insufficient magnetic amplifier damping | , |
| | f. Unstable basic fuel system | |
| 8. GOVERNED R.P.M. DECREASI STARTS AT WRONG ALTITUDE | a. Faulty altitude compensation | If practicable, plug in Routine Test Set, and, during a climb to height, record L.P.C. current against altitude. If the control current progressively decreases with height, then the basic fuel system is more likely to be at fault—see Primary Cause b |
| | unit cut-in point by 2000 to 30 | compensating unit be connected in error to the aircraft total 1000 feet dependent upon the airspeed. At altitudes higher should a leak occur from the cockpit pressure line to the |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|---|--|---|---------------------------|
| | | | |
| i. Incorrectly set hydraulic governor | | Adjust hydraulic governor | |
| ii. Faulty hydraulic gover- nor mechanism | | Change fuel pump | |
| If the point of rise of controlling current occurs outside the limits 10000 r.p.m. to 10100 r.p.m. the amplifier gain setting is incorrect. | | Change magnetic amplifier | Aircraft hand- book |
| | | Suspect, and change, in this order:— L.P.C. unit Servo throttle Fuel flow distributor. Apply D.C. Check after each change | |
| i. Unstable 110 V. inverter output | Check inverter output | Change inverter | Aircraft hand- book |
| i. Unstable tachometer generaor signal to mag- netic amplifier | Check wiring | Rectify wiring Change tachometer generator | Aircraft hand- book |
| i. Wrongly set "VFB" and 'A' controls on magnetic amplifier | | Change magnetic amplifier | Aircraft hand- book |
| i. Faulty magnetic am- plifier | | Change magnetic amplifier | Aircraft hand- book |
| . Faulty B.P.C. | | Change B.P.C. | |
| i. Faulty fuel flow dis- tributor | | Change fuel flow distributor | |
| Faulty altitude compensating unit | Fit a vacuum pump to the altitude compensating unit in place of the flight instruments' static pressure pipe, with an altimeter in the circuit. Run the engine at full throttle and slowly depress the A.C.U. static pressure and check the indicated height at which the engine speed starts to decrease. This should occur between 22000 and 23000 ft. If faulty, change the altitude control unit | | Aircraft hand- book |
| | "static" pressure, this would result in dela trolled engine speed would vary proportion atic pressure line. | | |

| Symptom | Primary Cause | Primary Investigation |
|--|--|---|
| 8. GOVERNED R.P.M. DECREASE STARTS AT WRONG ALTITUDE (contd.) | b. Inadequate fuel supply to burners giving the impres- sion that the negative rate compensation starts too soon | |
| 9. GOVERNED R.P.N | M. TOO HIGH | , |
| 9-1. ENGINE R.P.M. CANNOT BE REDUCED BY MEANS OF DATUM ADJUSTMENT | a. Inadequate magnetic amplifier datum range | Apply Gain Check. Record L.P.C. control current a 10350 r.p.m. If control current is less than 300 m.A., the probable cause is i, ii, or iii |
| | | If control current is appreciably higher than 300 m.A the fault is probably in the fuel system; iv |
| 9·2. TEMPORARY | NOTE.—This symptom can b | e caused by an over-sensitive r.p.m. indicator |
| EXCESS OVER- SHOOT OF R.P.M ON OPENING THE THROTTLE FROM ABOUT 10000 R.P.M. (i.e., GREATER THAN 150 R.P.M.) | | |
| | | |
| 9·3. IF AT ALTITUDE | c. Wrongly set negative rate control on magnetic am- plifier | |

| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------|---|---|--|---------------------------|
| i. | Faulty B.P.C. | | Change B.P.C. | |
| ii. | Faulty A-F.R.C. | Disconnect the compressor delivery pressure line to A-F.R.C. Disconnect pipe control valve assembly to A-F.R.C. at the control valve assembly: fit adapter T.79474 to the control valve assembly in place of the pipe: connect pressure gauge T.75050 to the adapter, and reconnect the pipe line to the other end of the pressure gauge T-piece, using adapter T.77097. Run the engine at full throttle: the pressure recorded should be not less than 550 lb. per sq. in. | Change A-F.R.C. | |
| iii. | Faulty fuel flow dis- tributor | | Change fuel flow distributor | |
| | Defective datum adjust- ment in magnetic am- plifier Defective datum adjust- | With the engine throttled to an r.p.m. well below max. permissible, exercise each datum control in turn | If still unsatisfactory change magnetic amplifier or altitude compensating unit as appro- priate | Aircraft book hand- |
| | ment in altitude com- pensating unit | | 4 | |
| iii. | Faulty magnetic ampli- fier internal circuit | | Change magnetic amplifier | Aircraft hand- book |
| iv. | Too flat a L.P.C./servo throttle group control characteristic | Apply D.C. Check. The results, when plotted, should show a minimum slope of 6 r.p.m. per milliamp between 250 and 350 m.A. applied current | Suspect, and change in this order:— L.P.C. Servo throttle Fuel flow distributor Apply D.C. Check after each change | |
| i. | Incorrectly set 'Velocity Feed Back' and 'Antici- pation' controls on mag- netic amplifier | | Change magnetic amplifier | Aircraft hand- book |
| ii. | Too high a magnetic amplifier gain setting | | Change magnetic amplifier | Aircraft hand- book |
| iii. | Over-sensitive magnetic amplifier internal circuits | | Change magnetic amplifier | Aircraft hand- book |
| iv. | Over - sensitive fuel system | | Suspect, and change, in this order:— L.P.C. Servo throttle | |
| | , | | Adjust negative rate control spindle marked "NR" on magnetic amplifier. One quarter turn of the control spindle clockwise will give approximately 20 r.p.m. decrease at altitude | |

| Symptom | Primary Cause | Primary Investigation |
|--|--|---|
| 9·3. IF AT ALTITUDE (contd.) | d. Faulty altitude compensating unit, or faulty wiring between altitude compensating unit and magnetic amplifier | Fit a vacuum pump to the altitude compensating unit, in place of the flight instruments' static pressure pipe, and with an altimeter in the circuit. Run the engine at full throttle and slowly depress the altitude compensating unit to about 40000 ft. indicated. This should result in a reduction of the controlled r.p.m. by about 200 r.p.m. |
| | e. Faulty magnetic amplifier | |
| | f. Too high a basic fuel system flow | |
| 10. GOVERNED R.P.M. TOO LOW | a. Incorrect hydraulic gover- nor setting | Switch off the electric max. r.p.m. control, by switching off the aircraft inverters, and determine whether the electric system is in control |
| 10·1. R.P.M. CANNOT BE INCREASED BY DATUM ADJUSTMENT | b. Faulty electrics | Apply Gain Check and note the L.P.C. controlling current at full throttle. If the current does not rise from the standing current then refer to Primary Cause c below. If, however, the current rises above the standing current then the cause is electrical. |
| | c. Inadequate fuel supply to | |
| | This defect could result from the H.P. fuel cut-off valve in the control valve assembly not opening fully. Before undertaking the following tests refer to page 4 — Symptom 2, d, i. | |
| | | |

| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------|--|---|--|----------------------------|
| | | | Change altitude compensating unit Rectify wiring | Aircraft hand- book |
| i. | Faulty negative rate adjustment | Adjust negative rate control | | |
| ii. | Too low an amplifier gain | Apply Gain Check | Change magnetic amplifier | Aircraft hand- book |
| iii. | Faulty internal nega- tive rate circuit | | Change magnetic amplifier | Aircraft hand- hand- |
| i. | Faulty L.P.C. / servo throttle group charac- | Apply D.C. Check. The slope of the resultant curve should be not less than 6 r.p.m. per m.A. between 250 and 350 m.A. | If unsatisfactory, suspect, and change, in this order:— L.P.C. Servo throttle Fuel flow distributor Apply D.C. Check after each change | |
| ii. | Too high B.P.C. setting at altitude condition | | Change B.P.C. | |
| | | Check hydraulic governor setting | Adjust hydraulic governor | |
| i. | Faulty datum adjustment in magnetic amplifier | Re-set datum adjustment on magnetic amplifier | | |
| ii. | Faulty amplifier internal circuit | | Change magnetic amplifier | Aircraft hand- book |
| iii. | Speed signal to mag- netic amplifier from the wrong phase of tacho- meter generator | | Rectify incorrect connection | |
| i. | Faulty L.P.C. | Blank off the pipe line servo throttle to L.P.C. at the servo throttle. If the engine can now be overspeeded, then the L.P.C. is faulty. | Change L.P.C. | |
| ii. | Faulty servo throttle | Remove the banjo pillar from the top of the high pressure fuel filter and in its place fit pressure test adapter T.79447. To this attach pressure gauge T.75050, keeping the blank on the other end of the pressure gauge T-piece. Remove the banjo pillar from the servo throttle pipe connection at the base of the control valve assembly and substitute pressure gauge adapter T.79450. To this attach a second pressure gauge T.75050, keeping the blank on the other end of the T-piece. Switch off the electric max. r.p.m. by switching off the aircraft inverters, open the throttle to max. permissible r.p.m. and measure the pressure drop across the servo throttle. If this drop exceeds 100 lb. per sq. in. the servo throttle is defective. | Change the servo throttle | |

| Symptom | Primary Cause | Primary Investigation |
|--|--|---|
| 10·1. R.P.M. CANNOT BE INCREASED BY DATUM ADJUSTMENT (contd.) | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| 10·2. ENGINE ACCELERATION SLUGGISH AT HIGHER R.P.M. | d. Over anticipation by mag- netic amplifier | |
| | | |
| | e. Inadequate fuel supply to burners | Refer to c. on page 42 |
| | f. Faulty L.P.C./servo throttle group | |
| 10·3. R.P.M. LOW AT ALTITUDE ONLY | g. Negative rate adjustment wrongly set | |
| ONLT | h. Insufficient negative rate adjustment in system | Plug in Routine Test Set and record the control current during a full throttle climb to height. If the control current progressively decreases with height, this indicates an inadequate fuel supply to the burners—refer to c. on page 42. |
| | | |
| | | |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|---|--|--|---------------------------|
| iii. Faulty fuel pump | With the pressure gauge T.75050 still in place in the high pressure fuel filter banjo pillar, blank off the servo pressure lines to the B.P.C. and A-F.R.C. and switch on the electric max. r.p.m. control by switching on the aircraft inverters. Run the engine at full throttle and note the pump delivery pressure. If this falls off to about 1000 lb. per sq. in., either the pump hydraulic governor is set too low or the fuel pump output is low. | Increase the governor setting, and if the pump delivery pressure still falls off, change the pump | |
| iv. Faulty B.P.C. | Reconnect the servo pipe line from pump to B.P.C. Disconnect the delivery pressure pipe line fuel pump to B.P.C. at the fuel pump connection, fit pressure gauge T.75050 with adapter T.77098 to this pump connection and reconnect the pipe to the pressure gauge T-piece. With the engine running slowly a pressure of 1350 ± 100 lb. sq. in. should be recorded. If this pressure is not maintained at all engine r.p.m. except governing, the B.P.C. is faulty | Change B.P.C. | |
| v. Faulty A-F.R.C. | Reconnect the fuel pump servo line to the A-F.R.C. With pressure gauge T.75050 still fitted in the high pressure fuel filter banjo pillar, open the throttle fully and record fuel pump delivery pressure. If this falls off on approaching max. r.p.m. then either the A-F.R.C. is faulty or the compressor delivery pressure line to the A-F.R.C. is leaking. | Check the compressor delivery pressure line to A-F.R.C. for leaks. If there are no leaks change the A-F.R.C. | |
| vi. Faulty burners | High burner pressure | Change burners | |
| vii. Faulty fuel flow dis- tributor | | Change fuel flow distributor | |
| i. Incorrectly set "Antici- pation" control on the magnetic amplifier | | Change magnetic amplifier | Aircraft hand- book |
| ii. Faulty magnetic am- plifier | | Change magnetic amplifier | Aircraft hand- book |
| Refer to c. above | | | |
| | | Change in this order:— L.P.C. Servo throttle | |
| | | Adjust control "NR" on magnetic amplifier | |
| i. Faulty altitude com- pensating unit | | Change unit | Aircraft hand- book |
| ii. Faulty wiring between al- titude compensating unit and magnetic amplifier | | Rectify wiring | Aircraft hand- book |
| iii. Faulty magnetic amplifier | | Change unit | Aircraft hand- book |

DEFECT DIAGNOSIS TABLE Ghost 53 Mk. 1

de Havilland Ghost Forty-eight

| | Symptom | Primary Cause | Primary Investigation |
|-----|---|--|--|
| 11. | GOVERNED R.P.M. INCREASES WITH FORWARD | a. Too low an amplifier gain | Apply Gain Check. If the gain is correctly set, refer to b. below. |
| | SPEED | b. Too high a basic fuel system flow | |
| 12. | GOVERNED R.P.M. FALLS | a. Faulty hydraulic governor setting | Check hydraulic governor setting |
| , | EXCESSIVELY WITH FORWARD SPEED | b. Insufficient fuel system compensation with forward speed | |
| | | c. Too great a fuel operating pressure increase with forward speed | |
| | | d. Inadequate fuel pressure | |
| | ELECTRIC MAX. R.P.M. CONTROL DATUM DIFFICULT TO SET | a. Faulty controls within the magnetic amplifier | Check, by individual manipulation of the datum control spindles, whether the symptom is applicable to the adjustment located in the altitude compensating unit, or that in the magnetic amplifier itself |
| | | b. Uneven L.P.C. / servo throttle group characteristics; i.e., steps in the characteristic curve | Apply D.C. Check but increasing the input current in very small stages. The result should be a smooth curve |
| 14. | TOO GREAT A VARIATION OF | a. Incorrectly set isolation trim adjustment | |
| | R.P.M. ON OPERATING THE ISOLATING SWITCH | b. Incorrect rates in the speed control equipment | Disconnect from the isolating switch the compensating current from the magnetic amplifier, and check the engine r.p.m. response on switching the isolating switch ON. This should be about 50 r.p.m. increase. |

| Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|---|--|---|---------------------------|
| | | Change magnetic amplifier | Aircraft hand- book |
| i. Too flat an L.P.C./servo throttle group charac- teristic | Apply D.C. Check. The slope of the curve between 250 m.A. and 350 m.A. should not be less than 6 r.p.m. per m.A. | Suspect, and change: L.P.C. Servo throttle in that order, repeating D.C. Check after each change | |
| ii. Faulty B.P.C. | | Change B.P.C. | |
| iii. Faulty fuel flow dis- tributor | | Change fuel flow distributor | |
| - | | Adjust as necessary | |
| i. Inadequate B.P.C. total head air pressure | Check for blockage or leaks | Rectify. Ensure that Aircraft Modification Venom 840 is incorporated | Aircraft hand- book |
| ii. Faulty B.P.C. | | Change B.P.C. | |
| i. Faulty fuel flow distri- butor | | Change fuel flow distributor | |
| ii. Low flow number burners, or blocked burner filters | Check burner pressure | Change burners. NO dismantling of burners is permissible without approval and the necessary equipment, specialists, and test rigs. | |
| Faulty compressor de- livery supply to A-F.R.C. or faulty A-F.R.C. | Check compressor delivery pressure line to A-F.R.C. for leaks | If compressor line is satisfactory, change A-F.R.C. | |
| ii. Low fuel pump output | | Change fuel pump | |
| i. If confined to the fine datum control in the alti- tude compensating unit | | Change altitude compensating unit | Aircraft hand- book |
| ii. If peculiar to the main datum control in mag- netic amplifier | | Change magnetic amplifier | Aircraft hand- book |
| iii. If common to both adjustments | | Change magnetic amplifier | Aircraft hand- book |
| | | Suspect, and change in this order:— L.P.C. Servo throttle Fuel flow distributor Fuel pump Apply D.C. Check after each change until corrected | |
| - | | Re-adjust isolation trim con- trol in magnetic amplifier | |
| If the engine r.p.m. rise exceeds 50 r.p.m., then the following are likely causes: Too high or too low an amplifier gain | Apply Gain Check | If the gain is outside the stated limits, change magnetic amplifier | Aircraft hand- book |

| | Symptom | Primary Cause | Primary Investigation |
|-----|--|--|--|
| 14. | TOO GREAT A VARIATION OF R.P.M. ON OPERATING THE ISOLATING SWITCH (contd.) | | - |
| | | c. Faulty electrics in the isolator compensating circuit | Connect Routine Test Set and switch on aircraft inverters, With test set switch at position No. 1 there should be a current increase of 30/40 m.A. on switching ON the isolating switch with the engine static |
| | | | |
| 15. | INCORRECT OIL PRESSURE | Refer t | o Symptom 9 on page 12 |
| 16. | SUSPECTED OIL LEAKAGE OR HEAVY OIL CONSUMPTION | Refer to Symptom 10 on page 12 | |
| 17. | INCORRECT JET PIPE TEMPERATURE | Refer to Symptom 11 on page 12 | |
| 18. | ENGINE VIBRATION | Refer to Symptom 12 on page 14 | |
| 19. | FUEL PRESSURE WARNING LIGHT COMING ON AT ALTITUDE FOR NO APPARENT REASON | R efer to | Symptom 13 on page 14 |


| | Secondary Cause | Secondary Investigation | Remedial Action | Refer to |
|------|--|--|--|-------------------------|
| i. | Too high or too low a line pressure control/servo throttle characteristic | Apply D.C. Check. The resultant curve slope should be not less than 6 r.p.m. and not more than 14 r.p.m. per m.A. applied current | Change, in this order:— L.P.C. Servo throttle Fuel flow distributor | |
| | | | Apply D.C. Check after each change | |
| iii. | Faulty B.P.C. or A-F.R.C. | Check fuel system pressures as described in Symptom 10, c, iv, and v. Note that variation of 100 lb. per sq. in. operating pressures will only result in 10/15 r.p.m. change | Change B.P.C. or A-F.R.C. as appropriate | |
| i. | Faulty cables or con- nections in the isolator current supply to mag- netic amplifier | This would result in a rise in r.p.m. on isolation | Rectify wiring and connections | |
| ii. | Wrong polarity of the isolator current supply to the magnetic amplifier | There would be no compensating current and the speed would rise on isolation | Correct the polarity | |
| iii. | Incorrect voltage of the isolator current supply to magnetic amplifier | Invariably a low voltage would give a rise in r.p.m. and a high voltage a drop in r.p.m. | Rectify voltage of the current supply to magnetic amplifier | |
| iv. | Faulty magnetic amplifier internal isolator compensating circuit | The result could be either a rise or a drop in r.p.m. dependent upon the precise nature of the failure | Change magnetic amplifier | Aircraf hand book |
| | | | | |
| _ | | | | |
| | | | | |
| | | | | |
| | | | | |
| _ | | | | |
| | | | | |
| _ | | 36 | | |
| | | | | |
| | | | | |
| | | | | |

April, 1957

ASSEMBLY AND CALIBRATION OF TEST EQUIPMENT FOR GHOST 53 Mk. 1 ELECTRIC MAX. R.P.M. CONTROL EQUIPMENT

| Operators should improvise this equipment from local resources, on the following lines. | Quantity Description A.M. Ref. 1 Moving coil microammeter, | 0. |
|---|--|----|
| ROUTINE TEST SET | 0-500 μ A, $2\frac{1}{2}$ in. scale, resistance 75 ohms, flush mounting, tropicalised (or a similar meter having a | |
| To make up a suitable Routine Test Set, the following materials, or their equivalents will be | resistance of not more than 200 ohms) 5Q/152 | |
| required · — Quantity Description A.M. Ref. | Single-pole, 2-way, toggle switch, Rotax 0 5401, R.C.L.151 5CW/4197 | |
| | | |
| 1 4-pole plug, Mk. 4 Cable Inter-services unit (Code 43) Z560290 | Fixed resistors, 10 ohms ± Inter-service 1% 3 watt, tropicalised Z113272 | 28 |
| Wire-wound potentiometer, 0-500 ohms, 1 watt, | Fixed resistor, 100 ohms ± Inter-service 1%, 3 watt, tropicalised Z113296 | es |
| normal spindle, tropi- Inter-services calised, R.C.L.121 Z271506 | A suitable panel and a shallow box Locally mad | le |

Mk. 4 CABLE UNIT PLUG Z560290 (CODE 43) 4-POLE



The components should be mounted on a suitable flat panel and wired up in accordance with the diagram, Fig. 5. The 0-500 ohms potentiometer should be mounted on the back of the panel so that, when boxed, its adjustment cannot be touched

without unscrewing and separating the panel from the box. Before screwing the assembled panel into the box, this Test Set must be calibrated. A suitable Calibration Set can be made with materials as described in the next paragraph.




Fig. 6. Diagram of suggested Test Set for calibration of Ghost 53 Mk. 1 Routine Test Set.

CALIBRATION OF ROUTINE TEST SET

To make up a suitable Calibration Set, the following materials, or their equivalents, will be required:—

| Quantity | Description | A.M. Ref. |
|----------|---|---------------------------|
| 1 | Two-volt accumulator cell | |
| 1 | Wire-wound, variable resistor 0-5 ohms ± 5%, 2 watt, normal spindle, tropicalised | Inter-services Z271058 |
| 1 | Fixed resistor, 0.5 ohms \pm 1%, 4.5 watt, tropicalised (or a similar resistor, tolerance not more than \pm 5%, and not less than 2 watt) | 10W/15064 |
| I | Moving coil milliammeter 0-500 m.A., $2\frac{1}{2}$ in, scale, flush mounting, tropicalised, R.C.L.231 | 5Q/3092 |
| 1 | 4-pole socket, Mk. 4 panel unit (Code 43) or alternatively Panel Mtg. coupler socket | Z560250 Inter-services |
| | | |

Wire up these components as shown in Fig. 6 (but do not connect up the 2-volt accumulator cell) and connect this Calibration Set to the Routine Test Set. Set the 0-5 ohms variable resistor, and the 0-500 ohms potentiometer to their maximum values and connect up the 2-volt accumulator cell.

Adjust the 0–5 ohms variable resistor until the milliammeter reads 20 m.A. Adjust the 0–500 ohms potentiometer until the microammeter reads 250 μ A.

Re-adjust the 0-5 ohms variable resistor until the milliammeter reads 125 m.A. The microammeter should now read 125 μ A, if it does not, re-adjust the 0-500 ohms potentiometer until a reading of 125 μ A is obtained.

Re-adjust the 0-5 ohms variable resistor until the milliammeter reads 500 m.A. The micro-ammeter should now read 500 μ A.

Taking care to ensure that the milliammeter reading never exceeds 500 m.A., ensure that the microammeter reads one-thousandth of the milliammeter for all settings of the 0-5 ohms variable resistor. Trim as necessary with 0-500 ohms potentiometer. Do not disturb the 0-500 ohms potentiometer once satisfactory conditions have been attained.

Disconnect the calibration equipment and screw the Routine Test Set into its box. The set is now ready for use.

> Issued by Amendment No. 132 April, 1957

Ghost 53 Mk. 1

D.C. TEST SET

To make up a suitable D.C. Test Set, the following materials, or their equivalents, will be required: -

| Quantity | Description | A.M. Ref. |
|----------|--|-----------|
| 1 | Breeze connector socket | 5X/6374 |
| 1 | Milliammeter 0 to 500 m.A., with scale graduated in 25 m.A. stages | 5Q/3092 |
| 1 | Variable potentiometer 0-50 ohms, 7.5 watt | 10W/18131 |

A suitable panel and box

24 volt direct current supply

The milliammeter and the potentiometer should be mounted on the panel with the milliammeter visible and the potentiometer control accessible above the panel for subsequent operation. The components should be wired in accordance with the diagram, Fig. 7, and the panel then fixed to the top of the box. Allow sufficient lengths of flexible lead between the control panel and the Breeze con-nector socket to permit the operator to sit in the aircraft cockpit with the connector socket attached to the line pressure control unit, and with sufficient input lead to reach the external source of 24 volt direct current supply.




Fig. 7. Diagram of suggested D.C. Test Set for Ghost 53 Mk. 1 electric max. r.p.m. control equipment.

