# AIR PUBLICATION **112G-0612-1**

# PROBE, (REF. No. 6A/12668)

# GENERAL AND TECHNICAL INFORMATION

BY COMMAND OF THE DEFENCE COUNCIL

17. Dunnett

Ministry of Defence

FOR USE IN THE ROYAL AIR FORCE

(Prepared by the Ministry of Technology)

**Issued June 68** 

# AMENDMENT RECORD SHEET

•

4.L. No.	AMENDED BY	DATE	A.L. No.	AMENDED BY	DATE
1			34		
2	-		35		
3			36		
4			37		
5			38		
6			39		
7			40		
8			41		
9			42		
10			43		
11			44		
12			45		
13			46		
14			47		
15			48		
16			49		
17			50		
18			51		
9			52		
0			53		
1			54		
22			55		
23			56		
24			57		
25			58		
26			59		
27			60		
28			61		
29			62		
30			63		
31			64		
32			65		
33			66		

To record the incorporation of an Amendment List in this publication, sign against the appropriate A.L. No. and insert the date of incorporation.

## Chapter 1

# PROBE (Ref. No. 6A/12668)

# DESCRIPTION

#### Leading particulars

Probe (total temperatur	e sens	or). Ty	pe 102	BB2K	 		Ref. No.	6A/12668
Dimensions:		,, -,	1					,
Projection into airstr	eam				 			3.25 in.
Length of housing					 			3.5 in.
Mating connector, Pless	ey Uk	-AN T	ype 14	S-5S	 		Ref. N	o. 5X/8038
Temperature range					 	-100	to + 35	0 degrees C
Weight					 			9-10 oz.

#### Description

1. The probe is used to provide a measurement of total air temperature. Air flows straight through a stainless-steel housing. Part of the airstream is caused to execute a sharp right-angled turn past a temperature sensitive platinum wire resistance thermometer element. The sharp right turn prevents particles of dust and droplets of water from coming into contact with the element.

2. In executing the right-angled turn the airflow

loses most of its forward velocity. The turn is aided by holes provided in the raised forward lip of the element chamber: air drawn through these holes prevents the formation of an eddy about the lip of the element chamber and causes a smooth airflow past the element. A cylindrical shield around the element minimises the effect on the element of heat radiation from the main body of the sensor. Small holes drilled in the housing reduce the heating effect of the boundary layer of the airstream flowing through the housing. No deicing system is fitted.




Fig. 1. Sectional view of probe




Fig. 2. Circuit diagram

Issued June 68



# Chapter 2

## PROBE (Ref. No. 6A/12668)

# STANDARD SERVICEABILITY TEST

#### Introduction

1. This chapter describes the tests to be applied to the probe, Type 102BB2K (Ref. No. 6A/12668) immediately prior to installation in an aircraft and at any time the serviceability is suspect.

#### Test equipment

The following test equipment is required: —

 Insulation resistance tester, Type C (Ref. No. 5G/152)

(2) Multimeter, Type 12889 (Ref. No. 5QP/ 6625-99-105-7049)

(3) Thermometer, precision (Ref. No. 6C/9432934)

(4) Boxes, Cambridge resistance (Ref. No. 10S/16237) - 2 off

(5) Resistor, Type 321, variable 15 ohms (Ref. No. 10W/9846)

(6) Resistor, Type 10504, fixed 100 ohms  $\pm 0.1\%$  (Ref. No. 10W/19365)

(7) Socket Plessey, Type UK-AN14S-5S (Ref. No. 5X/8038)

#### **Power supplies**

3. A 28V d.c. power supply is required.

#### Cleaning

4. Using dry rag (Ref. No. 32B/1257), clean the probe and examine for damage. Ensure that the orifices are clear of foreign matter.

# TESTING

#### Insulation resistance

5. Using the insulation resistance tester, measure the resistance between pins A, B, C and D connected together, and pin E. The resistance is to be not less than 20 megohms.

#### **Resistance element**

6. Prepare the test circuit shown in fig. 1, ensuring that all leads used in the resistance bridge are of negligible resistance. Secure the precision thermometer so that the bulb is in close proximity to the probe. Shield probe and precision thermometer from moving air. Allow probe and precision thermometer time to attain the same temperature, then proceed as follows:—

(1) Set S1 to the off position and adjust the variable resistance, Type 321 until the voltmeter indicates 5 volts.

(2) Set the multimeter in the bridge circuit to the 250  $\mu$ A d.c. range.

- (3) Set R1 to 1000 ohms.
- (4) Set S1 to the on position.

(5) Adjust R2 until the multimeter indicates zero current.

(6) Note the reading of the precision thermometer.

(7) Check that the resistance indicated on R2 is within the limits indicated in the relevant column of Table 1 against the temperature indicated by the precision thermometer.

(8) Set S2 to the off position.

Disconnect the probe from the test circuit.




Fig. 1. Test circuit

**Issued June 68** 

TA	BI	LE	1
	~		_

#### **Calibration** values

Precision thermometer (degrees C)	Resistance box R2 (ohms)		
10	1351 to 1357		
11	1356 to 1362		
12	1361 to 1368		
13	1367 to 1373		
14	1372 to 1378		
15	1377 to 1383		
16	1382 to 1389		
17	1387 to 1393		
18	1392 to 1399		
19	1398 to 1404		
20	1403 to 1409		
21	1408 to 1414		
22	1413 to 1419		
23	1418 to 1424		
24	1423 to 1429		
25	1428 to 1434		
26	1433 to 1440		
27	1439 to 1445		
28	1444 to 1450		
29	1449 to 1455		
30	1454 to 1460		

4

Page 2 Printed for H.M.S.O. by Christchurch Times Ltd., Christchurch. (6668) 629457 180 9/68 483/1