

NBC Intercommunication Unit 10D/5831-99-658-0607 (Dowty/UEL Type 706)

Mod No B 0219 (Class C/3)

File Ref D/SM 49/10/32/4462
ADP No ZBB 02190

Introduction of switch Part No 12TW-10 (5930-99-659-6599) in lieu of
switch Part No 12TW-50 (5930-99-656-9763).

Amendment Instructions: Remove and destroy Leaflet No 1 issued as
Amdts 1 and 2. Substitute this revised leaflet (1 leaf). Record the
incorporation on the Amendment Record Sheet.

NOTE: This leaflet is issued for informatory purposes only.

1. INTRODUCTION

The operational requirement to fit a replacement non-biased
function switch has now been cancelled and the corresponding
modification (B0219) has been withdrawn.

The following actions are required:-

- (1) Units at Mod State 0. No modification action is required.
Strike off numbers 1 and 2 on the unit modification record label
to indicate that the correct (ie, original) function switch is
fitted.
- (2) Units at Mod State 1. Incorporate the reversionary Mod No
B1472, as described in Leaflet No 2, and strike off number 2 on
the unit modification record label.

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.



LIGHTNING MK. 1
COVER PITOT HEAD
EB2-88-5111