


CHAP. 4 AIRFRAME S.P. 404 A.L. 1 SHEET 1 OF 2	SERVICING PROCEDURE F53 T55	BAC F53 & T55 (SA) 5A3A Section 1 2nd Edition
Main Undercarriage Side-stay Brackets - Cracking		AFSC 43151 53450 53470
Safety and Servicing Notes are to be complied with throughout the work detailed on this card.		TIME EST
SPECIAL TOOLS AND EQUIPMENT Nil.		ASSOCIATED PROCEDURES
<u>43151</u>		
1. EXAMINATION		
1.1 Main undercarriage side-stay brackets (Part No. EB1-20-1629 or Part No. EB1-20-1630, at joint to Rib 11B).	Examine, particularly for cracks (See Fig.1).	
<u>53450</u>		
NOTE: Item 2 is applicable only where cracks are found in side-stay brackets.		
2. RECTIFICATION		
2.1 Defective brackets.	Repair as necessary.	
<u>53470 (INSPECTOR)</u>		
3. INSPECTION STAGE		
3.1 Inspect.	Item 2, if applicable.	
Continued Overleaf		

CHAP. 4 AIRFRAME
S.P. 404 A.L.
SHEET 2 OF 2

SERVICING PROCEDURE
F53 T55

BAC F53 & T55 (SA)
5A3A Section 1
2nd Edition

Safety and Servicing Notes are to be complied with
throughout the work detailed on this card.



MAIN UNDERCARRIAGE SIDE-STAY BRACKET

FIGURE 1

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

