

8th November 1960

From: R.D.A.(Defects), M. of Av., St. Giles Court, St. Giles High Street,
W.C.2. Tel. No. MUSEum 3644, Ext. 474.

CLASS B

- (A) Servicing Instruction/Hunter/63
Wing Tips: Rivets Pulling.
- (B) Hunter Mk.6, 9 and 10 aircraft.
- (C) Cases reported of rivets in wing tips becoming loose.
- (D)1. Within 7 Days of receipt of this Instruction and subsequently at each Primary Servicing, proceed as follows:-
- (a) Inspect all rivets in port and starboard wing tips (Ref. 26FX/8533 and 8534) for signs of pulling or looseness.
 - (b) Where rivets are found loose, they are to be removed and new rivets fitted.

Estimated Man hours to inspect: Negligable
to rectify: Variable, 1 to 2

- (E) Record on appropriate Form and enter in the Supplementary Servicing Record Sheet of the Servicing Schedule.

/(F)



This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.