

CHAP	2	SP 104		SERVICING PROCEDURES				AP 101B-1000-5A3 F (Section (1st Edition) 2				TIME	ACT	
TRADE	AIR COMMS		LIGHTNING											
SHEET	1	OF	2	SHEET/S		3		5	6	AL NO	19	DATE		EST
TITLE	Telebrief Installation								SERVICING RECORD - RAF F.29888 AC NO DATE					
Safety and Servicing Notes are to be complied with throughout the work detailed on this Card.									(1)	(2)	(3)	(4)	(5)	
Special Tools and Equipment									MAN HOURS	TRADESMEN INIT	BRIEF DETAILS OF OR SUSPECTED DEFECT	F. 720B NO	N.C.O. INITIALS	ASSOCIATED PROCEDURE CARDS
T.S. 395														
AIR COMMS														
1. Preparation														
1.1 T.S. 395. Connect to telebriefing plug in starboard wheel compartment.														
1.2 Telebriefing lamps. Ensure lit.														
1.3 PEC cover(s). Remove and stow.														
1.4 Headset. Connect to TS Pilot's mic/tel socket using appropriate adapters. (T5 aircraft connect to Pilot's and Pupil's mic/tel sockets).														
2. Functional Checks														
2.1 TS 395.														
(a) On/Off switch. Set to 'ON'.														
(b) Red lamp. Ensure lit.														
2.2 I/C facility. Ensure available between TS Pilot's mic/tel socket and each crew station in turn. (T5 aircraft ensure available from Pilot's and Pupil's mic/tel sockets).														
2.3 Telebriefing buttons. (As applicable). Depress in turn.														
2.4 TS Green lamp. Ensure lit.														
2.5 Telebriefing buttons. Release in turn.														
2.6 TS Green lamp. Ensure extinguished.														
SMS/82/37/12									Continued				SP NO	104

[illegible]



Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

