

Chapter 3 EMERGENCY CONTROLS, EQUIPMENT AND EXITS

WARNING...

Before entering or leaning into the cabin refer to the ejection seat, canopy jettison system and MDC safety precautions detailed in A.P. 101B-1202-4A2 or A.P. 101B-1202-4A3(N).

1. The emergency controls, equipment and exits in post-Mod 1188 aircraft are identical to those described and illustrated in A.P.101B-1202-1A, Cover 1, Sect. 1, Chap. 3 except for the observer's seat. Seats installed in post-Mod 1188 aircraft by Mod 1580 incorporate splayed thigh guards to allow additional knee clearance required when a Martel display unit is installed.

2. Seats compatible with the observer's miniature detonating cord (MDC) system (Mod 1596) are introduced by Mod 1598. As the only difference between these seats and those referred to in Sect. 1, Chap. 3 lies in the splayed thigh guards, references in that chapter to items introduced by Mod 1597 are also applicable to post-Mod 1598 seats.