

Chapter 6 MISCELLANEOUS INSTRUMENTS

Introduction

1. The miscellaneous instrument systems on this aircraft are similar to those described in AP 101B-1202-1B, Cover 2, Sect 7, Chap 6 with the exception of the liquid oxygen tank contents indication electrical supply fuses and relocation of the miscellaneous temperatures indicator.

2. On Mk.2B aircraft with Mod 1651 embodied, the liquid oxygen tank contents indication ground servicing supply fuse, D6 on panel R-C, is also used to supply a video tape recorder circuit (Sect 20, Chap 6). On post-Mod 1709 aircraft, this fuse is up-rated to 5 amp. A wiring diagram is included in Sect 17 of the SDM.

3. Prior to embodiment of Mod 1800 the miscellaneous temperatures indicator, AA, is located on the navigator's port console. On introduction of Mod 1800 the indicator is relocated on panel C-HK which is attached to the console.