

AIR COMMS

SERVICING PROCEDURES
MISCELLANEOUS
HUNTER ALL MARKS

AP101B-1300-5A3C
Sect 4
Chap 8

List of Contents

SP No.

UHF Aerials (10B/2222399) Protective Finish - Cracking	511
Not Allocated	512 to 515

SMS/ 141

PF 200

Page (XLV)(XLVI)
HUN/5A3C/1.213

AIR COMMS SP 511 (1) (1 to 2)				SERVICING PROCEDURES MISCELLANEOUS HUNTER ALL MARKS				AP101B-1300-5A3C Sect 4 Chap 8		SERVICING RECORD RAF Form 2988B (Revised Jan 85)			
										Aircraft Ser No: Date:			
<u>UIIF AERIALS (10B/2222399) PROTECTIVE FINISH - CRACKING</u>								TRADESMAN		Brief Details of Suspected Defect and SNOW When Applicable		SUPERVISOR	
								MAN HRS 1	INITS & TDM 2	3	MAN HRS 4	INITS & TDM 5	
TRADE AC	M/HRS	TRADE	M/HRS	ASSOCIATED PROCEDURE CARDS				Code					
<u>SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD</u>													
<u>Special Tools and Equipment:</u>													
33J/1293933 Silicone carbide paper, waterproof. 33B/2242079 Primer. 33B/2242592 Paint polyurethane, Matt Black.													
BLOCK 1				AIR COMMS									
1. <u>Examination</u>													
1.1 Aerial protective finish.				Examine for cracks across central region. (Three cracks appear approx 0.5 in. above and 0.2 in. below the centre band. They are horizontal and do not exceed 1.75 in. in length).									
BLOCK 2				AIR COMMS									
NB: Item 2 is only applicable if cracks are found in Item 1.													
2. <u>Rectification</u>													
2.1 Aerial protective finish.				(i) Lightly clean and roughen the central part of the aerial blade to a distance of 3 1/2 in. from base plate. (ii) Mask off top and bottom of the blade leaving central 2 1/2 in. clear.									
SMS/ <u>142</u>													

AIR COMMS SP 511 (2)	SERVICING PROCEDURES MISCELLANEOUS HUNTER ALL MARKS	AP101B-1300-5A3C Sect 4 Chap 8	SERVICING RECORD		RAF Form 2988B (Revised Jan 85)		
			Aircraft Ser No: Date:				
UHF AERIALS (10B/2222399) PROTECTIVE FINISH - CRACKING			TRADESMAN		Brief Details of Suspected Defect and SNOW When Applicable		
SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD			Code	MAN HRS 1	INITS & TDM 2	MAN HRS 3	INITS & TDM 5
BLOCK 1	AIR COMMS						
2. <u>Rectification</u> (Contd)							
2.1 Aerial protective finish. (Contd)	(iii) Prime and paint iaw AP119A-06001-1B Chap 1. Apply four coats of finish paying particular attention to the leading edge. (iv) Remove masking and allow sufficient time to cure before aircraft's next flight.						
SMS/142A							



This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.