

AL23

NON-DESTRUCTIVE TEST SCHEDULE  
HUNTER ALL MARKS

AP 101B-1300-5G

SECTION 1

**Radiography**

## LETHAL WARNING

1. RADIOACTIVE SOURCES AND X-RAY EQUIPMENTS USED FOR NON DESTRUCTIVE TESTING IN THE ROYAL AIR FORCE PRODUCE IONIZING RADIATIONS WHICH HAVE AN ADVERSE EFFECT ON THE HUMAN BODY.
2. MAXIMUM PERMISSIBLE LEVELS OF PERSONAL DOSE RATE ARE LAID DOWN IN CURRENT REGULATIONS ~~EXPOSURE TO RADIATION IS TO BE AVOIDED AND DOSE RATE LEVELS ARE TO BE KEPT TO A MINIMUM.~~ (AP4687A VOL 2 LEAFLET C2 REFERS).
3. EXPOSURE TO RADIATION IS TO BE AVOIDED AND DOSE RATE LEVELS ARE TO BE KEPT TO A MINIMUM.

## LIST OF CHAPTERS

- Chapter 1 Deleted
- Chapter 2 X-Radiographic Techniques
- Chapter 3 Gamma Radiographic Techniques

This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.

