

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|--------------------|----------|----------------------------------|----------|----------------------------------|----------|----------------------------------|----------|
| Clare | | Dowty Equipment— continued | | Dowty Equipment— continued | | Dowty Equipment— continued | |
| RL.9003 | EB.12A | | | | | | |
| RL.9005 | EB.12A | | | | | | |
| RL.9006 | EB.12A | C.1223Y Mk.12NP | EB.20 | D.5212Y | NH.7 | 08950Y-B02 | NE.6 |
| RP.7641 | HJ.14 | C.1223Y Mk.15N | FA.9 | D.5213Y | NE.6 | 08950Y-B03 | NH.7 |
| RP.9005 | HJ.13 | C.1223Y Mk.27 | FA.9 | | NF.8 | 08950Y-B04 | NH.7 |
| RP.9006 | HJ.13 | C.1831 Mk.2 | EB.18 | | NK.2 | 08950Y-B05 | RC.1 |
| | | C.1831 Mk.102C | EB.2 | D.5220Y | NE.6 | 08963Y-B01 | NE.6 |
| | | | JD.11 | | NF.8 | 1.00426.001 | DD.5 |
| | | | NF.8 | | NG.4 | 1.1269Y.A01 | JK.1 |
| | | | T.29 | | NH.7 | 1.00043.012 | NH.7 |
| | | | T.33 | D.5230Y | NG.4 | 1.00043.013 | NH.7 |
| C.W.C. Ltd. | | C.2701Y Mk.H | NH.7 | D.5853Y Mk.B | NE.6 | 1.00051.034 | NH.7 |
| | | C.2076Y Mk.C | NF.7 | D.6102Y | NF.3 | 1.00051.035 | NG.3 |
| XD.777 | FA.6 | C.4076Y Mk.F | NF.8 | D.6207Y | NH.6 | 1.00073.004 | NH.8 |
| XD.778 | EB.2 | C.4122Y Mk.A | NH.7 | D.7375Y Mk.B | NF.8 | 1.02032.001 | NH.7 |
| | EB.12 | C.4122Y Mk.E | NF.8 | D.7523Y | NH.7 | 1.03021.002 | RC.1 |
| | EB.20 | C.4122Y Mk.G | NH.7 | D.8680Y Mk.A | NF.8 | 1.03665.001 | NH.2A |
| | EB.21 | C.4603Y Mk.A | NF.3 | D.8756Y | NE.6 | 1.03665.002 | NH.2A |
| | EB.22 | | NF.8 | SP.597/9 | GA.13 | 2.00108.001 | RC.1 |
| XD.779 | EB.21 | | NG.4 | SP.815/2 | FA.3 | 2.00728.001 | RA.1 |
| | FA.6 | | NH.7 | | JC.4 | 2.00728.002 | RA.1 |
| | FA.9 | C.4973Y Mk.A | NE.6 | | JC.9 | 2.00734-001 | RC.1 |
| XD.780 | FA.6 | C.5148Y Mk.5S | FA.8 | SP.900/9 | FA.7 | 2.200046-003 | RA.1 |
| XD.781 | EB.4A | C.5148Y Mk.19N | FA.8 | SP.900/19 | NH.7 | 2.200046-004 | RA.1 |
| XD.782 | EB.14 | C.5162Y Mk.2 | DB.1 | SP.900/22 | NG.2 | 1322Z Mk.4 | RD.2 |
| XD.784 | EA.4 | | FA.6 | 04862Y-B07 | NH.7 | | |
| | FA.6 | | HJ.22 | 04862Y-B08 | NG.2 | | |
| | MF.3 | | MF.3 | | NH.6 | | |
| XD.786 | EB.1 | | T.25 | 06010Y-A01 | NF.3 | | |
| | EB.21 | C.5162Y Mk.3 | HJ.17 | 06102Y-A2 | NF.3 | Dowty Seals | |
| XD.787 | EB.12 | C.5162Y Mk.7 | HL.5 | 06102Y-A03 | NF.3 | GD.1288 | NB.6 |
| | EB.19 | C.5165Y Mk.1 | EA.2 | 06104Y-A01 | NF.8 | GD.1307/A | NM.3 |
| | EB.22 | | EB.14 | 06207Y-B01 | NH.6 | GD.1307/B | NM.3 |
| XD.788 | EB.12 | | EB.18 | 07390P-A03 | NH.2A | GD.1307/BB | NB.5 |
| | EB.21 | | FA.5 | 07390S-A03 | NH.2A | GD.1307/D | NM.3 |
| | FA.6 | | FA.8 | 07554P-A03 | NE.3 | GD.1307/G | NC.3 |
| XD.789 | EB.14 | | MF.2 | 07554S-A03 | NE.3 | GD.1307/H | NB.2 |
| | EB.21 | C.5165Y Mk.1B | HJ.20 | 07581Y-A02 | NH.2A | GD.1307/J | NB.5 |
| | FA.5 | C.5165Y Mk.2 | FA.2 | 07584Y-A02 | RE.1 | GD.1307/J | NB.5 |
| | FA.9 | | FA.5 | 08264Y-A02 | RC.1 | GD.1307/3 | NB.5 |
| | MF.3 | | FA.8 | 08394Y-A02 | NF.2A | | NC.3 |
| | | | MF.2 | | NH.1 | | NM.3 |
| | | C.5165Y Mk.2B | HJ.20 | 08416Y-B02 | NF.3 | | NM.5 |
| | | C.5182Y Mk.3D | FA.9 | 08417-A04 | NF.3 | GD.1307/4 | NC.3 |
| | | C.5182Y Mk.8D | FA.9 | 08673Y-A02 | JD.16 | GD.1307/6 | NB.5 |
| | | C.5183Y Mk.4D | FA.8 | 08673Y-A04 | JD.16 | | NB.6 |
| Dowty Equipment | | C.7375Y | NH.7 | 086982Y-A05 | NG.1 | GD.1307/23 | NB.6 |
| A.8963Y Mk.A | NE.6 | D.4140Y | NF.7 | 08808Y-A04 | NG.4 | | NM.3 |
| C.484Y Mk.E | NE.6 | D.4141Y | NF.7 | 08808Y-B06 | NH.7 | GD.1308/1 | HC.2 |
| C.1220Y Mk.3 | EE.5 | D.4930Y | NH.7 | 08808Y-B07 | NG.4 | | NB.4 |
| C.1223Y Mk.12 | EB.19 | | | 08816Y-A03 | NG.3 | GD.1308/2 | NB.4 |
| C.1223Y Mk.12N | EB.20 | | | 08817Y-A05 | NH.7 | | NB.7 |
| | | | | 08817Y-A06 | NH.7 | | NC.2 |
| | | | | 08818Y-A02 | NG.3 | | NC.4 |
| | | | | 08832Y-A02 | NF.8 | GD.1308/4 | NC.2 |

INDEX OF PART NUMBERS

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|---------------------------|----------|-----------------------------|----------|-----------------------------|----------|-----------------------|----------|
| Dowty Seals— continued | | Dunlop Rubber— continued | | Dzus Fasteners continued | | Europe Ltd. | |
| GD.1308/5 | HB.3 | ACM.18798 | NF.3 | R.5 | JD.20 | AJ/3/30 | JD.20 |
| | HC.2 | ACM.19552/14 | NN.1 | S.3.150 | HJ.20 | | |
| GD.1308/8 | NB.6 | ACO.26079 | CA.4 | S.4.200 | JB.13 | | |
| GD.1309/65 | NN.1 | AH.50247 | RA.1 | S.4.225 | EB.7 | | |
| GD.1309/7 | JC.4 | AH.50248 | RA.1 | S.5.200 | EB.8 | | |
| | JE.3 | AH.50701 | RA.2 | | EB.16 | Ferranti | |
| GD.1309/14 | JE.4 | AH.50720 | RA.1 | | HJ.3 | | |
| GD.1309/15 | JE.5 | AH.50721 | RA.1 | S.5.325 | JB.4 | ZS.10A | HJ.19 |
| GD.1309/16 | NC.1 | AH.51338 | RA.2 | | JB.21 | ZS.78 | EB.12 |
| GD.1309/18 | HC.2 | AC.61130 | NN.1 | | JD.5 | | HJ.13 |
| GD.1309/21 | NB.7 | AC.61132 | NN.1 | | JD.7 | 94/12586 | CB.2 |
| | NC.2 | AC.62644 | NN.1 | SLA.5/225 | JD.13 | 94/12605 | CB.2 |
| | NC.4 | AC.62658 | NN.1 | | | 64/33171 | FA.2 |
| GD.1309/23 | NC.2 | AC.62908 | RA.1 | | | | |
| GD.1309/25 | NB.4 | AC.62910 | RA.1 | | | | |
| | NC.1 | AC.64616 | DD.2 | | | | |
| GD.1309/26 | NB.4 | | DD.4 | | | | |
| GD.1309/27 | HB.3 | 2/W14/261/8/8 | NG.1 | Electronic Components | | Fairey Aviation | |
| | NB.4 | 16.0 | | | | | |
| GD.1453C Mk. 18 | JC.2 | 2/W14/261/8/8 | NF.2A | | | | |
| GD.1576 | NG.3 | 22.5 | NH.2 | 22508/685°C | EB.17 | AH.1525 | DE.1 |
| GD.1579 | NG.3 | 2/W14/261/8/8 | NG.1 | | | AH.957 | KA.1 |
| | | 26.5 | | | | AH.958 | KA.1 |
| | | 4/W14/261/8/8 | NG.1 | | | BH.2175 | NG.1 |
| | | 16.0 | | | | | NH.2 |
| Dowty Rotol | | 4/W14/261/8/8 | NH.2 | | | FS.430/B | HC.1 |
| | | 22.5 | | Elliot | | FS.430/D | CA.5 |
| 11884.PB01 | RA.1 | 4/W14/261/8/8 | NG.1 | RL.9006 | EB.12 | | CA.6 |
| 11884.SB01 | RA.1 | 23.0 | | | | | HB.2 |
| | | | | | | FS.430/E | JB.23 |
| | | | | | | FS.553 | JB.4 |
| Dunlop Rubber | | | | | | | |
| WH.30/1 | HN.1 | | | | | | |
| TW.49A | GA.2 | Dzus Fasteners | | English Electric | | | |
| DAS/412/E/3.0 | NK.1 | A.4/25 | EB.20 | | | | |
| DAS/412/E/5.5" | NK.1 | A.4/30 | JB.13 | AS.5 | EB.3 | Field A/C Services | |
| WDM.564 | GA.11 | A.4/35 | EA.1 | AS.25 | MF.1 | | |
| | GA.13 | | JB.13 | | EB.3 | | |
| | GA.14 | | EB.4A | | EB.4A | B76-P19 | HN.1 |
| AEM.1815 | RA.2 | | EB.6 | | EB.8 | B76-P20 | HN.1 |
| DT.2200 | RC.1 | | JB.13 | E/F3/80/3997 | HJ.12 | B76-P31 | HN.1 |
| DR.10295 | RA.2 | AW.425 | JC.13 | | | B76-P34 | HN.1 |
| A.5826 | GA.3 | AW.530 | EB.8 | | | B76-P35 | HN.1 |
| ACO.6580 | NK.2 | WJW/5/35 | EB.14 | | | B76-P36 | HN.1 |
| ACO.7273 | NK.1 | EF.5/45/B | HJ.5 | | | B76-P42 | HN.1 |
| ACO.7738 | CA.4 | | JB.4 | Erma | | B76-P101 | HN.1 |
| ACO.7739 | CA.4 | F5/40 | JB.21 | ERMA12102 | HM.1 | B75-P115 | HN.1 |
| ACO.8011 | BF.8 | F/5/T/12 | JD.5 | ERMA12104 | HJ.12 | B76-P160 Sht.5 | HN.2 |
| AH.9336 | RC.1 | | JD.6 | ERMA12105 | HJ.12 | C76-P28 Sht.1 | HN.2 |
| A.10039 | GA.3 | | JD.20 | ERMA12108 | ME.2 | D76-P33/5 | HN.2 |
| A.10054 | GA.3 | F/5/T/14 | JD.20 | ERMA12109 | EB.6 | D76-P43/1 | HN.1 |
| DR.10296 | RA.2 | GA.4/250 | EA.1 | | ME.3 | D76-P43/5 | HN.2 |
| AC.12732 | NF.8 | GF6/250 | EE.3 | | ME.3 | D76-P97/2 | HN.2 |
| AC.12734 | NF.8 | | EE.8 | ERMA12432 | ME.3 | D76-P200 | HN.1 |
| AC.14010 | NF.1 | GH.4 | EB.6 | ERMA12434 | ME.3 | | |
| ACM.16782 | NF.1 | GH.5 | JD.6 | | | | |
| | NK.1 | | JD.20 | | | | |
| ACM.17992 | JJ.1 | | | | | | |
| ACM.18570 | NF.3 | | | | | | |

INDEX OF PART NUMBERS

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|-----------------------------------|----------|---------------------------|----------|-------------------|----------|---------------------|----------|
| Hellermann Electric— continued | EB.22 | Honeywell | | Kelvin and Hughes | | Latch and Batchelor | |
| NY.18007A continued | EB.21 | 1TL-1-3D | HJ.13 | KSD/02/01 | EB.22 | 1/00 | DG.1 |
| | EB.22 | 2TL1-1A | FA.2 | KVC.0101 | FA.8 | | |
| | EC.3 | 2TL1-3D | FA.6 | LND.644 | T.72 | | |
| | EC.4 | 2TL1-3G | EB.21 | LND.645 | T.72 | | |
| | EE.4 | | HJ.5 | LND.647 | T.72 | | |
| | EE.5 | 2TL1-10A | HJ.18 | WTA.143574 | HJ.11 | Lodge Plugs | |
| | FA.4 | | FA.2 | | | CG.11 | EA.6 |
| | FC.1 | 5PA8 | ME.5 | | | EA6-90° | EA.6 |
| | HJ.12 | | FA.2 | | | N.28 | EA.6 |
| | HJ.17 | | FA.5 | | | SF.6 | EA.6 |
| | HJ.25 | | MF.2 | | | SS.18 | EA.6 |
| | HL.7 | | | King Aircraft | | SS.23 | EA.6 |
| | HM.3 | | | D.3060/2 | JD.12 | | |
| | JH.1 | | | | JB.16 | | |
| | MA.4 | | | C.3099 | JB.2 | | |
| | MB.1 | Hymatic Engineering | | | JB.3 | | |
| | MC.1 | | | C.3100/H | JB.15 | Marconi Ltd. | |
| | MC.4 | | | C.3102 | JD.21 | | |
| | MC.5 | AC.2 | NK.1 | C.3103/H | JD.12 | RID.1004/A | MB.1 |
| | MC.8 | | NK.2 | C.3829S | NB.2 | RID.1011/1/8b | MB.1 |
| | MD.1 | CS.51642 | NB.6 | C.3903/1 | JB.15 | RID.1012/1/14b | MB.1 |
| | ME.4 | D.9205 | NM.3 | C.3903/2 | JB.15 | RID.1012/2/14b | MB.1 |
| | MF.1 | NR9 Mk. 6 | NM.3 | C.3903/3 | JB.15 | RID.1004/1 | MA.3 |
| | MF.3 | PS.29/4 | NM.3 | C.4205/1/A | NJ.1 | | MA.4 |
| | MG.2 | SV.9 | NK.1 | C.4205/1/B | NM.1 | RID.1004/2 | MA.3 |
| | NJ.2 | | | C.4205/1-1/4 | | | MA.4 |
| | RD.2 | | | —1-1/2/B | NH.1 | RID.1004/3 | MA.3 |
| NY.18067 | EA.7 | | | C.4205/1-3/4—2/B | NH.1 | | MA.4 |
| | EB.1 | | | C.4370/1/A | NJ.1 | RID.1004/4 | MA.3 |
| | ED.1 | | | C.4370/B/1 | NM.1 | | MA.4 |
| | ED.4 | International Rectifier | | C.4370/B/1-1/4 | | 3D/760/2 | HJ.16 |
| | EE.4 | | | —1-1/2 | NM.1 | | |
| P.3 Grey | EB.18 | | | C.4370/B/1 | | | |
| | EB.21 | 1R10D1 | EB.12 | —3/4—2 | NM.1 | | |
| R.2032 | HB.2 | | | C.4460/S | NB.2 | | |
| | MC.5 | | | D.4798 | CA.6 | Marston Excelsior | |
| 0003-033-000 | EB.21 | | | D.5067 | JD.11 | | |
| | HJ.2 | | | D.5089 | CA.5 | | |
| 150HT15 x 3/4 | EB.19 | | | | JC.12 | AM.1910 | QA.2 |
| | | I.V. Pressure Controllers | | C.5183 | JG.1 | AM.1911 | QA.2 |
| | | | | C.5331 | CA.5 | AM.2101 | QA.2 |
| | | | | C.5642/B/1 | | AM.2102 | QA.2 |
| | | | | —1/4—1-1/2 | NL.1 | AM.2103 | QA.2 |
| | | | | C.6395 | NB.2 | AM.2104 | QA.2 |
| | | | | C.6397 | NB.2 | AM.2105 | QA.2 |
| | | | | C.6595 | CA.5 | AM.2106 | QA.2 |
| | | | | | JC.12 | AM.2107 | QA.2 |
| | | | | | CA.5 | AM.2108 | QA.2 |
| | | | | D.6597 | CA.6 | AM.2238 | QA.1 |
| | | | | C.7032 | CA.6 | AM.2239 | QA.1 |
| | | | | C.7057 | CA.5 | AM.2645 | QA.1 |
| | | | | C.7810 | CA.3 | | |
| | | | | | CA.6 | | |
| | | | | | JC.13 | | |
| Hoffmann | | | | | | | |
| CF.2A | PC.2 | | | CH4205/B1-1/4 | | | |
| CF.2LA | DA.1 | | | —1-1/2 | NL.1 | | |
| NA.12 | KB.1 | | | | | | |
| NR.12 | KB.1 | Jermyn Industries | | | | | |
| T.17 | DD.5 | | | | | | |
| T.21 | DC.1 | | | | | | |
| T.29 | JC.9 | ELL.8L | EB.12A | | | | |

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|------------------------------------|--------------|-----------------------|----------|------------------|----------|-----------------------|----------|
| Marston Excelsior— continued | | Ministry of Supply | | Painton | | Plessey— continued | |
| AM.2646 | QA.1 | ARM.63909 | HE.2 | 200L-1-103 | EB.12A | CZ.1051/2 | MC.5 |
| AM.2653 | QA.2 | ARM.93597 | T.47 | | | CZ.23144/B | EB.6 |
| AM.2654 | QA.2 | | | | | CZ.23144/C | EB.6 |
| CM.3746 | QA.1 | | | | | CZ.23144/D | EB.6 |
| CM.3747 | QA.1 | | | | | CZ.23144/Z | EB.6 |
| CM.3748 | QA.1 | Mollart Eng. Co. | | Palmer | | CZ.56108 | EB.7 |
| CM.3749 | QA.1 | | | C.58 | NK.2 | CZ.71751 | EB.7 |
| CM.3750 | QA.1 | 0.1 | GA.1 | C.58B | NK.1 | CZ.71753 | EB.7 |
| CM.3751 | QA.1 | | | No. 74 | RB.2 | CZ.71754 | EB.7 |
| D.113/7A | NL.1 | | | D.10721 | NB.2 | CZ.23212/1 | HB.1 |
| | | | | | | CZ.24285 | HB.1 |
| | | | | | | | HL.6 |
| | | M.L. Aviation Ltd. | | | | CZ.24640 | HJ.3 |
| | | | | | | CZ.24646 | HJ.3 |
| | | | | | | CZ.26808 | HL.6 |
| | | | | | | CZ.28009 | EB.6 |
| Martin Baker | | | | | | | EB.8 |
| B/MBCJ/191 | JE.4 | DL.617/282C | T.48 | Oliver Pell Ltd. | | | T.26A |
| BMCJ/174 | JE.4 | DL.617/330 | HB.2 | | | | ME.2 |
| MBCJ/186 | JE.4 | | | RH.2/1 | EB.12B | CZ.48992 | ME.2 |
| MBCJ/187 | JE.4 | | | | | CZ.48994 | HJ.14 |
| MBCJ/440 | JE.3 | Negretti & Zambra | | | | CZ.49061/1 | HJ.14 |
| MBEU/18553 | JE.3 | | | | | CZ.49112 | HJ.14 |
| MBEU/8516 | JJ.1 | | | | | CZ.49112/4 | HJ.14 |
| MBEU/19007 | JJ.1 | M1707 | HJ.2 | Plessey | | CZ.49182 | HJ.14 |
| | | KAA.1301K | HJ.2 | | | CZ.49184 | HJ.3 |
| | | | | PC.68-222 | HJ.14 | CZ.49187 | HJ.14 |
| | | | | 680B-16-25SX.ET | T.72 | CZ.49221 | HJ.11 |
| | | | | 681B-22-42SY.EY | T.63 | CZ.49223 | HJ.14 |
| | | | | 681-22-55SET | HJ.14 | CZ.49229/1 | HJ.14 |
| | | | | 681-22-55S.Y.ET | HJ.15 | CZ.49458 | HJ.14 |
| | | | | 681-22-55-SZ.ET | HJ.15 | CZ.50205 | HB.1 |
| | | | | 682A-8-3 | HJ.15 | CZ.50357 | HJ.3 |
| | | | | 682-12-12-P.ET | HJ.15 | CZ.50360 | HJ.3 |
| | | | | 682-12-12-S.ET | HJ.15 | CZ.50823 | EB.6 |
| | | | | 682-22-42P.WET | HJ.15 | CZ.51538 | HJ.6 |
| | | | | 682-22-42PX.ET | HJ.15 | | MD.1 |
| | | | | 682-22-42SW.ET | HJ.15 | CZ.51540 | MD.1 |
| | | | | 682-22-42SX.ET | HJ.15 | | HL.2 |
| | | | | 682-22-42SY.ET | HJ.15 | CZ.54709/10/A | NM.5 |
| | | | | 691-16-25PX.ET | T.72 | CZ.56073 | MC.1 |
| | | | | 691B-22-42PY.ET | T.63 | CZ.56108 | EB.7 |
| | | | | 691B-22-42PW.ET | T.63 | CZ.56743 | EB.1 |
| | | | | 691B-22-42PX.ET | T.63 | CZ.61889 | HJ.17 |
| | | | | 691B-22-42SW.ET | T.63 | CZ.62271 | MF.3 |
| | | | | 691B-22-42SX.ET | T.64 | CZ.62275 | MF.3 |
| | | | | 691B-22-42SY.ET | T.64 | CZ.62277 | HJ.17 |
| | | | | 692A-8-3S.ET | T.63 | | MF.3 |
| | | | | 692B-12-12P.ET | T.63 | CZ.64581/A | NL.2 |
| | | | | 692B-12-12S.ET | T.64 | CZ.71751 | EB.7 |
| | | | | 692B-22-42SX.ET | T.63 | CZ.71753 | EB.7 |
| | | | | 692B-22-42PW.ET | T.63 | CZ.71754 | EB.7 |
| | | | | 692B-22-42PX.ET | T.63 | CZ.71757 | MA.1 |
| | | | | 692B-22-42PY.ET | T.63 | CZ.72256 | ND.1 |
| | | | | 692B-22-42SW.ET | T.63 | CZ.72257 | CA.6 |
| | | | | CE.4063/40 | EB.11 | | |
| Mills | | | | | | | |
| GP.2 5/32" x 7/16" | NH.7 NF.8 | Oddie | | | | | |
| | | No. 212 | EB.3 | | | | |
| | | | EB.4 | | | | |
| GP.4 3/16" x 5/8" | JC.14 | No. 213/2 | EB.3 | | | | |
| EN.16T | NF.8 | No. 214 | EB.3 | | | | |
| | | No. 219 | JB.3 | | | | |

INDEX OF PART NUMBERS

PROPRIETARY FIRMS

| Part No. | Page No. |
|-----------------------|----------|-----------------------|----------|-----------------------|----------|-----------------------|----------|
| Plessey— continued | | Plessey— continued | | Plessey— continued | | Plessey— continued | |
| 2CZ/83672 | EA.3 | 508/1/03442/003 | EB.10 | 508/1/40049/322 | ME.3 | 508/1/40469/320 | HM.1 |
| 2CZ84046 | HL.6 | | HJ.16 | 508/1/40056/320 | EB.9 | 508/1/41035 | HJ.17 |
| CZ.97636/2 | EB.11 | 508/1/03443/003 | EB.10 | 508/1/40056/321 | EB.9 | | HM.1 |
| 2CZ.111067 | EB.9 | 508/1/05577/003 | HJ.14 | 508/1/40060/320 | EB.8 | | MA.1 |
| 2CZ.111209 | ME.5 | 508/1/05577/011 | HJ.14 | | ME.2 | | ME.2 |
| 2CZ.111224 | EB.9 | 508/1/05602/002 | EB.7 | | ME.3 | 508/1/41036 | ME.2 |
| 2CZ.111225 | EB.4A | 508/1/06413 | HJ.3 | 508/1/40061/320 | HJ.11 | 508/1/41037 | HJ.17 |
| 2CZ.111226 | EB.9 | 508/1/07049/221 | HM.2 | 508/1/40063/320 | EB.5 | 508/1/01386 | HJ.4 |
| 2CZ.111227 | EA.2 | 508/1/07621/003 | DB.1 | | EB.12B | 508/1/03272 | CB.1 |
| 2CZ.111229 | EA.2 | | HJ.2 | 508/1/40063/322 | ME.2 | | DB.1 |
| | EB.4A | | HJ.3 | 508/1/40066/320 | EB.3 | 508/2/05602/002 | EB.9 |
| | EB.9 | 508/1/07622/003 | EB.6 | 508/1/40069/320 | EA.2 | 508/2/05604/002 | EB.9 |
| 2CZ.111238 | EB.9 | 508/1/07624/003 | EB.6 | | EB.8 | 508/2/07657/003 | CB.1 |
| 2CZ.111299 | EB.4A | 508/1/07625/001 | HM.2 | | HJ.11 | 508/2/07705/200 | LB.1 |
| 2CA.111401 | EA.2 | 508/1/07627/003 | EB.6 | | MC.1 | | EB.6 |
| 2CZ.111404 | EA.2 | | HJ.3 | | MC.5 | | HJ.3 |
| CZ.111666 | HJ.3 | 508/1/07630/003 | DB.1 | | ME.2 | 508/2/07706/200 | EB.6 |
| 2CZ.139401 | EB.9 | 508/1/07631/003 | EB.6 | 508/1/40069/321 | EB.9 | 508/2/07707/200 | EB.6 |
| 2CZ.139485 | EB.9 | 508/1/07636/003 | EB.8 | | ME.2 | | EB.8 |
| Z.1840 | EB.3 | | HJ.2 | 508/1/40069/324 | MC.1 | 508/2/07708/200 | DB.2 |
| Z.1841 | EB.14 | 508/1/07706/300 | HM.2 | | MC.5 | | HJ.3 |
| Z.18500/B | EB.6 | 508/1/07785/001 | HM.2 | | ME.2 | 508/2/07709/200 | EB.6 |
| Z.18500/D | EB.6 | 508/1/40000/320 | EB.7 | 508/1/40075/321 | HA.1 | 508/2/07710/200 | EB.6 |
| Z.22430 | HJ.11 | 508/1/40003/320 | EB.7 | 508/1/40075/322 | HA.1 | 508/2/07711/200 | HJ.2 |
| | HJ.12 | 508/1/40003/325 | HJ.3 | 508/1/40076/320 | EA.2 | 508/2/07713/200 | EB.6 |
| | NM.1 | 508/1/40006/320 | HJ.2 | | EB.9 | | EB.9 |
| Z.22431 | EB.5 | | HJ.3 | 508/1/40160/320 | HJ.17 | 508/2/07719/200 | DB.1 |
| | EB.8 | 508/1/40015/320 | EB.7 | | MA.1 | 508/2/07720/200 | EB.6 |
| Z.22432 | DB.1 | | EB.9 | 508/1/40163/320 | HJ.17 | 508/2/07721/200 | EB.6 |
| Z.22433 | EB.6 | | HJ.3 | 508/1/40169/320 | HJ.17 | 508/2/07732/007 | DB.2 |
| | ME.4 | 508/1/40015/323 | HJ.3 | | HL.3 | 508/2/07746/007 | DB.1 |
| Z.22634 | EB.3 | 508/1/40021/320 | DB.1 | | MC.4 | 508/2/07753/007 | EB.6 |
| Z.22675/B | MA.1 | 508/1/40023/320 | DB.1 | | MC.8 | | T.69 |
| Z.22675/D | EE.10 | 508/1/40029/320 | EB.7 | 508/1/40169/322 | HJ.17 | 508/2/07754/007 | EB.6 |
| Z.22676/D | EE.10 | 508/1/40029/321 | EB.7 | 508/1/40180/320 | HJ.26 | 508/2/07758/007 | EB.6 |
| Z.23197 | EA.2 | 508/1/40040/320 | HJ.11 | 508/1/40182/320 | MC.4 | 508/2/07810/005 | MA.3 |
| Z.24949 | EE.2 | | HM.1 | | MC.8 | | MA.5 |
| | EE.3 | | MA.3 | | ME.5 | | MC.8 |
| | EE.8 | | ME.3 | 508/1/40183/320 | EB.1 | | ME.5 |
| Z.28426 | HL.6 | 508/1/40040/321 | ME.3 | | HJ.17 | 508/2/07811/005 | MC.2 |
| Z.28614 | EE.2 | 508/1/40040/323 | ME.3 | 508/1/40189/320 | HJ.17 | | MC.4 |
| | EE.3 | 508/1/40043/320 | EB.5 | | HL.3 | | MC.6 |
| | EE.8 | | EB.9 | | MC.4 | | MC.8 |
| Z.49075 | HJ.14 | | HJ.11 | | MC.8 | | ME.5 |
| Z.49081 | ME.5 | | ME.3 | | ME.5 | 508/2/07812/005 | MC.4 |
| Z.54092 | HJ.14 | 508/1/40043/322 | HA.1 | 508/1/40189/321 | HJ.17 | 508/2/11230 | EB.5 |
| Z.60665 | HJ.3 | 508/1/40046/320 | EB.3 | | MC.4 | | EB.7 |
| Z.60668 | HJ.14 | | MC.1 | | MC.8 | 508/2/11231/002 | EA.2 |
| Z.60669 | HJ.14 | | MC.5 | | ME.5 | | EB.5 |
| Z.62237 | HJ.14 | 508/1/40049/320 | EB.9 | 508/1/40440/320 | HM.1 | | HJ.2 |
| Z.62240 | DB.2 | | MC.1 | 508/1/40442/320 | HM.1 | 508/2/11232/002 | EA.2 |
| Z.67406 | HJ.14 | | MC.5 | 508/1/40443/320 | HM.1 | | EB.7 |
| Z.67407 | HJ.3 | | ME.3 | 508/1/40461/320 | HM.1 | | EB.9 |
| | | 508/1/40049/321 | HA.1 | | | | MA.1 |
| | | | MC.1 | | | | |
| | | | MC.5 | | | | |
| | | | ME.3 | | | | |

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|-----------------------|----------|-----------------------|----------|-----------------------|----------|---------------|----------|
| Plessey— continued | | Plessey— continued | | Plessey— continued | | Rose Bearings | |
| 508/2/11422/300 | HA.1 | 703/1/00420 | EB.2 | 703/2/00260 | EA.1 | RBJB.9R | RE.1 |
| 508/4/11182 | EB.4 | | EB.4 | | EB.16 | 208LZ | RB.2 |
| | EC.3 | | EB.7 | 703/2/00267 | EA.1 | | |
| 508/4/11292/005 | EA.5 | | EB.13 | | EB.1 | Rolls Royce | |
| 703/1/00190 | EB.12 | | EB.15 | | EB.15 | | |
| | EC.4 | 703/1/00430 | ME.1 | | EB.21 | BA.88561 | LC.1 |
| 703/1/00226 | HJ.20 | 703/2/00244 | ME.2 | | EC.1 | D.29850 | EA.6 |
| | EC.1 | | EA.1 | | EC.2 | | |
| | EE.7 | | EA.2 | 703/2/00267 | ED.1 | Ross Courtney | |
| | HJ.24 | | EB.2 | | EE.1 | | |
| | MC.3 | | EB.7 | | EE.2 | No. 00 | FA.3 |
| | MC.7 | | EB.13 | | EE.7 | | FA.4 |
| 703/1/00232 | EB.11 | | EB.15 | 703/2/00267/1 | EE.8 | | HJ.2 |
| 703/1/00238 | EB.1 | | EB.20 | 703/2/00301 | EB.15 | | HJ.11 |
| | EB.15 | | EC.1 | 703/2/00320 | HJ.26 | | HJ.20 |
| | EC.1 | | EC.2 | | EB.2 | | HM.1 |
| | EC.2 | | ED.1 | 703/2/00359 | EB.3 | No. 01 | EB.9 |
| | ED.1 | | EE.1 | 703/2/00362 | EB.8 | | EC.4 |
| | EE.1 | | EE.2 | 703/2/00363 | EB.4A | | HJ.13 |
| | HC.1 | | EE.3 | | EB.8 | | HJ.20 |
| | HJ.24 | | EE.7 | 703/2/00465 | EB.20 | | HJ.22 |
| | MC.3 | | EE.8 | | EB.8 | | ME.3 |
| | MC.7 | 703/2/00251 | HC.1 | | EB.15 | No. 44 | HJ.14 |
| 703/1/00249 | EA.1 | | EA.1 | 703/2/00467 | ME.1 | No. 73 | HJ.13 |
| | EA.2 | | EA.2 | | EB.4A | | HJ.14 |
| | EB.1 | | EB.6 | 703/2/00468 | EB.16 | RC.2120 | EA.2 |
| | EB.2 | | EB.8 | 703/2/00471/100 | EB.16 | | EB.3 |
| | EB.5 | | EB.16 | | EB.4A | | EB.4 |
| | EB.7 | | EB.19 | 703/2/00472 | EB.13 | | EB.7 |
| | EB.15 | | EB.20 | 703/2/00477 | EB.5 | | EB.9 |
| | EC.1 | | EC.1 | 703/2/08267 | EB.5 | | EB.12 |
| | EC.2 | | EC.2 | | HN.2 | | EB.15 |
| | EE.2 | | EE.1 | | | | EB.16 |
| | EE.3 | | EE.2 | | | | HC.2 |
| | EE.7 | 703/2/00252 | EE.7 | Purcell Bros. | | | HJ.1 |
| | EE.8 | | EA.1 | | | | HJ.2 |
| 703/1/00262 | EC.1 | | EB.1 | No. 25 | EB.6 | | HJ.5 |
| | EE.2 | | EB.6 | | | | HJ.14 |
| | EE.7 | | EB.8 | | | | EA.2 |
| 703/1/00264 | EB.1 | | EE.2 | | | | EB.5 |
| | EB.15 | | EE.3 | | | | EB.7 |
| | EC.1 | | EE.8 | Pye | | | EB.9 |
| | EC.2 | | HC.1 | | | | EB.16 |
| | ED.1 | 703/2/00253 | EA.1 | 400 | EB.21 | | HJ.1 |
| | EA.1 | | EB.6 | 401 | EB.21 | | HJ.2 |
| | EB.15 | | EB.15 | 523 | HJ.21 | | HJ.3 |
| | EC.1 | | EB.20 | 20821 | HJ.22 | | HJ.24 |
| | EC.2 | 703/2/00254 | EA.2 | | HJ.4 | | HL.5 |
| | EC.3 | | HB.2 | | | | MC.4 |
| | EE.1 | | HC.1 | | | | MC.8 |
| | EE.2 | 703/2/00255 | EA.1 | | | | EA.2 |
| | EE.7 | 703/2/00259 | EA.1 | Ransome and Marles | | | EB.5 |
| 703/1/00266 | EB.1 | | EB.6 | | | RC.2122 | EB.9 |
| | EB.12A | | EB.8 | FT.3/8" | GA.2 | | HJ.1 |
| | EC.2 | | EB.14 | | | | HJ.2 |
| | EE.2 | | EB.16 | | | | HJ.3 |
| | | | EC.2 | | | | |

INDEX OF PART NUMBERS

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|------------|----------|---------------------|----------|--------------------------|----------|------------------------|----------|
| Rotax | | Rotax— continued | | Salter & Co. "Truarc" | | S.B.A.C.— continued | |
| 16337 | T.61 | N.100397/6 | EB.12 | 5100/43 | GA.1 | AS.164/505 | KD.6 |
| 16936/1 | T.62 | N.100397/7 | EB.12 | | | AS.164/506 | KD.7 |
| A.1612/1 | T.61 | | EB.19 | | | AS.1242/1C | KD.6 |
| C.5021/2 | T.62 | | EB.21 | | | | KD.7 |
| D.0701 | EC.1 | N.100397/8 | EB.20 | | | AS.1242/7C | KD.5 |
| H.4501 | KB.3 | N.100397/9 | EB.20 | Sangamo-Weston | | | PE.1 |
| | EA.2 | N.100397/20 | FA.9 | | | | DD.2 |
| | FA.5 | | MA.4 | | | | DD.3 |
| H.4602/5 | MF.2 | N.100397/33 | EB.19 | FD.871 | EB.16 | AS.1248/2C | PE.1 |
| | FA.5 | N.100397/34 | EB.19 | | | AS.1892 | NA.1 |
| D.5320 | MF.2 | N.100397/37 | EB.12 | | | AS.1894 | NA.1 |
| D.5435 | JD.19 | | EB.14 | | | AS.1903-E12 | DG.2 |
| | FA.2 | | EB.21 | | | AS.2295/1 | JB.7 |
| D.19501/2 | HJ.21 | N.100397/43 | FA.9 | | | AS.2295/5 | JB.3 |
| D.10004 | EC.3 | | MA.5 | Saunders Valve | | AS.2295/8 | JB.7 |
| D.10007 | ME.3 | N.100397/50 | MF.3 | A.102/3 | NB.2 | AS.2295/9 | JB.7 |
| | FA.2 | N.100397/51 | MF.3 | L/51/B12 | NB.1 | AS.2434/44 | GA.2 |
| | FA.6 | N.147415/1 | FA.6 | N.1002 | NA.1 | AS.2434/45 | GA.1 |
| D.11201 | MF.3 | | MF.3 | 42/A/10 | NB.1 | AS.2722 | EB.13 |
| F.1303 | EB.1 | N.147415/2 | FA.6 | 5112/5 | NB.1 | AS.2733 | HL.5 |
| F.1306 | EB.21 | | MF.3 | 708AA/25B | NB.6 | AS.2724 | EB.12B |
| H.1104 | EB.20 | XU.1509L | HL.5 | | | AS.2806 | EB.17 |
| | FA.5 | ZA.2402/1 | ME.3 | | | AS.2903 | DD.1 |
| | MF.3 | | | | | AS.3360/B/4E | |
| H.2702 | FA.1 | | | | | AS.3360/B/5B | T.72 |
| | FA.5 | | | | | AS.3360/B/5C | HJ.10 |
| | MF.3 | | | | | AS.3360/B/6B | HJ.24 |
| H.2703 | FA.5 | Rotol | | S.B.A.C. | | AS.3360/B/6E | HJ.10 |
| | MF.3 | | | | | | HJ.25 |
| H.2705 | FA.5 | FFP.2/2 | NB.2 | AS.111 | JC.4 | | HJ.26 |
| | MF.3 | | | | JC.6 | AS.3360/B/7 | T.59 |
| N.5.BN | EB.1 | | | AS.163/304 | DD.2 | AS.3360/B/5B | T.59 |
| | EB.10 | | | AS.163/404 | DD.2 | AS.4573/1 | GA.13 |
| | EB.2 | | | AS.164/304 | DD.2 | AS.5401 | NJ.2 |
| | EB.11 | | | | DD.3 | | NM.5 |
| N.56091 | HJ.25 | Royal Air Force | | | KD.6 | AS.5402 | NM.5 |
| | FA.5 | | | | KD.7 | | NL.2 |
| N.65290 | MF.2 | CS.5401 | HJ.25 | | KD.5 | AS.5419/3 | HB.1 |
| | EB.11 | 13887 | HJ.25 | AS.164/404 | DD.2 | AS.5419/6 | EC.4 |
| | EB.20 | 13894 | HJ.24 | AS.164/405 | DD.3 | AS.5403 | NM.5 |
| | FA.3 | 22089 | HJ.2 | | KD.5 | | |
| | FA.4 | 22090 | HJ.24 | | KD.6 | | |
| | FA.5 | 22091 | HJ.24 | | KD.7 | | |
| | FA.6 | 31856 | HJ.25 | | DD.2 | | |
| | HJ.21 | 31857 | HJ.24 | AS.164/406 | DD.3 | | |
| N.65291 | EB.11 | 31858 | HJ.25 | | KD.6 | | |
| | EB.14 | 31861 | HJ.25 | | KD.7 | | |
| N.67548 | HJ.5 | 40634 | HJ.25 | | DD.2 | | |
| N.100397/1 | EB.21 | 40857 | HJ.24 | AS.164/407 | DD.2 | | |
| | EB.22 | 41018 | HJ.25 | AS.164/409 | DD.2 | | |
| N.100397/2 | EB.21 | 41021 | HJ.25 | | DD.3 | | |
| | EB.22 | 41068 | HJ.24 | AS.164/414 | DD.2 | | |
| N.100397/5 | EB.12 | 41595 | HJ.25 | AS.164/415 | DD.3 | | |
| | EB.21 | | | | DD.2 | | |
| | EB.22 | | | | DD.3 | | |

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|-----------------------------------|----------|---------------------------|----------|---------------------|----------|-----------------------------|----------|
| Self-Priming Pump and Engineering | | Smiths Waymouth Equipment | | Teddington Controls | | Teleflex Products—continued | |
| SPE/1007 Mk. 2 | NB.4 | CA.10 | EB.13 | ES/A/390 | NM.3 | | |
| SPE/1107 Mk. 3 | NB.4 | CA.14 | EB.13 | ES/A/430 | NM.3 | C.41552 | DH.2 |
| SPE/10306 | NB.5 | CA.30 | EA.4 | FAW/A.325 | NA.1 | C.41558/C | DH.1 |
| SPE/11645 | NB.5 | CA.37 | EA.4 | FHG/A/49 | NM.4 | C.44637/56/ | |
| SPE/2191 | NB.6 | CA.62 | EA.4 | FHJ/A/7 | EB.12A | C.44637 | JE.2 |
| SPE/B.P.26 | NB.5 | CA.125 | EA.4 | FHK/A/26 | EB.20 | C.44661 | JE.2 |
| | | CA.140 | EA.4 | FHM/A/25 | EB.2 | C.78914 | HJ.6 |
| | | CS.21 | EB.10 | FHO/A/96 | EB.22 | DS.307/2 | DA.1 |
| | | CS.75 | EA.4 | FJB/A/3 | EB.21 | | DH.1 |
| | | CJC.65 | EC.3 | FJB/A/5 | EB.21 | DS.337 | DH.2 |
| | | F.A.B./18 | EB.12B | FKX/A/1 | EB.21 | | JE.2 |
| | | JX.12 | EB.12B | FLJ/A/2 | NM.5 | | |
| Skefko | | JX.13 | EA.1 | FLM/A/5 | EB.2 | | |
| 08 | GA.11 | JX.14 | EB.12B | | | | |
| | GA.14 | JX.15 | EA.1 | | | | |
| | | 715SUE/1 | HJ.14 | | | | |
| | | | | | | Terry Springs | |
| | | | | | | 80X/12 | JB.3 |
| | | | | | | 80/0 | HJ.18 |
| | | | | | | 80/000 | JB.7 |
| | | | | | | 80/4 | JB.7 |
| | | | | | | 80/5 | JB.7 |
| | | | | | | 80X/2 | JB.3 |
| | | | | | | | JB.7 |
| Smiths Aircraft Instruments | | Standard Telephones | | Teleflex Products | | | |
| | | LP.733614 | ME.2 | A.821 | DH.1 | | |
| | | | HJ.14 | A.35335 | DA.1 | | |
| AG.38 | FA.5 | LP.733615 | HJ.13 | | DH.1 | | |
| | MF.2 | | ME.2 | A.35336 | DH.2 | | |
| AG.39 | FA.5 | LP.736720 | HJ.13 | | DA.1 | | |
| | MF.2 | | ME.2 | | DH.1 | | |
| CG.1 | EE.3 | | T.49 | A39953 | DH.2 | | |
| | EE.9 | 335/LWA/140B | MF.2 | B.731 | RB.2 | Texas | |
| CRC.54 | EE.3 | | | B.10898/C | DH.1 | 1S7130A | EB.12A |
| | EE.9 | | | B.35340/B | DA.1 | 2N1711LL | EB.12A |
| EAP.2340 | EB.4 | | | B.35375/B | DH.1 | 187130A | EB.12. |
| EC.4/2 | EB.12B | | | B.44665 | DB.3 | | |
| EC.4/4 | EB.12B | Superflexit | | C.28169/A | JE.2 | | |
| JM.14 | NC.2 | SC-011-16 | T.55 | C.36250 | DB.3 | | |
| JU.6 | NC.2 | | T.73 | C.36313 | DB.1 | | |
| JU.7 | NB.5 | | T.74 | C.36314 | DB.1 | | |
| RD.1 | EB.14 | SCF-463-16 | T.55 | C.36421 | DB.3 | Thermal Control | |
| | EB.15 | | T.73 | C.36424 | DB.3 | | |
| | EB.16 | | T.74 | C.36427 | DA.1 | T.P.1300 | NG.3 |
| Std.1503 | FA.2 | V.834 | T.55 | C.36428 | DA.1 | T.P.5207 | NF.6 |
| | HJ.21 | | T.73 | C.36429 | DA.1 | T.P.5266/1 | NB.5 |
| 19HSD | FA.2 | | T.74 | C.36706/B | DB.3 | T.P.5300/2 | NG.3 |
| 1/A.C.R. | EB.20 | | | C.39260 | DA.1 | T.P.5555 | NF.7 |
| 7/H.S.D. | FA.2 | | | C.39262 | DA.1 | T.P.5566 | NG.4 |
| 213/MV | EB.3 | | | C.39701 | DA.1 | | NH.7 |
| 227/FL | EC.4 | | | C.40076/R/70-1/4 | DH.1 | | |
| 470/FL | ED.1 | | | C.40076/R/71 | DH.1 | | |
| 501/FL | EB.17 | Tecalamite | | C.41551/B | DH.2 | | |
| | EB.18 | | | | | Thermotank | |
| 587/FL | FA.2 | A.F.P.4300/101 | NE.2 | | | AR.1-1/2 | NM.5 |
| 1696/FG | NB.5 | | | | | | |

INDEX OF PART NUMBERS

PROPRIETARY FIRMS

| Part No. | Page No. | Part No. | Page No. | Part No. | Page No. | Part No. | Page No. |
|-------------------|----------|--------------------|----------|---------------|----------|----------|----------|
| Thorn | | Ukan | | Volta Bloc. | | | |
| S68.15C3J1 | EB.12 | 8000/14S/7P | EB.9 | 19.VO.7 | ME.1 | | |
| 80/10/0055 | HJ.4 | 8000/22/14S | EB.9 | | | | |
| 80/10/0059 | HJ.4 | 9000/16/1S | EB.9 | | | | |
| 80/10/0064 | HJ.4 | 9202/14S/7S | EB.7 | | | | |
| 80/10/0678 | FA.3 | | | | | | |
| 80/10/0855 | EB.11 | | | | | | |
| | FA.3 | | | Western | | | |
| | FA.5 | | | Manufacturing | | | |
| | FA.7 | | | | | | |
| | HJ.21 | Ultra | | LS.1611 | EB.18 | | |
| | MF.3 | | | | EB.20 | | |
| 80/10/1189 | FA.3 | A.234 | EB.12B | | | | |
| 80/10/1190 | FA.3 | | | | | | |
| | FA.5 | | | | | | |
| | HJ.20 | | | | | | |
| | MF.3 | | | | | | |
| 80/10/1191 | FA.3 | | | | | | |
| 80/10/1192 | FA.3 | Undercarriage | | | | | |
| | FA.7 | Manufacturing | | | | | |
| | HJ.21 | Committee | | | | | |
| 80/10/1193 | FA.3 | | | | | | |
| | FA.5 | UMC.529 | NE.3 | | | | |
| 80/10/1194 | FA.3 | | | | | | |
| | FA.7 | | | | | | |
| 80/10/1236 | FA.3 | | | | | | |
| 80/10/1383 Iss. 1 | EB.20 | | | | | | |
| | | United Metallic | | | | | |
| | | No. 110 | EA.6 | | | | |
| | | | | | | | |
| Triplex | | Varley | | | | | |
| A.5500 | JF.4 | 15/35ED | HJ.5 | | | | |
| | | V.24/19/25C | EB.12A | | | | |
| | | 24.19/25C/V2 | EB.12B | | | | |
| | | V2092 L187/2 | EB.12B | | | | |
| | | | | | | | |
| Tucker | | Venner Time | | | | | |
| S.79 | EB.2 | Switches | | | | | |
| | EB.3 | | | | | | |
| | EB.4 | PTA/H/A/ W19055 | EA.7 | | | | |
| | | | | | | | |
| Turner | | Vickers | | | | | |
| 700/C/10904 | NE.6 | 92574/71 | JD.6 | | | | |
| | | A.5931 | JD.6 | | | | |



This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.