



ANNOTATED BY
SCOTT
BOUCHARD
19-01-2016

EMERG
↑
NORMAL
UHF CHANGEOVER

DISCONNECT
REBECCA DURING
TRANSMIT

FIG. 3. INTERCOMMUNICATION AND RADIO SUPPLIES-THEORETICAL DIAGRAM
◀MOD 1701 ADDED▶

JPMK3

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.



LIGHTNING MK. 1
COVER PITOT HEAD
EB2-88-5111