

CHAP. 2 AIRFRAME S.P. 133 A.L. SHEET 1 OF 1	SERVICING PROCEDURE F53 T55	BAC F53 & T55 (SA) 5A3A Section 1 2nd Edition
Independent Checks After Fitting and Adjusting Internal and External Canopy Jettison Cables		AFSC 42272
Safety and Servicing Notes are to be complied with throughout the work detailed on this card.		TIME EST
SPECIAL TOOLS AND EQUIPMENT Nil.		ASSOCIATED PROCEDURES
<p>NOTE: The independent checks detailed in this Servicing Procedure are to be carried out personally by a specialist inspector who has not been directly concerned with the fitting and adjusting of the internal and external canopy jettisoning cable or any of the related vital checks. The checks must be carried out every time the canopy jettisoning cable is completely fitted to the aircraft.</p> <p style="text-align: center;"><u>42272 (INSPECTOR)</u></p> <ol style="list-style-type: none"> 1. INDEPENDENT CHECK <ul style="list-style-type: none"> 1.1 Internal jettison cables (canopy). Ensure correctly routed and locked. 1.2 External jettison cables (canopy). Ensure correctly routed and locked. 1.3 Aircraft job card. Endorse as follows:- Certified I have personally carried out the independent checks detailed in Servicing Schedule BAC F53 and T55 (SA) 5A3A Section 1, SP 133 (AF). 		
<p>SERVICING PROCEDURE INSPECTION STAGES DO NOT EXCLUDE ADDITIONAL INSPECTION STAGES INCORPORATED AS NECESSARY IN MAINTENANCE CERTIFICATION DOCUMENTS</p>		

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

