

CHAP. 3 AIRFRAME
S.P. 303 A.L. 1
SHEET 1 OF 1

SERVICING PROCEDURE

F53

T55

BAC F53 & T55 (SA)

5A3A Section 1
2nd Edition

Aileron Controls


Safety and Servicing Notes are to be complied with
throughout the work detailed on this card.

AFSC


43151

42152

TIME EST




A



B

ASSOCIATED
PROCEDURES

WITH HYDRAULIC POWER AVAILABLE, RAISE THE AILERON
TO GAIN ACCESS TO THE SEVEN GREASE NIPPLES




TYPICAL ROD-TO-ROD CONNECTION, PRE-PACKED
BEARINGS (XG-287) WITH SIDEPLATES

ALL THE BALL BEARINGS IN
THIS ASSEMBLY ARE PRE-
PACKED WITH GREASE XG-287


KEY TO LUBRICANTS

SYMBOL NOMENCLATURE

XG-287



P PRE-PACKED BEARINGS



D

ALL THE BALL BEARINGS IN
THIS ASSEMBLY ARE PRE-
PACKED WITH GREASE XG-287

LUBRICATION OF CONTROLS

FIGURE 1

SERVICING PROCEDURE INSPECTION STAGES DO NOT EXCLUDE ADDITIONAL INSPECTION STAGES
INCORPORATED AS NECESSARY IN MAINTENANCE CERTIFICATION DOCUMENTS

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

