

CHAP. 3 AIRFRAME
S.P. 307 A.L. 1
SHEET 1 OF 1

SERVICING PROCEDURE
F53 T55

BAC F53 & T55 (SA)
5A3A Section 1
2nd Edition

Flaps

AFSC

TIME EST

Safety and Servicing Notes are to be complied with
throughout the work detailed on this card.

43151



42152

ASSOCIATED
PROCEDURES

KEY TO LUBRICANTS



SYMBOL NOMENCLATURE

 XG-287 



A OUTBOARD JACK
FORWARD MOUNTING

B FLAP POSITION TRANSMITTER



C TYPICAL JACK AFT
ATTACHMENT

D ARRANGEMENT OF CENTRE HINGE

FLAPS REMOVAL/ASSEMBLY

FIGURE 1

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

