

**CHAPTER 6**  
**REPLENISHMENTS**

## Chapter 6.

## SERVICING PROCEDURES

## LIGHTNING AIRCRAFT

## AIRFRAME

## REPLENISHMENTS

## LIST OF CONTENTS

BAC F53 &amp; T55 (SA)

5A3A Section 1

2nd Edition

A.L.11

| SP NO.  | TITLE  |
|---------|--|
| 600     | Brake Parachute - Replacement.   |
| 601     | Canopy Seal Air System - Replenishment.                                  |
| 602     | Hydraulic Accumulators (Nitrogen) - Skin Gauge Check and Replenishment.  |
| 603     | Hydraulic Reservoirs (Oil, OM-15) - Replenishment.                       |
| 604     | Main and Nose Undercarriage Struts (Oil, OM-15 and Air) - Replenishment. |
| 605     | Not Allocated.   |
| 606     | Tailplane Motor (Oil, OX-38) - Replenishment.                            |
| 607     | Shimmy Damper Accumulator (Oil, OM-15) - Replenishment.                  |
| 608-699 | Not Allocated.   |







This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.