

SUB-GROUP 113A

AIRBORNE ELECTRICAL EQUIPMENT -
GENERAL PUBLICATIONS

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113A | | | |
| -0001-1 | | General Shop Practice Requirements for the Repair, Maintenance a Test of Electrical Equipment | Nov 90 |
| -0002-1 | | Aircraft Electrical System Procedures General & Technical Information (-1) | Mar 92 |
| -0002-1 | | Aircraft Electrical System Inspection Procedures | Mar 91 |
| -0003-1 | | Aircraft Electric and Electronic Wiring General & Technical Information (-1) | Dec 91 |
| -0201-1 | -0201-1 | Earthing of Aircraft and Ground Support Equipment (including Safety Precautions for Portable Electrical Equipment) General and Technical Information | Nov 92 |
| -0301-1 | | Brush-Wear and Commutation in Rotary Machines | Feb 76 |
| -0307-1 | -0307-1 | Aircraft Bonding Screening & Earth Points General & Technical Information | Feb 92 |
| -0308-1 | -0308-1 | Servicing Techniques | Apr 92 |
| -0308-6 | | Servicing Procedures 3rd-Line | Nov 74 |
| -0308-D1 | | Brush Bedding on Rotating Machines | Nov 74 |
| -0308-D2 | | Servicing of DC Machines | Nov 74 |
| -0308-D3 | | Servicing of Electrical Contacts | 1974 |
| -0309-1 | -0309-1 | Waterproofing & Climatic Protection of Electrical & Electronic Equipment | - |
| -0310-1 | | Servicing of Electroluminescent Lamps | Jun 77 |
| -0401-1 | | Graphical Symbols for Aircraft Electrical Circuit Diagrams ... | - |

SUB-GROUP 113A

AIRBORNE ELECTRICAL EQUIPMENT -
GENERAL PUBLICATIONS

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113A | | | |
| -0001-1 | | General Shop Practice Requirements for the Repair, Maintenance a Test of Electrical Equipment | Nov 90 |
| -0002-1 | | Aircraft Electrical System Procedures General & Technical Information (-1) | Mar 92 |
| -0002-1 | | Aircraft Electrical System Inspection Procedures | Mar 91 |
| -0003-1 | | Aircraft Electric and Electronic Wiring General & Technical Information (-1) | Dec 91 |
| -0201-1 | -0201-1 | Earthing of Aircraft and Ground Support Equipment (including Safety Precautions for Portable Electrical Equipment) General and Technical Information | Nov 92 |
| -0301-1 | | Brush-Wear and Commutation in Rotary Machines | Feb 76 |
| -0307-1 | -0307-1 | Aircraft Bonding Screening & Earth Points General & Technical Information | Feb 92 |
| -0308-1 | -0308-1 | Servicing Techniques | Apr 92 |
| -0308-6 | | Servicing Procedures 3rd-Line | Nov 74 |
| -0308-D1 | | Brush Bedding on Rotating Machines | Nov 74 |
| -0308-D2 | | Servicing of DC Machines | Nov 74 |
| -0308-D3 | | Servicing of Electrical Contacts | 1974 |
| -0309-1 | -0309-1 | Waterproofing & Climatic Protection of Electrical & Electronic Equipment | - |
| -0310-1 | | Servicing of Electroluminescent Lamps | Jun 77 |
| -0401-1 | | Graphical Symbols for Aircraft Electrical Circuit Diagrams . . . | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113B

GENERATORS

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113B | | | |
| -0101-16 | | Generator Lucas Aerospace Type B2003 | - |
| -0102-16 | | Generators, AC Lucas Aerospace Type N0300 Series | May 75 |
| -0103-16 | | Generators Lucas Aerospace Type N0400 Series | Nov 71 |
| -0105-123A6 | | AC Generator Lucas Aerospace Type BA 1013 | Apr 80 |
| -0106-16 | | Generator, AC Lucas Aerospace Type N 0904-1 | May 80 |
| -0106-2 | | Generator, AC Rotax Type No 90411 | - |
| -0107-126 | | Generator, AC, Lucas Aerospace Type BA2402/3A | Apr 78 |
| -0108-136 | | Generator, AC, Plessey Type 8QL40BP (Pt No 503-1-04179-007) | - |
| -0108-2 | | Generator, AC, Plessey Types 503-1-04179-003 & 503-1-04179-007 | - |
| -0109-16 | | Generator, AC, Rotax Type N0504 | - |
| -0111-13A | | AC Generator, Pt No AGE59-2 | Aug 78 |
| -0114-1 | | Generator Type 165C (Pt No 503-1-01620-001) & Two-Speed Gearbox (No 4CZ95880/A) Plessey | - |
| -0114-2 | | Generator Type 165C (Pt No 503-01620-001) & Two-Speed Gearbox (No 4CZ95880/A) Plessey | - |
| -0115-16 | | Generator, AC Type 170 English Electric Type AE2060 | - |
| -0116-16 | | AC Generator Lucas Aerospace Type AE 2071 | Jul 74 |
| -0118-13A | | Generator, AC, 28B187-4-A | Oct 77 |
| -0420-136 | | AC Generator, Brushless, Type 28B135-29A | Jun 90 |
| -0121-1 | | 2kVA Regulated AC Brushless Generator Rotax Type BAF 1102 (N185318) | 1969 |
| -0122-1 | | Generator, AC, AM Type 175 Lucas Aerospace Type AE2023 Mk 3 | - |
| -0122-2 | | Generator, AC, AM Type 175 English Electric Type AE2023 Mk 3 | - |
| -0123-13 | | Generator, AC, Lucas Aerospace Type AE2078 Mk 1 | Feb 83 |
| -0123-2 | | Generator, AC, Lucas Aerospace Type AE2078 Mk 1 | May 75 |
| -0123-6 | | Generator, AC, Lucas Aerospace Type AE2078 Mk 1 | - |
| -0124-6 | | 3kW Brushless DC Generator Plessey (Pt No 503-1-05980) | - |
| -0126-1 | | Motor Generator Hawker Siddeley Dynamics Type B503-4 | - |
| -0128-1 | | Motor Generator Hawker Siddeley Dynamics Type B507 | Feb 69 |
| -0129-13A6 | -0129-136 | AC Generator Lucas Aerospace Ltd Type AD 2107 Pt No AE 210 7002 | - |
| -0130-16 | | AC Generator Lucas Aerospace Type AE 2044 (AM Type 158C) | Sep 75 |
| -0131-16 | | AC Generator Lucas Aerospace Type AD 2046/6 (AM Type 168) | Aug 75 |
| -0132-13A6 | | Alternator & Voltage Regulator Auxilec 1062 & 1040 Ref No 505UA/9549 and 505UC/25-13023 | - |
| -0133-1 | | AC Generator Auxilec Pt No 12210, 12210-1 & 12210-2 | Sep 81 |

SUB-GROUP 113B

GENERATORS

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113B-cont | | | |
| -0133-3A | | AC Generator Type 12210 & 12210-1 Voltage Regulator, Type 12310 Auxilec combined with AP113D-07132-3A | Aug 76 |
| -0134-136 | -0134-136 | Alternator Auxilec Type 520-1 | - |
| -0135-12 | | Generator, AC, Lucas Aerospace Type AE2124 Mk 1 | Jul 83 |
| -0135-6 | | Generator, AC, Lucas Aerospace Type AE2124 Mk 1 | Feb 74 |
| -0138-123A6 | | 6 kVA AC Generator Lucas Aerospace Type BAF1201 | Dec 72 |
| -0139-1 | | Generator, AC, Lucas Type AE2036/1 | Jun 73 |
| -0140-136 | | Alternator, Plessey, Pt No 503-1-02100 and 503-1-02700 Gen and Tech Info Parts Catalogue and Related Information Repair and Reconditioning Instructions | Nov 84 |
| | -0141-1 | Integrated Drive Generator Type AE8906 Lucas Aerospace Pt No AE8906352 | Mar 82 |
| | -0141-3 | Lucas Generator Drive Integrated | Sep 80 |
| -0142-12 | | Ram Air Turbine Lucas Aerospace Type BAT0103 Generator Lucas Aerospace Incorporating Type BA 1603 or BA 1604) | Apr 80 |
| -0143-13 | | Generators AC, Prestolite Type ALU 8402 and ALU 8421 | - |
| -0144-13A6 | | AC Generator Pt No AE2512 Mk 3 Lucas Pt No 179-60500-10 Boeing Vertol Co | Jan 82 |
| -0146-3 | | VSCF Package 6115-01-205-4796 | Aug 88 |
| -0146-6 | | Variable Speed, Constant Frequency (VSCF) Package Pt No 948F445-4 Repair & Reconditioning Instructions | Nov 91 |
| -0146-13 | | Variable Speed, Constant Frequency Package (VSCF) Pt No 948F445-4Gen and Tech Info. Illustrated Parts Catalogue | Sep 91 |
| | -0148-136 | AC Generator Type BA03501 General and Tech Info IPC Overhaul Instructions | Oct 93 |
| -0149-136 | | AC Generator General Electric Company Model No 2CM353C1H | Sep 92 |
| -0150-136 | | CFM 56-2A Engine Component Maintenance Manual Rotor 1 Stator General AC 77-11-21 | Dec 91 |
| -0151-1 | | Generator, AC Model Nos 2CM359CK, 2CM359CK, 2CM359D1 Pt Nos NSN 6115-00-252-3421, 6115-NCB923673 (General Electric) | Nov 90 |
| -0152-1 | | Generator, AC P/Nos 977 JO33 Through to 8 (Westinghouse) . | Nov 90 |
| -0153-1 | | Integrated Drive Generator P/N (E-3 Aircraft 714674 Series P/N (EC/RC/TC-135 H/P/S/W/T Aircraft) 727417 Series | Nov 90 |
| -0154-13 | | 30 KVA VSCF Generator Part No 949F857-1 Genera and Technical Information Illustrated Parts Catalogue | Sep 91 |
| -0163-2 | | Generator, AC General Orders and Modifications | Dec 92 |
| -0163-3 | | Generator, AC Illustrated Parts Catalogue | Dec 92 |
| -0163-6 | | Generator, AC Repair and Reconditioning Instructions | Dec 92 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113B

GENERATORS

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113B-cont | | | |
| -0166-3 | | Generator AC | Nov 94 |
| -0201-16 | | Starter Generator Lucas Aerospace Type BC0107/2 | Jan 78 |
| -0202-2 | | Generators, Rotax, Types B3503 and B3508 General Orders and Modifications | Jun 92 |
| -0202-16 | | Generator, Rotax Type B3503 & B3508 | Jan 72 |
| -0203-2 | | Generator, DC, Type 527A (English Electric Type AE2505 Style 3) | - |
| -0203-16 | | Generator, English Electric Type 527A AE205 Style 3 | 1966 |
| -0204-1 | | Bleed Air Turbine Generator Lucas Aerospace Type BT 0102 .. | Mar 75 |
| -0205-16 | | Generator, DC, Lucas Aerospace Type AE2519 Mk 2 | Aug 74 |
| -0205-2 | | Generator, DC, English Electric Type AE 2519 Mk 2 | Mar 75 |
| -0208-1 | | DC Generator, Lucas Aerospace Type AE2511 | Apr 78 |
| -0209-16 | | Generator, Leece-Neville Type G001-2591-GA (WAB2707 or WAB2707/1) | - |
| -0210-16 | | Generator, DC, Type 519 & 519A | - |
| -0212-13A6 | -0212-13A6 | Generators, lucas Aerospace Type B2100 Series | - |
| -0212-2 | | Generators, Lucas Aerospace Type B2100 Series | Mar 77 |
| -0213-1 | | Generator, DC, WAB3847 (Bendix Type 30E-1 Modified) | - |
| -0215-13A6 | | Generator, Lucas Aerospace Types B4101 & B4103 | Nov 84 |
| -0215-3 | | Generators, Lucas Aerospace Types B4101 & B4103 | Jun 89 |
| -0215-16 | | Generator, Lucas Aerospace Types B4101 & B4103 | - |
| -0216-1 | | Generator, Type 02 | - |
| -0217-1 | | Generator, Type P3 | Oct 71 |
| -0218-123A6 | -0218-123A6 | Starter Generator Lucas Aerospace Types BC0601 & BC0601/4 | - |
| -0219-13A | | Generator, Lucas Aerospace Type B1800 Series (IAM Type 500 Series) | May 74 |
| -0220-1 | | Generator, Lucas Aerospace Type B2000 Series | Jun 73 |
| -0222-1 | | Generator, Lucas Aerospace Type B2702/1 (AM TYPE 517) .. | Jun 73 |
| -0222-2 | | Generator, Lucas Aerospace Type B2702/1 | Oct 75 |
| -0222-6 | | Generator, Type 517 Lucas Aerospace Type B2702-1 | Sep 74 |
| -0223-136 | | 9 Kw Brushless DC Generator Plessey Pt No 503-1-06325-008 | Mar 87 |
| -0223-2 | | 9 Kw Brushless DC Generator Plessey Pt No 503-1-06325-008 | Jul 87 |
| -0224-13A6 | | Starter Generator Plessey Pt No 503-1-02090 | Jun 79 |
| -0224-2 | | Starter Generator Plessey Pt No 503-1-02090 | Feb 79 |
| -0225-1 | | Generator, Eclipse Pioneer Type 30E16-11-C | Mar 74 |
| -0226-16 | | Generator, Type HX2 | Mar 74 |
| -0227-136 | -0227-136 | Starter Generator General and Technical Information Parts Catalogue & Related Information Overhaul Instructions | Apr 88 |
| -0228-12 | | Generator, Lucas Aerospace Type AE2505 Style 1 (AM Type 514) | Oct 80 |
| -0230-13 | | Starter Generator, Lucas Aerospace Type BC0913 | Jan 90 |

SUB-GROUP 113C

BATTERIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113C | | | |
| -0001-1 | | Aircraft Batteries | Jan 90 |
| | -0001-13 | Aircraft Batteries | - |
| -0001-2 | | Aircraft Batteries | Oct 84 |
| -0001-3 | | Aircraft Batteries | Jun 92 |
| -0002-1 | | Aircraft Battery Marathon (Type TSP 900AT) | Jan 88 |
| -0003-13 | | Emergency Lighting Power Pack Pt No 516574-1 | Dec 88 |
| -0308-1 | -0308-1 | Sealed Nickel Cadmium Cells DEAC Types | - |
| -0311-1 | | Battery Chloride Alcad Type N 1.2V 10Ah | Sep 75 |
| -0313-13A6 | | Aircraft, Nickel Cadmium Storage Batteries Type MA-2 Etc .. | Jun 63 |
| -0316-1 | | Sealed Nickel Cadmium Cell (Alkaline Batteries Ltd) | - |
| -0317-1 | | Cell Nickel Cadmium Nife Type SL114 | Mar 72 |
| | -0321-3 | Varta Battery F20-40 HI with Temperature Sensors MRCA complete | Aug 82 |
| | -0328-1 | One Shot Battery Silberkraft GMBTH | Mar 86 |
| | -0328-3 | Silberkraft Battery One Shot | Jul 86 |
| -0331-13 | | Nickel - Cadmium Battery P/N 43B050KB01, Boeing P/N 204-13038-2 (General Electrical Battery Business Dept) .. | Nov 90 |
| -0332-1 | | Aircraft Nickel Cadmium Storage Batteries | Nov 90 |
| -0332-3 | | Aircraft Nickel Cadmium Storage Batteries | Nov 90 |
| -0333-13 | | Battery Power Supply P/N 60-1321-1 (Grimes) | Nov 90 |
| -0334-13 | | Navigational Computer System Batery Unit P/N 7883480-011 (Boeing) | Nov 90 |

SUB-GROUP 113C

BATTERIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113C | | | |
| -0001-1 | | Aircraft Batteries | Jan 90 |
| | -0001-13 | Aircraft Batteries | - |
| -0001-2 | | Aircraft Batteries | Oct 84 |
| -0001-3 | | Aircraft Batteries | Jun 92 |
| -0002-1 | | Aircraft Battery Marathon (Type TSP 900AT) | Jan 88 |
| -0003-13 | | Emergency Lighting Power Pack Pt No 516574-1 | Dec 88 |
| -0308-1 | -0308-1 | Sealed Nickel Cadmium Cells DEAC Types | - |
| -0311-1 | | Battery Chloride Alcad Type N 1.2V 10Ah | Sep 75 |
| -0313-13A6 | | Aircraft, Nickel Cadmium Storage Batteries Type MA-2 Etc .. | Jun 63 |
| -0316-1 | | Sealed Nickel Cadmium Cell (Alkaline Batteries Ltd) | - |
| -0317-1 | | Cell Nickel Cadmium Nife Type SL114 | Mar 72 |
| | -0321-3 | Varta Battery F20-40 HI with Temperature Sensors MRCA complete | Aug 82 |
| | -0328-1 | One Shot Battery Silberkraft GMBTH | Mar 86 |
| | -0328-3 | Silbercraft Battery One Shot | Jul 86 |
| -0331-13 | | Nickel - Cadmium Battery P/N 43B050KB01, Boeing P/N 204-13038-2 (General Electrical Battery Business Dept) .. | Nov 90 |
| -0332-1 | | Aircraft Nickel Cadmium Storage Batteries | Nov 90 |
| -0332-3 | | Aircraft Nickel Cadmium Storage Batteries | Nov 90 |
| -0333-13 | | Battery Power Supply P/N 60-1321-1 (Grimes) | Nov 90 |
| -0334-13 | | Navigational Computer System Battery Unit P/N 7883480-011 (Boeing) | Nov 90 |

UK RESTRICTED

**AP 100Z-0101 AL136
SUB-GROUP 113D**

**CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES**

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|---|--------|
| 113D | | | |
| -0003-1 | -0003-1 | DC & AC Carbon Pile Voltage Regulators | - |
| -0012-1 | -0012-1 | Manually & Mechanically Opeated Switches | Feb 95 |
| -0012-5F | | Manually & Mechanically Operated Switches | - |
| -0013-1 | | Relay Solenoid & Automatic Switches 12/28V | - |
| -0013-5F | | Relay Solenoid & Automatic Switches 12/28V | Nov 74 |
| Cover 1 | | | |
| -0013-5F | | Relay Solenoid & Automatic Switches 12/28V | - |
| Cover 2 | | | |
| -0015-5F | | Relay Solenoid & Automatic Switches 100/250V | Nov 74 |
| Cover 1 | | | |
| -0015-5F | | Relay Solenoid & Automatic Switches & Control Switch Boxes | - |
| Cover 2 | | | |
| -0015-5F | | Relay Solenoid & Automatic Switches 100/250V | - |
| Cover 3 | | | |
| -0015-5F | | Relay Solenoid & Automatic Switches 100/250V | - |
| Cover 4 | | | |
| -0101-13A6 | | Rotary Inverters Lucas Aerospace Type D2-A2 Forms B5/1 & B7 | Jun 79 |
| -0101-2 | | Rotary Inverters AEI Type D2-A2 Form B5/1 & B7 | - |
| -0102-16 | | Rotary Inverter Bendix Type 32E01-18-A | - |
| -0103-16 | | Rotary Interter AEI Type DAI Form B4/3 | - |
| -0104-16 | -0104-16 | Rotary Inverters Types 100A & 100C | - |
| -0104-2 | | Rotary Inverters Types 100A & 100C | - |
| -0105-16 | | Rotary Inverter Jack & Heintz F45-10 | Jul 81 |
| -0106-16 | | Rotary Inverters Type 103 (Lucas Aerospace S3100) Series 28V Operation | Aug 72 |
| -0107-13A6 | | Rotary Inverter Lucas Aerospace Type D2A2 Forms B2/9 & B6/3 | Feb 76 |
| -0107-2 | | Rotary Inverter Lucas Aerospace Type D2A2 | Oct 88 |
| -0109-16 | | Rotary Inverters Type 108, 108A & 108B (Lucas Aero Space S3303/2S3304 & S3307) | May 72 |
| -0111-16 | | Inverter Leyland Type MGH182-100 | 1967 |
| -0112-1 | | Rotary Inverter AEI Types 350 & 350G | - |
| -0113-16 | | Rotary Inverter AEI Type 200 | - |
| -0114-16 | | Inverter Plessey Type 115A (Pt No 402-1-00460) | 1967 |
| -0117-13A | | Rotary Inverter Lucas Aerospace Type S2701/1 (AM Type RC8A) | Oct 75 |
| -0117-6 | | Rotary Inverter Lucas Aerospace Type S2701/1 (AM Type RC8A) | Oct 75 |
| -0118-1 | | Rotary Inverter AM Type 102A | 1969 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -0119-1 | | Inverter Plessey Type 117 (Pt No 502-1-00445) | - |
| -0120-1 | -0120-1 | Rotary Inverters Type 100B (Rotax S2902) & 100D (Rotax S2909) | - |
| -0121-1 | | Rotary Inverter RC2 | Dec 73 |
| -0122-1 | | Rotary Inverter Type MG4B | Apr 74 |
| -0123-1 | | Rotary Inverter Type 201B | Apr 74 |
| -0124-1 | | Rotary Inverter Type 206 | Apr 74 |
| -0125-1 | | Rotary Inverter Type 304 | Apr 74 |
| -0126-1 | | Rotary Inverter Type MG7 Lucas Aerospace | Mar 74 |
| -0128-1 | | Rotary Inverter Type 153A Lucas Aerospace S3107/1 | Mar 75 |
| -0129-1 | | Rotary Inverter Bendix Type 1518-7-J | Nov 76 |
| -0130-13A6 | | Inverter Bendix Type 32B50-19-B | Jan 79 |
| -0203-1 | | Rotary Transformer Type 88X | Dec 73 |
| -0302-1 | | Static Inverter Unit Ferranti Type F1 18 | Jul 65 |
| -0302-6 | | Static Inverter Unit Ferranti Type F1 18 | - |
| -0303-1 | | Inverter Vibrator Valradio Type 230/30/28AT | - |
| -0304-16A | | Static Inverter HSA Type 1/V12873 | - |
| -0305-16 | | Static Inverter GEC Pt No 509-1-01-230 General & Technical Information Repair & Reconditioning Instructions | Sep 91 |
| -0306-13A | | Static Inverters Ekco Types E182, E184/1 & Mounting Rack Type M2228/A | - |
| -0307-1 | | Static Inverter HSD Type CO3E-101013A | - |
| -0307-6 | | Static Inverter HDS Type Core-101013A | Nov 72 |
| -0308-1 | | Static Inverter Plessey Type 200VA (Pt No 509-1-01780-002) .. | 1969 |
| -0308-3 | | Static Inverter Plessey Type 200VA 6125-99-198-9148 | Sep 94 |
| -0308-6 | | Static Inverter Plessey Type 200VA (Pt No 509-1-01780-002) .. | - |
| -0309-16 | | Inverter Unit Type 375 (Ref No 5UB/6125-99-198-6443) | - |
| -0310-1 | | Static Inverter Ekco (Pt No M3014A) | Jun 80 |
| -0311-13A6 | | Static Inverter SFENA Type TSG420-101 Ref No 505UB/9657 .. | - |
| -0312-13A | | Static Inverter Intertechnique | - |
| -0313-1 | | Transverter Valradio Type A28/400TA (Modified) | Jun 75 |
| -0314-136 | -0314-136 | Static Inverter General & Technical Information Parts Catalogue & Related Information Repair and Reconditioning Instructions | Mar 91 |
| -0315-13A6 | | Static Inverter Ferranti Types F145E & F145F | Jul 77 |
| -0316-123A | | Static Inverter Type TSG 456-101 & Type TSG 456-103 | Nov 83 |
| -0316-6 | | Static Inverter Type TSG 456-103 | Sep 84 |
| -0318-12 | | Static Inverter Plessey Pt No 509-1-02401-001 | Jul 80 |
| -0319-1 | | Static Inverter Flite - Tronics Type PC15 Series | Jul 74 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -0320-16 | | Vibrator Power Unit Type 596 | Mar 75 |
| -0321-1 | | Static Inverter Lucas Aerospace Type U-6729M | Jun 76 |
| -0321-3 | | Static Inverter type U6729M 6130-99-620-7571 | Mar 90 |
| -0322-126 | | Static Inverter Unit Type F1Sq (SUB/6610-99-113-1173) | Jan 84 |
| -0324-13A6 | | Inverter AC Pt No ASH 584-2 Leland Electro Systems INC | Feb 83 |
| -0326-13A6 | | Inverter 100 VA 1 Phase Class B Multi-Purpose Pt No PS 283 (MS16057-3)EMP Electronics | Jan 83 |
| -0327-136 | | Static Inverter SFENA Pt No TSG 420-103 | Nov 83 |
| -0328-136 | 0328-136 | Static Inverter SFENA TSG 420-203 | - |
| -0331-13 | | Static Inverter ASH 500 1PB General & Technical Information Illustrated Parts Catalogue | Feb 91 |
| -0335-13 | | Static Inverter Pt No 01-001-0102-0068 | Nov 89 |
| -0336-6 | | Static Inverter Type 39B168-4-A Bendix Electric Power Division Repair and Reconditioning Instructions | Oct 92 |
| -0401-1 | | Transformers Ferranti Types | Oct 84 |
| -0402-1 | | Single Phasing Discriminator Unit AEI Type LTB Form Y2 | - |
| -0403-1 | | 3-Phase Transformer English Electric Type AE5705 | 1967 |
| -0404-1 | | Rectifier Unit Type CP40(AED) | - |
| -0405-16 | | Transformer Rectifier Unit Rotax Types U7001 & U7001/1 | - |
| -0405-2 | | Transformer Rectifier Unit Rotax Type U7001 | - |
| -0409-1 | | Transformer Plessey Type 407-1-90116 | - |
| -0410-1 | | Transformer Plessey Type 407-1-90274 | - |
| -0411-1 | | Transformer Plessey Type 7CZ143982 | - |
| -0412-1 | | Current Transformer Rotax Type P6601 | - |
| -0413-1 | | Transformer Rectifier Unit Rotax Type ZA12201 | - |
| -0414-16 | | Transformer Rectifier Unit Rotax Type U1800 Series | 1966 |
| -0415-16 | | Transformer Rectifier Unit Rotax Type U5502 | - |
| -0415-136 | | Transformer Rectifier Unit Lucas Aerospace Type U5502 | Jul 91 |
| -0416-1 | | Transformers Sangamo Weston Type S117 Form 1 & Type S457 Form1 | - |
| -0417-1 | | Current Transformer Package Plessey Type 503-1-04000.003 | Mar 94 |
| -0418-1 | | Current Transformer Unit English Electric Type AE5372 Mk 1 | Dec 66 |
| -0419-1 | | Auto Transformer Unit English Electric Type AE5745 | - |
| -0420-126 | | Transformer Rectifier Units Ferranti Types TR150 & TR150A | Oct 78 |
| -0423-16 | | Rectifier Battery Blocking English Electric Type AE7011 | 1968 |
| -0424-1 | | Differential Protection Current Transformer Plessey (Pt No 700-1-12560) | - |
| -0425-3A | | Converter 100A-Class C Type MS17967-2 (Pt No 28VS100Y-10) | May 66 |
| -0425-6 | | Converter 100A Class C Type MS17967-2 (Pt No 28VS100Y-10) | May 66 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -0426-1 | | Transformer Rectifier Unit Lucas Aerospace Types AE5717 & AE451 | Apr 73 |
| -0428-1 | | Transformer Thorn Type 07-0196 | 1969 |
| -0431-13A | | Transofrmer Rectifier Unit Lucas Aerospace Type U15902 ... | Jun 79 |
| -0431-6 | | Transformer Rectifier Unit Lucas Aerospace Type U15902/2 .. | Jun 74 |
| -0432-1 | | Lucas Aerospace Type AE5781 Current Transformer | Oct 75 |
| -0433-13A | | Auto-Transformer EAS Pt No 1206 | Dec 75 |
| -0435-1 | | Transformers Plessey Types | 1969 |
| -0436-1 | | Transformer Unit HSA Type 6M4N12315 | 1969 |
| -0437-16 | | Power Supply NATO Code No 1560-99-107-8517 | - |
| | -0439-3 | Siemens Transformer Rectifier Unit -Acs | Apr 82 |
| -0439-13 | | Transformer Rectifier Unit Type 6GQ8 120-1B | Feb 90 |
| -0440-13 | | Transformer Rectifier Unit Rotax Type AE5754 | Dec 82 |
| -0440-6 | | Transformer Rectifier Unit English Electric Type AE5754 | - |
| -0441-1 | | Transformer Rectifier Unit Lucas Aerospace Type AE5755 ... | Jan 75 |
| -0442-1 | | Rectifier Battery Blocking English Electric Type AE7024 | 1970 |
| -0443-1 | | Lucas Aerospace Type U3102/1 Transformer Rectifier Unit ... | May 74 |
| -0446-1 | | Auto Transformer Haddon Type PK251/3 | May 74 |
| -0447-1 | | Compounding Unit Lucas Aerospace type U3001/2 | Jul 74 |
| -0449-1 | | Transformer - Rectifier Unit ferranti Type RD7221 | Feb 75 |
| -0450-13A | | Transformer FAS pt No 127 | Aug 76 |
| -0451-1 | | Tap Changing Transformer Controller Plessey Type 700-1-15820 | Sep 79 |
| -0452-13A6 | | Transformer Rectifier Unit Lucas Aerospace Type U13404 ... | Apr 76 |
| | -0453-1 | Battery Charger Type FCC101B Ferranti Instruction Ltd Pt No 84-58158 | Mar 82 |
| | -0453-3 | Ferranti Battery Charger | Mar 94 |
| -0454-1 | | Transformer Lucas Aerospace Type LTS50 Form Z1/1 | Dec 75 |
| -0455-1 | | Current Transformer Lucas Aerospace Type AE5712 | Dec 75 |
| -0456-1 | | Current Transformer Lucas Aerospace Type AE5703 Mk2 | Dec 75 |
| -0457-1 | | Transformer Rectifier Unit Aerospace Type U5201/1 | Dec 75 |
| -0458-1 | | Rectifier Unit Type CP19 (Lucas Aerospace U1604) | Dec 75 |
| -0459-1 | | Transformer Lucas Aerospace Type P2403 | Dec 75 |
| -0460-1 | | Auto Transformer Lucas Aerospace Type P11701 | Dec 75 |
| -0461-1 | | Transformer Rectifier Unit Lucas Aerospace Type U5501 | Jan 76 |
| -0462-1 | | Current Differential Protection Transformer Pt No 9016D23.2 | Jul 87 |
| -0463-1 | | Current Transformer Pt No 9002D05-4 | Oct 86 |
| -0464-16 | | Frequency Standard Battery Shelf (Stoneleigh SB122K5) | Aug 86 |
| -0465-13 | | Actuator Pt No MA11A1114 and MA11A11173 (ITT General Controls) | Mar 94 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -0467-36 | | Transformer - Rectifier Power Supply | Nov 94 |
| -0601-1 | | Frequency Changer Rotax Type 270 | - |
| | -0701-3 | Lucas Phase Sequency Undervoltage | Oct 82 |
| -0701-13A6 | -0701-13A6 | Undervoltage Phase Sequence Units Pt No EE Types AE 5600, AE 5601 & AE 5608 | - |
| -0702-16 | | Voltage Control & Protection Unit Lucas Aerospace Type U6401 | Jul 75 |
| -0702-2 | | Voltage Control & Protection Unit Lucas Aerospace Type U6401 | Sep 75 |
| -0703-2 | | Control & Protection Unit, DC, Lucas Aerospace Type U6403 .. | Sep 75 |
| -0704-16 | | Control & Protection Unit Lucas Aerospace Type U 7704/1/2/3 | Mar 87 |
| -0705-16 | | Protection Unit Rotax Type F7501 | - |
| -0705-2 | | Protection Unit rotax Type F7501 | - |
| -0706-16 | | Control Panel Rotax Type U3715 | - |
| -0706-2 | | Control Panel Rotax Type U3715/1 | Jun 72 |
| -0707-1 | | Frequency Sensitive Unit rotax Type F4800 | - |
| -0708-16 | | Protection Unit Lucas Aerospace Type F7511 | - |
| -0708-2 | | Protection Unit Rotax Type F7511 | - |
| -0709-16 | | Voltage Sensing Unit HSA Type 1/V13147 | - |
| -0710-16 | | Control & Protection Unit Lucas Aerospace Type U8601/1M .. | May 78 |
| -0710-2 | | Control & Protection Unit Rotax Type U8601 | - |
| -0713-16 | | Reverse Phase Protection Unit rotax Type U3613 | - |
| -0714-1 | | Over-Voltage Protection Units GEC Type 28 Pt Nos 700-1-12200 & 506-1-00916 | Jan 91 |
| -0714-6 | | Over-Voltage Protection Unit Type 28 Plessey Pt No 700-1-12200 | - |
| -0719-126 | | Voltage Regulator Rotax Type U5801/1 | Jun 66 |
| -0719-1236 | | Voltage Regulator Rotax Type U5801/1 | - |
| -0720-16 | | Voltage Regulators Lucas Aerospace Type U6106, U6112 & U6119 | - |
| -0720-2 | | Voltage Regulators Rotax Types U6106, U6112 & U6119 | - |
| -0721-2 | | Control Panel Type 12 Lucas Aerospace Type F2801 | Dec 91 |
| -0721-16 | | Control Panel, Type 12 Lucas Aerospace Type F2801 General and Technical Information Repair & Reconditioning Instructions | Mar 92 |
| -0722-6 | | Load Controller English Type 687115 | Jul 69 |
| -0722-13 | | Load Controller Type 687115 | - |
| -0723-2 | | Control & Protection Unit Rotax Type U3704/2, 3 & 4 | Jun 72 |
| -0723-16 | | Control & Protection Unit Lucas Aerospace Type U3704/4 ... | - |
| -0724-1 | | Control & Protection Unit Lucas Aerospace Type U7703 | Jul 85 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -0725-16 | | Voltage Regulator Newton Type 23 | Sep 74 |
| -0726-1 | | Frequency Regulator AE1 Type LKK Form Z1/3 | 1967 |
| -0728-1 | | Voltage Regulator Newton Type 23/47848E | - |
| -0729-1 | | Voltage Regulator Stones Type 32 | May 71 |
| -0730-1 | | Voltage Regulator Newton Type 116 | - |
| -0731-13A6 | 00731-13A6 | Regulator & Cut-Out Unit Type C Lucas Aerospace Type F 3301 | - |
| -0732-126 | | Over-Voltage Protection Unit Lucas Aerospace Type U3617/1 .. | Jun 80 |
| -0733-126 | | Transient Detector Unit Lucas Aerospace Types U3618, U3618/1 | Jun 80 |
| -0734-1 | | Voltage Control Panel Lucas Aerospace Type AE7311 | May 74 |
| -0735-16 | | Control Panel English Electric Type AE7014 Mk 2 | Jan 67 |
| -0736-1 | | Control & Protection Unit Lucas Aerospace Types AE7023, AE7057, AE7023/2 & AE7057/2 | Nov 74 |
| -0738-16 | | Control Panel Rotax Type AE7002 Mk 3 | - |
| -0739-16 | | Control Panel English Electric Type AE7003 Mk 3 | - |
| -0741-16 | | Labinal Generation System Protection Control Units | - |
| -0742-16 | | Voltage Control Panel Rotax Type AE7307 Style 2 (AM Type 50A) | - |
| -0743-1 | | Control Panel Type 40 (AE1) | - |
| -0744-12 | | Control Panel (Main) Plessey Type AVZ-104A Pt No 503-1-04481-002 | - |
| -0744-3 | | Control Panel (Main) Plessey Type AVZ-104A Pt No 503-1-04481-002 I.P.C. | Oct 89 |
| -0744-6 | | Control Panel (Main) Plessey Pt No 503-1-04481-001 | - |
| -0745-1 | | Control Panel (Auxiliary) Plessey Pt No 503-1-04556-001 | - |
| -0745-123 | | Control Panel (Auxiliary) GEC Pt No 503-1-04556-001 | - |
| -0745-6 | | Control Panel (Auxiliary) Plessey Pt No 503-1-04556-001 | Jan 69 |
| -0747-1 | | Control Panel AEI Type 38 | 1967 |
| -0749-1 | | Protection Control Units Type a (Plessey Types) | - |
| -0750-1 | | Generator Protection & Warning Unit, AC, HSA Type 1/V/12524 | 1967 |
| -0751-1 | | Electronic Regulator Type 2B (AE1) | 1968 |
| -0752-1 | | Control Panel Type 16 (AEI) | 1967 |
| -0753-1 | -0753-1 | Voltage Sensing Units page Types C8320, C8320/1 & C10250 .. | - |
| -0754-1 | | Rectifier & AC Control Box AEI Type LK400 Form B3/5 | 1967 |
| -0754-2 | | Rectifier & AC Control Box AEI Type LKB400 Form B3/5 | - |
| -0755-1 | | Marconi Voltage Regulation Units 925, 1252, 1255, 1555, 1555A & 1809 | 1967 |
| -0755-2 | | Regulators, Voltage Marconi Types 925, 1252, 1253, 1555, 1555A & 1809 | 1975 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -0756-1 | | Frequency Control Unit Godfrey & Partners Type CPS 3 Mks 1, 2 & 3 | Aug 80 |
| -0758-1 | | Control Panel Type 46 | 1967 |
| -0759-1 | | Control Panel Plessey Type 47 (Frequency Regulator) | 1969 |
| -0761-1 | -0761-1 | Voltage Regulator GEC Type CR2795-B1-05A1 | - |
| -0762-1 | | Frequency Sensitive Unit Ultra Type A820 | - |
| -0764-1 | | Voltage Regulator Plessey Pt No 503-1-04064-004 | Nov 88 |
| -0764-6 | | Voltage Regulator Plessey Pt No 503-1-04064-004 | Jun 90 |
| -0764-13 | | Voltage Regulator GEC Pt No 503-1-04064-004 | - |
| -0766-2 | | Control Panel Bendix Type 21B30-3-A | - |
| -0767-2 | | Voltage Regulator Type 66 Lucas Aerospace F4101 | Apr 75 |
| -0768-3A | | Power Control Box, AC, Pt no 6043H1-5 | - |
| -0768-6 | | Power Control Box, AC Pt No 6043H1-5 | - |
| -0771-1 | -0771-1 | Voltage Regulator Newton Type 126 Pt No 23/44018E | - |
| -0772-136 | | Voltage Regulators Types 70/60907 and 70/404152 | Nov 92 |
| -0772-13A6 | | Voltage Regulators Types 70/60907 & 70/404152 | Aug 74 |
| -0773-13A | | Voltage Regulator Type 114 Pt No 153689 | Dec 87 |
| -0774-13A6 | | Voltage Regulator Lucas Aerospace Type U6103 | - |
| -7777-13A6 | | Control Panels Lucas Aerospace Types U1504, U1507, U1507/1, U1509, U1509/1, U1511 & U1511/1 | Feb 75 |
| -0777-2 | | Control Panels Rotax Type U5104, U5109 & U1511 | Jan 71 |
| -0780-13A6 | | Control Panel Lucas Aerospace Type U1502/2 (AM Type 15) | Dec 72 |
| -0781-13A6 | | Lucas Aerospace Type AE7017 Control & Protection Mk 2, Mk 3 & Mk 4 | Jun 78 |
| -0781-2 | | Control & Protection Unit Lucas Aerospace Type AE 7017 Mk 2 | Aug 74 |
| -0782-1 | | Over Voltage Unit Lucas Aerospace Type AE 5611 | Jun 77 |
| -0782-6 | | Over Voltage Unit type AE 5611 | Jun 77 |
| -0783-1 | | Protection Unit Plessey Type 54 (Ref No 700-1-12520) | 1969 |
| -0783-6 | | Protection Unit Plessey Type 54 (Ref No 700-1-12520) | - |
| -0784-1 | | Control Panel Plessey Type 55 (Ref No 700-1-12530) | 1969 |
| -0784-2 | | Control Panel Plessey Type 55 (Ref No 700-1-12530) | - |
| -0785-1 | | Control Panel Plessey Type 56 (Ref No 700-1-12540) | 1969 |
| -0785-6 | | Control Panel Plessey Type 56 Pt No 700-1-12540 | - |
| -0786-1 | | Control Panels Plessey Type 57 (Ref No 700-1-12550) & Type 48 No 2 (Ref No 503-1-01110) | 1969 |
| -0786-6 | | Control Panel Plessey Type 57 Pt No 700-1-12550 | - |
| -0787-6 | | Transformer Rectifier Unit Chatham Electronics Pt No 28VS 200Y.13 | May 77 |
| -0788-3A | | Power Control Box Pt No A1017A | 1968 |
| -0788-6 | | Power Control Box Pt No A1017A | 1968 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -0789-6 | | Power Control Box AC, No 6043H4 | - |
| -0790-13A | | Control Panel Plessey Type 58 Pt No 700-1-12900 | - |
| -0790-2 | | Control Panel Plessey Type 58 Pt No 700-1-12900 | - |
| -0790-6 | | Control Panel Plessey Type 58 Pt No 700-1-12900 | - |
| -0791-13A | | 2k VA Transformer Rectifier Unit Plessey Pt No 509-1-01740 | 1969 |
| -0791-2 | | 2k VA Transformer Rectifier Unit Plessey Pt No 509-1-01740 | - |
| -0792-12 | | Control Panel Lucas Aerospace Types U11902 & U11904 | Jun 80 |
| -0792-3A6 | | Control Panel Type 21B30-3-B-UK | 1969 |
| -0793-1 | | Control Unit Code No C/42/10A Hawker Siddeley Dynamics | Feb 75 |
| -0794-1 | | Capacitor & Junction Box Code No C/E2/20A | 1969 |
| -0795-13A | | Control Units type B-300-2/B300-3 & Capacitor & Junction Box Type B7002-2 | 1969 |
| -0796-1 | | Voltage Reference Unit Lucas Aerospace Type U3606/1 | Mar 75 |
| -0797-13A | | Panel, Supervisory and Voltage Control Bendix Type 21 B29-6B | Mar 93 |
| -0798-1 | | Control Panel Type 19 (Lucas Aerospace U1603/1) | Sep 75 |
| -0799-1 | | Control Panel Type 25 Lucas Aerospace U2402 | Jul 75 |
| -07100-1 | | Starter Panel Rotax Type U1110 | 1969 |
| -07101-13A6 | | Control Panel Type 24 Lucas Aerospace U2401 | May 75 |
| -07103-136 | -07103-136 | Control & Protection Unit Lucas Type AE 7053 Mk2 Pt No 7053202 AE7053 Mk3 Pt No 7053302 AE7053 Mk4 Pt No 7053402 | Jan 85 |
| -07104-1 | | Voltage Regulator Flight Refuelling Pt No 6310490 | - |
| -07105-1 | | Generator Failure Warning Unit HSA Type 6M4N12105A | Sep 69 |
| -07105-6 | | Generator Failure Warning Unit HSA Type 6M4N121051A | Sep 69 |
| -07106-1 | | Voltage Regulator Type 121 | 1969 |
| -07107-16 | | Voltage Regulator AM Type 129 Lucas Aerospace Type AE7306 Mk 3 | Sep 74 |
| -07109-1 | | Negative Phase Sequence Unit Static Sensing English Electric Type AE5640 | 1969 |
| -07109-6 | | Negative Phase Sequence Unit Static Sensing English Electric Type AE5640 | - |
| -07110-1 | | Control & Protection Unit Rotax Type AD7025 | - |
| -07110-2 | | Control & Protection Unit Rotax Type AE7025 | - |
| -07110-3 | | Control & Protection Unit Rotax Type AE 7025 6610-99-108-4485 | Feb 83 |
| -07110-6 | | Control & Protection Unit Lucas Aerospace Type AE7025 Mk 1 & 1A | Aug 84 |
| -07111-13 | | Auxiliary Control Unit Lucas Aerospace Type AE 7026 | Jan 83 |
| -07111-2 | | Auxiliary Control & Protection Unit Rotax Type AE7026 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -07111-6 | | Auxiliary Control Unit Lucas Aerospace Type AE7026 | May 76 |
| -07112-1 | | Twin Channel Load Control English Electric Type AE7742 ... | 1969 |
| -07112-6 | | Twin Channel Load Control Unit English Electric Type AE7742 | 1970 |
| -07113-1 | | Bus-Bar Diode Unit Plessey Pt No 700-1-15550 | 1970 |
| -07113-6 | | Bus-Bar Diode Unit Plessey Pt No 700-1-15550 | - |
| -07114-13 | | Voltage Regulator | Nov 94 |
| -07114-2 | | Voltage Regulator Plessey Pt No 700-1-15560 | - |
| -07114-6 | | Voltage Regulator Plessey Pt No 700-1-15560 | - |
| -07115-1 | | Transformer Rectifier Unit Rotax Type U3306 | 1969 |
| -07116-13A | | Over Voltage Unit Rotax Type U3611 | Oct 75 |
| -07119-13A6 | -07119-136 | Voltage Regulator Pt No 85210-10 | - |
| -07120-12 | | Protection Unit Rotax Type U3634 | Jun 80 |
| -07120-6 | | Protection Unit Rotax Type U3634 | - |
| -07121-1 | | Motor Overload Protection Units Type V11313 | Feb 82 |
| -07122-16 | | Voltage Regulator Newton Types 22 & 22A | Aug 74 |
| -07123-1 | | Control Unit Lucas Aerospace Type U3702 | Sep 74 |
| -07123-2 | | Control Panel Rotax Type U3702/3 | Jun 72 |
| -07124-1 | | Voltage Regulator Lucas Aerospace Type AE7301 (AM Type 122) | May 75 |
| -07125-1 | | Voltage Regulator Lucas Aerospace Type 7523 Mk 1 & Amplifier Unit Type AE 7518 Mk 2 | Jun 76 |
| -07126-1 | | Regulator Unit Lucas Aerospace Type ZA6405/1 | Jul 75 |
| -07127-1 | | Synchronising Monitoring Unit Lucas Aerospace Type AE7508 Mk 1 & Mk 2 | Apr 75 |
| -07128-13A6 | | Voltage Regulaotr Lucas Aerospace Pt No U13806/1 (Ref No 5UC/1178892) | Mar 73 |
| -07129-13A6 | | Transformer Rectifier St Chamond Granat Type 6153A Ref No 505UC.9388 | - |
| -07120-13 | | Control & Protection Unit ECE Pt No 4332 & 4332Y01 | Sep 81 |
| -07131-1 | | Differential Protection Unit ECE 9604Y01 | Dec 73 |
| -07132-1 | | Regulator Auxilec Pt No 12310-2, 12310-2, 12310-22 & 12310-23 | May 84 |
| -07132-3A | | AC Generator Type 12210 & 12210-1n & Voltage Regulator .. Type 12310 Auxilec (Combined with AP 113B-0133-3A) ... | - |
| -07133-13A6 | | Transformer Rectifier Unit Ferranti Type TR151A, B & C | Apr 65 |
| -07134-16 | | Frequency & Load Controller Lucas Aerospace Type AE7507 Mks 2, 3 & 4 | May 76 |
| -07135-1 | | Frequency Pick-Up Unit Lucas Aerospace Type AE7705 | Jan 73 |
| -07136-1 | | Bus-Bar Protection Unit HSA Type 6R 4N 3623A | Nov 72 |
| -07136-6 | | Bus-Bar Protection Unit HSA Type 6R 4N 3623A | Nov 72 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -07137-1 | | Protection Unit HSA Type U16398 | Jul 72 |
| -07138-1 | | Control & Protection Unit Lucas Aerospace Type AE7061 | Aug 74 |
| -07138-2 | | Control & Protection Unit Lucas Aerospace Type AE7061 | Sep 78 |
| -07138-6 | | Control & Protection Unit Lucas Aerospace Type AE7061 | Nov 74 |
| -07139-1 | | Control Panel Type 39 Lucas Aerospace Type U3401 | Aug 74 |
| -07139-2 | | Control Panel Lucas Aerospace Type U3401/2 | Oct 72 |
| -07140-13A6 | | Protection Unit Lucas Aerospace Type U3641 | Nov 72 |
| -07141-13A6 | | Alternator Control Unit ECE Pt No 4333 Ref No 505UC/9306 .. | Feb 74 |
| -07142-13A6 | | Alternator Control Unit ECE Pt No 4322-1 | Nov 72 |
| -07143-1 | | Voltage Regulator Newton Type EU2 | Aug 75 |
| -07144-1 | | Over Voltage Protection Unit Lucas Aerospace Type U4001 .. | Aug 74 |
| -07144-2 | | Over Voltage Protection Unit Lucas Aerospace Type U4001 .. | - |
| -07145-1236 | | Voltage Regulator Plessey Pt No 700-1-18910-008 G & TI. Gen Orders 4 Modifications Parts Catalogue & Related Info Repair & Reconditioning Instructions | Feb 89 |
| -07146-1 | | Voltage Regulator Type 98B | Dec 73 |
| -07147-1 | | Voltage Regulator Type 118 | Dec 73 |
| -07148-1 | | Protection Unit Lucas Aerospace Type F5402 | Oct 75 |
| -07150-1 | | Voltage Regulator Type 4/60136 | Dec 73 |
| -07152-13A | | Panel Ground Heater BAC Pt No EM2-870802-401 | Aug 77 |
| -07154-13A6 | | Regulator & Cut-Out Unit Newton Type A2' | Oct 75 |
| -07155-1 | | Voltage Regulator Type 46 | Oct 73 |
| -07156-1 | | Voltage Regulator Type 54 | Oct 73 |
| -07157-1 | | Voltage Regulator Type 57 | Oct 73 |
| -07158-1 | | Regulator & Cut-Out Unit Type B | Oct 73 |
| -07159-1 | | Voltage Regulator Type 26 | Oct 73 |
| -07160-1 | | Regulator & Cut-Out Unit Type A | Oct 73 |
| -07161-1 | | Regulator & Cut-Out Unit Type FO402 | Oct 73 |
| -07162-1 | | Voltage Regulator Types 60 & 127 | Oct 73 |
| -07163-1 | | Voltage Regulator Type 69 | Oct 73 |
| -01764-1 | | Voltage Regulator Type 111 | Dec 73 |
| -07166-1 | | Voltage Regulator Type 94 | Jan 93 |
| -07167-1 | | Regulator & Cut-Out Type B2 | Oct 73 |
| -07168-1 | | Voltage Regulator Marconi Type 1555A | Oct 73 |
| -07170-1 | | Voltage Regulator Type 228-LU-14D | Oct 73 |
| -07171-1 | | Voltage Regulator Type 40 | Oct 73 |
| -07172-1 | | Voltage Regulator Newton Type 31 Series | Oct 73 |
| -07173-1 | | Voltage Regulator Newton Type 50/58158E (Main) | Oct 73 |
| -07174-1 | | Voltage Regulator Newton Type 22/56534 MOD 2 (Pilot) | Oct 73 |
| -07175-1 | | Voltage Regulator Bendix Type 1589-1-D, 1589-1-E & 1589-1-F | Jan 76 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -07176-1 | | Voltage Regulator Newton Type 56 | Oct 73 |
| -07178-1 | | Voltage Regulator Type 119 | Oct 73 |
| -07179-1 | | Voltage Regulator Newton Type 37/59491 | Oct 73 |
| -07180-13A6 | | Adapter Unit Plessey Pt No 700-1-12953 | Apr 79 |
| -07181-13A6 | | Unit Protection Plessey Pt No 700-1-12680 & 700-1-15670 ... | Sep 79 |
| -07182-13A | | Undervoltage Unit Plessey Pt No 700-1-12630 | Sep 79 |
| -07183-13A6 | | Voltage Regulator Plessey Pt No 700-1-12970 & 700-1-19030 . | Sep 79 |
| -07185-1 | | Control Panel Type 9A | Dec 73 |
| -07187-1 | | Control Panel Type 34 | Dec 73 |
| -07190-1 | | Control & Protection Unit Lucas Aerospace Type U3711 | Jun 74 |
| -07191-5F | | Voltage Regulators | Aug 74 |
| -07192-1 | | Voltage Control Unit Lucas Aerospace Type U3703/2 | Jun 74 |
| -07192-2 | | Voltage Control Unit Lucas Aerospace Type U3703/2 | Aug 85 |
| | -07193-1 | Transformer Rectifier Unit Type 204C. Ferranti Instrumentation Ltd Pt No 84-58050 | Oct 82 |
| | -07193-3 | Ferranti Transformer Rectifier Unit Type TR204C | Sep 80 |
| -07193-6 | | Transformer Rectifier Unit type 204C. Ferranti Instruments Ltd Pt No 84-58050 | Oct 83 |
| | -07194-1 | Generator Control Unit Type AE 7067 Lucas Aerospace Pt No AE 7067382 | Aug 94 |
| -07194-1B | | Automatic Test Equipment Tornado Aircraft. LF Station. Generator Control Unit W.B.S. OM-2.1-2.1.3 | - |
| | -07194-3A | Lucas Control Unit Generator | Oct 80 |
| | -07194-3B | Lucas Control Unit Generator | Jan 83 |
| | -07195-3 | Plessey Controller Electrical Power System | Sep 82 |
| -07199-13A6 | -07199-13A6 | Voltage Regulator & Over Voltage Protection Unit Lucas Aerospace Pt No U13806/2 | - |
| -07200-1 | | Voltage Regulator Type E11 | Aug 75 |
| -07202-16 | | Negative Phase Sequence Unit Lucas Aerospace Type AE 5642 Mk 1 | Oct 76 |
| -07203-1 | | Transformer-Rectifier Unit Lucas Aerospace Type AE5704 ... | Nov 75 |
| -07204-1 | | Resistor Box Lucas Aerospace Type AE7701 Mk 2 | Dec 75 |
| -07206-13A | | Busbar Diode Unit Plessey Pt No 700-1-12650 | Mar 79 |
| | -07208-1 | Ground Power Control Unit Type FGPC1 Ferranti Instrument Ltd Pt No 35-67600 | May 82 |
| | -07208-3 | Ferranti Ground Power Control Unit FGPC1 | Mar 81 |
| | -07208-6 | Ground Power Control Unit Type FGPC1 Ferranti Inst Ltd Pt No 35-67600 | May 82 |
| -07209-1 | | Open Phase Detector Plessey Pt No 612-1-39965-000 | Mar 81 |
| -07211-136 | | Control & Protection Unit E.C.E. Pt No 141 GA01 Ref No 505 UC/10107 | Feb 80 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -07213-1 | | Racks, Electrical Equipment Plessey Pt Nos 503-1-05286-001 & 503-1-05287-001 | Feb 81 |
| -07214-13A6 | | Power Supply Pt No 3569002-1003 Bendix Corp Pt No 114ES271-3 Boeing Vertol Col | Mar 82 |
| -07215-1 | | Transformer Rectifier Unit Pt No 28 VS200Y-9 Wagner Electric Corp | Aug 82 |
| -07216-13A6 | | Generator Control Unit Pt No AE7083 Mk2 Lucas Pt No 179-60500-5 Boeing Vertol | Jan 83 |
| -07217-13A | | External Power Monitor Pt No 94056-1 Tempo Inst Pt No 179-60550-1 Boeing Vertol Co | Feb 83 |
| -07218-136 | | Protection Unit Lucas Aerospace Type AE5641 | Feb 81 |
| -07220-1 | | Over-Voltage Protection Unit Plessey Pt No 700-1-18911-002 .. | Jan 82 |
| -07221-3 | | Control Unit Generator Pt No CB01701-GA, 1680-99-790-7941 | Dec 87 |
| -07223-1 | | Overcurrent Protection Unit Pt Nos 964C-723-5 & 968C-537-1 | May 90 |
| -07224-13 | | Standby Transformer Rectifier Unit Pt No 28VS50Y-12 | Aug 89 |
| -07226-2 | | Control and Protection Unit Lucas Aerospace Type AE7025 Mk 2 General Orders and Modifications | Jun 92 |
| -07226-16 | | Control and Protection Unit Lucas Aerospace Type AE7025 Mk 2 | Mar 88 |
| -07227-13 | | Electrical & Instruments Aux Control Protection Unit Nimrod Mk 2 and AEW | Mar 88 |
| -07230-1 | | System Control Unit Lucas Aerospace Type DCU 421 | Nov 87 |
| -07231-13 | | Converter 200 Ampere Class B & C Pt No 28VS 2007-4 & 4A | Jun 87 |
| | -07232-136 | Control & Protection Unit G & TI Repair and Reconditioning Instructions | Jul 90 |
| | -07235-1 | Monitor External Power Tempo Instruments Part No 93234-4 General and Technical Information | Jun 89 |
| -07237-13 | | Generator Control Unit Pt Nos 946F985-4 & 946F985-5 General & Technical Information (-1) Repair & Reconditioning Instructions (-3) | Sep 91 |
| -07238-13 | | Bus Power Control Unit P/N 946F986-3, 956F986-4 (Westinghouse) | Nov 90 |
| -07239-13 | | Ion Pump Power Supply Model D-1000A (Tripp Research) ... | Oct 90 |
| -07240-13 | | Power Supply, Type PP-7031/A Pt No 792-6305-001 (Collins) . | Nov 90 |
| -07241-13 | | Frequency Reference Unit Pt No 714441C, 714441B (Sundstand) | Nov 90 |
| -07242-13 | | Frequency and Load Controller P/Ns 71440E, 714440D (Sundstand) | Nov 90 |
| -07243-2 | | Control Panel, Genrator 114ES249-13 General Orders and Modifications | Feb 93 |

UK RESTRICTED

**AP 100Z-0101 AL136
SUB-GROUP 113D**

**CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES**

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -07243-3 | | Control Panel, Generator 114ES5249-13 Illustrated Parts Catalogue | Feb 93 |
| -07243-6 | | Control Panel, Generator 114ES249-13 Repair and Reconditioning Instructions | Feb 93 |
| -07244-1 | | Multiplexer Power Supply - Relay Assembly Group OB76/A .. | Nov 94 |
| -07245-36 | | Electrical Load Control Unit | Nov 94 |
| -0801-13A6 | | Differential Cut-Out ECE Type 1250M | Aug 75 |
| -0802-16 | | Differential Cut-Out Type A Mk 2 | - |
| -0803-1 | | Polarized Cut-Outs Lucas Aerospace F2200 Series | Sep 75 |
| -0805-13A6 | -0805-13A6 | Differential Cut-Out ECE Pt No 230 GC 01 | - |
| -0806-1 | | Protection Unit Lew Modeles Francais pt No 101 & 101-1 | Nov 79 |
| -0807-1 | | Battery Cut-Out Type J | Dec 73 |
| -0808-1 | | Reverse Current Cut-Out Type AN3025-300 | Mar 74 |
| -0809-1 | | Battery Cut-Out Type G | Mar 74 |
| -0901-16 | -0901-16 | Reverse Current Circuit Breakers AEI LEA Series | - |
| -0903-1 | | Circuit Breaker AEI Type LGA-B1/1 | 1967 |
| -0904-1 | | Circuit Breaker Klixon | Feb 81 |
| -0905-13A | | Circuit Breakers Lucas Aerospace Type LGC Form Y6M Series | Dec 72 |
| -0905-6 | | Circuit Breakers Rotax Type LGC Form Y6M Series | Mar 72 |
| -0906-1 | | Circuit Breakers AEI Type LGA Form B4 | Jun 65 |
| -0907-1 | | Circuit Breakers AEI Type LGC3 Form Y3 | Aug 65 |
| -0908-13A | | Circuit Breakers AEI Type LGK250-B1/3 & AM Types D1, D1B, D28 Magnetic Relay Switch AM Type R3 .. | Jun 69 |
| -0910-1 | -0901-1 | Circuit Breakers Plessey Type 700 & Mechanical Products MP930 Series | - |
| -0911-16 | -0911-16 | Reverse Current Cut-Out Relay Hartman Type AN3025-100 General and Technical Information, Repair & Reconditioning Instructions | Nov 91 |
| -0913-1 | | Circuit Breakers AEI Type LGA Form B6A Series | 1968 |
| -0914-1 | | Hermetically Sealed Reverse Circuit Breaker Rotax Type D20902 | 1969 |
| -0915-1 | | Circuit Breakers Rotax Type LGA-B5 & LGA-B5A Series | 1969 |
| -0916-13A | | Overcurrent Protection Unit ECE Pt No 3665-1M | Sep 79 |
| -0917-1 | | Push-Pull Circuit Breaker ECE Single-Pole Pt No 2150F, 21751F, 21753F 21756F, Three-Pole Pt No 21650, 21675, 21536 U15, 21536 U20 | Nov 78 |
| -0919-1 | | Circuit Breakers Rotax Type D5000 Series | - |
| -0920-1 | | Reverse Current Relay ECE Pt No 3654M 300 & 3654-1M ... | Jun 80 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------------|-------------|---|--------|
| 113D-cont. | | | |
| -0921-1 | | Circuit Breaker Type A | Oct 73 |
| -0922-1 | | Circuit Breaker Lucas Aerospace Type D6600 Series | Oct 74 |
| -0923-1 | | Circuit Breaker Lucas Aerospace Type D6500 Series | Oct 74 |
| -0926-1 | | Circuit Breaker Lucas Aerospace D9200 Series | Aug 75 |
| -0927-1 | | Circuit Breaker Overload Type 2A No 6 Lucas Aerospace D9413/1 | May 75 |
| -0928-1 | | Circuit Breakers Lucas Aerospace D11300 Series | Aug 75 |
| | -0929-1 | Circuit Breaker Thermal Overload Lucas Aerospace Type LGC 25-Y7/1 | Aug 86 |
| -0930-1 | | Circuit Breaker Lucas Aerospace Type B | Apr 82 |
| -0931-13 | | Cockpit Circuit Breaker Panel Pt No 75A800062-1007 | Jan 86 |
| -0932-13 | | Forward Main Circuit Breaker Panel Pt No 75A783010-1005 .. | Dec 86 |
| -0933-13 | | Forward Emergency circuit Breaker harrier GR5 | - |
| -0934-13 | | Forward Circuit Breaker/Distribution Panel Pt No 75A781011-1043 & 1045 Assembly Harrier GR Mk5 | Oct 87 |
| -1001-16 | | Protection Units Rotax Type F7504 | - |
| -1002-1 | | Generator Control Unit AEI Type LKF-B6/2 | 1967 |
| -1005-2 | | Generator Switching Units Rotax Type F6800 Series | 1970 |
| -1005-13A6 | -1005-13A6 | Generator Switching Units Lucas Type Aerospace F6800 Series | - |
| -1006-1 | | Generator Control Switchbox Type IY No 2 Mk 1 & Mk 2 Lucas Aerospace Type AE7007 Mk 1 & Mk 2 | May 75 |
| -1006-2 | | Switchbox Generator Control Type IV No 2 Lucas Aerospace Type AE7007 | Oct 74 |
| -1007-16 | | Control Unit Plessey IPn Series | Mar 83 |
| -1008-1 | | Auto Change-Over Unit Type 6M4N-12101A | Jul 75 |
| -1009-1 | | Frequency Sensitive Unit Lucas Aerospace Type F5301/1 | Jul 75 |
| -1010-1 | | Protection Unit Lucas Aerospace Type F7302 | Apr 75 |
| -1011-16 | | Generator Control Switchbox Lucas Aerospace Type AE 450 Mk 5 | Nov 78 |
| -1012-13A | -1012-13A | Collective Pitch Lever Control Box SNIAS Part No Pilot: 341A771201, Co-Pilot: 341A775000 (Ref No 526LE/3559) | - |
| -1013-1 | | Voltage Pick-Up Lucas Aerospace Type AE7723 Mk 1 | Jun 75 |
| -1015-13A | | Caution Light Control Unit Pt No 8022 & 8022-Y1 and A343-1B General & Technical Information. Illustrated Parts Catalogue | Jan 80 |
| -1016-6 | | Electrical Control Panel Assembly Pt No 75A-800048-1019 Repair & Reconditioning Instructions | Nov 90 |
| -1016-13 | | Electrical Control Panel Assembly Pt No 75A800048-1019 ... | Aug 86 |
| -1017-13 | | Ground Power Control Panel Assembly Pt No 75A800543-1005 | May 86 |

UK RESTRICTED

**AP 100Z-0101 AL136
SUB-GROUP 113D**

**CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES**

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -1018-13 | | Trim Position Indicator Control Panel Assembly Pt No 75A800042-1005 | Oct 93 |
| -1021-13 | | Miscellaneous Switch Panel Assembly Pt No 75A800299-1001 | Aug 86 |
| -1023-3 | | Flap Control, Electronic Module (7547000-22F)6615-01-211-3325 | Aug 87 |
| -1023-123 | | Flap Electronic Control Module Part No 7547000-22F 23 & 25 General & Technical Information. General Orders & Modifications Illustrated Parts Catalogue | Jan 93 |
| -1025-13 | | Generator Control Unit Pt No T808D10897 Phantom F-4J Aircraft | Sep 85 |
| -1027-13 | | Generator Control Unit Lucas Aerospace Type U13887 General & Technical Information | Jan 90 |
| -1028-3 | | Control Box Illustrated Parts Catalogue | May 88 |
| -1029-13 | | Integrated ECM Panel Pt No 75A800307-1001 | Nov 89 |
| -1030-136 | | CFM 56-2A Engine Component Maintenance Manual Electric Control 73-21-34 | Aug 89 |
| -1101-1 | | Manually Operated Switches Rotax Type D3500 Series | - |
| -1102-1 | -1102-1 | Push Switches Page Eng Series | - |
| -1103-1 | | Rotary Selector Switches Honeywell Controls Series | - |
| -1105-1 | | Time Control Switch Assembly page Type C1230 | - |
| -1106-1 | | Dimmer Switches Type R | Dec 66 |
| -1107-1 | -1107-1 | Dimmer Switches TBC Thorn Series | Apr 90 |
| -1108-1 | | Single Button Push Switches Dowty 5162Y Series & Wander Button Switch 1240Z | - |
| -1109-1 | | Miniature Toggle Switches Pye Series | - |
| -1110-1 | -1110-1 | Tumble Switches NSF | - |
| -1111-1 | | Frangible Crash Switches Cathodeon Types | 1967 |
| -1113-1 | | Manually Operated Switches Rotax Type D10000 Series | - |
| -1114-1 | | Push Switch NSF Type 8450-B1 | 1967 |
| -1115-1 | | Toggle Switches AEI Type LHA Series | 1969 |
| -1116-1 | -1116-1 | Sealed Single Pole Lever Switches Rotax Type D1300 Series | - |
| -1117-1 | | Sealed Double Pole Lever Switches Rotax Type D13500 Series | 1969 |
| -1118-1 | | Sealed Lever Switch Rotax Type D23502 | 1968 |
| -1119-1 | | Sealed Three-Pole Lever Switches Rotax Type D13600 Series | 1968 |
| -1120-16 | | Solenoid Switches Rotax Type D2200 Series General Technical Information Repair and Reconditioning Instructions | Jan 89 |
| -1121-3A6 | | Fuel Flow Transmitters Stock No R6680-761-2331-BFEK | Jan 66 |
| -1122-1 | | Sealed Four-Pole Lever Switches Rotax Types D16541, D16542 & D16568 | 1969 |
| -1123-1 | | Push Switch Rotax Type D0701 | 1968 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -1124-1 | | Single-Pole Lever Switches Lucas Aerospace Types D16601, D16603 & D16681 | - |
| -1125-13A | | Rotary Switch Lucas Aerospace Type D23201 & D23201/1 | Feb 76 |
| -1126-13A | | Crash Switch AMD-BA Pt No 215C | Jun 75 |
| -1127-1 | | Push Switches HSA types 6-4N21749A/2 & 6-4N2665A/2 | 1968 |
| -1128-1 | | Push Switches Dunlop New Series | 1968 |
| -1129-1 | | Throttle Grip Switches Dowty Types 6400.002.00, 6406.002.00 & 6407.001.00 | Nov 74 |
| -1130-1 | | Undercarriage Selector Switches Dowty Types | Apr 80 |
| -1132-1 | | Switch Rotary Page Type B980 | 1969 |
| -1133-1 | | Switch Light Module Page Type D8040-002 | 1969 |
| -1134-1 | | Switch Box Assembly Pt No Type 6M4N 8793A/1 & 6E4N 155A | Jun 84 |
| -1135-1 | | Dimmer Switch Miles Type FES75 | 1969 |
| -1136-1 | | Undercarriage Emergency Switch Page Type C6170 | 1969 |
| -1137-1 | | Lever Switches Dowty Types 5148Y & 1223Y | Dec 76 |
| -1139-13A | | Switches Trim Western Types | Jul 75 |
| -1140-1 | | Throttle Grip Switches Dowty Types 1231Z, 1344Z & 6410.001.00 | - |
| -1141-1 | | Undercarriage Selector Switch (Lever Operated) Dowty Type 1076Z | 1971 |
| -1142-136 | | Undercarriage Control Switch P.M.L Part No 12-496 | Feb 90 |
| -1143-136 | | Landing Gear Control Units Labinal Pt Nos 12-364-1 & 12-364-1/172, 12-365-1 & 12-365-1/172, 12-366-1 & 12-366-1/172 | Sep 81 |
| -1144-1 | | Switches Fuel Jettison Western Types | Nov 73 |
| -1146-1 | | Landing Selector Switch Ribali Elettrotecnica Ing Pt No R36E-1 | Sep 82 |
| | -1146-3 | Ribal SRL Landing Switch | Oct 85 |
| | -1148-1 | Master Armament Safety Switch Page Eng. Co. Ltd Pt No D336-07-001 | May 81 |
| -1152-13A | | Armament Switch Page Engineering Co Pt No D16050 & D16080 | Sep 79 |
| -1153-13A | | Flap Control Unit AMD-BA Pt Nos 121 S27-460-00-0 & 121 B27-470-00-0 | Apr 76 |
| -1154-1 | | Master Armament Safety Switch Pt Nos D336-03-001, D336-04-001 D336-12-001, D336-13-001, D336-14-001, Gen Tech Info | Jun 89 |
| -1154-2 | | Master Armament Safety Switch Pt Nos D336-03-001 D336-04-0001, D336-12-001, D336-13-001, D336-14-0001 | Jul 90 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -1156-136 | -1156-136 | Master Armament Safety Switch Page Engineering Pt Nos D17540/01, D17540/02 & D18540/02a | Feb 84 |
| | -1157-1 | Duplex Switch Aeritalia Pt No P-945212-403, 405, 407 & 807 . | Nov 94 |
| | -1157-3 | AIT Mechanism Assy | Apr 82 |
| -1158-1 | | Switch, Alternator Synchronizing Dowty Type C7644Y | Mar 80 |
| -1160-12 | -1160-12 | Master Armament Safety Switch (Dowty 5100 Series) | - |
| -1161-13 | | Water Combat Thrust Panel Assembly Pt No 75A800106-1037 . | Dec 85 |
| -1162-13 | | Generator Control Unit Pt No 947F947-10 General and Technical Information | Sep 91 |
| -1163-13 | | Late Arm Panel Assembly Pt No 75A800524-1003 | Jul 93 |
| -1164-13 | | Master Armament Safety Switch Part No 75A807100-1003 ... | Nov 89 |
| -1201-1 | -1201-1 | Microswitches, Honeywell Controls | - |
| -1203-1 | | Flasher Unit Normalair-Garrett Type FOG/A/Z | Oct 80 |
| -1204-1 | | Engine Starting Controller Type 1010 | - |
| -1206-13A6 | | Inertia Switches Graviner Piston Type Mks 1 & 2 | Jul 80 |
| -1207-1 | -1207-1 | Switch Mode Selector Western Helicopters Ltd Pt No WG1382-6100-043, WG1382-6100-045, WG1382-6100-047 | Sep 92 |
| -1208-1 | | Sealed Relay Cutler Hammer Type 6042H125 | 1967 |
| -1209-1 | | Drum Switches Dowty Type 1220Y Series | - |
| -1210-1 | | Limit Switch Dowty Types 1241Z, 1077Z & 1831Y | Oct 80 |
| -1211-1 | | Double Drum Switches Dowty Type 1028Z Series | Apr 80 |
| -1214-13A6 | | Micro-Switch Assembly Messier Pt No C1-22306 & C1-22606 . | - |
| -1215-123A | | Limit Switch Units, AVIAC Pt Nos 4402-11, 4407-11 & 4418-10 | Mar 82 |
| -1216-13A | | Switches Messier-Hispano Pt No A24801-10, A24801-10 (Amdt A) A124801-10, A24801-10 (Amdt A) A2-24801-10 & A24801-10 (Amdt A) | Jan 80 |
| -1217-13 | | Switch Messier-Hispano Pt No C22449-10 & C23193-1 | Aug 82 |
| -1220-1 | | Limit Switches Modeles Francais Pt Nos 23001 & 1866 A127 . | Aug 77 |
| | -1222-1 | Navigation Mode Selector Box Assembly | Oct 85 |
| -1227-1 | -1227-1 | Switch Push Button Page Engineering Co Pt No D12160/10A . | - |
| -1231-1 | | Switch Assembly Pt No 9406041 | Dec 85 |
| -1233-13 | | Dual Flashtube Aircraft Recognition Light P/N 30-1037-1 and Strobe Light Power Supply P/N 60-2650-1 (Grimes MFG Co) | Jul 90 |
| -1234-13 | | Distribution Box, J 3268/A Part No 204-18467-1 Distribution Box J3268A/A, Part No 204-18467-2 | Oct 90 |
| -1301-16 | | Contractors AEI LDA Switches | - |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -1302-16 | | Contractor AEI Type LDK 35 Form Y7 | - |
| -1304-13A | | Relay Unit Page Type C1620 | - |
| -1305-1 | | Relay Overspeed Rotax F6400 Series | - |
| -1305-6 | | Relay Overspeed Rotax Type F6400 Series | - |
| -1306-1 | | Contactor Rotax Type D13101 | - |
| -1307-1 | | Relay Current Indicator Rotax Type F5600 Series | - |
| -1307-6 | | Relay Current Indicator Rotax Type F5600 Series | - |
| -1308-16 | | Starter Unit Rotax Type U3501 | - |
| -1309-1 | -1309-1 | Magnetic Relay Switches Type 'S' 10B & 20B Series & Associated Hendrey Types | - |
| -1310-1 | -1310-1 | Relays Plessey, Type B | - |
| -1311-1 | | Relays Plessey Type S | 1967 |
| -1312-1 | -1312-1 | Relays Plessey Type S (Sealed) | - |
| -1313-1 | | Relays Plessey Type A | - |
| -1314-1 | | Magnetic Switches Lucas Aerospace Types D6311 (Type 5Y No 2) & D6321 | Apr 75 |
| -1315-16 | | Contactor Rotax Type D11801 Series | 1967 |
| -1317-16 | | Starter Units, Rotax Type U2000 Series (28V Operation) | Sep 66 |
| -1317-2 | | Starter Units Rotax Type U2000 Series (28V Operation) | - |
| -1318-1 | | Starter Unit Rotax Type U2801/1 | - |
| -1319-13A6 | -1319-13A6 | Balanced Contactor Lucas Aerospace D10500 Series | - |
| -1320-16 | | Contactor Lucas Aerospace Type LDA 400 Forms B11/1, B12 & B13M | Feb 78 |
| -1321-16 | | Contactor AEI Type LDJ 15 Form Y4 & Y2/1 | - |
| -1322-16 | | Contactor Rotax Type LDG60 Form Y1 | - |
| -1323-16 | | Contactor AEI Types LDA200 Form B9/1 & LDA 200 Form B13 | - |
| -1324-16 | | Contactor AEI Type LDA600 Form B1 & B3 | - |
| -1325-16 | | Contactor AEI Type LDG100 Form Y10/2 | - |
| -1326-1 | | Contactor AEI Type LDK1200 Form Y3 & Y5 | - |
| -1327-1 | | Magnetic Relay Switches Types J, K & T | Nov 65 |
| -1328-1 | | Magnetic Relay Switches Types Q & 9B Series | Jun 80 |
| -1329-16 | | Cartridge Selector Switches Teddington Type FJB Series | 1967 |
| -1330-1 | | Magnetic Relay Switches Hendrey Types D5120 & D4750 | - |
| -1331-16 | | Contactor AEI Type LDK60 Form Y2/1 | - |
| -1332-16 | | Contactor AEI Type LDA100 Form B8 | - |
| -1333-13A6 | -1333-13A6 | Latched Relays Rotax Types D12803/1, D12804 & D12805 | - |
| -1334-16 | | Contactors Lucas Aerospace Types LDJ15 Form Y14, Y15 & Y17 (formerly AEI Types LDJ 15 Form Y14 and Y15) | Jun 90 |
| -1335-16 | | Contactor AEI Type LDA1000 Form B2/3 | - |
| -1336-16 | | Contactor AEI Type LDJ60 Form Y1/1 | - |
| -1337-16 | | Contactor AEI Type LDG15 Form Y11 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -1338-1 | | Contactor Lucas Aerospace Type LDK15 Forms Y2/2 & Y4/1 | May 78 |
| -1339-16 | | Contactor AEI Type LDA150 Form B14 | - |
| -1340-16 | | Contactor AEI Type LDG35 Forms Y9 & Y19M | - |
| -1341-16 | | Contactor AEI Type D1-LDG35 Form Y13C | - |
| -1342-16 | | Contactors Lucas Aerospace Types LDG35-Y15 & Y22 | Jul 84 |
| -1343-16 | | Contactor AEI Type LDG15 Form Y15 | - |
| -1345-16 | | Contactor AEI Type LDA600 Form B4 | Dec 85 |
| -1346-16 | | Contactor AEI Type D1-LDG15 Form Y7/2 | Jun 66 |
| -1347-136 | | Contactor Lucas Aerospace Type LDG15 Form Y14 & Form Y28 | May 84 |
| -1348-16 | | Magnetic Switch Lucas Aerospace Type AE 5361 | May 77 |
| -1349-13A6 | | Contactors Lucas Aerospace Type LDA200 Form B4/3 (Type 14B No 2) & B6/1 | - |
| -1350-16 | | Contactor AEI Type LDA150 Form B2/5 | - |
| -1351-16 | | Contactors Lucas Aerospace Type LDG35 Forms Y3/4, Y4/1 & Y4/2 | Nov 77 |
| -1353-1 | | Relay Rotax Type F8101 | 1967 |
| -1356-16 | | Contactors AEI Types LDG15 Forms Y2/2, Y2M & Y10M | - |
| -1357-16 | | Contactors AEI Types LDK35 Forms Y1, Y3/2 & Y5 | - |
| -1358-13A6 | | Contactor Lucas Aerospace Type LDA150 Form B13/1 | - |
| -1359-16 | | Contactor AEI Type LDA50 Forms A2, A4/3 & A4/4 | - |
| -1360-16 | | Contactor AEI Type LDA150 Form A6/3 | - |
| -1361-16 | | Overspeed Relays Lucas Aerospace Type F1700 Series | Jun 79 |
| -1362-16 | | Contactors Rotax Type D13200 Series | - |
| -1363-16 | | Reversing Contactors Type 7A (Rotax Type D9300 Series) | - |
| -1364-16 | -1364-16 | Contactors Lucas Aerospace Type D6700 Series | - |
| -1365-16 | | Interlock Relay Rotax Type F3122 | - |
| -1366-13A6 | -1366-13A6 | Over-Voltage Relays Lucas Aerospace Type F6700 Series | - |
| -1367-13A | | Contactor Lucas Aerospace Type D15401 | Oct 75 |
| -1368-16 | | Contactor AEI Type LDJ100 Form Y2 | - |
| -1369-16 | | Contactor AEI Type LDA25 Form A1 | - |
| -1370-16 | | Contactor AEI Type LDA100 Form A5 | - |
| -1371-16 | | Contactor AEI Type LDA150-B7/1 | - |
| -1372-1 | | Switch Magnetic Thorn Type 31A | 1968 |
| -1373-16 | | Contactor AEI Type LDA200 Form B14 | - |
| -1374-13A6 | | Reversing Contactors Rotax Type D5105, D5107 & Variants | Oct 75 |
| -1377-1 | | Polarized Relays AEI Type LA Series | 1967 |
| -1378-1 | | Contactor Lucas Aerospace Type LDC200 Forms B4 & B5 | Jan 75 |
| -1378-6 | | Contactor Lucas Aerospace Type LDC200 Forms B4 & B5 | Jan 75 |
| -1379-13A6 | | Contactors Rotax Types D19501, D8723 & D8724 | - |
| -1379-2 | | Contactors Rotax Types D19501, D8723 & D8724 | Jun 72 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -1384-1 | | Torque Switch Smiths Type EAP Series | - |
| -1384-6 | | Torque Switches Smiths Type EAP Series | - |
| -1385-3A6 | | Magnetic Sequencing Switch Pt No 4150 | - |
| -1387-16 | | CAV BBNFA, BBNG & 267 Solenoid Switches | - |
| -1388-16 | | Relay Rotax Type F3110 | - |
| -1389-16 | | Auxiliary Relay Rotax Type F3112 | - |
| -1390-16 | | Voltage Pick-Up Relay Rotax Type F3103 & F3133 | - |
| -1391-16 | | Voltage Pick-Up Relay Rotax Type F3114 | 1967 |
| -1392-16 | | Voltage Pick-Up Relay Rotax Type F3117 | 1967 |
| -1394-1 | | Relays Diamond BR, BS, BRA, BSA Series General & Technical Information | Oct 91 |
| -1395-1 | -1395-1 | Relays Plessey P Series (Sealed) | - |
| -1396-13A | | Contactors AEI Type LDN15 Form YT4 | - |
| -1397-16 | | Magnetic Relay Switch Thorn Type T100B | 1967 |
| -1398-1 | | Switch Starting Lucas Aerospace Type U4201 | Aug 75 |
| -1399-1 | | Contactors AEI Type LDA50 Form BT1 | 1968 |
| -13100-13A | | Contactors Lucas Aerospace Type LDJ60 Form YT1 | - |
| -13101-13A | | Contactors Lucas Aerospace Type LDG35 Form YT4 | - |
| -13102-123 | | Starter Contactors with Undercurrent Relay Lucas Aerospace Types D23402 & D23042/1 | Aug 83 |
| -13102-6 | | Starter Contactors with Undercurrent Relay Lucas Aerospace Types D23402 & D23402/1 | May 73 |
| -13103-13 | | Hermetically Sealed Contactors Rotax Type D20802 | May 84 |
| -13104-1 | | Relays Hellermann Deutsch Minature Series | 1969 |
| -13105-1 | | Toggle Switches Honeywell ET Series | Aug 75 |
| -13106-1 | | Relays Sangamo Weston Type S54 Series | 1969 |
| -13107-1 | | Relays, Clare-Elliott Types F & XA | Nov 80 |
| -13108-13 | | Contactors Rotax Type LDK60-Y1/1 | May 84 |
| -13108-6 | | Contactors Rotax Type LDK60-Y1/1 | - |
| -13109-16 | | Contactors Plessey Type ECE 2411AU (501-4-07035) | Aug 77 |
| -13112-1 | | Switch Starting Lucas Aerospace Type U1108/1 & U1108/2 | Dec 78 |
| -13112-2 | | Switch Starting Lucas Aerospace Type U1108/1 | Sep 78 |
| -13113-1 | | Switch Starting Lucas Aerospace U2000 Series (112V Operation) | Aug 75 |
| -13114-1 | | Relays Plessey Type C | 1969 |
| -13115-1 | | Relays Plessey Type BH1/1DB/1DM/28/35/200AC & Type BH1/1DB/1DM/28/35/200 AC (R) | Mar 83 |
| -13116-1 | | Relay Box Tiltman Langley Type 1489 | 1969 |
| -13117-1 | | Switch Magnetic Relay Rotax Types D0209, D0213/1 & D0218 | 1969 |
| -13118-1 | | Contactors Rotax Types D4801/1 & D4802/1 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -13119-1 | | Magnetic Switches Rotax Types D6103/2, D6104/2, D6106/1 & D1608 | 1970 |
| -13120-16 | | Magnetic Switches Rotax Type D7001/2 & D7007 | - |
| -13121-16 | | Magnetic Switch Rotax Type D9011/3 | - |
| -13122-1 | | Control Ground Test NATO Code No 1560-99-107-8533 | - |
| -13123-1 | | Control Power Supply NATO Code No 1560-99-107-8539 | - |
| -13125-1 | | Interconnecting Box NATO Code No 1560-99-633-3953 | Feb 75 |
| -13126-1 | | Relays Plessey Types B Pt Nos 507-1-101081 & 507-1-01262 .. | - |
| -13127-1 | | Switch Starting Lucas Aerospace Type U2304 | Aug 75 |
| -13128-1 | | Switch Starting Lucas Aerospace Type U2602 | Aug 75 |
| -13131-13A | | Starter Panel Lucas Aerospace (formerly Rotax) Type ZA22401 | - |
| -13132-1 | | Contacteur English Electric Type AE5373 Mk 1 | 1969 |
| -13132-6 | | Contacteur English Electric Type AE5373 Mk 1 | - |
| -13133-1 | -13133-1 | Contacteur ECE 2535 Series | - |
| -13134-1 | | Contacteur Lucas Aerospace Type AE5354 Mk 3 | Jul 77 |
| -13135-13A | | Contacteur Lucas Aerospace Type AE5368 | Mar 79 |
| -13135-2 | | Contacteur Lucas Aerospace Type AE5368 | Nov 78 |
| -13136-1 | | Miscellaneous Relays, Sea King Aircraft | Apr 93 |
| -13137-1 | | Contacteur Rotax Type LDG35-Y5/1 | 1969 |
| -13138-1 | | Speed Sensitive Switch HSA Type 6M4N18311S | Sep 69 |
| -13138-6 | | Speed Sensitive Switch HSA Type 6M4N18311A | - |
| -13139-1 | | Voltage Switch, DC, HSA type 6M4N18343A | Sep 69 |
| -13139-6 | | Voltage Switch, DC, HSA Type 6M4N18343A | - |
| -13141-1 | | Magnetic Relay Switches Plessey/Ericsson Types 1A & 2 | - |
| -13145-1 | | Control Infrared Shutter NATO Code No 1560-99-633-3954 .. | Mar 75 |
| -13146-1 | | Contacteur Rotax Type D8604/4 | - |
| -13146-6 | | Contacteur Rotax Type D8604/4 | - |
| -13147-1 | | Contacteurs Rotax Type LDA400 Form B6/2 & B3/5 | - |
| -13148-13A6 | | Hood Control Relay Rotax Types F1306 & F1307 | Jul 75 |
| -013150-13A6 | -13150-13A6 | Contact ECE2540 Series ECE2540M | - |
| -13151-13A | -13151-13A | Relays ECE Pt No 1420 Series, 1400 Series, 1406 Series 1407 Series, 1607A, 1476Y2 2-1375, 1415Y1, 155A3-5 | - |
| -13153-13A6 | | Contacteur ECE25500 Series | - |
| -13154-13A | | Phase Sequence Detector Electronique Aerospatiale Type 31-2 .. | Oct 75 |
| -13155-136 | -13155-13A6 | Contacteur Type 2525 Series | - |
| -13157-1 | -13157-1 | Relay ECE Type 5 1455Y2 Ref No 505CW?2549917 | - |
| -13158-1 | -13158-1 | Relay ECE Type 14457 Ref No 505CW/13447 | - |
| -13159-1 | -13159-1 | Relay ECE Type 1403Y1 Ref No 505CW/13465 | - |
| -13160-136 | -13160-136 | Phase Sequence Relay St Chamond Granat Type 60 Ref No 505CW/13312 | - |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -13161-13 | | Contacto ECE Pt No 2526AM Ref No 505C/W/2642101 General & Technical Information Illustrated Parts Catalogue | Sep 71 |
| -13162-13A6 | | Contacto ECE Pt No 25810BM Ref No 505CW/2280623 | Feb 73 |
| -13162-13 | | Contacto Part No 25810BM | - |
| -13164-13A6 | -13164-13A6 | Ground Power Protection Control Unit ECE Pt No 170GA01Y | - |
| -13165-1 | | Contacto ECE2405AM | 1973 |
| -13166-13A6 | | Contacto Modele Francais Type 7055 | Nov 78 |
| -13167-1 | | Contacto Modeles Francais Pt No 125-200 (Ref No 505CW/13495) | Aug 73 |
| -13168-1 | | Relay Plessey Type AHP/2CO/28/5 & BHP/2CO/28/10 | Nov 74 |
| -13169-1 | | Current Limiting Contacto Rotax Type AE5375 Mk 1 | May 72 |
| -13169-6 | | Current Limiting Contacto Rotax Type AE5375 Mk 1 | Nov 72 |
| -13170-1 | | Contacto ECE2515AM | Jul 73 |
| -13171-13A | | Relay Assemblies Associated Automation Ltd Pt Nos 607/18060, 607/19751, 607/14187, 607/19752, 607/19753 | Jun 77 |
| -13172-1 | | Magnetic Relays Deutsch Pt No LLR26AAK18 & VS26WDK18 | Jan 78 |
| -13173-1 | | Current Relay Modeles Francais Type 888CIR | Jun 73 |
| -13174-13A6 | | Contacto Tachometric Jaeger Pt No 66101-000-1 & 66101-000-2 | Sep 81 |
| -13175-13A6 | | Contacto Lucas Aerospace Type LDA200 Form B18C | Apr 76 |
| -13176-1 | | Contacto Lucas Aerospace Type D45101 | Oct 76 |
| -13177-1 | | Contacto Lucas Aerospace Type LDA150 Form B20 | Jul 76 |
| -13179-1 | | Contacto GEC Pt No 507-1-01316 or Leach Pt No 7264-9158 | Aug 91 |
| -13180-1 | | Contacto Pt No Plessey 507-1-01222 or Leach 7264-283 | Aug 79 |
| -13181-1 | | Contacto Pt No Plessey 507-1-01224 or Leach 9123-8058 | Aug 79 |
| -13185-1 | | Switch Magnetic Type 8A No 4 Lucas Aerospace Type D8901/4 | Aug 74 |
| -13188-13A | | Contacto Lucas Aerospace Type LDG100Y21C | Jul 79 |
| -13190-13A | | Switches Magnetic Lucas Aerospace Types F3104, F3109, F3111, F3115 & F3116 | Jul 75 |
| -13191-1 | | Relay Plessey Pt Nos 507-1-00140-002, 507-1-00330-002, 507-1-00517-002 & 507-1-00920 | Oct 79 |
| | -13192-1 | DC Cont actor Lucas Aerospace ltd Pt No D26704 | - |
| | -13192-3 | Lucas Cont actor 125 AMP Single Phase | - |
| -13192-6 | | DC Contacto Lucas Aerospace Ltd Pt No D26704 | - |
| -13197-126 | | Current Limiting Contactors Lucas Aerospace Types AE 5376 Mk 1 and Mk 2 | Feb 80 |
| -13199-1 | -13199-1 | Contacto ECE Pt No 2505 AM | - |
| -13201-13A6 | -13201-13A6 | Voltage Sensing Unit Pt No C14450-01 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| | -13201-136 | Voltage Sensing Unit Gen & Tech Info Parts Cat & Rec Info Overhaul Instructions | May 88 |
| -13202-136 | -13202-136 | Contactors Lucas Type D21605/1 | Jul 80 |
| | -13205-1 | Relay | Nov 85 |
| | -13210-1 | AC Contactor Assembly British Aerospace | Jun 94 |
| | -13210-3 | British Aerospace Contactor Assy AC | Jan 81 |
| -13214-16 | | Magnetic Switch Lucas Aerospace Type AE5359 (AM Type 6YN04) | Aug 78 |
| -13214-2 | | Magnetic Switch Lucas Aerospace Type AE5359 (AM Type 6YN04) | Feb 79 |
| -13215-1 | | Contactors Hartman Electrical Manufacturing Co Pt No DH-7ATK | Jan 80 |
| -13216-1 | | Contactors Hartman Electrical Manufacturing Co Pt No DH-7GRK | Jan 80 |
| -13220-1 | | Relay pt No MS24183-D1 | Nov 81 |
| -13221-1 | | Contactors Pt No DH-7TA Hartman Electric | Nov 81 |
| -13222-1 | | Contactors Pt No A-1077B Hartman Electric | Feb 83 |
| -13223-13A6 | | Contactors Pt No B-233K Hartman Electrical Pt No A02ES205-2 Boeing Vertol Co | Jun 83 |
| -13224-1 | | Contactors Lucas Aerospace Type LDJ35 Form Y1 | Aug 83 |
| -13225-1 | | Relay Over-Voltage Pt No V110-J-029-A-C Leach Corp | Feb 83 |
| -13227-1 | | Voltage Indicator Unit Lucas Aerospace Type ZA 13702 | Jan 85 |
| -13228-136 | | Contactors Three-Phase Plessey Pt No 506-1-08440-000 | Feb 85 |
| -13229-1 | | Magnetic Switch Thorn Type 31A | Feb 85 |
| -13230-123 | | Forward Relay Panel Assembly Pt No 75A871502-1019 | - |
| -13231-1 | | Switches Magnetic Lucas Aerospace D9100 Series | May 85 |
| -13235-1 | | Lucas Aerospace Contractor Type SA03206 | Jun 93 |
| -13236-1 | | Lucas Aerospace Contractor Type SA02204 | Jun 93 |
| -1402-1 | | Switch Time Delay Belling & Lee Type L413-1C-3-24 | - |
| -1403-1 | | Warning Horn Time Delay HSA Type 1/V10591 | - |
| -1404-126 | | Time Delay Switches Normalair Garrett Types FHM & 4202 Series | Jul 77 |
| -1406-126 | | Time Delay Units Lucas Aerospace Types ZA11101/2, ZA11102/2, ZA11103/2 & ZA11104/2 | Aug 84 |
| -1407-1 | -1407-1 | Engine Start Control Unit Page Engineering Ltd Pt No C17300 | - |
| -1408-1 | | Time Delay Units Types C5250 & C7130 | Oct 90 |
| -1409-13A6 | | Thermal Switch Rotax Type D6200 Series | - |
| -1410-16 | | Time Delay Unit Page Type C9600 | - |
| -1412-16 | | Time Delay Switches Rotax Type D8100 Series | - |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -1413-13 | | Time Delay Switches Normalair Garrett Type FTE Series General & Technical Info Parts Catalogue & Related Info | Dec 88 |
| -1414-1 | | Time Delay Switch Teddington Pt No 4201 003 000 & 4201 006 000 | Jul 73 |
| -1415-1 | | Sequence Timer Rotax Type D10705/1 & D10706/1 | 1967 |
| -1416-1 | | Time Delay Unit Rotax Type ZA11109 | 1968 |
| -1416-6 | | Time Delay Unit Rotax Type ZA11109 | 1970 |
| -1417-1 | | Relays, Time Delay Intertechnique (Formerly Coventry Controls) GV Series | Jun 79 |
| -1419-1B | | ATE Tornado Aircraft LF Station Secondary Power System Control Unit WBS OM-2.1.2.1.6 | Dec 86 |
| | -1419-3 | K.H.D. Control Unit Secondary Power System | Mar 81 |
| -1419-6 | | Secondary Power Control Unit VDO-L Pt No 2878906 | Mar 83 |
| | -1419-10 | Secondary Power System Control Unit VDO-L Pt No 2878906 | Dec 82 |
| -1420-1 | | Engine Starting Controller Darvall Type 1078 | 1969 |
| -1420-6 | | Engine Starting Controller Darvall Type 1078 | - |
| -1422-1 | | Time Delay Relay Leach Type D001-A40-010S & D001-F22-060S | 1969 |
| -1423-13A6 | | Time Delay Switches Rotax Type D8400 Series | Oct 75 |
| -1425-1 | | Time Delay Units Page Types D5430/01 & D7455/C.3 | Feb 84 |
| -1426-13A | | Flasher Unit SGE Pt No 13-041 | - |
| -1428-136 | | Temperature Regulator Electronique Aerospatiale Part No 206-1 | Nov 92 |
| -1429-1 | | Time Delay Unit Page Type C3570 | Feb 72 |
| -1430-1 | | Armed Time Indicator Mk 1 | Mar 72 |
| -1431-1 | | Relay Panel Dowty 1251Z Mk 3 | Jul 74 |
| -1432-1 | | Low Temperature Switch Assembly Pt No E470900/1 | May 79 |
| -1433-1 | | Time Delay Relays Deutsch Pt No TD2F, TD03F, TE1F & TE10F | Jan 78 |
| -1434-13A | | Control Box Microturbo Pt No 007-32C and 007-32D | Aug 88 |
| -1435-13A | | Switch Time Delay Starting Turbomeca Pt No 077 98781.00 505CW/13477 | Sep 72 |
| -1437-13A6 | | Sequencing Unit Lucas Aerospace Type U16303 | Dec 72 |
| -1438-1 | | Time Delay Switch ECE Pt No 2095-6 | 1973 |
| -1439-1 | | Timer Hamilton Standard Type HS726-576 | Jul 74 |
| -1440-1236 | | Control Box Microturbo Pt No 0473200 | Jan 83 |
| -1441-1 | | Flasher Unit type BR24G1 | Mar 74 |
| -1443-1 | | Timing Relay Deutsch Pt No TD3 | Aug 82 |
| -1445-1 | | Time Delay Unit Lucas Aerospace Type D15202/1 | Apr 76 |
| | -1446-1 | Fuel Temperatur Switching Unit | May 88 |
| -1447-1 | | Time Delay Unit R101-CKE-3001-FA | Jun 74 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -1450-13A | | Junction Box AMD - BA Pt No 121B-63, 430.000 & 121S-63.430.000 | May 76 |
| -1451-1 | | Time Delay Units Diamond H Series | May 75 |
| -1452-13A6 | | Time Delay Unit British Aerospace GES00889 | Aug 78 |
| -1458-13A | | 30-Second Timer Pt No 6E4N 2229A | Aug 84 |
| -1462-1 | | Thermal Switch Intertechnique Pt No 763-024 | Apr 86 |
| -1502-16 | | Ignition Switch Plessey IPN | - |
| -1503-13A6 | -1503-13A6 | Pressure Switch Jaeger Pt No 1914-04 | - |
| -1504-1367 | -1504-13A6 | Low Oil Pressure Switch Pt No 0076465070 & 0076635040 ... | Jan 88 |
| -1505-13A6 | -1505-13A6 | Pressure Switch Fuel Flow Limit Pt No 0076475010 | - |
| -1506-13A6 | -1506-13A6 | Differential Pressure Switch Jaeger Pt No 1-1023-05 | - |
| -1507-13A6 | -1507-13A6 | Starting Pressure Switch Pt No 0076485030 | - |
| -1508-1 | | Pressure Switch Type 8G 1099 | Apr 79 |
| -1509-1 | | Pressure Switch Ref 536 AM/1288 Turbomeca Pt No 0076375030 | May 75 |
| -1510-1 | | Switch Pressure Pt Nos 7G-29, 7G-30 & 7G-63-1 | Mar 78 |
| | -1511-3 | Plessey Sensor Pressure | Sep 80 |
| | -1512-1 | Low Pressure Dump Switch Elektro Metall Pt No 12178 | Jul 81 |
| -1513-1 | | Pressure Switches Turbomeca Pt Nos 076465000, 0076475000, 0076485050, 0076485070 & 0076635010 | Jan 89 |
| | -1514-1 | Pressure Switch Fimac S.p.A Pt No 20004 02 | Feb 82 |
| | -1514-3 | F.I.M.A.C. Pressure Switch | Mar 80 |
| | -1514-6 | Pressure Switch Fimac S.p.A Pt No 2004 02 | Feb 82 |
| -1515-36 | | Exhaust Gas Temperature Reset Pressure Switch Pt Nos CG 12483 & CG 12608 Phantom F-4J Aircraft | Nov 85 |
| -1516-36 | | After Burner Pressure Ignition Switch Phantom F-4J Aircraft .. | Sep 85 |
| -1517-36 | | Filter By-Pass Pressure Indicator Switch Phantom F-4J Aircraft | Sep 85 |
| -1601-13 | | Control Handles, Dunlop Type for Buccaneer Aircraft | Jun 84 |
| -1602-13 | | Control Handles Dunlop Part No AC 62968 & AC63730 Wasp Aircraft | Jan 89 |
| -1604-13A | | Control Handles Dunlop Type Harrier Aircraft | - |
| -1604-2 | | Control Handles Dunlop Harrier Aircraft | Jan 74 |
| -1605-13 | | Control Handles Wessex Aircraft Dunlop Types AC60044, AC60054, AC60978, AC60980, AC61296, AC61298, AC61302, AC61588, AC61812, AC61814, AC61822, AC62330, AC62924, AC62926, AC63470 & AC63472 | Jun 85 |
| -1605-2 | | Control Handles Dunlop Types for Wessex Aircraft | - |
| -1606-13 | -1606-13 | Stick Assemblies Cyclic & Collective Westland Pt Nos WG 1345-0110-0111 WG 1345-0126/0127 Series | - |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -1607-1 | | Control Handles Dunlop Type Lightning Aircraft | - |
| -1609-13 | | Control Handles Dunlop Pt Nos AC64614, 64616 & 64618 ... | Jul 86 |
| -1610-1 | -1610-1 | Control Handles Whirlwind & Scout Aircraft Dunlop Types AC62348, AC61860, AC14224 & AC63498 | - |
| -1611-1 | | Control Handles Dunlop Types AC12592, AC61320 & AC65200 Vulcan Aircraft | - |
| -1611-2 | | Control Handles Vulcan Aircraft Dunlop Types AC61320 & AC12592 | Sep 72 |
| -1612-13 | | Control Handles & Parking Lever Assembly Dunlop Type Canberra Aircraft | Jan 87 |
| -1613-1 | | Control Handles Gnat Aircraft Dunlop Type AC62964 & AC62966 | 1968 |
| -1615-13A | | Control Column Handle Pt No D415-01-001 | Nov 79 |
| -1617-1 | | Hand Grip Column Jet Provost Aircraft BAC Type K84-45-5589 | 1969 |
| -1618-13 | | Handles Collective Pitch Pt Nos 330A77-4006-0301 & 330A77-4006-0401 General & Technical Information Parts Catalogue Relevant Information | Jul 91 |
| -1618-13A | | Collective Pitch Lever Control Box Aerospatiale Pt No 5UD330-77-30500-300 | - |
| -1619-13 | | Handle Cyclic Pitch Pt No 330A77-4004-04 & 330A77-4004-05 General & Technical Information Parts Catalogue & Relevant Information | Jul 91 |
| -1621-1 | | Control Handle Samm Pt No PP-210-52 (Jaguar Aircraft) | Jan 74 |
| -1622-13A | -1622-13A | Control Handles Dunlop Types AC64862 Ref No 27J/1503367 & AC64864 Ref No 27J/1503368 | - |
| -1623-13A | | Jaquar Aircraft AMD-BA Throttle Boxes Pt No 121 B57-900-00-0M6, Pt No 121 S57-900-00-0M6, Pt No 121 B57-900-00-0M4, Pt No 121 S57-900-00-0M4 & Pt No 121 B57-900-00-0M2 | Jun 83 |
| -1624-13 | | Control Column Handle Part No D380-02-001 | - |
| | -1625-1 | Control Handle Dunlop Co Ltd Pt No AC 66696 | Mar 82 |
| | -1625-3 | Dunlop Handle Assembly Control | Nov 93 |
| -1626-13A | | Control Handle (Jaguar A/C) SAMM Pt No PP212-10, PP212-1 PP212-11, General & Technical Information, Illustrated Parts Catalogue | Jan 85 |
| -1627-13A | | Grip Assembly Thrust Control Pt No A218-966739-00 Guardian Electric Co Pt No 414ES272-1 Boeing Vertol Co | Oct 82 |
| -1628-13A | | Cyclic Stick Pt No 414C1106 Boeing Vertol Co | Jul 81 |
| -1629-13 | | Control Column Handle Pt No 6438-005-00 & 6438-008-00 ... | Nov 86 |
| -1630-13 | | Control Column Grip Assembly Pt No 9020012000-3 | Sep 86 |

AP 100Z-0101 AL136
SUB-GROUP 113D

UK RESTRICTED

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -1631-123 | | Grip Assembly Throttle Lever Pt No 730-6412 Harrier GR 5 .. | Sep 93 |
| | -1632-1 | Control Column Dowty Electrics Pt No 6460-002-00 | Aug 91 |
| | -1632-3 | Stick Top Hotas Pilots - Dowty Electrics Ltd | Sep 92 |
| -1700-1 | -1700-1 | Cables General Use Aircraft & Ground Equipment | Sep 93 |
| -1700-1 | -1700-1 | RF Cables Types UR URM & RG | - |
| -1703-13 | -1703-13 | Low Tension Cable Assembly Palmer Pt No 814300007, 814300027 and 814300048 | Apr 84 |
| -1704-1 | | Cable Assembly G75 Thermostat Pt No C472500 | May 79 |
| | -1800-1 | Cannon Connectors Type PV | Sep 86 |
| -1800-3 | | Plugs & Sockets Pt No to Alpha-Numeric Index | Jan 84 |
| -1802-1 | | Flight Socket AEI Type LR2A Form 1/1 & Flight Plug AE1 Type LR2B Form 1/1 | - |
| -1803-1 | -1803-1 | Cannon Connectors Type D Sub-Miniature | - |
| -1804-1 | -1804-1 | Cannon Connectors Type DPA | - |
| -1805-1 | -1805-1 | Cannon Connectors Type DPD | - |
| -1806-1 | -1806-1 | Cannon Connectors Type DPX1 & DPX2 | - |
| -1808-1 | -1808-1 | Cannon Connectors Type PV | - |
| -1809-1 | -1809-1 | Cannon Connectors Types MC, KO, KH, KM & KM Mk 2 | - |
| -1810-1 | -1810-1 | Cannon Connectors Type MS | - |
| -1811-1 | | Connectors Plessey UK Mk 6 | 1967 |
| -1812-1 | | Connectors Plessey UK Mk 8 & 12 | - |
| -1813-1 | | Connectors Plessey UK Mk 9 | 1967 |
| -1814-1 | -1814-1 | Cannon Connectors Types KPT, KSP & KPTM | - |
| -1815-1 | | Connectors Amphenol MS Series | 1968 |
| -1816-1 | -1816-1 | Connectors Amphenol 26 Series | - |
| -1817-1 | -1817-1 | Connectors Amphenol 48 Series | - |
| -1818-1 | -1818-1 | Connectors Amphenol 67 Series | - |
| -1820-1 | -1820-1 | Connectors Amphenol 165 Series (Miniature MS Type) | - |
| -1821-1 | -1821-1 | Connectors Amphenol Co-Axial Types | - |
| -1822-1 | -1822-1 | Hellermann Deutsch DM Series Connectors | - |
| -1823-1 | -1823-1 | Plessey UK-AN Connectors | - |
| -1824-1 | -1824-1 | Connectors Pattern 104 Plessey UK Mk 7 & AB Electronics Type SB104 | - |
| -1825-1 | -1825-1 | Plessey Standard Breeze Connectors | - |
| -1826-1 | | Unitor Connectors Belling-Lee Types | 1968 |
| -1827-1 | | Connectors McMurdo M range (Micronelectors) | 1968 |
| -1828-1 | -1828-1 | Connectors Ether Types MRE, SMRE, NMRE, BKM, KM, KMM and M Series | - |
| -1829-1 | -1829-1 | Connectors Hellermann Deutsch Types HAN 2 & HAN 3 | - |
| -1830-1 | | Co-Axial Plugs & Sockets Magnetic Devices Types | 1968 |
| -1832-1 | | Connectors MB Metals | 1968 |

SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113D-cont | | | |
| -1833-1 | -1833-1 | Connectors Carr Fasteners Cinch Sub-Miniature Range | - |
| -1834-1 | -1834-1 | Connectors McGeoch MG Series | - |
| -1835-1 | -1835-1 | Connectors Transradio VMP and SM Series | - |
| -1836-1 | -1836-1 | Connectors Hellerman Deutsch 460 Series | - |
| -1837-1 | -1837-1 | Connectors Hellermann Deutsch HBS Series | - |
| -1838-1 | -1838-1 | Connectors Hellermann Deutsch LPT, SLPT & NLPT Series | - |
| -1839-1 | | BICC - Burndy Bantam Connector | 1969 |
| -1840-1 | | Thorn PT & CPT Connectors | 1968 |
| -1841-1 | -1841-1 | Connectors Hellermann Deutsch DBA30 Series | - |
| -1842-1 | -1842-1 | Connectors Hellermann Deutsch DD Miniature Series | - |
| -1843-1 | -1843-1 | Connectors Hellermann Deutsch DC Series | - |
| -1844-1 | -1844-1 | Connectors Hellermann Deutsch Type DS Series | Apr 92 |
| -1845-1 | | Connectors Bambi Type 600 Series | - |
| -1846-1 | | Rack Electrical Equipment NATO Code No 1560-99-107-8535 | - |
| -1846-2 | | Rack Electrical Equipment 1560-99-107-8535 | - |
| -1847-1 | | Connectors Souriau 8.51 | Feb 78 |
| -1849-13A | | Connectors Deutsch Type 5 | May 76 |
| -1850-1 | -1850-1 | Connectors Hellermann Deutsch DTK Series | Nov 92 |
| -1851-1 | -1851-1 | Connectors Thorn MS Series | - |
| -1852-1 | -1852-1 | Connectors Amphenol 57 Series | - |
| -1853-1 | -1853-1 | Connectors Amphenol 126 Series | - |
| -1854-1 | | Connectors Amphenol 133/143 Series | Dec 73 |
| -1855-1 | -1855-1 | Connectors Pattern 602 | - |
| -1857-1 | | Ground Supply Receptacles Cannon Types GC-3LV-14, GCB-3LV-14 & GAC-6-14 | Jun 74 |
| -1860-1 | | Connectors, Hellermann Deutsch RSM Series | May 76 |
| -1864-1 | | Connectors, Hellermann Deutsch AA Series | Mar 80 |
| -1870-1 | | Connectors, Cannon Type DPJ Series | Jun 80 |
| -1872-1 | | Connectors AMP RM Series | Apr 81 |
| -1873-1 | | Connectors Thorn JT Series | Mar 85 |
| -1874-1 | | Connectors UR Series (Hellerman - Deutsch) | Feb 81 |
| -1875-1 | | Connectors Hughes C21 Series | May 84 |
| -1876-1 | | Connectors Hellermann Deutsch DBAS Series | Dec 84 |
| -1877-1 | | Connectors RF Greenpar | Mar 86 |
| -1878-1 | | Connectors 38999 Series 1 Pattern 616 | Mar 86 |
| -1879-1 | | Connectors Cannon Micro D Series | Mar 87 |
| -1880-1 | | Connectors Mil C 265000 Series | Feb 87 |
| -0901-1 | | Suppressor Unit Rotax Type ZA20101 | - |
| -1902-1 | | Suppressors Ministry Type | - |
| -1903-1 | -1903-1 | Terminal Blocks UECL/Ward Brooke | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113D

CONTROL AND DISTRIBUTION EQUIPMENT
FOR POWER SUPPLIES

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113D-cont | | | |
| -1905-1 | -1905-1 | Suppressor Unit Ferranti Type A | - |
| -1906-1 | -1906-1 | Box Fuse NATO Code No 5920-99-107-8541 | - |
| -1907-1 | -1907-1 | Box Fuse NATO Code No 5920-99-107-8518 | Dec 86 |
| -1909-1 | | Interconnecting Box NATO Code No 1560-99-624-8246 | Sep 73 |
| -1910-1 | -1910-1 | Modules & Terminal Studs Air-LB 1100 Series | - |
| -1911-13A | | Junction Box BAC Pt No EM2 870135-403 General and Technical Information, Illustrated Parts Catalogue | Aug 77 |
| -1913-13A | | ERU Junction Unit Pt No BAC EM2-870134-405 | Aug 77 |
| -1914-1 | -1914-1 | Fuses | Dec 86 |
| -1916-1 | | Standard SBAC Wiring System | Aug 80 |
| -1918-16 | | System 4 Fuse Switchboard (GEC) Air and Reconditioning Instructions | - |
| -1919-136 | | CFM 56-2A Engine Component Maintenance Manual Control Parameter Wiring Harness 73-21-62 | Aug 89 |
| -1920-136 | | CFM 56-2A Engine Component Maintenance Manual Alternator Electrical Load Assembly 73-21-64 | Aug 89 |
| -2001-1 | -2001-1 | Heat Shrinkable Sleeving Moulded Parts and Accessories | Oct 90 |
| -2001-5F | | Gas Purged Mini-Ray Heat Source Gun (Ray Chem) (4a 9010044) Maintenance Schedules | Jul 93 |
| -2002-1 | | Cable Termination ERMA Types | 1968 |
| -2003-1 | | Conduit Systems Icore International (Superflexit) | Nov 84 |
| -2005-1 | | Bungs Sealing Glands & Grommets | Oct 73 |
| -2006-1 | -2006-1 | Cable Terminations Hellermann | - |
| -2007-1 | -2007-1 | Cable Terminations & Crimping Process Instructions (AMP) .. | Dec 93 |
| -2008-1 | -2008-1 | Crimp Splices for Electrical Cables | Mar 94 |
| -2009-1 | | Soldered Sleeve Devices (Heat Shrink Materials) | May 84 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|---|--------|
| 113E | | | |
| -0001-16 | | Electrically Driven Airborne Pumps | Mar 75 |
| -0101-16 | | Actuator Rotax Type A0515/1 | - |
| -0102-16 | | Actuator Plessey Jaguar Type 500-1-00070-002 | - |
| -0103-16 | | Actuator Plessey Type Rationalized Jaguar 500-1-04800-300 .. | - |
| -0104-1 | | Actuator English Electric Type AE4012 Mk 4 | - |
| -0105-6 | | Actuator Cub Puma Plessey Type 500-1-01903 | - |
| -0106-16 | | Actuator Cougar Plessey Type 500-1-01904 | - |
| -0107-16 | | Actuator Plessey Type Jaguar Pt No 1CZ135470-B and 550-1-00925-001 | Oct 87 |
| | -0108-13A6 | Actuator Plessey Type C ub Jaguar 1CZ80360 Series | Dec 91 |
| -0109-16 | | Actuator Plessey Type Stoat Pt No 500-1-0-02275 | Mar 74 |
| -0110-1 | | Actuator English Electric Mk 2 Type AE4062 | - |
| -0111-16 | | Actuator Plessey Type Cub Jaguar 500-1-02221-001 | Oct 78 |
| -0112-16 | | Actuator Plessey Jaguar Type CZ64337-1 Variants & CZ77917 | - |
| -0113-16 | | Actuator Plessey Jaguar Type 500-1-02445-0001 | - |
| -0114-13A6 | -0114-13A6 | Actuator Plessey Cub Jaguar Type 500-1-02220 Series | - |
| -0115-16 | -0115-16 | Actuator Plessey Type Jaguar Pt No CZ53681 Series & 500-1-21090-001 | Aug 76 |
| -0117-16 | | Actuator Plessey Cub Jaguar Series Type 500-1-01320-001 ... | Jun 77 |
| -0119-1 | | Linear Actuator Assembly Pt No R584M7-IUK | Sep 78 |
| -0120-16 | | Actuator Plessey Jaguar Types 500-1-01517-002 & 500-1-04447-002 | - |
| -0121-1 | | Linear Actuator Rotax Type A2801 | 1967 |
| -0123-16 | | Actuator Plessey Cub Jaguar Types 500-1-00148 & 500-1-00973 | - |
| -0124-13A6 | | Actuator Plessey Type Stoat 500-1003828 & 500-1-04457 ... | Aug 77 |
| -0125-16 | | Actuator Plessey Jaguar Type 500-1-03545-001 | 1968 |
| -0126-16 | | Actuator Plessey Type Rationalised Jaguar 500-1-03657-300, 500-1-03668-001, 500-1-03663-001 & 500-1-00257-002 | - |
| -0127-16 | | Actuator Plessey Type Hand-Wind Twin-Motor | Aug 77 |
| -0128-1 | | Actuator Plessey Chipmunk Type 500-1-02380 | - |
| -0128-6 | | Actuator Plessey Chipmunk Type 500-1-02380 | 1967 |
| -0129-16 | | Actuator Plessey Type Aileron Trim Strut Type 500-1-00299 .. | Jan 88 |
| -0129-2 | | Aileron Trim Strut Plessey Type 500-1-00299 | - |
| -0130-16 | | Actuator Plessey Type Cub Jaguar 500-1-03270 | 1968 |
| -0131-13A6 | | Actuator Plessey Type Cub Jaguar 500-1-02630-001 | Apr 69 |
| -0132-13 | | Actuator Plessey, Type Jaguar Part No 500-1-00445-001 | Mar 90 |
| -0133-1 | | Actuator Plessey Type Rationalised Jaguar 500-1-03355-600 .. | - |
| -0133-6 | | Actuator Plessey Type Rationalised Jaguar 500-1-03355-001 & 500-1-03355-600 | 1967 |
| -0134-13A6 | | Actuator Plessey Type Cub Jaguar 500-1-00640 Series | Sep 75 |
| -0135-6 | | Actuator Western Types MAA3001 & 4001 | Aug 72 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------|-------------|--|--------|
| 113E-cont | | | |
| -0135-13A | | Actuators Western Types MAA3001 & MAA4001 | Aug 76 |
| -0136-13A | | Actuator Lucas Aerospace Types AE4554 Mk 1, 2 & 4 | Mar 75 |
| -0136-2 | | Actuator Lucas Aerospace Types AE4554 Mki 1, Mk 2 and Mk 4 | Feb 86 |
| -0137-13A | | Linear Actuator Assembly Pt No R144M 39-2 and R144M 39-15 | Jan 79 |
| -0141-12 | | Linear Actuator Lucas Aerospace Type 4023 Mki 2 | Mar 83 |
| -0142-126 | | Actuator English Electric Type AE4022 Mk 2 | Mar 83 |
| -0143-16 | | Actuator English Electric Types AE258 Mk 6 & 259 Mk 2 ... | - |
| -0144-1 | | Linear Actuator Rotax Types A0206/2, A0215 & A0220 | 1969 |
| -0145-1 | | Actuator Miles Eng Type MAL-19 Mk 1 & Mk 2 | - |
| -0145-2 | | Actuator Miles Eng Type MAL-19 Mk 1 & 2 | May 75 |
| -0146-1 | | Actuator Miles Eng Type MAL-6 | 1968 |
| -0148-16 | | Actuator Plessey Type Jaguar Pt No 500-103910-001 | - |
| -0150-13A6 | | Actuator Linear Rotax Type A0900 Series | Jul 75 |
| -0152-13A | | Actuator, Plessey, Type Cub Jaguar Pt No 1CZ135630/A3, General and Technical Information Parts Catalogue and and Related Information | Aug 89 |
| -0152-6 | | Actuator Plessey Type Cub Jaguar 1CZ135630/A3 | Sep 89 |
| -0153-1 | | Actuator Western Type EOJ150 Mk 3 | 1972 |
| -0154-1 | | Actuator Plessey Type Rationalised Jaguar 500-1-03610-001 .. | 1969 |
| -0154-6 | | Actuator Plessey Type Rationalised Jaguar 500-1-03610-001 .. | - |
| -0155-13 | | Actuator Plessey Type Twin Motor Jaguar Pt No 500-1-03660 Series | Aug 89 |
| -0155-6 | | Actuator Plessey Twin Type Motor Jaguar 500-1-03660 Series, Repair and Reconditioning Instructions | Nov 89 |
| -0160-16 | | Actuator Plessey Type Cub Jaguar 1CZ135840-B Variants and 500-1-02042-001 | 1969 |
| -0161-16 | | Actuator Plessey Stoat 500-1-03830, 500-1-04458 & 500-1-04565 | - |
| -0162-136 | | Actuator Plessey, Type Cub Jaguar PIN 1CZ82360 Series and 500-1-21026-001 General Information Repair and Reconditioning Instructions | - |
| -0163-1 | | Actuator Plessey Type Jaguar Pt No 500-1-04420 Series | Oct 78 |
| -0163-6 | | Actuator Plessey Type Jaguar Pt No 500-1-04420 Series | Oct 78 |
| -0165-13A6 | | Actuator Plessey Type Twin Motor Jaguar Pt No 1CZ80383/1 .. | - |
| -0166-16 | | Actuator Plessey Type Jaguar CZ63626-2 Variants | 1970 |
| -0167-1 | | Actuator Miles Eng Type MAL-12 | Nov 88 |
| -0167-2 | | Actuator Miles Eng Type MAL-12 | Jan 75 |
| -0168-12 | | Linear Actuator Rotax Type AE4024 Mk 2 | Mar 83 |
| -0170-136 | -0169-136 | Rotary Actuator Type AE4740 Mk 1 Elliott Pt No 60-021-01 .. | Dec 84 |
| -0170-136 | -0170-136 | Rotary Actuator Type AE4742 Mk 1 Elliott Pt No 60-022-01 .. | Feb 85 |
| -0171-1 | | Actuator Western Type EJ25 Mk 1F | Oct 73 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| | -0172-136 | Rotary Actuator Type AE4743 Mk 1 Elliott Pt No 60-023-01 ... | Dec 84 |
| -0173-1 | | Actuator Lucas Aerospace Type A0117-A & A0117-D | Feb 75 |
| -0174-1 | | Actuator Labinal Type SAL11A3 & SAL11A5 | Aug 79 |
| -0175-136 | | Linear Actuator PH Labinal Pt No VL13A-3, VL13A-4, VL13B-1, VL13B-4, VL13C-1 & VL13C-2 | Sep 81 |
| -0176-13A6 | | Actuator Plessey Type Jaguar Pt No 500-1-04005-002 | Aug 74 |
| -0177-13A6 | | Actuator Plessey Type Shrew Jaguar | Apr 76 |
| -0178-1 | | Actuator (Seat Adjusting) Martin Baker DC Types | Nov 72 |
| -0178-3 | | Actuator (Seat Adjusting) Martin Baker DC Types | Dec 93 |
| -0179-1 | | Actuator (Seat Adjusting) Martin Baker AC Types | Nov 72 |
| -0179-3 | | Actuator (Seat Adjusting) Martin Baker AC Types | Dec 93 |
| -0179-6 | | Seat Adjusting Actuator Martin-Barker AC Type | Apr 81 |
| -0180-16 | | Actuator Plessey Type Cub Puma Pt No CZ77790 | Mar 73 |
| -0182-16 | | Actuator Plessey Type Jaguar Pt No CZ72257 | Mar 73 |
| -0184-1 | -0184-1 | Actuator Westland Helicopters Pt Nos H12-45-581, H12-45-583, H13-45-381 & H13-45-383 | Aug 86 |
| -0185-16 | | Actuator Plessey Type Jaguar Pt No 1CZ135400 | Mar 74 |
| -0186-13 | | Linear Actuator Lucas Aerospace Type AE4097 Mk 1 | May 85 |
| -0187-123 | | Linear Actuator Lucas Aerospace Type AE4098 Mk 1 | May 85 |
| -0188-1 | | Linear Actuator Lucas Aerospace Type EXP5440-1 | Feb 74 |
| -0188-2 | | Linear Actuator Lucas Aerospace Type EXP5440-1 | Oct 75 |
| -0189-5F | | Linear Actuator | Dec 74 |
| | -0191-1 | Linear Actuator Type AE4122 Mk 2 Lucas Aerospace Ltd Pt No AE4122102 | Dec 82 |
| | -0191-3 | Lucas Actuator Linear | Oct 80 |
| -0192-1 | | Actuator Lucas Aerospace Type A1612 | Jul 75 |
| -0193-1 | | Actuators Lucas Aerospace Type A1700 Series | May 75 |
| -0195-1 | | Linear Actuator Lucas Aerospace Type AE4026 Mk 2 | Oct 76 |
| -0196-1 | | Actuators Lucas Aerospace Type AE4010 Series | Jul 75 |
| -0197-1 | | Actuator Lucas Aerospace Type AE4028 | May 75 |
| | -0198-1 | Pitch Trim Actuator, Roll Trim Actuator Elektro-Metall Export GmbH Pt No D3246-3, D3247-3 | Nov 82 |
| -0198-3 | | Elektro Metall Actuator Trim Pitch Roll | Jun 81 |
| -0198-6 | | Pitch Trim Actuator Roll Trim Actuator Elektro-Metall Export GmbH Pt No D3246-3, D3247-3 | Jan 84 |
| | -01100-1 | Linear Actuator Type AE 4099 Mk 2 Lucas Aerospace Ltd Pt No AE4099102 | Aug 84 |
| -01100-3 | -01100-3 | Lucas Actuator Linear | Sep 80 |
| | -01101-1 | Linear Actuator Aerospace Ltd Pt No AE4101102 | Oct 82 |
| | -01101-3 | Lucas Actuator Linear | Jun 81 |
| -01101-6 | | Linear Actuator Lucas Aerospace Ltd Pt No AE4101102 | Jun 83 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| -01102-1 | | Linear Actuator labinal pt No VL 27A1 | Jun 80 |
| -01103-13A | | Actuator Linear Pt No SYLC50594-11 (Lower) SYLC50594-10(Upper) Barber Colman Co Pt No 414CS100-11 (Lower) 414CS100-10(Upper) Boeing Vertol Co | Oct 82 |
| -01104-1 | | Actuator Cyclic Pitch Pt No 145cs114-1 (FWD), Pt No 145CS114-2 (AFT) Boeing Vertol Co | Jun 83 |
| -01104-6 | | Actuator Cyclic Pitch Pt No 145CS114-1 (FWD), Pt No 145 CS114-2 (AFT) Boeing Helicopters Repair and Reconditioning Instructions | Dec 89 |
| -01107-13 | | Aileron Trim Actuator pt No P87-P15A | Feb 93 |
| -01108-13 | | Tailplane Trim Actuator Pt No P86-P13A & 13B | Nov 89 |
| -01109-1 | | Tail Plane Trim Inverter | Jun 93 |
| -01110-12 | | Aileron Trim Inverter Pt No P87-P16C | Jun 93 |
| | -01112-3 | Parts Catalogue Plessey Actuator Wing Baulk | Mar 88 |
| -01117-13 | | Electro-Mechanical Rotary Actuator Model R1604M8 (Plessey Airborne Corp) | Dec 93 |
| -01118-13 | | Electro-Mechanical Linear Actuator Pt No R1550M12 Pt No R1550M12-2 | Aug 93 |
| -01119-13 | | Electro-Mechanical Actuator Pt No R1585M10-3 | Aug 93 |
| -01121-2 | | Cockpit Control Drive Actuator (CCDA) General Orders and Modification | Dec 92 |
| -01121-3 | | Cockpit Control Drive Actuator (CCDA) Boeing Helicopters Pt No 145C6100-1/-3 Illustrated Parts Catalogue | |
| -01121-6 | | Cockpit Control Drive Actuator (CCDA) 145C56100-1-3 Repair and Reconditioning Instructions | Dec 92 |
| -01122-1 | | Actuator Electro-Mechanical Linear, Dash Pt No SYLC 504980-1 Barker Colman Co Pt No 145CS100-5 Boeing Helicopters | Mar 92 |
| -01122-2 | | Actuator, Electro-Mechanical Linear, Dash Pt No SYLC50480-1 Barker Colman Co Pt No 145CS100-5 Boeing Helicopters | Mar 92 |
| -01122-3 | | Actuator Electro-Mechanical Linear, Dash Pt No SYLC50480-1 Barker Colman Co Pt No 145CS100-5 Boeing Helicopters Illustrated Parts Catalogue | Feb 92 |
| -01122-6 | | Actuator, Electro-Mechanical Linear, Dash Pt No SYLC50480-1 Barker Colman Co Pt No 145CS100-5 Boeing Helicopters Repair & Reconditioning | Mar 92 |
| -01123-1 | | Integrated Lower Control Actuator Pt No 145H7300-12, -17, -18, -19, -20 | Feb 93 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -01123-2 | | Integrated Lower Control Actuator Pt No 145H7300-12, -17, -18, -19,-20 | Feb 93 |
| -01123-3 | | Integrated Lower Control Actuator Assembly Pt No 145H7300-12, -17, -18, -19, 20 Boeing Helicopters ... | - |
| -01123-6 | | Integrated Lower Control Actuator Pt No 145H7300-12, -17, -18, -19, -20 Boeing Helicopters | Feb 93 |
| -01124-13 | | Ram Air Actuator Assembly (Clifton Precision Pt No 7501-0305) (Hamilton Standard Pt No 757050-1) (Clifton Precision) General & Technical Information (-1) Parts Catalogue & Related Information (-3) | Aug 91 |
| | -011126-3 | Wing Sweep Baulk Actuator - HTE | Jul 92 |
| -01127-36 | | Electric Actuator Assembly | Nov 94 |
| -0201-1 | | Actuators Single-speed Normalair-Garrett Type FJC Series | Aug 81 |
| -0201-3A6 | | Actuators (Single Speed) TAC Type FJC Series | Mar 76 |
| -0202-16 | | Rotary Actuator Rotax Type C11408 | - |
| -0203-16 | | Actuators (Dual Speed) Normalair-Garrett Type FJC Series ... | Apr 80 |
| -0204-126 | | Actuators Teddington Type FJC Series (3-Position) | - |
| -0205-16 | | Miniature, Single Speed Series Actuators Normalair-Garrett Ltd | May 80 |
| -0206-16 | | Rotary Actuator EE Type AE4549 | - |
| -0207-1 | | Rotary Actuator Rotax Type C10802 | 1969 |
| -0207-6 | | Rotary Actuator Rotax Type C10802 | - |
| -0208-16 | | Geared Motor Units Saunders Types A501 & A502 | - |
| -0209-13A6 | | Geared Motor Units Saunders Types A500, A701 & A702 Series | - |
| -0210-1 | | Saunders Sandwich Switchboxes | - |
| -0211-123A6 | | Rotary Actuators Lucas Aerospect Type C5000 Series | Oct 79 |
| -0212-16 | | Actuator Plessey Type Squirrel Pt No 500-1-0222-001 | Oct 78 |
| -0213-2 | | Rotary Actuator Lucas Aerospace Type AE4540 Mk 1 | Jun 90 |
| -0213-13 | | Rotary Actuator Lucas Aerospace Type AE4540 Mk 1 | Nov 82 |
| -0213-6 | | Rotary Actuator Lucas Aerospace Type AE4540 Mk 1 | - |
| -0214-16 | | Actuator Plessey Squirrel Type 1CZ135792 | Jun 77 |
| -0215-13A6 | | Rotary Actuators Rotax Type C5200 Series | Apr 79 |
| -0216-13A | | Screwjack Assembly Pt No R532M28-111UK | Mar 80 |
| -0217-13A | | Rotary Actuator Assembly Pt Nos R1694-1, R1694-1UK | Nov 76 |
| -0218-1236 | | Rotary Actuators Lucas Aerospace Type C5500 Series | Mar 85 |
| -0219-136 | | Actuator Plessey Type Panther Pt No CZ54709/5 & 5S & C7/69748/B | Sep 84 |
| -0220-16 | | Actuator Plessey, Cub Panther (Pt No 1CZ135790/1/A) | Nov 78 |
| -0221-16 | | Actuator Plessey, Type Raven Pt No 1CZ136490 & 500-1-04410 | Aug 85 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| -0222-16 | | Actuator Plessey Type Squirrel Pt Nos 1CZ136480, 1CZ136480-2 and 1CZ136530-1 | Jan 94 |
| -0223-16 | | Actuators Plessey Type Squirrel Pt No CZ75792 & Pt No CZ76518 | Jan 78 |
| -0224-16 | | Actuator Plessey Type Squirrel Pt No 500-1-02640-001 | - |
| -0225-13A | | Rotary Electro Mechanical Actuator Pt Nos 541594-1 & 541594-3-1, including DC Motor Pt No 517604-1-1 | Mar 77 |
| -0227-13 | | Double Rotary Actuator Rotax Type C12201 | Feb 83 |
| -0227-6 | | Double Rotary Actuator Rotax Type C12201 | - |
| -0228-16 | | Operating Unit for Landing Lamps | Jan 76 |
| -0229-13 | | Actuator Normalair-Garrett Pt No 5106 002 100, 1108 005 000 & FJC/A.980 | Aug 83 |
| -0229-6 | | Actuators Teddington Types 5106-002-100, 1108-005-000 & FJC/A/980 | - |
| -0230-1 | | Actuators Teddington Pt No 1108-004-000 & 1108-011-000 | - |
| -0230-6 | | Actuators Teddington Pt No 1108-004-000 & 1108-011-000 | - |
| -0231-1 | | High Temperature Engineers Pt No HTE 9037 Sing Motor Actuator General and Technical Information | Jan 92 |
| | -0231-1 | Rotary Actuators High Temperature Engineers Ltd Pt No HTE 9038/39/40/42/52/78/88 | Jul 94 |
| -0234-16 | | Actuator Plessey Type Panther Pt No CZ54709/10A | 1970 |
| -0235-136 | | Actuator Unit with Integral Switch Box FR/Saunders A949CD | Nov 82 |
| -0236-1 | | Rotary Actuator, Type D 168253 | Dec 91 |
| -0236-6 | | Rotary Actuator, Type D 168253 | Dec 91 |
| -0237-16 | | Actuator Plessey Cub Panther Slow Speed Pt No 1CZ135520-1E | Jun 77 |
| -0238-1 | | Actuator HSD Type 100A221686A | 1969 |
| -0238-6 | | Actuator HSD Type 100A221686A | - |
| -0239-1 | | Actuator Vactric Type 35280 | 1969 |
| -0240-1 | | Actuator Western Type X0001/2 | 1970 |
| -0240-6 | | Actuator Western Type X0001/2 | Aug 70 |
| -0241-3A6 | | Linear Actuator Pt No D2050-2 | Nov 86 |
| -0243-13 | | Actuator Plessey Type Cub Panther 500-1-04325-001 | Mar 83 |
| -0243-6 | | Actuator Plessey Type Cub Panther 500-1-04325-001 | Aug 77 |
| -0244-6 | | Rotary Actuator Bendix Pacific Series 118 | May 77 |
| -0245-6 | | Actuator Plessey Squirrel Type 500-1-03595-009 | - |
| -0245-13A | | Actuator Plessey Squirrel Type 500-1-03595-009 | - |
| -0246-3A6 | | Rotary Electromechanical Actuator (Pt Nos 541146-1-1, 541146-2-1 & 541146-3-1) | Dec 72 |
| -0247-16 | | Actuator Plessey Kestrel Type 1CZ131630 & Motor Type S1010C/3 Pt No 4CZ94950 | - |
| -0248-1 | | Rotary Actuator Lucas Aerospace Type AE200 Mk 1 | Mar 79 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|---------------------|-------------|---|--------|
| 113E-cont | | | |
| -0249-1 | | Rotary Actuators English Electric Type AE233 & AE234 | Dec 69 |
| -0250-1 | | Rotary Actuator English Electric Type AE4529 Mk 4 | 1969 |
| -0250-2 | | Rotary Actuator Lucas Aerospace Type AE4529 Mk 4 | Feb 86 |
| -0250-6 | | Rotary Actuator English Electric Type AE4529 Mk 4 | - |
| -0251-12 | | Canopy Actuating Unit Lucas Aerospace Type AE6320 Mk 2 | Mar 83 |
| -0251-6 | | Canopy Actuating Unit Lucas Aerospace Type AE6320 Mk 2 | Apr 84 |
| -0252-13A | | Rotary Actuators Lucas Aerospace Types C5075/1, C5077/1, C5081 & C5082 | May 77 |
| -0252-2 | | Rotary Actuators Lucas Aerospace Type C5075/1, C5077 & C5077/1 | Jul 74 |
| -0252-6 | | Rotary Actuators Lucas Aerospace Types C5075/1, C5077 & C5077/1, C5081, C5082 | May 77 |
| -0254-13A6 | -0254-13A6 | Rotary Actuator High Temperature Engineers Types 1810 & 9002-001 | - |
| -0255-13A6 | | Rotary Actuator Type 5400 Teleflex-Syneravia Pt No AR10-800-211 | May 76 |
| -0256-1 | | Actuator Teddington Pt No 1108-009-000 | - |
| -0256-6 | | Actuator Teddington Pt No 1108-009-000 | - |
| -0257-13A6 | | Fuel Cock Actuator Teleflex Type ARS314-EA112A | Mar 73 |
| -0258-13A6 | -0258-13A6 | Rotary Actuator Semca Pt No 915 OE 01 | - |
| -0259-13A6 | | Rotary Actuator Lucas Aerospace type C14101/1 | Nov 74 |
| -0261-1 | | Actuator Western Type ERJ60 Mk 19 & Mk 22 General & Technical Information (-1) | Jul 91 |
| -0263-13A | | Actuators Tac (Aircraft Controls) Pt Nos 7506N000, 7507N000 & 75068N000 | Aug 76 |
| -0264-1 | | Double Rotary Actuator Lucas Aerospace Type C8103-1 | May 73 |
| -0266-1 | | Double Rotary Actuator Aerospace Type CA1102 | Sep 74 |
| -0267-5F Cover 1 | | Rotary Actuators (Electric) | Dec 74 |
| -0267-5F Cover 2 | | Rotary Actuators (Electric) | - |
| -0268-13 | | Rotary Actuator Lucas Aerospace Types AE4728 Mk 3 & 4 | May 85 |
| -0269-13A | | Rotary Actuator AVIAC Pt No 2759-90 | Dec 79 |
| -0270-16 | | Actuator Plessey Type Panther Pt Nos CZ64581 & CZ64581A | May 75 |
| -0271-16 | | Actuator Plessey Type Panther Pt No CZ72256 | Mar 75 |
| -0273-1 | | Rotary Actuator Lucas Aerospace Type AE4723 Mk 1 | Apr 77 |
| -0274-1 | | Rotary Actuator FG Miles Eng ltd Pt No MR A22 Mk 2 | May 79 |
| -0275-13A6 | | Rotary Actuator Lucas Aerospace Type AE 4762 Mk 1 | 1977 |
| -0276-136 | -0276-136 | Rotary Actuator DC Plessey Pt No 500-1-20344 & Pt No 500-1-21166-000 | - |
| -0277-1 | | Rotary Actuator Lucas Aerospace Type AE 4518 Mk 2 | Oct 76 |
| -0278-1 | | Retraction Unit Lucas Aerospace Type C 8901 | Jun 76 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| -0279-1 | | Actuator Lucas Aerospace Type 5622 | Jun 76 |
| -0280-13A6 | | Rotary Actuators Normalair-Garrett Pt No 4457C000 & 7223C060 | Jan 79 |
| -0281-1 | -0281-1 | Actuator Rotary High Temperature Engineers HTE 9004 001 & HTE 9047 | Apr 77 |
| -0284-1 | -0284-1 | Actuator Rotary High Temperature Engineers Ltd Pt No HTE9005 001 Ref No 5W/1680-99-6379115 | - |
| -0285-1 | -0285-1 | Actuator Rotary High Temperature Engineers Pt No HTE 9003-001C | - |
| -0287-123A | | Rotary Actuator Lucas Aerospace Type AR 008 01 | Jun 82 |
| | -0288-6 | Dowty Fuel Systems Ltd Electro-Mechanical Rotary Actuator Pt No 1293-A-1094 | Aug 93 |
| | -0288-7 | Dowty Fuel Systems Ltd Electro-Mechanical Rotary Actuator (Turndown) N 18MGHF3 (Dowty) Pt No 1293-1005) | Feb 80 |
| | -0289-6 | Dowty Fuel Systems Ltd Electro-Mechanical Rotary Actuator (Temperature Trim) C 125804-A (Dowty Pt No 1290-1009) .. | Aug 80 |
| | -0289-7 | Dowty Fuel Systems Ltd Electro-Mechanical Rotary Actuator (Temperature Trim) C 125804-A (Dowty Pt No 1290-1009) .. | Feb 80 |
| -0290-136 | -0290-136 | Fuel Cock Actuator Artus Pt No 2256-1-C | - |
| -0292-13A6 | | Control Driver Cockpit Actuator Pt No 165H6000-16 (Pre Mod 63) Pt No 165H600-17 (Post Mod 63) Boeing Vertol Co | Oct 83 |
| -0293-1 | | N2 Actuator Pt No NYLC 9899 Barber Colman Co Pt No 114PS205-2 Boeing Vertol Co | Mar 82 |
| -0294-1 | | N1 Actuator Pt No 1964344-3 Bendix Corp Pt No 114PS206-3 Boeing Vertol Co | Jan 82 |
| -0295-13A6 | | Actuator Longitudinal Cockpit Control Driver Pt No 145C6000-10 Boeing Vertol Co | Apr 82 |
| -0296-123 | | Fail Safe Actuators Flight Refuelling Ltd Pt No 9406035 & 9406036 | Aug 83 |
| -0298-123 | | Actuator Assembly Flight Refuelling Ltd Pt No 9406028 and 9406053 General & Technical Information General Orders and Modifications Illustrated Parts Catalogue | Apr 92 |
| -0299-13 | | Actuator Flight Refuelling Ltd Pt No 9300597 | Jan 85 |
| -02100-1 | | Electro-Mechanical Control Actuator Pt No P88C | Dec 90 |
| -02101-13 | | Electrically Controlled Valve Le Bozec et Gautier Type DN 25 Pt No 326A25-9 AMDT-D | Dec 85 |
| -02102-136 | -02102-136 | Rotary Actuator Type AE4740 Mk 1 Elliott Pt No 60-021-01 .. | - |
| | -02103-136 | Rotary Actuator | Jan 87 |
| -02104-136 | | Rotary Actuator Type AE 4743 Mk 1 Elliott Pt No 60-023-01 .. | - |
| -02105-36 | | Rotary Actuator Pt No NYLC 9905 Phantom F-4J Aircraft | Sep 85 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -02106-13 | | Flat Actuator (0-90 deg) Flight Refuelling Pt No 9406043 (Part) & 9406044 (STBD) | - |
| -02107-3 | | Twin Actuator Type 9404005 | Apr 85 |
| | -02108-3 | Normalair Garrett Actuator Auto Wing Sweep | Nov 93 |
| -02110-3 | | Actuator 1680-15-060-6902 | May 88 |
| -02111-1 | | Actuator Motor-Dukes Inc 1400-00-1 | May 88 |
| -02112-13 | | Model R1624-4 Rotary Actuator Assembly (Airborne Accessories Corporation) | Nov 90 |
| -02113-13 | | Electromechanical Rotary Actuator P/N 540666-3 (Airesearch) . | Nov 90 |
| -02114-13 | | Actuator P/Ns 106788A140, 102842LX, 106788A103, 106788A128, 106788A131 (ITT Aerospace Products) | Nov 90 |
| -02115-13 | | DC Motors P/N 102650BA, 106785B109, 106785A110 (General Controls) | Jul 90 |
| -02116-13 | | Electromechanical Rotary Actuator P/N 2021942-1-1, includes Alternating Current Motor P/N 516568-1-1 (Airesearch) | Nov 90 |
| -02117-6 | | Actuator Pt No 3755-2 (General Design, Inc) Repair and Reconditioning Instructions (1-6) | Mar 94 |
| -02118-13 | | Rotary Electro-Mechanical Actuator and Alternating Current Motor | Mar 94 |
| -02119-13 | | Electro-Mechanical Actuator Pt No 2734147 (Parker Hannifin) . | Mar 94 |
| -0300-1 | | Electric Motors Blowers & Fan Units | 1972 |
| -0303-16 | | Blowers Airmax Fans Types H3-Y3566 & H3-Y3567 | 1967 |
| -0305-16 | | Motor AE1 Type LK1616 Form A2 | - |
| -0306-1 | | Geared Motor Unit English Electric Mk 7 Type AE824 | 1967 |
| -0306-6 | | Geared Motor Unit English Electric Mk 7 Type AE824 | 1967 |
| -0308-16 | | Motor Lucas Aerospace Type PL 804 Form A2 | Jun 77 |
| -0310-16 | | Motor AE1 Type LD1005 Form 9F/3 & Gearbox DP2 Form A/3 | 1967 |
| -0311-1 | | Motor Lucas Aerospace Type LD 1206 Form 10/1 | Jan 78 |
| -0311-2 | | Motor Lucas Aerospace Type LD 1206 Form 10/1 | Jan 77 |
| -0314-16 | | Motor, DC, Plessey Type C1305A/5 Pt No 4CZ94470 | - |
| -0315-16 | | Motor, Plessey Type C1606B-19 (Pt No CZ 78311 Type C1606B & (Pt No 501-1-06019) | Nov 77 |
| -0316-16 | | Motor AEI Type LK454 Form A4 | - |
| -0317-16 | | Fan Units Airscrew Weyroc 68c6 Series | - |
| -0318-16 | | Motor Plessey Type C1606B-1 & 24 | - |
| -0318-136 | | Motor Plessey Type C1606B-1 & 24 | Mar 90 |
| -0319-136 | | Motor Plessey Type C1305A-8 Pt No 4CZ95868 | Jan 88 |
| -0320-16 | | Motor AEI Type LK1212 Form A1/1 | - |
| 0321-16 | | Motors, DC Plessey Types C1606G/49 (501-1-05074)C1606G/44 & (4CZ94690) | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| -0322-1 | | Windscreen Wiper Motor Lucas Aerospace Type TO303 | Aug 76 |
| -0322-16 | | Motor AEI Type LK808 Form C13/1 | - |
| -0324-16 | | Motor Rotax Type D1-LK11706 Form C2C | - |
| -0324-2 | | Motor Rotax Type D1-LK1706 Form C2C | - |
| -0325-16 | | Motor AEI Type LD1508 Form 10 | - |
| -0326-16 | | Motor AEI Type LK 1406 Form D3C | - |
| -0327-16 | | Motor AEI Type LK1616 Form B1 | - |
| -0328-16 | | Motor AEI Type LK1616 Form E1/1 | - |
| -0329-16 | | DC Motor, Plessey Type C1606B-59 Pt No 501-1-06210 | Mar 76 |
| -0331-16 | | Axial Flow Blower Plannair Type 2PL-81-242 | - |
| -0332-16 | | Fan Motor Rotax Type C12601 | - |
| -0333-16 | | Motor AEI Type LK808 Form C15 | - |
| -0334-1 | | Motor AEI Type LD1511 Form 8 | - |
| -0335-1 | | Motor AEI Type LD1910 Form 108 | - |
| -0336-16 | | Motor AEI Type LD0704 Form 9/1 with Gearbox Type TS2 Form A2 | - |
| -0337-16 | | Motor Lucas Aerospace Type CA1205/3 | - |
| -0338-136 | | Blower, Axial Flow Type 5PL-101-566 | - |
| -0339-136 | | Blower, Axial Flow Type 5PL-101-430 | - |
| -0340-13 | | Blower, Axial Flow Type 3PL-181-465 | - |
| -0341-136 | | Blower, Axial Flow Type 8PL-401-423 | - |
| -0342-16 | | Motor & Brake Lucas Aerospace Type C9603 | 1974 |
| -0343-16 | | Feathering Pump Motor Lucas Aerospace Type C2801 | Oct 76 |
| -0345-16 | | Motor Nelco Type DCE23 | - |
| -0346-1 | | Motor AEI Type LD1206 Form 7F | - |
| -0347-16 | | Fan Unit Airscrew Weyroc Type 45C3-512 | - |
| -0348-13A | -0348-13A | Planniar Axial Flow Blower Type 3PL-241-176 | Aug 74 |
| -0348-16 | | Axial Flow Blower Plannair 3PL-241-176 | 1974 |
| -0351-16 | | Motor Nelco Type DCG31, DCG31/1 & DCG32 | - |
| -0352-1 | | Fan Unit Airscrew Weyroc Type 55A0141, 55A0151 | - |
| -0353-13A | | Axial Fan Unit Airscrew - Weyroc Types 5540, 121 & 70A0111 | Sep 74 |
| -0354-16 | | Fan Unit Airscrew Weyroc Type 57A0111 | - |
| -0355-16 | | Axial Flow Blower Plannair Type 2PL81-115 | - |
| -0356-16 | | Blower Heater Plannair Type 2PL82-111H | - |
| -0357-16 | | Blower Heater Plannair Type 2PL82-425H | May 66 |
| -0358-16 | | Motor Nelco Type DCE22 & DCE21 | - |
| -0359-1 | | Axial Blower Units Plannair Types 3PL181-170, 198, 241, 252, 321 & 458 Mk 2 | - |
| -0360-1 | | Axial Flow Blower Plannair Type 4PL121-489 | Aug 74 |
| -0361-16 | -0361-16 | Motor Plessey Type C1606H/1 | - |
| -0363-16 | | Motor AEI Type LD1915 Form 11F/2 | - |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -0364-1 | | Motor Lucas Aerospace Type CA1201/1 | Nov 78 |
| -0364-2 | | Motor Rotax Type CA1201 | - |
| -0365-1 | | Motor Lucas Aerospace Type CA1203 | - |
| -0366-1 | | Motor & Gearbox Lucas Aerospace Type CA1401 | Dec 78 |
| -0368-1 | | Motor Rotax Type C13202/1 | - |
| -0369-16 | | Motor Lucas Aerospace Type LD1915 Form 108/2 | - |
| -0370-1 | | Axial Flow Blower Unit Plannair Type 1PL82-596 | Sep 74 |
| -0371-16 | | Axial Flow Blowers Plannair Types 2PL81-105, 108, 108H, 129 & 135 | - |
| -0372-16 | | Motor Plessey Type C1606B-37 (Pt No 4CZ92990) | - |
| -0374-16 | | Axial Flow Blower Plannair | - |
| -0375-1 | | Axial Flow Blower Plannair Type 1PL121-114 Mk 2 | Aug 74 |
| -0376-1 | | Axial Flow Blower Plannair Type 1PL121-402 | Aug 74 |
| -0377-16 | | Fan Unit Airscrew Weyroc Type 59A1, 111 | - |
| -0378-16 | | Axial Flow Blower Plannair Type 2PL81-128 | - |
| -0380-16 | | Two Stage Axial Flow Blower Plannair Type 3PL182-271 Mk 3 | - |
| -0381-16 | | Axial Flow Blower Plannair Type 3PL-241-88 | - |
| -0381-16 | | Axial Flow Blower Plannair Type 3PL-241-88 | - |
| -0382-16 | | Axial Flow Blower Plannair Type 3PL-L241-110 | - |
| -0383-1 | | Axial Flow Blower Type 3PL-241-218 | Dec 74 |
| -0384-1 | | Axial Flow Blower Plannair Type 4PL-121-485 | Aug 74 |
| -0385-1 | | Air Blower Lucas Aerospace Type 710 Mk 2 | Oct 76 |
| -0386-1 | | Motor Rotax Type C10402 | 1967 |
| -0386-6 | | Motor Rotax Type C10402 | - |
| -0387-16 | | Motor Plessey C1305B/6 (Pt No 4CZ943930) & C1305B/1 (Pt No 4CZ73100 & 4CZ73100/1) | - |
| -0389-13A6 | | Motor Rotax Type LK804 Form C2/1 & Gearbox QS1 Form A, Type LK804 for C3/1 & Gearbox QS1 Form B, Type LK804 Form C2/1, LK808 Form C20 & Gearbox QS6 Form A1 | - |
| -0390-1 | | Motor AEI Type LK606 Forms A3 & A4 | 1967 |
| -0391-1 | | Motor AEI Type LK404 Forms A4 & A7 | 1967 |
| -0392-1 | | Motor AEI Type LK502 Form A1 | 1967 |
| -0393-1 | | Motor AEI Type LK604 Forms A6 and A9 | - |
| -0394-1 | | Motor Lucas Aerospace Type LK1716 Form B3/1 | - |
| -0395-1 | | Motor Lucas Aerospace Type LK1818 Form B1/1 | Oct 75 |
| -0398-16 | -0398-16 | Blower Motors AK Fans Type H3-Y2407-55/1 & H5-Y3529 .. | - |
| -0399-16 | | Blower Motors AK Fans Type H3-Y3419 & H3-Y3514 | - |
| -03100-1 | | Fan Motor Woods Type AF744 | 1968 |
| -03100-6 | | Fan Motor Woods Type AF744 | - |
| -03101-1 | | Fan Motors Woods Types DF92/7 & DF74/7 | 1968 |
| -03102-1 | | Motor AEI Type LD0704 Form 15/1 | 1968 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -03103-1 | | Motor Lucas Aerospace Types LD0704 Form 19 & Form 21/2 | - |
| -03104-1 | | Blower Type 1 | Oct 75 |
| -03106-1 | | Fan GEC Type V93 | - |
| -03109-16 | | Motor, Plessey Type C12305E-17 Pt No 501-1-06420 & C1305B-10 Pt No 501-1-05490 & C1305E-A | Feb 94 |
| -03111-16 | | Motor Plessey Type S1510E Series | - |
| -03113-16 | | Motors Windscreen Wiper ALCO | 1967 |
| -03115-6 | | Motor Type A/DC/A Pt No CZ26817) Repair & Reconditioning Instruction | Feb 92 |
| -03116-1 | | Axial Flow Blower Plannair Type 1PL41-426 Mk 3 | 1968 |
| -03116-6 | | Axial Flow Blower Plannair Type 1PL41-426 Mk 3 | 1970 |
| -03117-1 | | Blower Unit Type 4B | Oct 75 |
| -03118-1 | | Fan Auriema Type A071147 | Jun 79 |
| -03120-1 | | Motor Rotax Type LD2412-9/4 | - |
| -03121-13 | | Motor Gearbox Unit Rotax Types LK1616-E4 & SP7-A1 | Feb 84 |
| -03121-2 | | Motor Gearbox Unit Rotax Types LK1616-E4 & SP7-A1 | - |
| -03121-6 | | Motor Lucas Aerospace Type LK1616 Form E4 & Gearbox Type SP7-A2 | 1972 |
| -03122-13 | | Motor Rotax Type LD1206-13/1 | Jan 83 |
| -03122-6 | | Motor Rotax Type LD1206 Form 13/1 | - |
| -03123-1 | | Motor Lucas Aerospace Type LK808-C17 | Jan 79 |
| -03123-6 | | Motor Rotax Type LK808 Form 17 | - |
| -03124-1 | | Motor Rotax Type LK1007-E1 | 1969 |
| -03124-6 | | Motor Rotax Type LK1007-E1 | - |
| -03125-1 | | Motor Rotax Type LK1406-B1 | 1969 |
| -03125-6 | | Motor Rotax Type LK1406 Form B1 | - |
| -03126-1 | | Motor, Lucas Aerospace, C2200 Series | Sep 76 |
| -03127-16 | | Motor, Plessey Type C1606B/7 (Pt No CZ67427 & CZ67427/1) | Mar 76 |
| -03128-126 | | Motors Plessey Type C1606H/4 (Pt No 4CZ93327) | Feb 83 |
| -03129-16 | | Motor Plessey Type C1606G/18 (4CZ92200) | 1969 |
| -03131-1 | | Stick Shaker Mk 11 (Aircraft Unit Engineering) Type B1499 | 1969 |
| -03132-1 | | Fan Unit Airscrew Weyroc Type 65A1511 | Jul 68 |
| -03132-6 | | Fan Unit Airscrew Weyroc Type 65A1511 | 1970 |
| -03133-1 | | Fan Unit Airscrew Weyroc Type 40C3511 | 1968 |
| -03133-6 | | Fan Unit Airscrew Weyroc Type 40C3511 | - |
| -03134-1 | | Fan Unit Airscrew Weyroc Type 45C3531 | 1968 |
| -03134-6 | | Fan Unit Airscrew Weyroc Tuype 45C3531 | 1970 |
| -03135-1 | | Fan Unit Airscrew Weyroc Type 60C9511 | 1968 |
| -03135-6 | | Fan Unit Airscrew Weyroc Type 60C9511 | - |
| -03136-13A | | Motor, DC, Plessey Type C1606B Pt No 501-1-06840 | - |
| -03136-6 | | Motor, DC, Plessey Type C1606B-66 Pt No 501-1-06840 | 1969 |
| -03137-13A | | Motor Plessey Type C1606H/67 Pt No 501-1-06960 | 1969 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -03137-6 | | Motor DC, Plessey Type C1606H67 Pt No 501-1-06960 | 1970 |
| -03138-6 | | Motor Plessey Type C2520A2, CZ74585 | 1969 |
| -03139-13A | | Blower Plannair Type 3PL182-271 Mk 5 | - |
| -03139-6 | | Blower Plannair Type 3PL182-271 Mk 5 | - |
| -03141-1 | | Fan Heater AK Fans Type X4674 | 1970 |
| -03141-6 | | Fan Heater AK Fans Type X4674 | - |
| -03143-1 | | Motor, DC, Plessey C1696V/68 (501-1-07180) | 1969 |
| -03143-6 | | Motor, DC, Plessey C1606V/68 (501-1-07180) | 1970 |
| -03144-6 | | Motor, GEC Type C2520A-6 (Part No 501-1-06110) | Jan 92 |
| -03145-6 | | Motors TAC Part No 2701 Series | - |
| -03146-16 | | Blower Heater Unit Plannair Type 2PL-81-1228H | - |
| -03147-1 | | Blower Airmax Fan Type H3-Y3755 | - |
| -03148-1 | | Axial Flow Blower Plannair Type 1PL121-713 | 1969 |
| -03148-6 | | Axial Flow Blower Plannair Type 1PL121-713 | 1969 |
| -03149-1 | | Axial Flow Blower/Heater Plannair Type 3PL181-859H | Oct 69 |
| -03149-6 | | Axial Flow Blower/Heater Plannair Type 3PL181-859H | - |
| -03150-16 | | Motor Plessey Type C1606C/12 Pt No CZ64244 | - |
| -03153-1 | | Blower Plannair Type 2PL81-164 Mk 2 | - |
| -03153-6 | | Blower Plannair Type 2PL81-164 Mk 2 | - |
| -03154-6 | | Motor Plessey Type SPE14275 & SPE21405 | 1970 |
| -03161-1 | | Axial Flow Blower Plannair Type 3PL-182-271 Mk 4 | - |
| -03162-1 | | Winch Motor Assembly AEI Type LD1710 Form 1 | - |
| -03162-6 | | Winch Motor Assembly AEI Type LD1710 Form 1 | - |
| -03163-16 | | Motor Plessey Type C1606C/20 Pt No 4CZ92197 | - |
| -03164-1 | | Motor Rotax Type LD2412-11 | - |
| -03164-6 | | Motor Lucas Aerospace Type LD 2412 Form 11 | Nov 72 |
| -03165-1 | | Motor Lucas Aerospace Type AE1246 Mk 1 | Sep 74 |
| -03165-6 | | Motor Lucas Aerospace Type AE1246 Mk 1 | Sep 74 |
| -03166-13A | | Windscreen Wiper Teleflex-Syneravia Type 11F | - |
| -03169-13A6 | | Motor Rotax Type LD1005 Form 20/1 & Gearbox Type DP6 Form A1 | Jul 75 |
| -03169-2 | | Motor Lucas Aerospace Type LD 1005 Form 20/1 Gear Box Type DP6 Form A1 | Jan 77 |
| -03171-1 | | Motor Stick Shaker Safe Flight Inst Corp (USA) Type C79202 | - |
| -03172-123 | | Geared Motor - Eccentric Drive Plessey | Oct 93 |
| -03172-6 | | Geared Motor - Eccentric Drive Plessey | Oct 85 |
| -03173-1 | | Fan Unit Mk 19B Airscrew Fans Ltd | Nov 73 |
| -03174-1 | | Motor Feathering Pump Dowty Rotol Type FPM/4 | Feb 74 |
| -03176-1 | | Motor Lucas Aerospace Type C9001 | Mar 73 |
| -03177-13A6 | | Motor Lucas Aerospace Type LD1005 Form 13/2 | Oct 75 |
| -03178-13A | | Fan Unit Plannair Type 2PL-81-1185 | Jun 74 |
| -03179-1 | | Stick Shaker Mk 13 | Nov 73 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -03180-1 | | Fan Motor Herman Smith Type HE61040 M90 | Jul 74 |
| -03182-13A | | Fan Unit Airscrew Howden Pt No 2PL-21-1344 | Sep 77 |
| -03186-136 | -03186-136 | Vaneaxial Fan Pt No C70144 (Pt No 8038C000 Alternative) General & Technical Information Parts Catalogue & Related Information Overhaul Instructions | May 91 |
| -03187-3 | | Fan Assemblies Pt No A70595 Type 27-A1-512 and Pt No D98370 Type 70-AA6-512 Illustrated Parts Catalogue .. | Mar 92 |
| -03187-13A6 | -03187-13A6 | Blower Motor Airscrew Howden Pt No A70595 Type 27-A1-512 | |
| -03188-136 | -03188-136 | Fan Unit Airscrew Howden Ltd Type 3PL-41-1246 Mk 4 Pt No D85441 | |
| -03189-13A | | Heater Blower Assembly AK Fans Airmax Type NS-X5675 ... | May 78 |
| -03191-1 | | Stick Shaker Unit Mk 9 | Nov 75 |
| -03192-1 | | Blower Unit Ref No 5UD/4389485 | Nov 75 |
| -03193-1 | | Blowers Lucas Aerospace Types AE6001 Mk 2 and AE6006 Mk 1 | Nov 75 |
| -03194-136 | -03194-136 | Motor DC Plessey Type C1106-D12 Pt No 501-1-08440 | - |
| -03195-1 | | Ground Cooling Fan Unit Normalair-Garrett Ltd Pt No 1225D000 Repair & Reconditioning Instructions (Topic 6) | May 89 |
| | -03195-3 | Normalair Garrett Fan Ground Conditioning | Sep 80 |
| -03195-6 | | Ground Cooling Fan Unit Normalair - Garrett Ltd Pt No 1225D000 Repair & Reconditioning Instructions (Topic 6) | May 89 |
| | -03196-1 | Fan, Forward Compartment Airscrew Howden Ltd Pt No D87502 | Aug 81 |
| | -03196-3 | Airscrew Howden Fan Unit | Sep 80 |
| | -03196-6 | Fan, Forward Compartment Airscrew Howden Ltd Pt No D87502 | Aug 81 |
| -03197-136 | -03197-136 | Fan Unit Airscrew Howden Ltd Type 55-AO-543 Pt No 086705 | Oct 80 |
| -03199-1 | | Blower Unit Lucas Aerospace Type CA1301 | Aug 76 |
| -03202-16 | | Motors Normalair Garrett Type FJA/A/Series | Jun 77 |
| -03203-1 | | Blower Pt No A02 9011 | Mar 78 |
| -03205-1 | | Windshield Wiper Motor Teleflex Pt No XW21157-2 | Jan 79 |
| -03206-1236 | | Electric Motor Microturbo Pt No 60 C2-301 | Mar 85 |
| -03207-1 | | Fan, Ground Handling Type 75 MAI-522 | Apr 79 |
| -03208-1 | | Fan Mixed Flow Airscrew Howden Type MA1-532, MA1-533 .. | Apr 83 |
| -03209-1 | | Fan Axial Flow Airscrew Howden Type 2 PL 82275 Mk 2 ... | Apr 80 |
| -03210-1 | | Digital Speed Sensing Unit Type E387ANC511 | Sep 81 |
| -03211-13A6 | | Fan Unit Type 125 AA! 541 | Sep 81 |
| -03212-13A6 | | Fan Electric Avionic Cooling Pt No 728502 Sundstrand Corporation Pt No 414AS701-2 Boeing Vertol Co | Aug 82 |
| -03214-13A | | Fan Centrifugul Pt No 500702-5310 Sundstrand Aviation Pt No 114E4041-2 Boeing Vertol Co | Mar 82 |
| -03216-13A | | Fan Unit Airscrew Howden Pt No 70 AA5 511 | Oct 81 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -03217-12 | | Fan Unit Airscrew Howden Pt No 68 AO 511/2 | Jan 83 |
| -03218-13 | | Stepper Motor & Control Box Assembly Flight Refuelling Ltd Pt No 4332823 Stepper Motor & Power Line Unit Flight Refuelling Ltd Pt No 43321870 | Feb 85 |
| -03219-1 | | Fan Unit Airscrew Howden Type 100 CC3 521 | Oct 83 |
| -03220-13 | | Fan Avionics Cooling Part No 23E26-3 | Oct 88 |
| -03222-13 | | Fan Assembly Pt No D93365 | May 87 |
| -03224-13 | | Fan, Vane Axial Type NS Y7184 | Jun 88 |
| -03225-13 | | Fan Type 95 MAI 541 | - |
| | -03226-3 | Airscrew Howden Fan Unit Ground Cooling | Sep 88 |
| | -03227-3 | Parts Catalogue AK Fans Fan Assembly 75mm | Mar 90 |
| | -03228-3 | Parts Catalogue Airscrew Howden Fan Heater | Jun 89 |
| -03229-136 | | Motor Fan Ventilation Pt No 3968DO1 4140-14-303-5654 | - |
| -03234-13 | | Motor Assembly | Nov 90 |
| -03235-2 | | Fan, Hydraulic Cooling, Electric Pt No 723092A Sundstrand Aviation Pt No 145HS202-4 Boeing Helicopters | Sep 92 |
| -03235-3 | | Fan, Hydraulic Cooling, Electric Pt No 723092A Sundstrand Aviation Pt No 145HS202-4 Boeing Helicopters | Sep 92 |
| -03235-6 | | Fan, Hydraulic Cooling, Electric Pt No 723092A Sundstrand Aviation Pt No 145HS202-4 Boeing Helicopters | Sep 92 |
| -03236-2 | | Fan, Hydraulic Cooling, Reservoir Pt No 723094B Sundstrand Aviation Pt No 145HS202-5 Boeing Helicopters | Nov 92 |
| -03236-6 | | Fan Electric Hydraulic Cooling Reservoir Pt No 723094B Sunstrand Aviation Pt No 145HS202-5 Boeing Helicopters | Nov 92 |
| -03237-1 | | Windshield Wiper Motor/Gearbox 414E5106-3, -4 General & Technical Information | Apr 93 |
| -03237-2 | | Windshield Wiper Motor/Gearbox 414E5106-3, -4 General Order and Modifications | Apr 93 |
| -03237-3 | | Windshield Wiper Motor/Gearbox 414E5106-3,04 Illustrated Parts Catalogue | Apr 93 |
| -03238-1 | | Windshield Wiper Centre Gearbox 4260284 Teleflex Syneravia 414ES106-7 Boeing Helicopters | Apr 93 |
| -03238-2 | | Windshield Wiper Centre Gearbox 414E5106-7 General Orders and Modifications | Apr 93 |
| -03238-3 | | Windshield Wiper Centre Gearbox 414E5106-7 Illustrated Parts Catalogue | Apr 93 |
| -0401-3A6 | | Pump Fuel Plessey Element Type 7102 & Canisters Type 7103, 7104, 7105 & 7306 | Dec 76 |
| -0404-6 | | Pump Water/Methanol Plessey Type SPM8/RS Series | Dec 84 |
| -0405-6 | | Pump Fuel Plessey Type SPE6210 Series | Oct 79 |
| -0406-6 | | Pump Methanol/Water Plessey Type SPE 6301 | Oct 79 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -0407-6 | | Pumps, Fuel, Plessey Types BP1, BP1F & BP1/RS Series | Oct 78 |
| -0408-3A6 | -0408-3A6 | Pump Fuel Plessey Type BP14 & BP14/RS Series | - |
| -0409-6 | | Fuel Transfer Pump Lucas FTP Series | Apr 77 |
| -0413-3A6 | | Pumps Fuel Plessey BP5 & BP5/RS Series | Oct 79 |
| -0415-1 | | Fuel Booster Pump type 2070C-01 (Intertechnique Ltd) | Feb 78 |
| -0416-6 | | Pump Fuel & De-Icing Plessey Type AI Mk 5 | - |
| -0417-1 | | Pump Fuel Thomson Type 258800-1 | - |
| -0417-6 | | Pump Fuel Type TRW258800-6 | - |
| -0418-6 | | Pump Fuel Plessey Type PUL907 Mks 3 & 4 | Oct 73 |
| -0423-6 | | Pump Fuel Plessey Type SPE 2009A Mk 7 | Oct 79 |
| -0425-6 | | Pump Fuel Plessey Type SPE 35236 Mk 1 & 2 | Nov 82 |
| -0428-6 | | Pump Water Glycol Plessey Type SPE 330 WG | Dec 84 |
| -0430-16 | | Fuel Pump & Suppressor Lear Siegler Type RG15150L | - |
| -0431-6 | | Fuel Transfer Pump Plessey Type FTP 080 | Aug 80 |
| -0432-6 | | Pump Fuel Plessey Type SPE 3365 Mk 1 | Nov 82 |
| -0433-6 | | Pump Water Plessey Type SPE 234W Mk 4 | Dec 84 |
| -0434-6 | | Pump Fuel Assembly Type PAC 500 Mk 3 | Feb 81 |
| -0435-16 | | Fuel Pump Lear Siegler Pt No RG17230-9 | Jan 73 |
| -0438-1 | | Pump Fuel Type SPE1003 Mk 3 & Mk 4 | Dec 66 |
| -0438-6 | | Pump, Fuel, Plessey Type SPE 1003 Series | Dec 82 |
| -0439-3A6 | | Fuel Booster Pump Pt No 266800-1 | - |
| -0440-3A | | Submerged Fuel Pump Models Types TB117300-3, TB117300-5 & 245200-1 | - |
| -0440-6 | | Submerged Fuel Pump Models Types TB117300-3, TB1173005 & 245200-1 | - |
| -0441-6 | | Pumps Fuel Type PAC1200 Series | 1967 |
| -0442-6 | | Pump Fuel Plessey Type SPE1234 Series | - |
| -0445-1 | | Pump Fuel Plessey Type FP3 Series | Mar 67 |
| -0445-6 | | Pump Fuel Plessey Type FP3 Series | Feb 70 |
| -0446-1 | | Pumps Plessey Type DP022 Series | 1967 |
| -0446-2 | | Pumps Plessey Type DP022 Series | - |
| -0446-6 | | Pumps Plessey Type DP022 Series | Aug 78 |
| -0449-6 | | Pump Fuel Plessey Type SPE1235/6/7 Mks 3 & 5 | - |
| -0450-6 | | Pump Fuel Plessey Type SPE1201 Series | 1972 |
| -0451-6 | | Pump Fuel Plessey Types SPE1235 Mks 1B & 1D, SPE1236 Mks 1B & 1D SPE1237 Mks 1B & 1D | 1971 |
| | -0452-1 | Fin Tank Transfer Pump Type 7603 Mk1 Plessey Aero Ltd Pt No 568-1-25191-001 | Feb 82 |
| | -0452-3 | Plessey Pump Assy Fuel Type 7603 Mk 1 | Sep 80 |
| | -0452-6 | Fin Tank Transfer Pump Type 7603 Mk 1 Plessey Aerospace Ltd Pt No 568-1-25191-001 | Feb 82 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|---------------------|-------------|--|--------|
| 113E-cont | | | |
| -0453-6 | -0453-6 | Fuel Booster Pump Hobson Type 605 Mk 1, & Canister Type 606 Mk 1 | Seb 89 |
| -0458-1 | | Motorised Air Pump Rotax Type N184434-RG19140 | - |
| -0458-6 | | Motorised Air Pump Rotax Type N184434-RG19140 | - |
| -0459-1 | | Motorised Air Pump Lucas Type MAP101 | - |
| -0459-6 | | Motorised Air Pump Lucas Type MAP101 | - |
| -0460-3A6 | | Pump Fuel Plessey Type 6903 | Aug 76 |
| -0461-6 | | Pump Fuel Plessey Type SPE1007 Series | Jul 75 |
| -0462-2 | | Pump Fuel Plessey Type PDC20 Mk 2 | - |
| -0462-6 | | Pump Fuel Plessey Type PDC20 Mk 2 Inverted Flight Valve Chamber | - |
| -0464-13A6 | | Fuel Pump Bronzavia Pt Nos C11BA0101 & C11BA0102 | Jul 78 |
| -0465-136 | -0465-136 | Fuel Pump Bronzavia Pt No C11A0301 Ref No 505UE/10374 | - |
| -0467-13A6 | | Fuel Pump Intertechnique | - |
| -0468-13A | | Pump Fuel Transfer Type 2052B Intertechnique Pt No 205097 | Dec 83 |
| -0469-13A6 | | Pump Fuel Transfer Plessey Type 6902 Mk 4 | Mar 79 |
| -0471-6 | | Pump Fuel Plessey Element Type 7010 & Cannister Type 7011 | Feb 74 |
| -0472-13 | | Pump Fuel Double-Ended GEC Type 7202 General & Technical Information Parts Catalogue & Related Information | - |
| -0473-13A | | Electro-Pump Microturbo Type 007-08C | Dec 74 |
| -0474-123A | | Fuel & Oil Pump Microturbo Pt No 0470800 | Apr 78 |
| -0475-16 | | Pump Fuel Adel Type 70373 | May 74 |
| -0476-13A6 | -0476-13A6 | Fuel Pump & Mounting Ring Lucas Pt No CHA-745-100 | - |
| -0477-16 | | Pump De-Icing Weldon Type 105B | Mar 75 |
| -0478-1 | | Pump De-Icing TKS Type XA9500 Series | Mar 74 |
| -0479-5F Cover 1 | | Pumps Electric | Dec 74 |
| -0479-5F Cover 2 | | Pumps Electric | - |
| | -0480-3 | Intertechnique Pump DC Emergency | Aug 82 |
| -0482-6 | | Pump Fuel Plessey Type SPE2437 Mk 1 | Nov 75 |
| | -0482-6 | AC Fuel Transfer Pump Secondo Mona S.p.A. Pt No 60-931 | Jul 82 |
| | -0483-3 | Seconda Mona Pump AC Fuel Transfer | Jun 81 |
| -0483-6 | | AC Fuel Transfer Pump Seconda Mona S.p.A. Pt No 60-931 | Mar 83 |
| | -0483-3 | AC Fuel Transfer Pump Seconda Mona S.p.A. Pt No 60-931 | Mar 83 |
| -0484-3A6 | | Inverted Flight Valves Plessey Type BP21/F Mk 4 & BP26 Mk 2 | May 76 |
| | -0485-1 | DE Fuel Boost Pump, Type 7100 Mk 3, Plessey Co Ltd Pt No 568-1-24730-003 | Nov 83 |
| | -0485-3A | Plessey Pump Double Ended Boost Parts Catalogue | Feb 86 |
| | -0485-3B | Plessey Pump Double Ended Boost Parts Catalogue | Aug 86 |
| -0485-3 | | Plessey Pump Double Ended Boost (Type 7100 Mk 3) | Nov 80 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113E-cont | | | |
| -0485-3B | | Plessey Pump Double Ended Boost | Aug 86 |
| -0485-6 | | DE Fuel Boost Pump Type 7100 Mk 3 Plessey Co Ltd Pt No 568-1-24730-003 | Nov 84 |
| -0490-6 | | Pump Fuel Plessey Type PAC100 Mk 3 | Jul 76 |
| -0492-6 | | Pump Fuel Plessey Type PDC 1001 Mks 1 & 3 | Dec 76 |
| -0494-6 | | Pump Fuel Plessey Type PUL Mks 4 & 5 | Dec 76 |
| -0495-13A6 | -0495-13A6 | Fuel Pump Intertechnique Pt No 2180F | - |
| -0496-13A6 | -0496-13A6 | Fuel Pump Bronzavia Pt No CIZ LA0102 | - |
| -0497-16 | -0497-16 | Ignition Micropump | - |
| -04100-3A6 | | Pump Fuel Motor Operated APU Pt No RG 15150 G Lear Siegler INC Pt No 114P4010-1 Boeing Vertol Co | Jul 82 |
| | -04102-1 | AC Single Ended Transfer Pump Seconda Mona S.p.A. Pt No SM 2265 | Jun 83 |
| | -04102-3 | Seconda Mona - Pump AC Transfer Single ended | Jul 90 |
| -04103-6 | | AC Single Ended Transfer Pump Seconda Mona S.p.A. Pt No 2265 | Jun 83 |
| -04103-36 | | Fuel Booster Pump Pt No 568-1-25300-004 | Nov 89 |
| -04105-123A | | Fuel Booster Pump Intertechnique 228-032 | May 88 |
| -04108-1 | | Submerged Booster Pump Models TB012200, TB102200-2, XTB102200, 102200-3, TB102200-3B (Thomson Ramo Woolridge) | Nov 90 |
| -04108-3 | | Submerged Booster Pump Models TB102200-3, TB102200, XTB102200, 102200-3, TB102200-3 (Thomson Ramo Woolridge) | Nov 90 |
| -04109-13 | | Motor Pump Assembly P/N 10470-5 (Task Corporation) | Nov 90 |
| -0501-16 | | Starter Lucas Aerospace Type C12507 Incorporating Motor Type C14202 | - |
| -0501-3A | | Starter Motor Rotax Type C12507 (Starter Motor CH202, Gearbox ZA14601) | 1968 |
| -0503-136 | | Starter Motors Lucas Aerospace Type C14200 Series | Nov 83 |
| -0504-136 | | Starter Motor Lucas Aerospace Type C5109 | Nov 83 |
| -0505-1 | | Starter Motor Rotax Type C6800 Series | - |
| -0505-3A | | Starter Motor Rotax Type C6800 Series | - |
| -0505-6 | | Starter Motor Rotax Type C13500 Series | - |
| -0506-2 | | Starter Motor Rotax Type C13500 Series | - |
| -0508-16 | | Starter Motor Lucas Aerospace Type C1247/2 | Nov 75 |
| -0509-1236 | | Electric Motor Microturbo Pt No 0470100020 | Mar 85 |
| -0510-13A6 | | Starter Motor Plessey Type C3616A-1 (CZ75300), C3616A-3 (4CZ93552) & C3616A-6 (501-1-06675) | - |
| -0511-16C | | Starter Bendix Type 756-22-E | - |
| -0512-1 | | Starter Motor Rotax Type C13102 | 1967 |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| -0512-3A | | Starter Motor Rotax Type C13102 | - |
| -0512-6 | | Starter Motor Rotax Type C13102 | 1967 |
| -0513-3A | | Starter Motor Rotax Type C14204 | - |
| -0514-13 | | Starter Motors Lucas Aerospace Types C3305 & C3306 | Nov 83 |
| -0515-3A | | Starter Motors Rotax Type C1200 Series | - |
| -0517-1 | | Starter Motor Rotax Type C8601 | 1967 |
| -0517-6 | | Starter Motor Rotax Type C8601 | - |
| -0519-3A | | Starter Motor Rotax Type C6204 | 1967 |
| -0519-13 | | Starter Motor Lucas Aerospace Type C6204 | Nov 83 |
| -0520-3A | | Starter Motor Rotax Type C4703 | - |
| -0521-3A | | Starter Motors Rotax Type C4600 Series | 1967 |
| -0522-1 | | Motorized Air Pump Lucas (Starting System) Type MAP100 .. | 1967 |
| -0524-16 | | Starter Motors Plessey Types C2612A/2 & 3, 501-1-07600 & 07650 | 1969 |
| -0525-1 | | Starter Motor Lucas Aerospace Type C16702 | Apr 77 |
| -0525-6 | | Starter Motor Rotax Type C16702 | Nov 76 |
| -0526-13A | | Starter Motor Lucas Aerospace Type C0624 | Nov 76 |
| -0526-6 | | Starter Motor Rotax Ref No 37F/4508 Type C0624 | - |
| -0527-13 | | Starter Motor Lucas Aerospace Type C10905 | Nov 83 |
| -0527-6 | | Starter Motor Rotax Type C10905 | - |
| -0530-13A | | Engine Starter Societe Electrotechnique de Boulogne - Billancourt (SEB) Pt No 1028B | May 79 |
| | -0531-1 | APU Starter Motor Klockner Humboldt Deutz Pt No C16505 .. | Aug 83 |
| | -0531-3 | K.H.D Starter Motor | Mar 81 |
| -0531-6 | | APU Starter Motor Klockner Humboldt Deutz Pt No C16505 .. | Sep 84 |
| -0532-1236 | | Starter Motor Lucas Aerospace Type C16503 | Nov 83 |
| -0533-1 | | Starter Motor Eclipse Pioneer Type 915-3F | Mar 74 |
| -0534-1 | | Starter Motor Eclipse Microturbo Type 007-01-02B & 007-01-006 | May 81 |
| -0536-16 | | Starter Motor Lucas Aerospace Type C4703 | Nov 75 |
| -0537-1 | | Starter Motor Prestolite Type MHB400 1R | Jan 77 |
| -0700-5F | | Winches Loading Airborne Electric General Information | Sep 72 |
| -0701-5F | | Winch Cargo Loading Pt No FLW3500-60 (Hawker Siddeley Dynamics) | Jun 73 |
| -0702-126 | | Aircraft Winch Heavy Duty | Mar 84 |
| -0702-3A | | Heavy Duty Winch Pt No HU 01/1310 | Jul 85 |
| -0702-5F | | Aircraft Winch Heavy Duty (HSA) Pt No YEU/71/1 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113F | | | |
| -0001-1 | | Conversion Procedure & Table for Chrome Alumel | - |
| -0002-1 | -0002-1 | Solenoid Actuators Lighting and Braking Control Equipment .. | - |
| -0101-16 | | Actuating Solenoids Rotax Type D5300 Series | 1966 |
| -0102-13A | | Solenoid Valves Teddington Type FAW/A Series | - |
| -0102-6 | | Solenoid Valves Teddington Type FAW/A Series | 1972 |
| -0104-13A | | Solenoid Valve Dunlop Pt No ACM25760 | Aug 68 |
| -0105-1 | | Solenoid Stanley Type 6N/3877 | 1969 |
| -0106-1 | | High Pressure Switch Anti-Dribble Valve & Solenoid Valve .. | - |
| -0107-1 | | Solenoid Unit Cannon Type 11512 | - |
| -0111-1 | | Solenoid Units (Dowty) | Jun 81 |
| -0112-1 | | Pressure Switch BF Goodrich Type 1D-1194-1 | Mar 74 |
| -0113-1 | | Air Bleed Valve Solenoid Control Valve | Jun 77 |
| -0201-16 | | Landing Lamp, Grimes Types, G3800A/3 L&R, 17Z & 18Z/10348 | Aug 70 |
| -0203-13A | -0203-13A | Grimes Anti-Collision Lamps Rotating Lamps Type | - |
| -0203-6 | -0203-6 | Anti-Collision Lamps Grimes Rotating Lamps | - |
| -0204-13 | | Exit Light Plessey Pt No 614-1-03270 & Emergency Light Pt No 614-1-03460 | Mar 82 |
| -0204-2 | | Exit Light Plessey pt No 614-1-03460 & Emergency Light Pt No 614-03470 | Sep 72 |
| -0205-1 | | Lighting Unit GEC Type 1E/110/6589/1 | - |
| -0206-1 | | Control Units Phillips Types FA1620/S/MS & FA1650/S/MS. Invertor Phillips Type FA1636 & Ballast Unit Type FA1637 .. | - |
| -0207-1 | | Step Lights Thorn Types CF105 & 106 | - |
| -0208-6 | | Anti Collision Lamps Grimes Type G9950 - Series Repair & Reconditioning Instructions | Mar 92 |
| -0208-13 | | Anti Collision Lamps Grimes Type G9950 Series General & Technical Information Illustrated Parts Catalogue .. | Mar 92 |
| -0208-13A | | Anti-Collision Lamps Grimes Type G9950 Series | - |
| -0208-6 | | Anti-Collision Lamps Grimes Types G9950-1, G9950-4, G9950-11 & G9950-13 | - |
| -0209-1 | | Lamps Taxying & Floodlight Type A | - |
| -0210-16 | | Retractable Landing Lamp Harley Type 11 Series | - |
| -0211-1 | | Landing Lamps Harley Type 6 | - |
| -0212-1 | | Floodlights Harley Type 4 Mk 4 | - |
| -0214-1 | | Floodlights Harley Type 11 RLD | - |
| -0215-1 | | Cockpit Lighting Unit Page Engineering Type C5900 | - |
| -0216-136 | | Landing Lamp GEC Type 8SBR Mk1A | - |

SUB-GROUP 113E

ROTARY CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113E-cont | | | |
| -0512-3A | | Starter Motor Rotax Type C13102 | - |
| -0512-6 | | Starter Motor Rotax Type C13102 | 1967 |
| -0513-3A | | Starter Motor Rotax Type C14204 | - |
| -0514-13 | | Starter Motors Lucas Aerospace Types C3305 & C3306 | Nov 83 |
| -0515-3A | | Starter Motors Rotax Type C1200 Series | - |
| -0517-1 | | Starter Motor Rotax Type C8601 | 1967 |
| -0517-6 | | Starter Motor Rotax Type C8601 | - |
| -0519-3A | | Starter Motor Rotax Type C6204 | 1967 |
| -0519-13 | | Starter Motor Lucas Aerospace Type C6204 | Nov 83 |
| -0520-3A | | Starter Motor Rotax Type C4703 | - |
| -0521-3A | | Starter Motors Rotax Type C4600 Series | 1967 |
| -0522-1 | | Motorized Air Pump Lucas (Starting System) Type MAP100 .. | 1967 |
| -0524-16 | | Starter Motors Plessey Types C2612A/2 & 3, 501-1-07600 & 07650 | 1969 |
| -0525-1 | | Starter Motor Lucas Aerospace Type C16702 | Apr 77 |
| -0525-6 | | Starter Motor Rotax Type C16702 | Nov 76 |
| -0526-13A | | Starter Motor Lucas Aerospace Type C0624 | Nov 76 |
| -0526-6 | | Starter Motor Rotax Ref No 37F/4508 Type C0624 | - |
| -0527-13 | | Starter Motor Lucas Aerospace Type C10905 | Nov 83 |
| -0527-6 | | Starter Motor Rotax Type C10905 | - |
| -0530-13A | | Engine Starter Societe Electrotechnique de Boulogne - Billancourt (SEB) Pt No 1028B | May 79 |
| | -0531-1 | APU Starter Motor Klockner Humboldt Deutz Pt No C16505 .. | Aug 83 |
| | -0531-3 | K.H.D Starter Motor | Mar 81 |
| -0531-6 | | APU Starter Motor Klockner Humboldt Deutz Pt No C16505 .. | Sep 84 |
| -0532-1236 | | Starter Motor Lucas Aerospace Type C16503 | Nov 83 |
| -0533-1 | | Starter Motor Eclipse Pioneer Type 915-3F | Mar 74 |
| -0534-1 | | Starter Motor Eclipse Microturbo Type 007-01-02B & 007-01-006 | May 81 |
| -0536-16 | | Starter Motor Lucas Aerospace Type C4703 | Nov 75 |
| -0537-1 | | Starter Motor Prestolite Type MHB400 1R | Jan 77 |
| -0700-5F | | Winches Loading Airborne Electric General Information | Sep 72 |
| -0701-5F | | Winch Cargo Loading Pt No FLW3500-60 (Hawker Siddeley Dynamics) | Jun 73 |
| -0702-126 | | Aircraft Winch Heavy Duty | Mar 84 |
| -0702-3A | | Heavy Duty Winch Pt No HU 01/1310 | Jul 85 |
| -0702-5F | | Aircraft Winch Heavy Duty (HSA) Pt No YEU/71/1 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113F | | | |
| -0001-1 | | Conversion Procedure & Table for Chrome Alumel | - |
| -0002-1 | -0002-1 | Solenoid Actuators Lighting and Braking Control Equipment .. | - |
| -0101-16 | | Actuating Solenoids Rotax Type D5300 Series | 1966 |
| -0102-13A | | Solenoid Valves Teddington Type FAW/A Series | - |
| -0102-6 | | Solenoid Valves Teddington Type FAW/A Series | 1972 |
| -0104-13A | | Solenoid Valve Dunlop Pt No ACM25760 | Aug 68 |
| -0105-1 | | Solenoid Stanley Type 6N/3877 | 1969 |
| -0106-1 | | High Pressure Switch Anti-Dribble Valve & Solenoid Valve .. | - |
| -0107-1 | | Solenoid Unit Cannon Type 11512 | - |
| -0111-1 | | Solenoid Units (Dowty) | Jun 81 |
| -0112-1 | | Pressure Switch BF Goodrich Type ID-1194-1 | Mar 74 |
| -0113-1 | | Air Bleed Valve Solenoid Control Valve | Jun 77 |
| -0201-16 | | Landing Lamp, Grimes Types, G3800A/3 L&R, 17Z & 18Z/10348 | Aug 70 |
| -0203-13A | -0203-13A | Grimes Anti-Collision Lamps Rotating Lamps Type | - |
| -0203-6 | -0203-6 | Anti-Collision Lamps Grimes Rotating Lamps | - |
| -0204-13 | | Exit Light Plessey Pt No 614-1-03270 & Emergency Light Pt No 614-1-03460 | Mar 82 |
| -0204-2 | | Exit Light Plessey pt No 614-1-03460 & Emergency Light Pt No 614-03470 | Sep 72 |
| -0205-1 | | Lighting Unit GEC Type 1E/110/6589/1 | - |
| -0206-1 | | Control Units Phillips Types FA1620/S/MS & FA1650/S/MS. Invertor Phillips Type FA1636 & Ballast Unit Type FA1637 .. | - |
| -0207-1 | | Step Lights Thorn Types CF105 & 106 | - |
| -0208-6 | | Anti Collision Lamps Grimes Type G9950 - Series Repair & Reconditioning Instructions | Mar 92 |
| -0208-13 | | Anti Collision Lamps Grimes Type G9950 Series General & Technical Information Illustrated Parts Catalogue .. | Mar 92 |
| -0208-13A | | Anti-Collision Lamps Grimes Type G9950 Series | - |
| -0208-6 | | Anti-Collision Lamps Grimes Types G9950-1, G9950-4, G9950-11 & G9950-13 | - |
| -0209-1 | | Lamps Taxying & Floodlight Type A | - |
| -0210-16 | | Retractable Landing Lamp Harley Type 11 Series | - |
| -0211-1 | | Landing Lamps Harley Type 6 | - |
| -0212-1 | | Floodlights Harley Type 4 Mk 4 | - |
| -0214-1 | | Floodlights Harley Type 11 RLD | - |
| -0215-1 | | Cockpit Lighting Unit Page Engineering Type C5900 | - |
| -0216-136 | | Landing Lamp GEC Type 8SBR Mk1A | - |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0217-16 | | Anti-Collision Lamps, Grimes Types G9220-1, G9220-3, G9220-4, 43325, 43325-16870 and 44400A Gen & Tech Info Repair & Reconditioning Instructions | Apr 92 |
| -0218-16 | -0218-16 | Anti-Collision Lamps Grimes Types 44410-1-24 & 44410-2-24 | - |
| -0219-1 | | Wing Tip Navigation Lamp High Intensity Thorn Type | 1968 |
| -0220-1 | | Tail Navigation Lamps Thorn Types 80/10.0200 & 80/10/1623 | - |
| -0221-13A | | Landing & Search Lamp Grimes Type G6250-1 | - |
| -0222-1 | | Lamp Cockpit Floodlight Type D | Mar 76 |
| -0223-1 | -0223-1 | Single Miniature Pillar Lamps Thorn | - |
| -0223-2 | | Single Miniature Pillar Lamps Thorn Types | Jun 75 |
| -0224-1 | -0224-1 | Miniature Pillar Lamp Bridges Thorn Types | - |
| -0224-2 | | Miniature Pillar Lamp Bridges Thorn Types | Sep 74 |
| -0225-1 | | Passenger Individual Lamps GEC Types 1E/61274 & 1E/6302 | - |
| -0227-1 | | Navigation Lamps | - |
| -0228-1 | | Signalling Lamps | - |
| -0229-1 | | Navigation Lamp Tail Type A | - |
| -0230-1 | | Fuselage Navigation Lamp Thorn Type FNL/50 | - |
| -0233-13 | -0233-13 | Light Assembly Search & Landing Grimes Type 41850A, 41850A-8 & 41850A-4580 | Mar 85 |
| -0234-13A | | Light Assembly Rotating Beacon Grimes Types G6965-11 & G6965-31 | 1969 |
| -0235-1 | | Warning Lamps Rotax Type H2700 Series | 1968 |
| -0236-1 | | Cockpit Lamp Type C No 2 | 1968 |
| -0239-13A | | Wander Lamp Grimes Type 36170-1 | - |
| -0240-13 | | Anti-Collision Lamp Grimes Type G-9325A-3 & G9325A-5 | Dec 82 |
| -0240-6 | | Aircraft Rotating Warning Lamp Grimes Type G-9325A-3 & 9325A-5 | Feb 83 |
| -0241-1A | | Searchlight Strong Type AN/AVQ-2C | - |
| -0241-6 | | Searchlight Strong Type AMN/AVQ-2C | Oct 80 |
| -0242-1 | | Lighting Control Units GEC Types 1E2/6566 & 1E2/6570 Series | 1970 |
| -0243-13A | | Lamp Landing Plessey Type 500 Mks 1-1 & 1-3 | - |
| -0244-1 | | Control Unit Type AWE149 & Control Box Type AWE143/6 | - |
| -0245-1 | | Landing Lamp Plessey Harley Type II Mk 11 AWA | Nov 74 |
| -0246-1 | | Landing Lamp Plessey Type L | - |
| -0247-1 | | Life Preserver Lamp Sea Activiated Type B | - |
| -0249-136 | | Landing Lamp Teleflex - Syneravia Pt No PEO-600-3 Ref No 505CX/2650992 | Sep 84 |
| -0250-13A | | Anti-Collision Lamp SGE Pt No 32-76-5 Ref No 505CX/7583 | - |
| -0251-13A | -0251-13A | Landing Lamp Teleflex - Synervia Pt No PES46-A3-250 Ref No 505CX/7658 | - |
| -0252-13A | | Control Unit ABADIE Pt No 23.171 | Jan 85 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| -0253-13A6 | | Power Supply Unit ABADIE Pt No 18420-1 | Mar 76 |
| -0254-1 | -0254-1 | Flasher Unit ECE Pt No 110RC1702 Ref No 505C2/8889 | - |
| -0255-13A6 | | Lamp, Anti-Collision, Plessey Pt No 614-1-04670-0001 & 614-1-04670-002 | Jul 78 |
| -0256-13A | | Lamp Units ABADIE Pt Nos 10-2250-2B, 10-2250-3B, 10-2250-2T, 10-2250-122-1, 10-2250-322-1A & 10-2250-422-1A | Aug 77 |
| -0257-13 | | Wander Lamp Grimes Pt No 15-0369-1 & D-6810A | Jan 82 |
| -0258-13A | | Units Resistance Dimming PM Labinal Pt Nos 13.326 & 13.326-1 | Sep 75 |
| -0259-16 | | Plastek Panels | Feb 75 |
| -0260-1 | | Anti-Collision Lamp Plessey Model ACB70-31 Pt No 614-1-04681-002 | Jun 76 |
| -0261-16 | | Landing Lamp Lucas Aerospace Type H260/1 | Sep 74 |
| -0271-1 | -0271-1 | Landing Lamp Plessey Harley Type 6 Mk 4 | - |
| | -0273-1 | Low Intensity Strobe Light System HELLA/WM1 KG | Feb 86 |
| | -0276-1 | Pilots Internal Lights Panel British Aerospace PLC. Pt No P913832-405/409/411/413/415/417 | Mar 84 |
| -0280-13 | -0280-13 | Anti-Collision Lamp Hueck Pt No 2LA-001-624-00 | - |
| -0282-15F | -0282-15F | Nightsun Searchlight System Type SX16C General & Technical Information (-1) Bay Maintenance Schedule (-5F) | Jun 93 |
| -0282-2 | | Nightsun Searchlight System Type SX16C | Aug 81 |
| -0282-3 | | Nightsun Searchlight Systems Type SX-16C 5855-99-623-3968 and Type SX-16C Mk2 5855-99-641-9531 Illustrated Parts Catalogue | Dec 91 |
| | -0282-3 | Nightsun Searchlight System Type SX-16C. Illustrated Parts Catalogue | Mar 88 |
| -0283-13A | | Lamp Plessey Type 5H/500 Mk 9 Pt No 614-1-04684 | Feb 79 |
| -0284-13 | -0284-13 | High Intensity Strobe Light System | - |
| -0284-2 | | High Intensity Strobe Light System | Mar 90 |
| -0284-6 | | High Intensity Strobe Light System | Oct 84 |
| -0285-1 | | Flasher Unit - Exterior Light Pt No D6270-1 | Jul 79 |
| -0286-1 | | Flasher Unit Exterior Light Pt No DC10716A | Jul 79 |
| | -0287-1 | Lamps Dimming Unit British Aerospace Plc, Pt No A911145-403 | Feb 88 |
| | -0287-3A | British Aerospace Box Assy Dimmer (126VE) | Nov 93 |
| | -0287-3B | British Aerospace Box Assy Dimmer | Feb 85 |
| | -0287-3C | BAe Bracknell Box Assy Dimmer 226VE Structure | Aug 88 |
| | -0287-10 | Lamps Dimming Unit British Aerospace plc Pt No A911145-403, P917261-401/403/405, P916845-403/405/407, P970030-401, P970031-401 | Feb 94 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0288-13A | | Lamp Emergency Exit Pt No 10-0055 Grimes MFG Co Pt No 114ES247-2/4 Boeing Helicopters, General and Technical Information, Illustrated Parts Catalogue | Nov 81 |
| -0289-13A | | Light Balance Unit Installation Pt No 414E2155-3 Boeing Vertol Co | Dec 81 |
| -0290-13A | | Light Balance Unit Assembly Pt No 414E 2152-3 Boeing Vertol Co | Nov 81 |
| -0291-13A6 | | Lamp Retractable Landing Pt No A07ES100-1 Grimes MFG Co | Jan 82 |
| -0292-13A | | Light Balance Unit Assembly Pt No 414E2156-2 Boeing Vertol Co | Dec 81 |
| -0293-13A | | Light Balance Unit Assembly Pt No 414E2152-3 Boeing Vertol Co | Dec 81 |
| -0294-13A6 | | Lightning Control Unit Pt No 180-59193-1 Boeing Seattle Pt No 414ES208 Boeing Vertol Co | Apr 83 |
| -0295-13 | | Lamp Aircraft Cabin Type DHS 1101 | Mar 82 |
| -0296-13 | | Lighting Relay Control Box Flight Refuelling Ltd Pt No 43321860 | Dec 82 |
| -0297-1 | | Lamp Cockpit and Inspection Thorn Type 80-10-1200 | Feb 90 |
| -0298-13 | | Dimmer Unit Part No E445-01-001 | - |
| -0299-136 | | Electric Light Control A05A198-1 & /2 | Sep 84 |
| -02100-2(R)1 | | Transilluminated Panels | Jan 95 |
| -02100-13 | | Transilluminated (Plasteck) Panels PC and NP Series | Apr 94 |
| | -02104-136 | Rotary Actuator | Dec 86 |
| -02109-13 | | Interior Lights Controller Panel Assembly Pt No 75A871504-1009 | Dec 86 |
| -02110-13 | | Interior Lights Control Panel Assemy Pt No 75A800050-1007 .. | Jan 86 |
| -02111-12 | | Indicating Light Panels Oppenheimer Type MD 80001 Series General & Technical Information Gen Order & Modification .. | Feb 87 |
| -02112-1 | | Lamp Landing HELLA 1X4005078 Series | Jun 90 |
| -02113-3 | | Handlight Assembly Model EFI | Mar 88 |
| -02114-1 | | Power Supply Anti Collision Light HELLA 8ES005-421-01 ... | Jun 90 |
| -02115-13 | | Dual Mode Searchlight (Grimes Pt No45-0253-1) | Feb 92 |
| -0301-1 | | Temperature & Engine Speed Control Amplifier Elecma Types VT853/1 & VT853/2 | Jun 76 |
| -0301-3A | | Temperature & Engine Speed Control Amplifier Elecma Types VT853/1 & VT853/2 | Oct 76 |
| -0301-6 | | Temperatur & Engine Speed Control Amplifier Elecma Types VT853/1 & VT853/2 | Jul 76 |
| -0302-1 | | Bleed Valve Control Unit Ultra Type A4, A30 | 1972 |
| -0306-1 | | Speed Sensitive Switch HSA Type V125114 | - |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| -0308-1 | | Temperature & Engine Speed Control Amplifier Elecma Types VT1153 & VT1153/1 | Jul 76 |
| -0308-3A | | Temperature & Engine Speed Control Amplifier Elecma Types VT1153 & VT1153/1 | Jul 76 |
| -0308-6 | | Temperature & Engine Speed Control Amplifier Elecma Types VT1153 & VT1153/1 | Jul 76 |
| -0309-1 | | Temperature & Engine Speed Control Amplifier - Elecma Type VT1353 | Jul 79 |
| -0310-3 | | BGT Pyrometer Turbine Blade AMP Pt No 852-50-000000000-1C | Jun 80 |
| | -0310-6 | BGT TBT AMP Pt No 852-50-000000000 - 1D | Jan 83 |
| | -0311-3 | AEG Telefunken Oil/Fuel Thermometer Amplifier Pt No V22-645-7 | Apr 80 |
| | -0311-6 | AEG Telefunken Oil/Fuel Thermometer Amplifier Pt No V22-645-7 | Dec 81 |
| -0312-1B | | ATE Tornado Aircraft LF Station LFU Adapter | Sep 86 |
| | -0312-3 | Lucas Aerospace Ltd Main Engine Control Unit Pt No 220 1A1A1A | May 80 |
| | -0313-3 | VDO Comp Overspeed Gov Amplifier Pt No DL 201-75 | Sep 80 |
| | -0313-6 | VDO Comp Overspeed Gov Amplifier | Feb 82 |
| | -0314-3 | Vibro-Meter Jet Pipe Resonance Amplifier Pt No 214-300-000 .. | May 80 |
| | -0314-6 | Vibro-Meter Jet-Pipe RES AMP Pt No 241-300-000-101 | Dec 82 |
| | -0315-1 | Control Unit Electronic Main Engine Pt No CUE 300/1C/3B Lucas Aerospace | Sep 81 |
| | -0315-3 | Lucas Aerospace Ltd Control Unit Electronic | Oct 88 |
| -0315-6AA | | CUE 300/1C 1C/3B | Jul 83 |
| -0315-6AB | | CUE 300 Chapter 0 Series | - |
| -0315-6AC | | Chap 1 300/1C 1C/3B Card 1/7 (275) | Jul 83 |
| -0315-6AD | | Chap 2 CUE 300/1C 1C/3B Card 2/8 (229) | Jul 83 |
| -0315-6AE | | Chap 3 CUE 300/1C 1C/3B Card 3/9 (215) | Jul 83 |
| -0315-6AF | | Chap 4 CUE 300/1C 1C/3B Card 4/10 (218) | Jul 83 |
| -0315-6AG | | Chap 5 CUE 300/1C 1C/3B Card 5/11 (212) | Jul 83 |
| -0315-6AH | | Chap 6 CUE 300/1C 1C/3B Card 6/12 (209) | Jul 83 |
| -0315-6AJ | | Chap 7 CUE 300/1C 1C/3B Card 13 (220) | Jul 83 |
| -0315-6AK | | Chap 8 CUE 300/1C 1C/3B Card 14 (219) | Jul 83 |
| -0315-6AL | | Chap 9 CUE 300/1C 1C/3B Card 15 (222) | Jul 83 |
| -0315-6AM | | Chap 10 CUE 300/1C 1C/3B Card 16 (225) | Jul 83 |
| -0315-6AN | | Chap 11 CUE 300/1C 1C/3B Card 17 (211) | Jul 83 |
| -0315-6AP | | Chap 12 CUE 300/1C 1C/3B Card 18 (210) Pt No 77750804 .. | Jul 83 |
| -0315-6AQ | | Chap 13 CUE 300/1C 1C/3B Card 19 (226) | Jul 83 |
| -0315-6AR | | Chap 14 CUE 300/1C 1C/3B Card 20 (221) | Jul 83 |
| -0315-6AS | | Chap 15 CUE 300/1C 1C/3B Card 21 (227) | Jul 83 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| -0315-6AT | | Chap 16 CUE 300/1C 1C/3B Card 22 (224) | Jul 83 |
| -0315-6AU | | Chap 17 CUE 300/1C 1C/3B ML1 (214) | Dec 83 |
| -0315-6AV | | Chap 18 CUE 300/1C 1C/3B ML2 (201) | Dec 83 |
| -0315-6AW | | Chap 19 CUE 300/1C 1C/3B ML3 (213) | Dec 83 |
| -0315-6AX | | Chap 20 CUE 300 Module ML4 (203) Part Nos 77751522, 77751530, 77751956, 77751957, Repair and Recon Instrs ... | Dec 83 |
| -0315-6AY | | Chap 21 CUE 300/1C 1C/3B ML5 (259) | Dec 83 |
| -0315-6AZ | | Chap 22 CUE 300/1C 1C/3B Board BD1 (470) Pt Nos 77752591 & 77752492 | Apr 84 |
| -0315-6BA | | Chap 23 CUE 300/1C 1C/3B BD2 (271) | Dec 83 |
| -0315-6BB | | Chap 24 CUE 300/1C 1C/3B BD3 (272) | Dec 83 |
| -0315-6BC | | Chap 25 CUE 300 LOOM LM1 Part Nos 77751599 & 77751897 Repair & Reconditioning Instructions | May 84 |
| -0315-6BD | | Chap 26 CUE 300 Board BD7 (267) Pt No 77750941 | Feb 86 |
| -0315-6BE | | Chap 27 CUE 300 Board BD8 (268) Pt No 77750935 | Feb 86 |
| -0315-DIA | | CUE 300 Wiring Loom | Jun 84 |
| -0315-DIB | | CUE 300 Wiring Loom | Jun 84 |
| -0315-DIC | | CUE 300 Wiring Loom | Jun 84 |
| -0315-DID | | CUE 300 Wiring Loom | Jun 84 |
| -0315-DIE | | CUE 300 Wiring Loom | Jun 84 |
| -0315-DIF | | CUE 300 Wiring Loom | Jun 84 |
| | -0316-3 | Graviner Amplifier Afterburner Ignition Detection Pt No 53813-056 | May 80 |
| | -0317-3 | VDO Vibration Warning Amplifier Pt No WA 202-75 | Apr 80 |
| | -0318-3 | Plessey Aerospace Ltd Turbine Pressure Ratio Amplifier Pt No 700-1-19323-000 | Mar 94 |
| | -0318-6 | Amplifier Turbine Pressure Ratio Plessey Pt No 700-1-19323-000 | Sep 94 |
| | -0319-1 | Control Box Positioning Remote Pt No SYLZ7561-3 (Pre Mod 46) Pt No SYLZ7561-4 (Pre Mod 46) Barber Colman Co | Jun 83 |
| | -0320-1 | Quadrant Pt No 375907-1 Bendix Corp Pt No 414ES82-1 Boeing Vertol Co | Jan 82 |
| | -0321-1 | Control Box (NI) Pt No 1964343-1 Bendix Corp Pt No 114ES283-1 Boeing Vertol Co | Jan 82 |
| | -0322-3 | VDO Vibration Warning Amplifier Pt No WA202-76 | Oct 93 |
| | -0322-6 | VDO Vibration Warning Amplifier Pt No WA202-76 Chaps 1-5 | Jun 82 |
| | -0323-1 | Control Unit Electronic Main Engine, Pt No CUE 400/1A Lucas Aerospace Ltd | Jul 84 |
| | -0323-1B | ATE Tornado Aircraft LF Station Main Engine Control Unit 400 (MECU) WBS OM 2-1-2-1-25 | Apr 87 |
| | -0323-3 | Lucas Aerospace Ltd, Control Unit, Electronic Pt No 400-1A1A | Dec 84 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0323-6AA | | CUE 400/1A-1A Preliminary Material | Mar 85 |
| -0323-6AB | | CUE 400/1A-1A Chapter 0 Series | Mar 85 |
| -0323-6AC | | Chap 1 CUE 400/1A-1A Card CD 1/7 (475) Pt No 77752272 .. | Mar 85 |
| -0323-6AD | | Chap 2 CUE 400/1A-1A Card CD 218 (429) Pt No 77752204 .. | Mar 85 |
| -0323-6AE | | Chap 3 CUE 400/1A-1A Card CD 3/9 (415) Pt No 77752175 .. | Mar 85 |
| -0323-6AF | | Chap 4 CUE 400/1A-1A Card CD 4/10 (418) Pt No 77752545 .. | Mar 85 |
| -0323-6AG | | Chap 5 CUE 400/1A-1A Card CD 5/11 (412) Pt No 77752178 .. | Mar 85 |
| -0323-6AH | | Chap 6 CUE 400/1A-1A Card CD 6/12 (409) Pt No 77752134 .. | Mar 85 |
| -0323-6AJ | | Chap 7 CUE 400/1A-1A Card CD 13 (420) Pt No 77752159 .. | Mar 85 |
| -0323-6AK | | Chap 8 CUE 400/1A-1A Card CD14 (419) Pt No 77752141 .. | Mar 85 |
| -0323-6AL | | Chap 9 CUE 400/1A-1A Card CD15 (422) Pt No 77752157 .. | Aug 85 |
| -0323-6AM | | Chap 10 CUE 400/1A-1A Card CD16 (425) Pt No 77752222 .. | Aug 85 |
| -0323-6AN | | Chap 11 CUE 400/1A-1A Card CD17 (411) Pt No 77752211 .. | Aug 85 |
| -0323-6AP | | Chap 12 CUE 400/1A-1A Card CD18 (410) Pt No 77752195 .. | Aug 85 |
| -0323-6AQ | | Chap 13 CUE 400/1A-1A Card CD19 (426) Pt No 77752323 .. | Aug 85 |
| -0323-6AR | | Chap 14 CUE 400/1A-1A Card CD20 (421) Pt No 77752192 .. | Aug 85 |
| -0323-6AS | | Chap 15 CUE 400/1A-1A Card CD21 (427) Pt No 77752278 .. | Aug 85 |
| -0323-6AT | | Chap 16 CUE 400/1A-1A Card CD22 (424) Pt No 77752138 .. | Aug 85 |
| -0323-6AU | | Chap 17 CUE 400/1A-1A Module ML1 (414) Pt No 77752295 .. | Mar 85 |
| -0323-6AV | | Chap 18 CUE 400/1A-1A Module ML2 (401) Pt No 77752294 .. | Aug 85 |
| -0323-6AW | | Chap 19 CUE 400/1A-1A Module ML3 (213) Pt No 77751518 .. | Mar 85 |
| -0323-6AX | | Chap 20 CUE 400/1A-1A Module ML4 (203) Pt Nos 77751956/7 | Mar 85 |
| -0323-6AY | | Chap 21 CUE 400/1A-1A Module ML5 (459) Pt No 77752577 .. | Aug 85 |
| -0323-6AZ | | Chap 22 CUE 400/1A-1A Board BD1 (470) Pt Nos 77752591/2 .. | Mar 85 |
| -0323-6B | | Chap 23 CUE 400 BD7 (467) Pt No 77752296 | Aug 86 |
| -0323-6BA | | Chap 23 CUE 400/1A-1A Board BD2 (271) Pt No 77751366 .. | Mar 85 |
| -0323-6BB | | Chap 24 CUE 400/1A-1A Board BD3 (272) Pt No 77751441 .. | Mar 85 |
| -0323-6BC | | Chap 25 CUE 400 Loom LM1 Pt No 77752430 Repair and Reconditioning Instructions | Aug 85 |
| -0323-6BE | | Chap 27 CUE 400 Board BD8 (468) Pt No 77752297 | Aug 86 |
| -0323-6BF | | Chap 28 CUE 400/1A-1A Module ML7 (460) Pt No 77752416 .. | Aug 85 |
| | -0325-1 | Digital Engine Control Unit Part No Decu 500/1C IC Lucas Aerospace Ltd | Feb 88 |
| | -0325-3 | Lucas Aerospace Ltd Control Unit Digital Electronic | Apr 88 |
| -0325-6B | | DECU 500 Chapter 0 Series | Aug 88 |
| -0325-6C | | DECU 500 Chapter 1 Power Supply Module ML1 (550) | Aug 88 |
| -0325-6D | | DECU 500 Chapter 2 Power Supply Module ML2 (551) Pt No 777534-32, 77753469, 77753749, 77753622, 77753909 Repair and Reconditioning Instructions | Aug 88 |
| -0325-6E | | DECU 500 Chapter 3 Actuator Drive Module ML3 (552) | Aug 88 |
| -0325-6F | | DECU 500 Chapter 4 RF1 Filter Module ML4 (553) | Aug 88 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0325-6G | | DECU Chap 5 LPC Drives Module ML5 (554) | - |
| -0325-6H | | DECU 500 Chap 6 Potentiometer/Resistor Board Module ML6(556) Pt No 77753311 | Aug 88 |
| -0325-6J | | Chapter 7 DECU 500 Relay Module ML7(557) Pt No 77752828 | Aug 88 |
| -0325-6K | | DECU 500 Chap 8 Motherboard Module ML10(555) | Aug 88 |
| -0326-1 | | Digital Electronic Control Unit Type 0520 KDC-01-0302 | Feb 90 |
| -0326-3 | | Digital Engine Control Assembly | Mar 89 |
| -03229-3 | | Quadrant Condition Control 1680-99-251-7943 & 1680-99-192-1312 | Jul 90 |
| -03230-6 | | Engine Condition Quadrant Pt No MCH-12-1 Logic Sp A Pt No 414ES282-14 Boeing Helicopters | Jul 90 |
| -03230-123 | | Engine Condition Quadrant Pt No MCH 12-1 Logic Sp A Pt No 414ES282-4 Boeing Helicopters | Jul 90 |
| -0402-1 | | Amplifier Unit Smiths Type EC4/4 | 1968 |
| -0403-13A | | Amplifier Unit Ultra Type A497 | - |
| -0404-1 | | Amplifier Unit Ultra Type A601/1 | Sep 69 |
| -0405-13A | | Amplifier Unit Ultra Type A133/1 | Nov 77 |
| -0407-1 | | Engine Control Amplifier Smiths Type 106ECU | - |
| -0407-6 | | Engine Control Amplifier Unit Smiths Type 106ECU/3 | - |
| -0408-13A | | Rotary Actuators Smiths Types 301/RAA1, 301/RAA2, 302/RAA1 & 302/RAA2 | Jul 80 |
| -0408-6 | | Rotary Actuator Smiths Type 302/RAA1 | - |
| -0409-1 | | Speed & Temperatur Control Amplifier Ultra Type A609/N ... | Jun 75 |
| -0410-1 | | Amplifier Unit Smiths Types EC27 & EC27/1 | - |
| -0411-1 | | Amplifier Units Smiths Type EC1/6 & EC1/7 | 1968 |
| -0413-13A | | Amplifier Unit Ultra Type A203 | - |
| -0414-1 | | Amplifier Units Ultra Types A206 & A432 | 1967 |
| -0414-2 | | Amplifier Unit Ultra Types A206 & A432 | Jul 72 |
| -0415-1 | | Amplifier Unit Ultra Type A207 | 1967 |
| -0417-1 | | Amplifier Unit Ultra Type A209 | 1967 |
| -0419-1 | | Amplifier Unit Ultra Type A8A33/2 & Control Ultra Types CU8A37 & CU8A38 | Oct 78 |
| -0419-6 | | Control Unit Ultra Type CU8A38 | Oct 78 |
| -0420-1 | | Engine Control Amplifiers Smith Types 610ECU/1 & 610ECU/2 | Apr 75 |
| -0420-3 | | Amplifier Units 6610-99-634-5875 2995-99-221-8109 | - |
| -0420-6 | | Engine Control Amplifier Smiths Types 610ECU/1 & 610ECU/2 | Apr 75 |
| -0422-13A | | Temperature Limiter Unit Smiths Types 504ECU/1 & 504ECU/2 | - |
| -0422-6 | | Temperature Limiter Unit Smiths Type 504ECU/2 | - |

AP 100Z-0101 AL136
SUB-GROUP 113F

UK RESTRICTED
STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0423-13A6 | | Monitoring Unit Smiths Type 0102KMU/1 | Feb 74 |
| -0424-1 | | Engine Control Amplifier Type 604ECU/1 Series | May 76 |
| -0425-1 | | Auto Trim Amplifier Ultra Type 2A100 | Feb 76 |
| -0426-1 | | Control Unit Type CU8A40 | Mar 81 |
| -0426-6 | | Control Unit Type CU8A40 | - |
| -0428-12 | | Control Amplifier Ultra Type CA5E 46 (5CZ/6342594) | Jun 81 |
| -0429-1 | | JPT/NF Limiter Unit type 510 ECU 9, 510 ECU 10, 510 ECU 13, 510 ECU 14 | Sep 83 |
| -0433-1 | | Speed & Temperature Limiter, Type CA 6E23 | Jul 93 |
| -0501-1 | | Engine Control System Ultra Type 244 | - |
| -0503-1 | | Throttle Control System Ultra Type BAP3 | 1969 |
| | -0504-1 | Front Throttle Box British Aerospace plc Pt No P530350 Series | Aug 94 |
| | -0504-3A | British Aerospace Box Assy Throttle Front | Dec 80 |
| | -0504-3B | British Aerospace Box Assy Throttle Front | Aug 84 |
| | -0505-1 | Rear Throttle Box British Aerospace plc Pt No P530600-403 .. | Jun 94 |
| | -0505-3 | British Aerospace Box Assy Throttle Rear | Dec 80 |
| | -0507-3 | Marconi-Elliott Actuator Autothrottle System | Sep 82 |
| -0601-1 | | Pilots Centralised Warning System (Belfast C Mk 1) | - |
| -0602-1 | | Undercarriage Position Indicator Dowty Type 1050Z | - |
| -0603-16 | | Flasher Unit Page Type C1775 | Dec 66 |
| -0604-1 | | Electric Horns Rotax Types V0200 & V0600 Series | Jun 66 |
| -0605-13A | | Flasher Unit, Page Type C360 & C360A | Mar 80 |
| -0606-1 | | Position Indicator Page Type B2640 & B2650 | - |
| -0607-13A | | Undercarriage Position Indicators Dowty Type 1224Y Series .. | Jun 75 |
| -0608-136 | | Master Control Units Page Type D7070 & D7070 & Indicator Units Page Type D10180 & D13750 | Mar 85 |
| -0610-1 | | Indicators Electro-Magnetic Plessey Types | Mar 94 |
| -0611-1 | | Two Rate Flasher Unit HSA Type V10776 | - |
| -0612-1 | | Cruise Stop Indicator Unit HSA Type 1/V12462 | - |
| -0613-1 | | Pressure Head Heater Failure Detector Unit HSA Type 1/V10989 | - |
| -0614-1 | -0614-1 | Three Position Electro-Magnetic Indicators, Dowty Type 5175Y | - |
| -0615-1 | | Two Position Electro-Magnetic Indicators, Dowty Types 5165Y, 1047Z, & 1245Z | Oct 88 |
| -0616-16 | | Rotation Indicator Ultra Type D928 | - |
| -0617-1 | | Engineers Centralised Warning System (Belfast C Mk 1) | - |
| -0618-1 | | Flasher Units Specto Types A & B | 1968 |
| -0619-16 | | Undercarriage Sensing Unit Rotax Type U3610 | - |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| -0620-1 | | Time Delay (Electronic) Unit Page Type C7500 | - |
| -0621-1 | | Bell Fire Warning Type L2245A | - |
| -0622-1 | | Audible Warning Unit Shipton Type 35 Mk 3 | 1967 |
| -0623-1 | | Cooling Air Failure Warning Units Smiths Types 23FWU/1/350 & 23FWU/3/300 | - |
| -0624-1 | | Rotation & Overspeed Indicator Ultra Type D926 | 1967 |
| -0627-13A | -0627-13A | Warning Lamps Page Engineering Series | - |
| -0628-13A | | Voltage Sensing Unit Rotax Types U3619/2 & U3624/2 | - |
| -0628-2 | | Voltage Sensing Unit Rotax Types U3619/2 & U3624/2 | - |
| -0628-6 | | Voltage Sensing Unit Rotax Types U3619/2 & U3624/2 | - |
| -0628-13 | | Voltage Sensing Unit Lucas Aerospace Type U3619/2 & U3624/2 | - |
| -0629-13A6 | | Electronic Fire Bell STC Type 107-LRU/61B | 1967 |
| -0630-1 | | Generator Failure Warning Unit HSA Type 30/V9900 | 1967 |
| -0632-13A6 | | Central Warning System for Buccaneer Mk 1 & 2 | Jun 67 |
| -0633-1 | | Servo Units Plessey Type 15 | Mar 87 |
| -0635-1 | | Voltage Indicating Unit Lucas Aerospace - Type LPA Form B2M | - |
| -0637-13A6 | | Centralized Warning Panel ECE Pt No 903YO2 | - |
| -0639-1 | | Warning Horn Klaxon Type K2/12215/GD | 1969 |
| -0640-1 | | Indicators Miniature Magnetic Plessey Pt Nos 506-1-06800-013, 434-1-90503-013 & 434-1-90552-013 | - |
| -0641-1 | | Lamp Indicator Flashing Plessey Type 678-1-90030-302 | 1968 |
| -0643-1 | | Central Warning System for Argosy | 1969 |
| -0643-6 | | Central Warning System for Argosy | - |
| -0644-13 | | Indicator Unit Page Type D13530 Series | Mar 83 |
| -0644-6 | | Indicator Unit Page Type D13530 Series | Mar 83 |
| -0645-1 | | Indicator Water Contents Page Type B4900 | 1969 |
| -0646-1 | | Power Failure Warning Unit Pt No 700-1-12260 | Mar 94 |
| -0646-6 | | Power Failure Warning Unit Pt No 700-1-12260 | Mar 94 |
| -0647-1 | | Indicator Control Unit Dowty Rotol Type EIU1/1 | 1969 |
| -0649-1 | | Flacon Electric Beacon Submarine Cables | Jan 75 |
| -0650-1 | -0650-1 | Miniature Electromagnetic Indicators pt Nos 6332/6342 & 6333/6343 | Nov 85 |
| -0651-13 | | Central Warning System for Jet Provost T Mk 3A, 5 & 5A ... | Jul 82 |
| -0651-6 | | Central Warning System for Jet Provost T Mk 5 Types C10000 & D10040 | - |
| -0653-13A | | Position Indicator Undercarriage/Leading Edge Slat/Wing Flap ECE Pt Nos 290-TS-01-Y02 & 290-TS-01-Y03 | Sep 77 |
| -0654-16 | | Master Control Unit Page Type D9650 | Apr 77 |
| -0655-1 | | Flasher Units page Types B1831 & B1833 | 1969 |
| -0657-16 | | Central Warning System for Lightning Mk 3, 5 & 6 Aircraft Page | |

UK RESTRICTED
STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0658-1 | | Central Warning System for Lightning Mk 4 Aircraft | 1970 |
| -0658-6 | | Central Warning System for Lightning Mk 4 Aircraft Indicator Page Type C3890, Flasher & Excitation Unit Page Type C3900 | 1972 |
| | -0659-13A6 | Central Warning System for Scout & Wasp | Jun 87 |
| -0660-13A6 | | Central Warning System for Wessex Mk 2, 4 & 5 Aircraft | - |
| -0662-1 | | Low Voltage Detector Unit Mk 1 Type YEU-10-1 | 1970 |
| -0663-13A | -0663-13A | Central Warning Panel ECE Pt No 550TS017 Ref No 505CZ/8888 | - |
| -0664-13 | | Thermistance Relay Box Intertechnique Pt No 721944-1 & 718112 & Sensing Units Intertechnique Pt No 721862-1 & 721863-1 | Nov 82 |
| -0665-1 | | Central Warning System for Lightning Mk 2 Aircraft Indicator Unit Type C3840 | Apr 72 |
| -0666-13A6 | | Control Unit Page Engineering Co Pt No D14980 | Jan 74 |
| -0667-13A | | Flap Control Relay Deutsch Pt No J210310SB | Feb 78 |
| -0668-1 | | Miniature Electro-Magnetic Indicators Dowty Types 6362 Series Two Position 6363 Series Three Position | Dec 73 |
| -0669-1 | -0669-1 | Under Carriage Position Indicator. Dowty Electrics Ltd Pt No 6345-005-00 | Jun 84 |
| - | -0669-3 | Dowty Electric Indicator Undercarriage Position | Sep 80 |
| -0670-13A6 | | Central Warning Panel Page Engineering Co Pt No D16260, D16750, D16970, D17420 & D17430 | Jan 85 |
| -0671-13A | | Alighting Gear Indicator ECE Type 961-2-0 | - |
| -0672-13 | | Master Indicator Unit Pt No D381-03-001, D381-13-001 Indicator Unit Pt No D381-04-001 & D381-14-001 | Mar 84 |
| -0673-1 | -0673-1 | Indicators & Warning Devices De-icing & Miscellaneous Equipment (Electric) | - |
| -0674-1 | | Voltage Sensing Unit Pt No C14450/02 | Sep 83 |
| -0675-1 | | Flashing Beacons McMurdo Type ZF5 Mk 3, ZF6 Mk 1 and ZF6 Mk 2 | Feb 86 |
| | -0678-1 | Central Maintenance Panel MBB-UA Pt No E5-1063-00000-00 | Jun 83 |
| | -0678-3 | MBB Central Maintenance Panel | Sep 82 |
| -0678-6 | | Central Maintenance Panel MBB-UA Pt No E5-1063-00000-00 | Nov 83 |
| | -0680-1 | Central Warning Unit Page Engineering Co Ltd | Nov 85 |
| | -0680-1A | Central Warning Unit Page Engineering Co Ltd | Jan 91 |
| | -0680-1B | Central Warning Unit Page Engineering Co Lt Pt Nos Various | Aug 90 |
| | -0680-3A | Page Engineering Co Ltd Central Warning Unit | Sep 80 |
| | -0680-3B | Page Engineering Co Ltd Central Warning Unit | Mar 84 |
| | -0680-3C | Page Engineering Unit Central Warning Unit | Dec 91 |
| | -0680-10 | Page Engineering Co Ltd Central Warning Unit | Oct 85 |
| | -0680-10A | Central Warning Unit Page Eng Co Ltd Pt No Various Servicing Diag | Jan 91 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|------------------|
| 113F-cont | | | |
| -0681-1 | -0680-10B | Page Engineering Co Ltd Central Warning Unit Indicators Electro-Magnetic Plessey Three-Position Rectangular Type | Aug 90 Nov 74 |
| -0682-13A6 | | Control Unit Page Engineering Co Pt No D16480 | Jun 76 |
| -0684-13 | -0684-13 | Centralised Warning Panel Grimes Pt No 80-0300 Series | - |
| | -0685-1 | Engine Test Switch Panel British Aerospace pt No P913842-403 | Oct 82 |
| | -0685-3 | British Aerospace Panel Assy Engine Test Switch | Dec 80 |
| -0686-1 | | Flasher Unit Dowty Electrics Type No 6607-000-00 | Jun 76 |
| | -0687-1 | Engine Control Panel British Aerospace Warton Division Pt Nos P917202-401-403, 405 | Jul 83 |
| | -0687-3 | British Aerospace Panel Assembly Engine Control | Mar 80 |
| -0688-1 | | Central Warning System for Jet Provost T Mk 4 | Feb 76 |
| -0689-13A | | Reconnaissance Control Panel British Aerospace Pt No EM2-872020-407 | Oct 81 |
| -0691-1 | | Ground Control Panel British Aerospace Pt No EM2-870160-0403 | Oct 82 |
| -0692-1 | -0692-1 | Digital Speed Sensing Unit Airscrew Howden Pt No SAC-E-31B 84909 Type SAC-E-31 | - |
| -0693-13 | | Panel Caution Westland Helicopters Ltd WD0181/22055/ 22551/22022 Series & Panel Caution Extension Westland Helicopters Ltd Pt Nos WDO 181-22552 WDO 381-22025 & WDO 481-22003 Series | May 85 |
| -0694-13 | | Panel Advisory Westland Pt Nos WDO 181-22047, WD 4181-22018-041, WD 4281-22033 Series | Aug 85 |
| | -0695-1 | CWS Interface Unit BAe (Warton) Pt No P916843-401/405 + P-088369 -303+P916843-407 | Jan 94 |
| | -0695-3 | British Aerospace Unit Assy Interface CWS | Nov 93 |
| -0695-6 | | Central Warning System Interface Unit British Aerospace (Warton) Pt Nos P916843-401 P916843-405 | Mar 85 |
| | -0696-1 | Power Supply Unit Westfaelische Metall Industries KG Pt No 8ES002769-03 | Sep 82 |
| | -0696-3 | W.M.I. Power Supply Unit | Sep 80 |
| -0697-1 | | Control & Flasher Unit Page Type D 17080 | Sep 84 |
| | -0698-1 | Canopy Audible Warning Horn WMI (Hella) Pt No 3BA 002768-18 | May 82 |
| -06102-1 | -06102-1 | Flasher Position Light Aircraft Dowty Type 663100100 | - |
| -06103-1 | | Flasher Unit Pt No 6E4N1995A | Jun 84 |
| -06104-1 | | Indicator, Magnetic, Plessey Pt No 506-1-00790 Series | Feb 81 |
| -06105-13A | | Panel Emergency Power Pt No 414E2158-1/2 Boeing Vertol Co | Nov 81 |
| -06106-13A6 | | Caution/Advisory Panel Pt No 80-0488-5 Grimes MFG Co Pt No 414ES 248-6 Boeing Vertol Co | Apr 83 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| -06107-136 | | Master Control Unit Pt No D410-01-001, D410-02-001, D410-03-001 & D410-04-001 | Jan 84 |
| -06108-13A | | Junction Box & Harness Assembly Pt No 37699-100 Solar ... | Mar 82 |
| -06109-1 | | Head-up Warning Panel British Aerospace Pt No GES03434-401 | Jun 83 |
| -06110-1 | | Panel Assy Landing Gear & Flaps Pt No 75A800041-1011 ... | Sep 86 |
| -06110-3 | | Panel Assy Landing Gear & Flaps (Y5A800041-1011) 1680-01-172-3453 IPC | - |
| -06110-6 | | Flap Position Indicator ALU-15/A Pt No 40-620-2 Repair & Reconditioning Instructions | Oct 91 |
| -06110-12 | | Landing Gear and Flaps Panel Assembly Pt No 75A800041-1011 & General Orders and Modifications | Aug 90 |
| -06111-13 | | Pilot Services Panel Assembly Pt No 75A800560-1007 | Dec 85 |
| -06112-1 | | Annunciator Light Controller Pt No 95790000-009 | Nov 93 |
| -06112-3 | | Annunciator Light Controller (95790000-009) | Dec 87 |
| -06113-1 | | Warning Light Panel Pt No 52172-105 | Jan 87 |
| -06114-1 | | Priority Caution & Threat Panel Pt No 5165/111 Harrier GR Mk 5 | Jun 86 |
| -06119-1 | | Indicator Control Unit Dowty Rotol Pt No 695002001 | Oct 85 |
| -06122-1 | | Engine Performance Indicator Pt No 8DJ340WADI | Mar 87 |
| -06122-3 | | Engine Performance Indicator (8DJ340WADI) 6620-01-204-9214 | Oct 87 |
| -06124-13 | | Control Unit Pt No D626-01-001 | - |
| -06125-13 | | Indicator Unit Pt No D626-02-001 | May 88 |
| -06126-13 | | Maintenance Annunciator Panel P/N 946F987-1 (Westinghouse) | Nov 90 |
| -06127-13 | | Door Warning Annunciator Module Assembly Pt No 69-46160-17 (Boeing) | Nov 90 |
| -0701-1 | | Follow-Up Resistors, Type FLJ Series (Normalair-Garrett) | May 80 |
| -0702-1 | | Follow-Up Resistors, (Toroidal) Type FLJ & 3202 Series (Normalair-Garrett) | May 80 |
| -0702-6 | | Follow-Up Resistors Teddington Type 3202-005-000 | - |
| | -0703-1 | Command Potentiometer Unit Dowty Rotol Pt No 200788002 . | Nov 94 |
| | -0703-3 | Dowty Rotol Potentiometer Command | Sep 82 |
| -0704-1 | | Datum Selector Resistor Units Ultra Types | 1968 |
| -0705-13A | -0705-13A | Calibration Box Jaeger Type 8218AK | - |
| | -0706-1 | Follow up Potentiometer Dowty Rotol Pt No 200789001 | Sep 94 |
| | -0706-3 | Dowty Rotol Potentiometer Follow Up | Sep 82 |
| -0707-13 | | Spike Suppression Assembly Flight Refuelling Ltd Pt No 43321850 | Apr 83 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0801-1 | | Electric Urns Herman Smith | - |
| -0802-1 | | Oven Fan Circulated Herman Smith Type HE47447M161 Mk 1 | Jun 74 |
| -0803-1 | | Oven Fan Circulated Herman Smith Type HE48313 | - |
| -0804-1 | | Heated Containers Herman Smith 200 Watt Series | Sep 74 |
| -0805-12 | | Hotcups 3-Pin 0.5kW Herman Smith Series | - |
| -0806-13 | | Heating Cabinets Types HE 42934 M1 Mk 2 & Mk 3 | Oct 82 |
| -0809-13 | | Water Heater Herman Smith Type HO 800 & HO 801 Series .. | Oct 82 |
| -0810-13 | | Beverage Containers 120 Watt Series | Oct 82 |
| -0811-16 | | Hotcups Herman Smith 2-Pin kW Series | - |
| -0817-16 | | Hot Cupboard Herman Smith Type HE32767 | - |
| -0818-1 | | Oven Fan Circulated Herman Smith Type HE39830 Mk 1 | - |
| -0819-3 | | Rapid Water Boilers HE 62008 4520-99-716-7692. HE 62168 1680-99-648-8791. Illustrated Parts Catalogue | Oct 89 |
| -0820-1 | | Refrigerator LEC Type P22 | - |
| -0821-16 | | Grill Infra-Red Type P500 | 1967 |
| -0822-13 | | Rapid Water Boilers Types HE 62010 Mk 1 & HE 53384 Mk 1 | Oct 82 |
| -0823-1 | | Infra-Red Grill Rima Princess Type 9011 | 1969 |
| -0824-123 | | Oven Fan Circulated Herman Smith Type HE67010 Mk 1 | Mar 83 |
| -0826-1 | | Flight Ration Heaters (Ref Nos 5V/4378627 & 5V/4378635) .. | Aug 75 |
| -0827-1 | | Oven Fan Circulated Herman Smith Type HE67030 | Jun 74 |
| -0828-1 | | Hot Cupboard Herman Smith Type HO3390 Mk 3 | 1969 |
| -0829-1 | | Refrigerator LEC Type 20000 Series | - |
| -0829-2 | | Refrigerator LEC Type 20000 Series | Jun 92 |
| -0830-1 | | Grill-Boiler Herman Smith type HE30828L6 Mk 2 | 1970 |
| -0833-1 | | Oven Fan Circulated Herman Smith Type HE39827M43 Mk 1 & Mk 2 | Mar 72 |
| -0834-1 | | Oven Part No HE 67183 and Controller Pt No HE 67182-L8 GTI | Dec 88 |
| -0835-3 | | Assembly, Grill 1680-99-787-2739 Illustrated Parts Catalogue . | Dec 88 |
| -0836-1 | | Oven, Fan Recirculated Type HE 67035 | Oct 91 |
| -0836-3 | | Oven, Warming, Electric HE 67035-001, 7310-99-635-0850 ... | Feb 90 |
| -0837-13 | | Liquid Container Assembly Model No 180-147 (Mansfield Aircraft Products Company) | Nov 90 |
| -0838-13 | | Lavatory Water Heater Pt Nos 8921082G1, 8921082G2, 8921082G3 (General Electric Company) | Nov 90 |
| -0839-13 | | Buffet Assembly Pt No 50327-5 (Universal Oil Products) | Jul 90 |
| -0840-13 | | Electric Refrigerator P/N SR165-C135-501 (Western Gear Corp) | Nov 90 |
| -0841-1 | | Coffee Brewer Pt No 2056-105 Federal Stock No 7310-065-7060 (Ref Dynamics) General & Technical Information | Jul 90 |
| -0841-3 | | Coffee Brewer Pt No 2056-105, NSN 7310-00-065-7060 (Ref Dynamics) | Nov 90 |
| -0842-1 | | Food Warming Oven Type 1 | Nov 90 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| -0842-3 | | Food Warming Oven Type 1 | Nov 90 |
| -0901-13 | | Timer Assembly - Reversing Pt No 3299-5 & 3299-13 (Monogram) | Jan 91 |
| -1001-1 | | Ammeters & Voltmeters Sangamo Weston Types | Apr 89 |
| -1002-1 | | Frequency Meters Sangamo Western Type S109 | - |
| -1003-1 | | Sangamo Weston Frequency Meters Type S149 & Accessory Units Type ACC1 | Jan 69 |
| -1004-1 | | Thermal Watt - Varmeters Sangamo Weston Types | 1969 |
| -1005-1 | | Ammeter Unit Turner Type W15 | 1968 |
| -1006-1 | | Ammeter & Voltmeters page Types | 1969 |
| -1007-1 | | Frequency Meter Sangamo Weston Type S105 | - |
| -1007-2(R)1 | | ARI 23328 Royal Air Force Support Authority General and Technical Orders and Special Instructions | Jan 92 |
| -1008-1 | | Ammeter Turner Type B8592 | - |
| -1009-13A6 | | Voltmeters Brion Leroux Ref Nos 505Q/1 & 2, Pt No 2511-1 & Pt No 2512-15-1 | - |
| -1010-1 | -1010-1 | Voltmeter Brion Leroux Type 2396-116-1 | - |
| -1011-13A | | Voltmeter Brion Leroux Pt No 2386-112-1 | Oct 75 |
| -1012-1 | | Probe Sensing LP Speed 619 Mk 1 | Jan 73 |
| -1013-1 | | Battery Voltmeter Indicator KRATOS 50657 | Jul 80 |
| -1016-1 | | Voltmeter Pt No AN 3203V30 | Dec 81 |
| -1017-1 | | AC Ammeter Kratos Type 50684 | Mar 83 |
| -1101-2 | | ARI 10851 & 18051/2 Radio Counter Measures Chaff Dispenser | - |
| -1102-1 | | Cargo Release Unit Type SP4208UK | 1968 |
| -1103-1 | | Combined Selector & Role-Panel Control Unit & Distributer Unit No 2 Mk 1 | 1969 |
| -1104-12 | | Radio Countermeasures Chaff Dispenser System ARI 18051/4 . | May 80 |
| -1104-3 | | Radio Counter Measures Chaff Dispenser System ARI 18051 .. | Feb 85 |
| -1104-6 | | Radio Countermeasures Chaff Dispenser System ARI 18051/4 Control Unit Printed Circuit Boards | Jan 84 |
| -1104-2(R)1 | | RAF Engineering Authority General Orders & Special Instructions ARI 18051/4 | - |
| -1106-1 | | Window Dispensing Equipment (Vulcan) | Oct 76 |
| -1107-1 | | Radio Countermeasures Chaff Dispenser System ARI/23328/1 (Phimat) Control Unit & Electronics System | Mar 90 |
| -1107-2 | | The ARI 23328/1 (Phimat) Chaff Dispenser System Control Unit and Electronics Electro-Mechanical System | Jun 84 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| -1107-2(R)1 | | RAF Engineering Authority General Orders & Special Instructions ARI 23328 | Jul 88 |
| -1107-3 | -1107-3 | Phimat Chaff Dispenser ARI 23328/1 | Jul 85 |
| -1107-10 | | Radio Countermeasures Chaff Dispenser System ARI/23328/1 (Phimat) Control Unit & Electronics System | Mar 90 |
| | -1108-1A | Chaff Infra Red Flare Dispenser System Phillips Pt No Various ARI 23336/1 BOZ 107 Chaff/Flare Dispenser RAF Support Auth General Orders and Special Instructions | Sep 94 |
| -1108-2(R)1 | | | Nov 91 |
| -1108-10 | | Chaff Infra Red Flare Dispenser System Philips Pt No 650600 . | May 88 |
| | -1108-3A | Philips Chaff/Flare Disp Pod Assy | Feb 87 |
| | -1108-3B | Philips Chaff/Flare Disp Control Unit | Jul 86 |
| | -1108-3C | Philips Chaff/Flare Disp Clock Unit | - |
| -1109-1A2 | | Countermeasures Dispensing Set AN/ALE 40(V) (ARI 23344) . | Nov 83 |
| -1109-1F | | Countermeasures Dispensing Set AN/ALE 40(N) & 40(U) ARI (23344) Equipment for use on Harrier & Sea Harrier GR3 & FRS1 | Apr 85 |
| -1109-1C | | Countermeasures Dispensing Set AN/ALE 40(N)(ARI 23344) Jaguar Aircraft | Apr 85 |
| -1109-1D | | Countermeasures Dispensing Set AN/ALE 40(N) 6 (ARI 23344) Nimrod Aircraft | Apr 85 |
| -1109-1F | | Countermeasures Dispensing Set AN/ALE 40(N) & 40(V) 6 ARI (23344) Buccaneer Aircraft | Apr 85 |
| -1109-1H | | Countermeasures Dispensing Set AN/ALE 40(V)6 (ARI 23344) Hercules Aircraft | Dec 93 |
| -1109-3 | | Countermeasures Dispenser Test Set AN/ALM-70 & 70A Phantom F-4J Aircraft | Sep 84 |
| -1109-10 | | Countermeasures Dispensing Set AN/ALE 40(V) (ARI 23344) . | Nov 83 |
| -1110-1 | | Countermeasures Chaff Dispensing Set, AN/ALE 29A Phantom F-4J Aircraft | - |
| -1110-3 | | Countermeasures Chaff Dispensing Set AN/ALE 29A | Jun 89 |
| -1110-13 | | Countermeasures Chaff Dispensing Set AN/ALE 29A Phantom F-4J Aircraft | Jul 85 |
| -1111-3 | | Countermeasures Dispenser Test Set AN/ALM 70 & 70A | Jun 89 |
| -1111-13 | | Countermeasures Dispenser Test Set AN/ALM-70 & 70A Phantom F-4J Aircraft | Sep 84 |
| -1112-12 | | Countermeasures Dispensing Set M-130 (ARI 23343) | Apr 85 |
| -1112-2(R)1 | | RAF Engineering Authority General Orders & Special Instrs ARI 23343 | Feb 88 |
| -1112-3 | | ARI 23343 M/130 Countermeasure System (Rotary Wint) | - |
| -1112-10 | | Countermeasures Dispensing Set M-130 (ARI 23343) | Apr 85 |
| -1113-1 | | Chaff/Flare Door Assembly Pt No C336742 & C337845 | Aug 86 |
| -1114-12 | | Bol 304 Chaff Dispenser | Oct 90 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113F-cont | | | |
| | -1201-13A | Control Box Anti-Skid Dunlop Type ACM 26742 | Jul 71 |
| -1201-6 | | Control Box Anti-Skid Dunlop Type ACM 26742 | Dec 70 |
| -1203-13 | | Anti-Skid Generator & Flywheel Assembly Goodyear Pt No E31044 | Mar 89 |
| -1204-1 | | Anti-Skid Control Box Goodyear Pt No E31082 | - |
| -1205-1 | | Anti-Skid Control Box Goodyear Pt No 9544179-1 | Jun 73 |
| -1206-1 | | Anti-Skid Wheel Driven Unit Jaguar | Jun 73 |
| -1207-12 | | Control Box Goodyear Pt Nos 6001432-2 & E31198 | Sep 76 |
| -1208-1 | | Wheel Driven Unit Goodyear Pt No 6001410 Gen & Tech Info | Mar 89 |
| | -1210-3 | Goodyear Anti-Skid Control Box | Dec 93 |
| | -1211-3 | Goodyear Wheel Drive Unit | Jun 81 |
| | -1212-3 | Goodyear Valve Control Assembly | Jun 81 |
| -1213-12 | | Anti Skid Control Unit Pt No AC67362/5 | Aug 93 |
| -1213-3 | | Control Unit Anti-Skid (AC67362/4) | Aug 87 |
| -1214-6 | | Hytrol Wheel speed Transducer Assembly Pt No 40-575 | Nov 94 |
| | -1301-1 | AICS Control Panel NORD-Micro ltd Pt No 10200-2 | Aug 83 |
| | -1301-3 | NORD Micro Panel Pilots | Jun 82 |
| | -1302-1A | Air Control Unit NORD-Micro Electronic Fein Mechanic AG Pt No 10050-11 | Jan 84 |
| -1302-1B | | Automatic Test Equipment Tornado Aircraft LF Station Operators Manuals air Intake Control System Actuator Control Unit WBS OM-2-1-2-15 | Dec 88 |
| -1302-3B | | NORD Micro Automatic Control Unit | Nov 84 |
| -1302-10 | | Air Control Unit NORD Micro Elek Fien Ag | Mar 86 |
| -1303-136 | | CFM 56-2A Engine Component Maintenance Manual Master Ballscrew. Actuator Assembly 75-31-51. | Aug 89 |
| -1304-136 | | CFM 56-2A Engine Component Maintenance Manual Flexible Shaft Assembly 75-31-31 | Aug 89 |
| -1305-136 | | CFM 562A Engine Component Maintenance Manual Cable Variable Stator Feed back 75-32-21 | Aug 89 |
| -1306-136 | | CFM 56-2A Engine Component Maintenance Manual Actuator Variable Stator 75-32-11 | Aug 89 |
| -1307-136 | | CFM 56-2A Engine Component Maintenance Manual Variable BleedValve Feedback Control 75-31-71 | Aug 89 |
| -1308-16 | | CFM 56-2A Engine Component Maintenance Manual Ballscrew Actuator Assembly 75-31-61 | Aug 89 |
| -1309-136 | | CFM 56-2A Engine Component Maintenance Manual BV Stop Mechanism 75-31-21 | Aug 89 |
| -1310-136 | | CFM 56-2A Engine Component Maintenance Manual BV Fuel Gear Motor 75-31-11 | Aug 89 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| | -1402-1 | Panel VFW Pt No P929971 A929971 | Sep 84 |
| -1403-13A | | Magnetic Brake Pt No R460M45 R460M46 Plessey Airborne Co Pt No 414CS101-1-2 Boeing Vertol Co | Jul 82 |
| -1405-13A | | Box Assembly Power Steering Pt No BSC10-1 Logic Pt No 414ES210-1 Boeing Vertol Co | Jan 83 |
| | -1406-1 | Nose Probe Heater Failure Detector Unit Rosemount Ltd Pt No E37045 | Apr 90 |
| -1410-13 | | Accessory Module Assembly, Cable Breakout Adaptor ADU-461/E(Boeing) | Mar 94 |
| -1411-13 | | Cooling Air Status Indicator Panel, 1D-20061A Pt No 204-18995-1(Boeing) | Nov 90 |
| -1412-1 | | Brake Magnetic, Electro-Mechanical | Jan 93 |
| -1412-2 | | Magnetic Brake, Electro-Mechanical Pt No R460M39-3, R460M39-4 GEC Aerospace Pt No 145CS101-3, 145CS101-4 Boeing Helicopter | Jan 93 |
| -1412-3 | | Magnetic Brake, Electro-Mechanical Pt No R460M39-3, R460M39-4 GEC Aerospace Pt No 145CS101-3, 145CS101-4 Boeing Helicopters | Jan 93 |
| | -1501-1 | Fuel Control Panel British Aerospace Pt No P913830-413, P913830-409, P913830-417 | Oct 82 |
| | -1501-3 | British Aerospace Panel Assy Fuel Control | Dec 80 |
| -1502-13 | | Panel Assy Fuel Control External Pt No 75A870622-1023 Harrier GR 5 | Apr 86 |
| -1503-13 | | Fuel Control Panel Assembly Pt No 75A800045-1019 | Nov 85 |
| | -1601-1 | Nose Wheel Steering Control Unit Dowty Electrics Ltd Superseding FAP 112H-0502-1 | Mar 88 |
| | -1601-3 | Dowty Rotol Unit Control Nose Wheel Steering | May 90 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113G

ARMAMENT AIRBORNE CONTROL EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113G | | | |
| -0101-1235F | | Fuze Control Unit Type ER Mk 1 | Apr 87 |
| -1013-1 | | Bombing System MB Metals Type 11/12 | - |
| -0103-2 | | Bombing System MB Metals Type 11/12 | Jan 74 |
| -0104-3A | | Bomb Release Intervalometer Type AO5A0024 | - |
| -0104-6 | | Bomb Release Intervalometer | - |
| -0106-1 | | Auto Selector Switches 2-Way Type B & C | - |
| -0107-1 | | Automatic Bomb Distributor 2-Way Mk 2 2 MB Metals | Oct 76 |
| -0108-12 | | Auto Selector Switches 4-Way & 3-Way Type C | Mar 79 |
| -0115-1 | | Weapon Control Panel 16-Way, Mk 1 Plessey Pt No 700/1/13510 | Mar 76 |
| -0115-2 | | Distributor Automatic Release 16-Way Mk 1 | - |
| -0115-6 | | Weapon Control Panel, 16-Way, Mk 1 Plessey Pt No 700/1/13510 | - |
| -0116-15F | | Weapon Control Panel & Monitor Unit 8-Way | Oct 76 |
| -0116-2 | | Weapon Control Panel 8-Way Mk 1 & 2 Monitor Unit 8-Way | - |
| -0116-6 | | Weapon Control Panel 8-Way & Monitor Unit 8-Way | Oct 76 |
| -0117-1 | | Pre-Selector Unit Type C | 1969 |
| -0117-2 | | Pre-Selector Unit Type C Mk 1 | Jul 74 |
| -0118-13A | | Fuzing Control Unit Type EL/EA Mk 1 | Jun 75 |
| -0120-13A | | Bomb Distributor (Bomb Pattern Selector) 8-Way Mk 2 | - |
| -0123-1 | | Sonobuoy Launcher Time Delay Unit HSA Type 6M4N12103A | - |
| -0123-6 | | Sonobuoy Launcher Time Delay Unit HSA Type 6M4N12103A | - |
| -0124-1 | | Stores Pattern Indicator HSA Type 6M4R-16177A | Sep 69 |
| -0125-1 | | Store Selection Unit HSA Type 6M4R-1615A | Sep 69 |
| -0126-1 | | Actuator Control Panel & Relay Tube for Retro-Launcher Matra Type RL8 AV310 | Sep 82 |
| -0129-1 | -0129-136 | Time Delay Unit Mk 2A | 1970 |
| -0130-1 | | Pulse Generators HSA Types 6M4N18329A & 6M4N20777A | - |
| -0131-1 | | Photographic Role Panel Pt No YB3-80-978 & YB6-80-405 | - |
| -0132-13A | | Control Unit Flare Height Settler | - |
| -0133-1 | | Junction Box (Single Sonobuoy Launcher) Type 6M4A & 6M4A 5849A/1 | Sep 80 |
| -0134-13A | | Pre-Release Timer (Pt No YEU-52-1) | - |
| -0135-1 | | 6001b/9501b Bombing Role Panel (Pt Nos YB6-80-214, YB6-80-395 & YB6-80-366) | - |
| -0136-1 | | Relay Panel Pt Nos YB3-67-1937 & YB3-67-2305 | - |
| -0137-1 | | Silicon-Controlled Rectifier Module Pt No YEU-54-1 | - |
| -0138-1 | | Auto Selectors Type F | - |
| -0139-1 | | Junction Box Rotary Sonobuoy Launcher Type 6M4A-7481A & 6M4A-7481A/1 | Sep 80 |

SUB-GROUP 113F

STATIC CONSUMER EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113F-cont | | | |
| | -1402-1 | Panel VFW Pt No P929971 A929971 | Sep 84 |
| -1403-13A | | Magnetic Brake Pt No R460M45 R460M46 Plessey Airborne Co Pt No 414CS101-1-2 Boeing Vertol Co | Jul 82 |
| -1405-13A | | Box Assembly Power Steering Pt No BSC10-1 Logic Pt No 414ES210-1 Boeing Vertol Co | Jan 83 |
| | -1406-1 | Nose Probe Heater Failure Detector Unit Rosemount Ltd Pt No E37045 | Apr 90 |
| -1410-13 | | Accessory Module Assembly, Cable Breakout Adaptor ADU-461/E(Boeing) | Mar 94 |
| -1411-13 | | Cooling Air Status Indicator Panel, 1D-20061A Pt No 204-18995-1(Boeing) | Nov 90 |
| -1412-1 | | Brake Magnetic, Electro-Mechanical | Jan 93 |
| -1412-2 | | Magnetic Brake, Electro-Mechanical Pt No R460M39-3, R460M39-4 GEC Aerospace Pt No 145CS101-3, 145CS101-4 Boeing Helicopter | Jan 93 |
| -1412-3 | | Magnetic Brake, Electro-Mechanical Pt No R460M39-3, R460M39-4 GEC Aerospace Pt No 145CS101-3, 145CS101-4 Boeing Helicopters | Jan 93 |
| | -1501-1 | Fuel Control Panel British Aerospace Pt No P913830-413, P913830-409, P913830-417 | Oct 82 |
| | -1501-3 | British Aerospace Panel Assy Fuel Control | Dec 80 |
| -1502-13 | | Panel Assy Fuel Control External Pt No 75A870622-1023 Harrier GR 5 | Apr 86 |
| -1503-13 | | Fuel Control Panel Assembly Pt No 75A800045-1019 | Nov 85 |
| | -1601-1 | Nose Wheel Steering Control Unit Dowty Electrics Ltd Superseding FAP 112H-0502-1 | Mar 88 |
| | -1601-3 | Dowty Rotol Unit Control Nose Wheel Steering | May 90 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113G

ARMAMENT AIRBORNE CONTROL EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113G | | | |
| -0101-1235F | | Fuze Control Unit Type ER Mk 1 | Apr 87 |
| -1013-1 | | Bombing System MB Metals Type 11/12 | - |
| -0103-2 | | Bombing System MB Metals Type 11/12 | Jan 74 |
| -0104-3A | | Bomb Release Intervalometer Type AO5A0024 | - |
| -0104-6 | | Bomb Release Intervalometer | - |
| -0106-1 | | Auto Selector Switches 2-Way Type B & C | - |
| -0107-1 | | Automatic Bomb Distributor 2-Way Mk 2 2 MB Metals | Oct 76 |
| -0108-12 | | Auto Selector Switches 4-Way & 3-Way Type C | Mar 79 |
| -0115-1 | | Weapon Control Panel 16-Way, Mk 1 Plessey Pt No 700/1/13510 | Mar 76 |
| -0115-2 | | Distributor Automatic Release 16-Way Mk 1 | - |
| -0115-6 | | Weapon Control Panel, 16-Way, Mk 1 Plessey Pt No 700/1/13510 | - |
| -0116-15F | | Weapon Control Panel & Monitor Unit 8-Way | Oct 76 |
| -0116-2 | | Weapon Control Panel 8-Way Mk 1 & 2 Monitor Unit 8-Way | - |
| -0116-6 | | Weapon Control Panel 8-Way & Monitor Unit 8-Way | Oct 76 |
| -0117-1 | | Pre-Selector Unit Type C | 1969 |
| -0117-2 | | Pre-Selector Unit Type C Mk 1 | Jul 74 |
| -0118-13A | | Fuzing Control Unit Type EL/EA Mk 1 | Jun 75 |
| -0120-13A | | Bomb Distributor (Bomb Pattern Selector) 8-Way Mk 2 | - |
| -0123-1 | | Sonobuoy Launcher Time Delay Unit HSA Type 6M4N12103A | - |
| -0123-6 | | Sonobuoy Launcher Time Delay Unit HSA Type 6M4N12103A | - |
| -0124-1 | | Stores Pattern Indicator HSA Type 6M4R-16177A | Sep 69 |
| -0125-1 | | Store Selection Unit HSA Type 6M4R-1615A | Sep 69 |
| -0126-1 | | Actuator Control Panel & Relay Tube for Retro-Launcher Matra Type RL8 AV310 | Sep 82 |
| -0129-1 | -0129-136 | Time Delay Unit Mk 2A | 1970 |
| -0130-1 | | Pulse Generators HSA Types 6M4N18329A & 6M4N20777A | - |
| -0131-1 | | Photographic Role Panel Pt No YB3-80-978 & YB6-80-405 | - |
| -0132-13A | | Control Unit Flare Height Settler | - |
| -0133-1 | | Junction Box (Single Sonobuoy Launcher) Type 6M4A & 6M4A 5849A/1 | Sep 80 |
| -0134-13A | | Pre-Release Timer (Pt No YEU-52-1) | - |
| -0135-1 | | 6001b/9501b Bombing Role Panel (Pt Nos YB6-80-214, YB6-80-395 & YB6-80-366) | - |
| -0136-1 | | Relay Panel Pt Nos YB3-67-1937 & YB3-67-2305 | - |
| -0137-1 | | Silicon-Controlled Rectifier Module Pt No YEU-54-1 | - |
| -0138-1 | | Auto Selectors Type F | - |
| -0139-1 | | Junction Box Rotary Sonobuoy Launcher Type 6M4A-7481A & 6M4A-7481A/1 | Sep 80 |

SUB-GROUP 113G

ARMAMENT AIRBORNE CONTROL EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113G-cont | | | |
| -0140-16 | | Weapon Control System 10-Way 1280-99-114-2255, 1280-99-114-2256, 1280-99-114-2258 | - |
| -0140-2 | | Weapon Control System 10-Way | Oct 74 |
| -0142-1 | | Pre-Selector Units 16 & 32 Point AC Patents Type B | - |
| -0143-1 | | Time Delay Units Mk 3 and Mk 4 (MB Metals) | Aug 75 |
| -0144-1 | | Distributor, Cartridge Flare Mk 1 | Sep 75 |
| -0145-1 | | Distributors Bomb Automatic MB Metals Types 6 & 7 | Mar 72 |
| -0146-123 | | Auto-Selectors 2 way Type G | Jun 85 |
| -0147-13 | | Weapon Control Panel and Weapon Monitor Panel (Hawk T Mk 1/TMk 1A) | - |
| -0148-1 | | 2-4 Way Auto-Selector Type PV207-150C (ML Aviation Co Ltd) | Jul 75 |
| -0149-12 | | Pre-Selector Unit Type 'C' Mk 2 | May 78 |
| -0150-1 | | Time Delay Unit Time OY Mk 1 ML Aviation | Oct 76 |
| -0152-1 | | Bombing Role Panel 9P (600lb/950lb) | Jun 75 |
| -0153-1A | -0153-1A | Weapon Programming Unit GEC Avionics Pt No 54-003-01) .. | Mar 87 |
| -0153-1B | | ATE Tornado Aircraft LF Station SMS Wpu Operators Manual WBS OM-2-1-2-1-14 | Aug 87 |
| | -0153-3 | Marconi Weapon Programming | Apr 82 |
| | -0153-10 | Weapon Programming Unit GEC Avionics | Sep 93 |
| | -0154-1 | Weapon Control Panel 1 Marconi Avionics Pt No 26-0004-01 .. | Jan 85 |
| -0154-1B | | ATE Tornado Aircraft LF Station Operators Manual Weapon Control Panel No 1 WBS OM-2-1-2-1-15 | Sep 87 |
| -0154-13 | | ATE Tornado Aircraft LF Station SMS Weapon Control Panel No 2(WCP2) | Oct 87 |
| | -0154-3 | Marconi Weapon Control Panel No 1 | May 94 |
| | -0154-10 | Weapon Control Panel 1 Marconi Avionics Pt No 26-004-02 & 03 | Mar 94 |
| | -0155-1A | Weapon Control Panel 2 Marconi Avionics Pt No 26-005-02, 03, 04 & 05 | Mar 94 |
| -0155-1B | | ATE Tornado Aircraft LF Station Weapon Control Panel No 2WBS OM 2-1-2-1-16 | Sep 86 |
| | -0155-3 | Marconi Weapon Control Panel No 2 | May 82 |
| | -0155-10 | Weapons Control Panel 2 GEC Avionics Pt No 26-005-02, -03, -04 and -05 | Mar 94 |
| -0156-1B | | ATE Tornado Aircraft LF Station SMS Pylon Decoder Unit 'B' 'C' & 'D' | Sep 87 |
| -0156-3A | | Marconi Pylon Decoder Unit Type A | Jun 81 |
| -0156-3B | | Marconi Pylon Decoder Unit Type B | Jun 81 |
| | -0156-3C | Marconi Pylon Decoder Unit Type C | Jun 81 |
| | -0156-3D | Marconi Pylon Decoder Unit Type D | Jun 81 |

UK RESTRICTED

**AP 100Z-0101 AL136
SUB-GROUP 113G**

ARMAMENT AIRBORNE CONTROL EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|--|--------|
| 113G-cont | | | |
| | -0156-10 | Pylon Decoder Unit Types BC & D GEC Avionics Pt No 32-009/10/11-10 & 32-009/10/11-02 | Mar 94 |
| | -0158-1A | Power Interface Unit Elliott Bros (London) Ltd Pt No 80-018-01 | Feb 94 |
| -0158-1B | | ATE Tornado Aircraft LF Station Operators Manuals Stores Management System Power Interace Unit WBS OM-2-1-2-1-18 | Aug 87 |
| | -0158-3 | Marconi Power Interface Unit | May 82 |
| | -0161-1 | Special Weapon Junction Box British Aerospace PLC Pt Nos P914926-409/413/419/421/423 | Jul 87 |
| | -0161-3 | British Aerospace Box Assy Junction | Oct 81 |
| | -0162-1 | Bomb Release Safety Lock Panel British Aerospace (Warton) Pt No P-96530-405 | Jul 87 |
| | -0162-3 | British Aerospace Panel Assy Bomb Release Safety Lock | Aug 81 |
| | -0163-1 | BRS� Relay Box British Aerospace Pt No P915142-401/407/409 | Jul 87 |
| | -0163-3 | British Aerospace Box Assembly Relay (013VE) | Apr 82 |
| -0164-126 | | Special Weapon Controller No 1 | Jun 82 |
| -0165-16 | | Auto Manual Selector Unit 6M4N23767A | Dec 80 |
| -0166-125F | | Special Weapon Controller No 3 Remote Relay Unit No 3 | Apr 81 |
| -0168-3 | | Stores Management Indicator 5895-01-223-8243 Illustrated Parts Catalogue | Sep 88 |
| -0168-12 | | Stores Management Control Indicator Pt No 7598700-101 Gen and Tech Info General Orders and Modifications | May 92 |
| -0168-123 | | Armament Stores Management Control Indicator | Dec 93 |
| -0168-6 | | Armament Stores Management Control Indicator | Apr 94 |
| -0169-1 | | Stores Management Computer CP-1451/AYQ-13 Pt No 7961500B003 | Jan 91 |
| -0169-3 | | Stores Management Computer 7050-01-261-6082 | Sep 88 |
| -0170-3 | | Controller Stores Station 5895-01-223-8128 | Jul 88 |
| -0170-12 | | Stores Station Controller Part [No 7958800-101 | - |
| -0170-123 | | Stores Station Controller Pt No 7958800-101 | Jun 91 |
| -0171-13 | | Intervalometer Control Box British Aerospace Pt No KB922 K0303-000 (Hawk T Mk 1A) | Feb 85 |
| -0201-1 | | Gun Firing Unit Pt No C303488 | Feb 83 |
| -0201-6 | | Gun Firing Units Hawker Siddeley Pt No C294795 & C303488 | - |
| -0202-1 | | Gun Firing & Weapon Safety Relays Junction Boxes British Aerospace PLC Pt No KB922K0027002 & KB922K0027004 Hawk T Mk 1/T Mk 1A | Jun 83 |
| -0203-13A | | Aden Gun Power Supply Box AMD-BA Pt No 121S64-310-00-0 | Jun 76 |

SUB-GROUP 113G

ARMAMENT AIRBORNE CONTROL EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113G-cont | | | |
| -0204-13 | | Weapon Control Junction Boxes British Aerospace PLC Pt No KB922K0037000 & KB922K0305000 (Hawk T Mk 1/T Mk 1A) Gen & Tech Info Illustrated Parts Catalogue | Sep 89 |
| | -0205-3 | Mauser Gun Electronic Unit | Dec 82 |
| -0208-1 | | Guns Junction Box Pt No D487400 | Jun 83 |
| -0301-13A | | Central Timing Unit RP Airlog | - |
| -0303-15F | | RP Distributor No 4 Mk 3, Mk 4 & Mk 5 | Sep 75 |
| -0304-1 | | RP Uniselector Firing System Type 2 | - |
| -0401-2 | | AUW Airborne Pre-Setter (Plessey) Mk 1, 2, 3, 5 & 7 | Aug 78 |
| -0401-6 | | AUW Airborne Pre-Setter (Plessey) Mk 1, 2, 3, 5 & 7 | Oct 77 |
| -0404-126 | | AUW Presetters Mk 8 & Mk 9 Marconi Type Mk 8-1 OWE-143900 Mk 91 OWE 143880 | Apr 83 |
| -0405-12 | | Auxiliary Power Supply System (APSS) | Nov 87 |
| -0405-123 | | Auxiliary Power Supply System (APSS) | - |
| -0601-1 | | Distributors Pyrotechnics MB Metals Type A Mk 1, 2 & 3 | - |
| -0602-1 | | Photoflash Distributor MB Metals Mk 1 | Nov 76 |
| -0701- | | Pavespike Role Panel Pt No YB6-80-547 (MOD 345) | Feb 80 |
| -0801-13A | -0801-13A | Air to air Missile Unit Pt No Various | Sep 88 |
| -0802-1 | -0802-1 | Missiles Control Panel Part No E486601 | Jun 81 |
| | -0802-3 | Base Ten Air To Air Missile Unit | Aug 88 |
| -0802-1B | | ATE Tornado Aircraft LF Station Air to Air Missile Unit WBS OM-2-1-2-1-24 | Apr 87 |
| | -0802-10 | Air to Air Missile Unit Pt No Various | Mar 94 |
| | -0803-1 | Missile Control Unit Teldix GMBH | Jan 90 |
| | -0803-3 | Parts Catalogue Teldix GMBH Missile Control Unit | Dec 93 |
| | -0803-10 | Missile Control Unit Teldix GMBH | Jan 90 |
| -0804-13 | | Missile Control Panel 111 Alpha | - |
| -0807-13 | | Missile Control Panel Pt No D336266 | Apr 88 |
| -0808-13 | | Missile Control Panel Pt Nos B334510 & B337215 | Apr 88 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113L

ENGINE IGNITION EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113L | | | |
| -0101-13A6 | -0101-13A6 | High Energy Ignition Units Lucas Aerospace Types C28TS/2, C44TS/1 & 4C72TS/1 | - |
| -0101-2 | | High Energy Ignition Units Lucas Aerospace Types C28TS/1 & /4, C272TS/1 & /2 | - |
| -0102-16 | | High Energy Ignition Unit Lucas Aerospace Type C34TS/2 | Feb 83 |
| -0106-2 | | High Energy Ignition Unit Lucas Aerospace Type C20TS/1 General Orderws & Modifications | Feb 90 |
| -0102-2 | | High Energy Ignition Unit Lucas Aerospace Type C34/T/2 | Mar 89 |
| -0103-1236 | | High Energy Ignition Unit Rotax Type C63TS/1 | Feb 83 |
| -0105-123 | | High Energy Ignition Unit AEI Type C105TS/101 | May 81 |
| -0105-6 | | High Energy Ignition Unit AEI Type C105TS/101 | 1968 |
| -0106-16 | | High Energy Ignition Unit AEI Type C20TS/1 | 1969 |
| -0108-16 | | High Energy Ignition Unit Rotax Type C27TS/1 | Feb 83 |
| -0108-2 | | High Energy Ignition Unit AEI Type C27TS/1 | - |
| -0109-16 | | High Energy Ignition Units AEI Types C10TS/3, G33TS | 1967 |
| -0109-2 | | High Energy Ignition Unit Lucas Aerospace Types C10TS/2 & C10TS/3 | Mar 89 |
| -0110-16 | | High Energy Ignition Units Lucas Aerospace Types NB 4103 & NB 4105 | Jun 79 |
| -0111-16 | | High Energy Ignition Unit AEI Type C51TS/1 | Feb 83 |
| -0114-1236 | | High Energy Ignition Units Lucas Aerospace Types NB 25/3, NB 55/1 & NB 3802/1 | May 82 |
| -0115-1 | | High Energy Ignition Unit AEI Type C45TS/2 | 1969 |
| -0115-6 | | High Energy Ignition AEI Type C45TS/2 | - |
| -0115-2 | | High Energy Ignition Unit Lucas Aerospace Type C45TS/2 | Mar 89 |
| -0117-1 | | High Energy Ignition Units Lucas Aerospace Types NBN8902/1 & NB8902/2 | - |
| -0117-6 | | High Energy Ignition Unit Lucas Aerospace Type NB8902/2 | - |
| -0118-1 | | High Frequency Ignition Unit Plessey Mk 8B | Mar 71 |
| -0119-16 | | 12kV HT Ignition Coil Assembly Plessey Prt No 506-1-06666 Gen & Tech Info Repair & Reconditioning | Mar 89 |
| -0120-1 | | High Energy Ignition Unit Rotax Type NB6103 | - |
| -0121-13A6 | -0121-13A6 | Igniter Unit Air Equipment Pt No 81268-121 & 81268-323 | Mar 93 |
| -0122-123A6 | | High Energy Ignition Units Lucas Aerospace Jaguar | Nov 73 |
| -0124-1236 | | High Energy Ignition Unit Lucas Aerospace Type NB 10802 | Aug 84 |
| -0126-1 | | High Energy Ignition Unit Lucas Aerospace Type NB 9520 | Oct 76 |
| -0128-13A6 | -0128-13A6 | High Energy Ignition Unit Lucas Aerospace Type NB 10002 | - |
| -0129-136 | -0129-136 | High Energy Ignition Unit Lucas Aerospace Type NB 00402 | - |
| -0131-3 | | Ignition Exciter Dual Circuit AC Type TFHLN-3 Phantom F-4J Aircraft | Sep 85 |

SUB-GROUP 113G

ARMAMENT AIRBORNE CONTROL EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113G-cont | | | |
| -0204-13 | | Weapon Control Junction Boxes British Aerospace PLC Pt No KB922K0037000 & KB922K0305000 (Hawk T Mk 1/T Mk 1A) Gen & Tech Info Illustrated Parts Catalogue | Sep 89 |
| | -0205-3 | Mauser Gun Electronic Unit | Dec 82 |
| -0208-1 | | Guns Junction Box Pt No D487400 | Jun 83 |
| -0301-13A | | Central Timing Unit RP Airlog | - |
| -0303-15F | | RP Distributor No 4 Mk 3, Mk 4 & Mk 5 | Sep 75 |
| -0304-1 | | RP Uniselector Firing System Type 2 | - |
| -0401-2 | | AUW Airborne Pre-Setter (Plessey) Mk 1, 2, 3, 5 & 7 | Aug 78 |
| -0401-6 | | AUW Airborne Pre-Setter (Plessey) Mk 1, 2, 3, 5 & 7 | Oct 77 |
| -0404-126 | | AUW Presetters Mk 8 & Mk 9 Marconi Type Mk 8-1 OWE-143900 Mk 91 OWE 143880 | Apr 83 |
| -0405-12 | | Auxiliary Power Supply System (APSS) | Nov 87 |
| -0405-123 | | Auxiliary Power Supply System (APSS) | - |
| -0601-1 | | Distributors Pyrotechnics MB Metals Type A Mk 1, 2 & 3 ... | - |
| -0602-1 | | Photoflash Distributor MB Metals Mk 1 | Nov 76 |
| -0701- | | Pavespike Role Panel Pt No YB6-80-547 (MOD 345) | Feb 80 |
| -0801-13A | -0801-13A | Air to air Missile Unit Pt No Various | Sep 88 |
| -0802-1 | -0802-1 | Missiles Control Panel Part No E486601 | Jun 81 |
| | -0802-3 | Base Ten Air To Air Missile Unit | Aug 88 |
| -0802-1B | | ATE Tornado Aircraft LF Station Air to Air Missile Unit WBS OM-2-1-2-1-24 | Apr 87 |
| | -0802-10 | Air to Air Missile Unit Pt No Various | Mar 94 |
| | -0803-1 | Missile Control Unit Teldix GMBH | Jan 90 |
| | -0803-3 | Parts Catalogue Teldix GMBH Missile Control Unit | Dec 93 |
| | -0803-10 | Missile Control Unit Teldix GMBH | Jan 90 |
| -0804-13 | | Missile Control Panel 111 Alpha | - |
| -0807-13 | | Missile Control Panel Pt No D336266 | Apr 88 |
| -0808-13 | | Missile Control Panel Pt Nos B334510 & B337215 | Apr 88 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113L

ENGINE IGNITION EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|-------------|-------------|--|--------|
| 113L | | | |
| -0101-13A6 | -0101-13A6 | High Energy Ignition Units Lucas Aerospace Types C28TS/2, C44TS/1 & 4C72TS/1 | - |
| -0101-2 | | High Energy Ignition Units Lucas Aerospace Types C28TS/1 & /4, C272TS/1 & /2 | - |
| -0102-16 | | High Energy Ignition Unit Lucas Aerospace Type C34TS/2 | Feb 83 |
| -0106-2 | | High Energy Ignition Unit Lucas Aerospace Type C20TS/1 General Orderws & Modifications | Feb 90 |
| -0102-2 | | High Energy Ignition Unit Lucas Aerospace Type C34/T/2 | Mar 89 |
| -0103-1236 | | High Energy Ignition Unit Rotax Type C63TS/1 | Feb 83 |
| -0105-123 | | High Energy Ignition Unit AEI Type C105TS/101 | May 81 |
| -0105-6 | | High Energy Ignition Unit AEI Type C105TS/101 | 1968 |
| -0106-16 | | High Energy Ignition Unit AEI Type C20TS/1 | 1969 |
| -0108-16 | | High Energy Ignition Unit Rotax Type C27TS/1 | Feb 83 |
| -0108-2 | | High Energy Ignition Unit AEI Type C27TS/1 | - |
| -0109-16 | | High Energy Ignition Units AEI Types C10TS/3, G33TS | 1967 |
| -0109-2 | | High Energy Ignition Unit Lucas Aerospace Types C10TS/2 & C10TS/3 | Mar 89 |
| -0110-16 | | High Energy Ignition Units Lucas Aerospace Types NB 4103 & NB 4105 | Jun 79 |
| -0111-16 | | High Energy Ignition Unit AEI Type C51TS/1 | Feb 83 |
| -0114-1236 | | High Energy Ignition Units Lucas Aerospace Types NB 25/3, NB 55/1 & NB 3802/1 | May 82 |
| -0115-1 | | High Energy Ignition Unit AEI Type C45TS/2 | 1969 |
| -0115-6 | | High Energy Ignition AEI Type C45TS/2 | - |
| -0115-2 | | High Energy Ignition Unit Lucas Aerospace Type C45TS/2 | Mar 89 |
| -0117-1 | | High Energy Ignition Units Lucas Aerospace Types NBN8902/1 & NB8902/2 | - |
| -0117-6 | | High Energy Ignition Unit Lucas Aerospace Type NB8902/2 | - |
| -0118-1 | | High Frequency Ignition Unit Plessey Mk 8B | Mar 71 |
| -0119-16 | | 12kV HT Ignition Coil Assembly Plessey Prt No 506-1-06666 Gen & Tech Info Repair & Reconditioning | Mar 89 |
| -0120-1 | | High Energy Ignition Unit Rotax Type NB6103 | - |
| -0121-13A6 | -0121-13A6 | Igniter Unit Air Equipment Pt No 81268-121 & 81268-323 | Mar 93 |
| -0122-123A6 | | High Energy Ignition Units Lucas Aerospace Jaguar | Nov 73 |
| -0124-1236 | | High Energy Ignition Unit Lucas Aerospace Type NB 10802 | Aug 84 |
| -0126-1 | | High Energy Ignition Unit Lucas Aerospace Type NB 9520 | Oct 76 |
| -0128-13A6 | -0128-13A6 | High Energy Ignition Unit Lucas Aerospace Type NB 10002 | - |
| -0129-136 | -0129-136 | High Energy Ignition Unit Lucas Aerospace Type NB 00402 | - |
| -0131-3 | | Ignition Exciter Dual Circuit AC Type TFHLN-3 Phantom F-4J Aircraft | Sep 85 |

SUB-GROUP 113L

ENGINE IGNITION EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113L-cont | | | |
| -0131-6 | | Ignition Exciter Dual Circuit AC Type TFHLN-3 Phantom F-4J Aircraft | Sep 85 |
| -0134-13A | | Igniter Unit Microturbo Type 006-07 & A.B.G. Semca Type 64890-01 | Jun 81 |
| | -0135-1 | Magneti Marelli High Energy Ignition Unit Pt No 63616500 .. | Aug 80 |
| | -0135-3 | Magneti Marelli High Energy Ignition Unit Pt No 63616500 .. | May 80 |
| -0136-3 | -0136-3 | FI Magneti Marelli High Energy Ignition Unit | Aug 88 |
| | -0140-136 | CFM 56-2A Engine Component Maintenance Manual Ignition Exciter 74-11-12 | Aug 89 |
| -0140-136 | | CFM 56-2A Engine Components Maintenance Manual Ignition Exciter 74-11-12 | Aug 89 |
| -0141-13 | | High Energy Ignition Unit Lucas Aerospace Type NB00104 + NB00102 | Dec 91 |
| -0142-13 | | High Energy Ignition Unit Lucas Aerospace Types NB01001 + NB01002 | Nov 91 |
| -0143-13 | | High Energy Ignition Unit Lucas Aerospace Type NB 00108 .. | Nov 91 |
| -0202-1 | | Lucas Aerospace Type NT 12 Series Magnetos | Jan 74 |
| -0203-1 | | Magneto Unit Type CGD/2 | - |
| -0204-1 | | Magnetos Type C9/A/3 & C9B/2 | - |
| -0205-1 | | Magneto Type CT4A/1 | - |
| -0206-1 | | Automatic Advance & Retard Magneto Couplings Types S18, S22 & S3B | May 73 |
| -0207-1 | | Magnetos Type AG4-6, 8 & 10 | - |
| -0207-136 | | Magnetos Lucas Aerospace Types AG4-6/1, AG4-8/1, AG4-10/1 Gen & Tech Info (-1) Illustrated Parts Catalogue (-3) Repair & Reconditioning Instructions (-6) | Nov 91 |
| -0208-1 | | Distributor Head Type CD6A | - |
| -0209-1 | | Impulse Starter Rotax (Formerly AEI) Types Z1-1 & Z1-18 ... | - |
| -0210-1 | | Hand Starting Magneto BTH Type AS4 | - |
| -0211-1 | | Magnetos Lucas Aerospace Type N14A/3 & N14B/1 | Dec 74 |
| -0212-1 | | Magnetos Bendix, Pt No S4-RN-21 | Jun 79 |
| -0301-1 | | Ignition Harnessfor Gipsy Major Mk 8 Engines Plessey | - |
| -0302-1 | | LT Booster Coil Rotax Type NBN18 | 1968 |
| -0302-6 | | LT Booster Coil Rotax Type NB18 | 1968 |
| -0303-1 | | Engine Starting Vibrator Bendix Type 10-87999-1 | 1967 |
| -0304-1 | | Booster Coils Rotax (Formerly AEI) Types C2TS, C2TS/1 & C2TS/3 | - |
| -0305-1 | | Booster Coils Rotax (Formerly AEI) Types C7TS/1 & C7TS/2 .. | - |
| -0306-13A | | Screened Ignition Coil Air Equipment Pt No 81268-21 | - |
| -0307-1 | | Low Tension Booster Coil Lucas Aerospace Type NB14/2 | Mar 76 |

UK RESTRICTED

AP 100Z-0101 AL136
SUB-GROUP 113L

ENGINE IGNITION EQUIPMENT

| AP CODE No | FAP CODE No | TITLE | DATE |
|------------------|-------------|---|--------|
| 113L-cont | | | |
| -0500-1 | | Aero-Engine Sparking Plugs Servicing | 1968 |
| -0601-1 | -0601-1 | Igniter Plugs KLG, Lodge, Smiths & Plessey | - |
| -0603-1 | | High Energy Igniter Plug | Oct 76 |
| -0604-1 | | High Energy Igniter Plugs AC Delco Type | - |
| -0605-1367 | | Torch Igniter Turbomeca Pt No 0249317500 & 0261307500 .. | Feb 88 |
| -0607-136 | | CFM 56-2A Engine Component Maintenance Manual Igniter Plug 74-21-32 | - |
| -0608-136 | | CFM 56-2A Engine Component Maintenance Manual Igniter Plug 74-21-34 | - |
| -0634-1 | | Igniter Plug Type 452-07-01, Ignition Cables Types 007-176-398 and 007-176-399 | May 74 |



This file was downloaded from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms, and more aircraft documents.

