

SERVICES
AIR SUPPLY TO SEALS

| Ref. No | Part No. | Description | | | | | | No. off | Material Specification | Class of Eqt. M.R. or L.M. | Plate No. |
|-------------|--------------------|--|---|---|---|---|---|---------|------------------------|----------------------------|-----------|
| | | 1 | 2 | 3 | 4 | 5 | 6 | | | | |
| | - | PIPING, INFLATION, TO CANOPY, HATCH AND NOSE SEALS (EB8.75.3093) Spares for:- | | | | | | - | - | - | |
| 28F/8011811 | AGS1118/B | CONE, tee piece | | | | | | 3 | - | C | |
| 28F/8011883 | AGS1102/B | COUPLING, pipe | | | | | | 9 | - | C | |
| 27VA/5212 | Dunlop ACM18302 | FILTER, line (For spares see AP.4515C, Book 3) | | | | | | 1 | - | B | |
| 30057 | EB8.75.2351 | GASKET, bulkhead union | | | | | | 2 | Neo-K-Tex | C | |
| 30056 | EB8.75.2345 | GASKET, flanged union at skin | | | | | | 1 | Neo-K-Tex | C | |
| 1128 | EB8.75.2345 | GASKET, bulkhead union | | | | | | 1 | Neo-K-Tex | C | |
| 30062 | EB8.75.2317 | PIPE, 1/2 in. o/d. ventilated suit system to connection forward frame 12 | | | | | | 1 | - | C | |
| 30061 | EB8.75.2315 | PIPE, 1/2 in. o/d connection forward frame 12 to union on equipment bay floor | | | | | | 1 | - | C | |
| 30773 | EB8.75.3087 | PIPE, 1/2 in. o/d, connection on floor to N.R.V. (Pre Mod. 3550) | | | | | | 1 | - | C | |
| 39655 | EB8.75.3785 | PIPE, 1/2 in. o/d, connection on floor to N.R.V. (Mod.3550) | | | | | | 1 | - | C | |
| 30772 | EB8.75.3085 | PIPE, 1/2 in. o/d. N.R.V. to tee-piece (Pre Mod.3550) | | | | | | 1 | - | C | |
| 39654 | EB8.75.3783 | PIPE, 1/2 in. o/d. N.R.V. to tee-piece (Mod. 3550) | | | | | | 1 | - | C | |
| 30774 | EB8.75.3089 | PIPE, 1/2 in. o/d. tee-piece to N.R.V. (Pre Mod. 3550) | | | | | | 1 | - | C | |
| 39656 | EB8.75.3787 | PIPE, 1/2 in. o/d, tee-piece to N.R.V. (Mod. 3550) | | | | | | 1 | - | C | |
| 30775 | EB8.75.3091 | PIPE, 1/2 in. o/d, N.R.V. to floor connection (Pre Mod. 3550) | | | | | | 1 | - | C | |
| 39657 | EB8.75.3789 | PIPE, 1/2 in. o/d, N.R.V. to floor connection (Mod. 3550) | | | | | | 1 | - | C | |
| 30771 | EB8.75.3083 | PIPE, 1/2 in. o/d, tee-piece to filter | | | | | | 1 | - | C | |
| 31020 | EB8.75.3215 | PIPE, 1/2 in. o/d, filter to reducing valve | | | | | | 1 | - | C | |
| 30063 | EB8.75.2321 | PIPE, assembly, reducing valve to bulkhead | | | | | | 1 | - | C | |
| | EB8.75.3255 | PIPE, 1/2 in. o/d, reducing valve to tee-piece (See pipe Chart) | | | | | | 1 | - | C | |

SERVICES
AIR SUPPLY TO SEALS

| Ref. No | Part No. | Description | | | | | | No. off | Material Specification | Class of Eqp. M.R. or L.M. | Plate No. |
|---------|-------------|--|---|---|---|---|---|---------|------------------------|----------------------------|-----------|
| | | 1 | 2 | 3 | 4 | 5 | 6 | | | | |
| | EB8.75.3251 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, tee-piece to uni-valve (See pipe chart) | | | | | | | | | |
| 30059 | EB8.75.2311 | PIPE, | | | | | | 3 | - | C | |
| | | exhaust at uni-valve | | | | | | | | | |
| 30067 | EB8.75.2341 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | C | |
| | | o/d, uni-valve to union for canopy seal hose connection | | | | | | | | | |
| | EB8.75.3257 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, tee-piece to coupling on bulkhead (See pipe chart) | | | | | | | | | |
| | EB8.75.3259 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, coupling to bulkhead union (See pipe chart) | | | | | | | | | |
| | EB8.75.3261 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, union to bulkhead to connection between frames 7 and 8 (See pipe chart) | | | | | | | | | |
| | EB8.75.3263 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, connection between frames 7 and 8 to connection between frames 5 and 6 (See pipe chart) | | | | | | | | | |
| | EB8.75.3265 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, connection between frames 5 and 6 to connection between frames 4 and 4A (See pipe chart) | | | | | | | | | |
| | EB8.75.3267 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, connection between frames 4 and 4A to connection between frames 3 and 4 (See pipe chart) | | | | | | | | | |
| 38961 | EB8.75.3621 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | C | |
| | | o/d, between connections on floor, starboard (See pipe chart) | | | | | | | | | |
| 38962 | EB8.75.3631 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | C | |
| | | o/d, between connections on floor, port (See pipe chart) | | | | | | | | | |
| | EB8.75.3275 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, port connection on floor to tee-piece aft frame 2 (See pipe chart) | | | | | | | | | |
| | EB8.75.3277 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, tee piece aft frame 2 to uni-valve (See pipe chart) | | | | | | | | | |
| | EB8.75.3291 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, uni-valve to nose seal hose (See pipe chart) | | | | | | | | | |
| | EB8.75.3279 | PIPE, $\frac{1}{2}$ in. | | | | | | 1 | - | | |
| | | o/d, tee piece aft frame 2 to connection on frame 2 (See pipe chart) | | | | | | | | | |

SERVICES
AIR SUPPLY TO SEALS

| Ref. No | Part No. | Description | | | | | | No. off | Material Specification | Class of Eqpt. M.R. or L.M. | Plate No. |
|-------------|-----------------------|--|---|---|---|---|---|---------|------------------------|-----------------------------|-----------|
| | | 1 | 2 | 3 | 4 | 5 | 6 | | | | |
| | EB8.75.3285 | PIPE, 1/2 in. o/d, connection between frames 1 and 1A to univalve (See pipe chart) | | | | | | 1 | - | | |
| | EB8.75.3287 | PIPE, 1/2 in. o/d, uni-valve to frangible hatch and hose (See pipe chart) | | | | | | 1 | - | | |
| | - | PIPING, inflation Valve in, Nose Wheel Bay (EB8.75.3067) Spares for:- | | | | | | - | - | | |
| 30776 | EB8.75.3071 | PIPE, 1/2 in. o/d, valve to floor | | | | | | 1 | - | C | |
| 28F/1013402 | AGS1111/B | UNION, bulkhead Attachment of union to floor | | | | | | 1 | - | C | |
| 28D/1008149 | A25/2B | Bolt, 4BA | | | | | | 6 | - | C | |
| 28M/1278189 | AGS2001/B1 | Nut, 4BA | | | | | | 6 | - | C | |
| 981 | EEAS20/2DR | Tab, locking | | | | | | 2 | - | C | |
| 28W/9419474 | SP15/B | Washer | | | | | | 6 | - | C | |
| 28F/9128928 | AGS1115/2 | Washer, plate | | | | | | 1 | - | C | |
| 30068 | EB8.75.2333 | SLEEVE, pipe connecting | | | | | | 1 | Silastic | C | |
| 30055 | EB8.75.2307 | UNION, flanged, canopy seal pipe Attachment of union to structure | | | | | | 1 | L56 | C | |
| 28Q/10406 | AS2227/507 | Rivet | | | | | | 6 | - | C | |
| 30069 | EB8.75.2319 | UNION, bulkhead, 1 in. pipe Attachment of union to bulkhead | | | | | | 1 | DTD423 | C | |
| 28D/9133012 | A25/3C | Bolt, 2BA | | | | | | 6 | - | C | |
| 28M/9433473 | AGS2002/C1 | Nut, 2BA | | | | | | 6 | - | C | |
| 3412 | EEAS20/3DR | Tab, locking | | | | | | 1 | - | C | |
| 30A/3060 | - | Wire locking (24 s.w.g) | | | | | | QR | DTD268 | C | |
| 28F/1013402 | AGS1111/B | UNION, bulkhead, equipment bay floor Attachment of union to floor | | | | | | 2 | - | C | |
| 28D/9436920 | A25/1C | Bolt, 2BA | | | | | | 6 | - | C | |
| 28D/9433473 | AGS2002/C1 | Nut, 2BA | | | | | | 6 | - | C | |
| 981 | EEAS20/2DR | Tab, locking | | | | | | 1 | - | C | |
| 28F/9128928 | AGS1115/2 | Washer, plate | | | | | | 1 | - | C | |
| 30A/3060 | - | Wire, locking (24 s.w.g). | | | | | | QR | DTD268 | C | |
| 27VB/5397 | Hymatic NAR131-002 | VALVE, non-return (For spares see AP4515E, Vol.3) | | | | | | 2 | - | B | |
| 27VB/5351 | Hymatic P.S.29/75 | VALVE, pressure reducing (For spares see AP4515E, Vol.3) | | | | | | 1 | - | A | |

SERVICES
AIR SUPPLY TO SEALS

| Ref. No | Part No. | Description | | | | | | No. off | Material Specification | Class of Eqpt. M.F. or L.N. | Plate No. |
|---------|----------|-------------|---|---|---|---|---|---------|------------------------|-----------------------------|-----------|
| | | 1 | 2 | 3 | 4 | 5 | 6 | | | | |
| | | | | | | | | | | | |

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

