

CHAP	2	SP 104	SERVICING PROCEDURES				AP 101B-1000-5A3 F (Section (1st Edition) 2)				TIME	ACT		
TRADE	AIR COMMS		LIGHTNING											
SHEET	1	OF	2	SHEET/S		3		5	6	AL NO	19	DATE		EST
TITLE	Telebrief Installation						SERVICING RECORD - RAF F.29888 AC NO DATE							
Safety and Servicing Notes are to be complied with throughout the work detailed on this Card.						(1)	(2)	(3)	(4)	(5)				
<u>Special Tools and Equipment</u>						MAN HOURS	TRADESMEN INIT	BRIEF DETAILS OF OR SUSPECTED DEFECT	F. 720B NO	N.C.O. INITIALS	ASSOCIATED PROCEDURE CARDS			
T.S. 395														
AIR COMMS														
1. <u>Preparation</u>														
1.1 T.S. 395. Connect to telebriefing plug in starboard wheel compartment.														
1.2 Telebriefing lamps. Ensure lit.														
1.3 PEC cover(s). Remove and stow.														
1.4 Headset. Connect to TS Pilot's mic/tel socket using appropriate adapters. (T5 aircraft connect to Pilot's and Pupil's mic/tel sockets).														
2. <u>Functional Checks</u>														
2.1 TS 395.														
(a) On/Off switch. Set to 'ON'.														
(b) Red lamp. Ensure lit.														
2.2 I/C facility. Ensure available between TS Pilot's mic/tel socket and each crew station in turn. (T5 aircraft ensure available from Pilot's and Pupil's mic/tel sockets).														
2.3 Telebriefing buttons. (As applicable). Depress in turn.														
2.4 TS Green lamp. Ensure lit.														
2.5 Telebriefing buttons. Release in turn.														
2.6 TS Green lamp. Ensure extinguished.														
SMS/82/37/12						Continued				ASSOCIATED TRADES				
										SP NO				
										104				



This file was downloaded from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms, and more aircraft documents.

