

Avon 109  
A.L.16

SECTION 3  
AVON 10901 ENGINE CHANGE UNIT

Page 469

REF. No.	Part No.	Description	No. QTY	STAT. SPEC.	M.R. CL. ST.	PL. S. ILL. No.
		AVON 10901 ENGINE CHANGE UNIT Complete as follows:-	1	-		
		AVON 109 ENGINE (As shown in Section 1)	1	-		
6A/3344		GENERATOR, TACHOMETER, MK.8C (Smith's Type 106RV/SB Mod.1) (Pre-Mod. 5235)	1	-	A	
6A/3344	BA.47894	GENERATOR, TACHOMETER (MOD.5235) (Smith's Type 106RV/SB Mark 8C)	1	-	A	
4188	BA.44883	Plate, engine change unit identification	1	-		
37F/ 11005	-	STARTER, TURBO, TRIPLE BREECH, Type TBS.720 Mk.2 (MOD.486)	1	-	A	
6A/1912		SWITCH UNIT, FUEL PRESSURE WARNING LIGHT, DIFFERENTIAL TYPE, Mk.1E*, Range 0-10 p.s.i. (Smith's Type 126/3PG)	1	-	A	

Avon 109  
A.L.10

REF. No.	PART No.						DESCRIPTION	No. OFF	MATL. SPEC.	M.R. CL of ST.	PL. & ILL. No.
		1	2	3	4	5					

Page 470 not issued.

S.O.S.P.104

This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.

