


Chap 3 RADAR  
Card 10  
A.L.13

SERVICING NOTES  
HUNTER F.6,T.7,T.7A,G.A.9 & F.R.10

A.P.4347F,G,J,K & R Vol 4/5  
Pt 1 Bk 2 Sect 1 (1st Ed)

1. Mountings and Trays. Mountings and trays are to be examined whenever the equipment they support is removed.
2. Tacan. The ventilating grill on the base of R.T.220C is mechanically weak and any distortion of it causes serious damage to the fan assembly. Particular care is to be taken when the R.T.220C is being handled.
3. I.F.F. MK. 10. Connection is to be made via the attenuator provided with the U.P.M.8, or via the High Level R.F. 'IN' socket on the P.T. 120Q4 if connection is made to the aerial socket on the transponder.
4. Rebecca MK. 8. The T.R. 8193 and C.U. 8197 are to be serviced and installed as a matched set.





This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.