

AIRFRAME MP 13(1) (1 and 2)		MAINTENANCE PROCEDURES COMPONENT REPLACEMENTS CANBERRA PR9		AP101B-0409A-5A3A 2nd Edition Sect 1 Chap 1		Maintenance Record Aircraft or Equipment Serial No:		MOD Form 707MS (Revised Jan 01) Date:			
AILERON - REMOVAL											
INFORMATION IN THE TOPIC 5A2 IS TO BE CONSULTED THROUGHOUT THE WORK DETAILED ON THIS CARD						Tradesman		Brief Details of		Supervisor	
Associated Procedures						Code	Man Hrs	Certification and TDM	suspected fault(s) and SNOW(s)	Man Hrs	Certification and TDM
<u>Special Tools and Equipment:</u> Extractor, 26FZ/95045.											
BLOCK 1 AIRFRAME											
1. <u>Preparation</u>											
1.1 Aileron jack accumulator Exhaust hydraulic pressure. (2 off).											
1.2 Upper and lower Open. hinged shrouds.											
1.3 Jack attachment shroud.) Remove.											
1.4 Outer hinge access panel.)											
BLOCK 2 ELECTRICAL											
2. <u>Preparation</u>											
2.1 External power supply. (i) Connect. (ii) Switch on.											
BLOCK 3 AIRFRAME											
3. <u>Preparation</u>											
3.1 Flare bay Ground/Flight Set to 'GROUND'. selector.											
3.2 Flap selector lever. Set to 'DOWN'.											
3.3 Flaps. Lower using hand pump.											
E0393(41)						Continued					

[illegible]