

CHAP	5	SP 514	SERVICING PROCEDURES	AP 101B-1000-5A3 E				
TRADE	FLT SYST		LIGHTNING	Section (1st Edition) 1				
SHEET	1	OF 2	SHEET/S	3	5	6	AL NO 12	DATE
TITLE	FCS Yaw Rate Gyro Type B.			SERVICING RECORD				
Safety and Servicing Notes are to be complied with throughout the work detailed on this Card.				AC NO DATE				
Special Tools and Equipment				(1)	(2)	(3)	(4)	(5)
Test Set Type 8A.				MAN HOURS	TRADESMAN INIT	BRIEF DETAILS OF DEFECT OR SUSPECTED DEFECT	F. 720B NO	N.C.O. INITIALS
NB This Procedure is applicable only if a serviceable component is replaced in a known serviceable system.								
FLT SYST								
1. Preparation								
1.1 Type 8A test set.				(i)	Connect to aircraft test sockets J, F and L.			
				(ii)	Connect to FC5 on FCC.			
1.2 External power supplies. (A.c. and d.c.).				(i)	Connect to aircraft.			
				(ii)	Set to 'ON'.			
1.3 Instrument master switch.				Set to 'ON'.				
2. Testing								
2.1 Type 8A test set.								
(a) M1 measure switch.				Set to 'RATE GYRO'.				
(b) Yaw rate gyro.				Select.				
2.2 PCU.								
(a) Master switch.				Set to 'ON'.				
(b) Stab switch.				Set to 'STAB'.				
SMS/80/453/42				Continued.				

SMS 17

ASSOCIATED PROCEDURE CARDS

ASSOCIATED TRADES

SP NO

514

[illegible]

This file was downloaded
from the RTFM Library.
Link: www.scottbouch.com/rtfm
Please see site for usage terms,
and more aircraft documents.

