


CHAP	2	SP 108		SERVICING PROCEDURES				AP 101B-1000-5A3F (Section 2 (1st Edition))		TIME	ACT			
TRADE	AIR COMMS		LIGHTNING											
SHEET	1	OF	1	SHEET/S	3	5	6	AL 23	RAF Form 2988B (Revised Jan 78)	EST				
TITLE	ARI 23329/1, Sonar Locator Beacon - Self Test.													
Safety and Servicing Notes are to be complied with throughout the work detailed on this Card.										Aircraft/Equipment Ser No: Date:				
Special Tools and Equipment										Tradesman Man Hrs	Tradesman Initials	Brief Details of Suspected Defect and MOD F720 ORN/SNOW When Applicable	Supervisor Man Hrs	Supervisor Initials
Stop Watch, 6B 9101001.										1	2	3	4	5
<p style="text-align: center;">AIR COMMS</p> <p>1. <u>Examination</u></p> <p>1.1 Sonar locator beacon. (i) Examine. (ii) Ensure secure.</p> <p>2. <u>Sonar Locator Beacon - Testing</u></p> <p>2.1 Pressure diaphragm switch. (i) Using finger pressure only, operate. (ii) Ensure regular acoustic pulsing is heard. (iii) Ensure the rate of pulse is 5 pulses in 7 to 10 seconds. (iv) Release switch. (v) Ensure pulsing stops</p>										ASSOCIATED PROCEDURE CARDS				
<p style="text-align: right;">SMS/3 STC</p>														
<p style="text-align: right;">108</p>														





This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.