

## NOTE TO READERS

*The coded system of A.P. reference numbering is now applied to this publication by A.L.No.22, as follows:-*

*101B-1005-1B (formerly A.P.4700E, Vol.1, Book 2)*

*New leaves issued subsequently to the introduction of the code reference will bear the coded Air Publication number: the reference caption of existing leaves will be amended only when the leaves are re-issued.*

The subject matter of this publication may be affected by Defence Council Instructions, Servicing schedules (Volume 5), or 'General Orders and Modifications' leaflets in this A.P., in the associated publications listed overleaf, or even in some others. If possible, Amendment Lists are issued to correct this publication accordingly, but it is not always practicable to do so. When an Instruction, Servicing schedule or leaflet contradicts any portion of this publication, the Instruction, Servicing schedule or leaflet is to be taken as the over-riding authority.

The inclusion of references to items of equipment does not constitute authority for demanding the items.

Each leaf, except the original issue of preliminaries, bears the date of issue and the number of the Amendment List with which it was issued. New or amended technical matter will be indicated by triangles positioned in text thus:- ◀-----▶ to show the extent of amended text, and thus:- ▶-----◀ to show where text has been deleted. When a Section or Chapter is issued in a completely revised form, the triangles will not appear.

If more than one copy of this publication is held, each set of covers should be given a copy number and kept together.

This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.

