

WEAPONS

SERVICING PROCEDURES
MISCELLANEOUS
HUNTER ALL MARKS

AP101B-1300-5A3C

Sect 4

Chap 2

List of Contents

SP No.

Low Pressure Oxygen Hose - Seizure ... 451

Pylon Hanger Bolts - Examination ... 452

Gun Compartment Ventilator Actuating Mechanism - Examination Mk7 ... 453

Not Allocated 454 - 465

WEAPONS SP 451 (1) (1 to 2)				SERVICING PROCEDURES MISCELLANEOUS HUNTER ALL MARKS				AP101B-1300-5A3C Sect 4 Chap 2		SERVICING RECORD Aircraft Ser No: Date:				RAF Form 2988B (Revised Jan 85)	
LOW PRESSURE OXYGEN HOSE - SEIZURE								TRADESMAN		Brief Details of Suspected Defect and SNOW When Applicable		SUPERVISOR			
SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD								MAN HRS 1	INITS & TDM 2	3	MAN HRS 4	INITS & TDM 5			
TRADE Wpn	M/HRS	TRADE	M/HRS	ASSOCIATED PROCEDURE CARDS				Code							
Special Tools and Equipment:															
Nil.															
BLOCK 1 WEAPONS NB: During Item 1 if undue force is required and seizure is indicated inform 'Airframe' Tradesman for rectification. 1. <u>Preparation</u> 1.1 Low pressure oxygen hose.								Disconnect from aircraft supply ensuring undue force is not required. A pull-off weight of over 30 lb is considered excessive.							
BLOCK 2 WEAPONS 2. <u>Examination</u> 2.1 Aircraft oxygen supply male portion.								(i) Clean, ensuring all traces of grease are removed. (ii) Examine. (iii) Apply a thin film of silicone grease, (Fomblin 348/1585).							
BLOCK 3 WEAPONS 3. <u>Completion</u> 3.1 Low pressure oxygen hose.								Reconnect.							
SMS/ 121								Continued							

WEAPONS SP 451 (2)		SERVICING PROCEDURES MISCELLANEOUS HUNTER ALL MARKS		AP101B-1300-5A3C Sect 4 Chap 2		SERVICING RECORD Aircraft Ser No: Date:				RAF Form 2988B (Revised Jan 85)	
LOW PRESSURE OXYGEN HOSE - SEIZURE						TRADESMAN		Brief Details of Suspected Defect and SNOW When Applicable		SUPERVISOR	
SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD						Code	MAN HRS 1	INITS & TDM 2	3	MAN HRS 4	INITS & TDM 5
BLOCK 1 WEAPONS 3. <u>Completion</u> 3.2 Aerolex clip.											
Ensure located squarely as near as possible to top of male portion.											
SMS/ 121A											

WEAPONS SP 452 (1) (1 to 2)				SERVICING PROCEDURES MISCELLANEOUS HUNTER ALL MARKS		AP101B-1300-5A3C Sect 4 Chap 2		SERVICING RECORD Aircraft Ser No: Date:				RAF Form 2988B (Revised Jan 85)	
PYLON HANGER BOLTS - EXAMINATION								TRADESMAN		Brief Details of Suspected Defect and SNOW When Applicable		SUPERVISOR	
SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD								MAN HRS 1	INITS & TDM 2	3		MAN HRS 4	INITS & TDM 5
TRADE Wpn	M/HRS	TRADE	M/HRS	ASSOCIATED PROCEDURE CARDS				Code					
Special Tools and Equipment:													
Nil.													
BLOCK 1 WEAPONS 1. <u>Examination</u> 1.1 Access panel. Remove. 1.2 Hanger bolt. (i) Examine and particularly for corrosion. (ii) Lubricate. (Grease, XG-285).													
BLOCK 2 WEAPONS NB: Item 2 is applicable only if corrosion is present. 2. <u>Rectification</u> 2.1 Drop tanks. (i) Ensure empty. (ii) Remove. (5A6). 2.2 Release housing support. Remove. 2.3 Hanger bolts. (i) Clean. (ii) Lubricate. (Grease, XG-285).													
SMS/ 122								Continued					

WEAPONS SP 453 (1) (1 of 1)				SERVICING PROCEDURES MISCELLANEOUS HUNTER ALL MARKS				AP101B-1300-5A3C Sect 4 Chap 2		SERVICING RECORD Aircraft Ser No: Date:				RAF Form 2988B (Revised Jan 85)	
GUN COMPARTMENT VENTILATOR ACTUATING MECHANISM - EXAMINATION NB: This Procedure is only applicable to Mk T7 Aircraft.										TRADESMAN		Brief Details of Suspected Defect and SNOW When Applicable		SUPERVISOR	
SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD										MAN HRS 1	INITS & TDM 2	3		MAN HRS 4	INITS & TDM 5
TRADE Wpn	M/HRS	TRADE	M/HRS	ASSOCIATED PROCEDURE CARDS				Code							
Special Tools and Equipment: Nil.															
BLOCK 1 WEAPONS 1. <u>Preparation</u> 1.1 Actuator. Disconnect from cross shaft lever.															
BLOCK 2 WEAPONS 2. <u>Examination</u> 2.1 Cross shaft. Ensure free in bearings. 2.2 Clevis pins. Ensure free in holes.															
BLOCK 3 WEAPONS 3. <u>Lubrication</u> 3.1 Bearings.) Lubricate. 3.2 Clevis pins.) (Oil, OX-24).															
BLOCK 4 WEAPONS 4. <u>Completion</u> 4.1 Actuator. Connect to lever. 4.2 Complete assembly. Test.															
SMS/ 123															

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

