

ELECTRICAL

SERVICING PROCEDURES

AP101B-1300-5A3C

MISCELLANEOUS

Sect 4

HUNTER ALL MARKS

Chap 3

AMENDED TO INCLUDE MK 9

List of Contents

SP No.

Cockpit Lamps ,Type 'C' No.2 - Cracking of Screens (Mk 6, 6A and 9 Aircraft)...	466
Bridge and Single Pillar Lampholders Lamp Housings - Insecurity Mk 7, 7A and 8B Only	467
Earth Point Servicing	468
Not Allocated	469
Main Trunking Junction Boxes - Sealing Mk7, 7A and 8B Only.	470
Not Allocated	471 - 475

<b>ELECTRICAL</b> SP 466 (1) (1 to 2) AL 22				<b>SERVICING PROCEDURES</b> MISCELLANEOUS HUNTER ALL MARKS		AP 101B-1300-5A3C Sect 4 Chap 1	<b>SERVICING RECORD</b> Aircraft Ser No: Date:			RAF Form 2988B		
<u>COCKPIT LAMPS, TYPE 'C' No 2 - CRACKING OF SCREENS</u> <u>(Mk 6, 6A AND 9 AIRCRAFT)</u>							<b>TRADESMAN</b>		<b>Brief Details of</b> <b>Suspected Defect and</b> <b>SNOW</b> <b>When Applicable</b>		<b>SUPERVISOR</b>	
				MAN HRS 1	INITs & TDM 2					MAN HRS 4	INITs & TDM 5	
<b>SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED          ON THIS CARD</b>												
TRADE EL	M/HRS	TRADE	M/HRS	<b>ASSOCIATED PROCEDURE CARDS</b>		Code						
<u>Special Tools and Equipment:</u>  Nil.												
<u>NB:</u>												
<b>BLOCK 1</b> <b>ELECTRICAL</b>												
<p><b>Note:</b> This procedure is applicable to Cockpit Lamps, Type 'C' No 2, Ref No 5CX/4058 fitted with screens Ref 5CX/2280, 3236, 3349, 3352, 3353, 3362, 3364, 3365, 3368, 3371, 3382, 3383, 3384, 3386, 3387, 3388, 3395, 3413, 3414, 3430, 4686, 4687, 4688, 4689, 4690, 4691, 4692, 4830, 5047, 5119, 5160, 5161, 5209.</p>												
		Continued										

ELECTRICAL  
SP 466 (2)  
(1 to 2)  
AL 22

SERVICING PROCEDURES  
MISCELLANEOUS  
HUNTER ALL MARKS

AP 101B-1300-5A3C  
Sect 4  
Chap 1

SERVICING RECORD  
Aircraft Ser No:  
Date:

RAF Form 2988B

COCKPIT LAMPS, TYPE 'C' No 2 - CRACKING OF SCREENS  
(Mk 6, 6A AND 9 AIRCRAFT)

SAFETY AND SERVICING NOTES ARE TO BE COMPLIED WITH THROUGHOUT THE WORK DETAILED ON THIS CARD	TRADESMAN	Brief Details of		SUPERVISOR	
		MAN HRS 1	INITS & TDM 2	Suspected Defect and SNOW When Applicable 3	MAN HRS 4
NB:					
BLOCK 1	ELECTRICAL				
1. <u>Examination</u>					
1.1 Cockpit lamps. Type 'C' No 2.	(i) Examine screens for signs of cracking or fracture without removing screen from body of lamp.  (ii) Ensure screen is not loose on lamp body.  (iii) Replace screen if cracked, fractured or loose.				

This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.

