



**AP 108B-0139-1**

# **AIRCREW EQUIPMENT ASSEMBLIES**

## **EJECTION SEATS, TYPE 9B**

**(MARTIN-BAKER)**

**AND**

## **AIRCREW LIST**

**(M.L. AVIATION)**

**(JAGUAR GR MK1/1A AND T MK2/2A)**

**GENERAL AND TECHNICAL INFORMATION**

BY COMMAND OF THE DEFENCE COUNCIL

Ministry of Defence

Sponsored for use in the

ROYAL AIR FORCE by D Air Eng 2 (RAF)

Prepared by Martin-Baker Aircraft Co. Ltd., Chalgrove

and

M.L. Aviation Co. Ltd., Andover, Hants

Publications authority: ATP/MOD (PE)

Service users should send their comments through the channel prescribed for the purpose in:

AP 100B-01 Order 0504 (RAF)

12

(

(

(

A.L. 1/74.

AMENDMENT RECORD SHEET

To record the incorporation of an Amendment List in this publication, sign against the appropriate A.L.No. and insert the date of incorporation.

A.L.No.	AMENDED BY	DATE
1	D. Rogers	16-12-74
2	Z. Williams	27-2-75
3	Z. Williams	25-5-76
4	Z. Williams	16-11-77
5	Z. Williams	7-8-78
6	M. Ken Linsie	23-5-79
7	Z. Williams	4-10-79
8	Z. Williams	16-5-80
9	Z. Williams	
10	Z. Williams	2-4-81
11	Z. Williams	21 <sup>12</sup> /81
12	J. Sobey	25-2-82
13	M. E. Turner	27-8-82
14	P. Walker	30-10-84
15	P. Walker	29-4-85
16	Jill Tazey	22-5-91
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		

A.L.No.	AMENDED BY	DATE
33		
34		
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		
60		
61		
62		
63		
64		







## CONTENTS



PRELIMINARY MATERIAL

Title page  
Amendment and AIL record  
Contents (this list)  
Lethal warning  
Modification record

GENERAL AND TECHNICAL INFORMATION (-1)Chapters

- 1 Aircrew equipment assembly, ejection seat, Martin-Baker, Type 9B Mk2, 9B1 Mk 2 and 9B2 Mk 2 (Pre-mods ES 3700, PA 571 and SE 108)
- 1-1 Aircrew equipment assembly, ejection seat, Martin-Baker, Types 9B Mk 2, 9B1 Mk 2 and 9B2 Mk 2 (Post-mods ES3700, PA 571 and SE 108)
- 1-2 Aircrew equipment assembly, ejection seat, Martin-Baker Types 9B Mk 3, 9B1 Mk 3 and 9B2 Mk 3
- 2 Aircrew list

Amendments

Changes of technical import to this publication are indicated by the symbols ----- outside the type area.



LETHAL WARNING

1. The assisted escape system and associated explosive operated jettison mechanisms fitted to aircraft are a potential source of lethal injury to personnel and damage to Government property if inadvertently operated.
2. Safety devices in the form of safety pins, levers and switches are provided for use when the aircraft is on the ground to safeguard against this danger,
3. On entering the cockpit/cabin of an aircraft, it is the responsibility of the individual to be able to recognise the assisted escape system safety device in that aircraft and to ensure that they are correctly applied at all times in accordance with para 4 below.
4. Instructions for the correct positioning of the assisted escape system safety devices in each aircraft type and mark are detailed in the Servicing Schedules and Aircrew Manual related to that aircraft.



MODIFICATION RECORD

The following record confirms that this publication incorporates all technical changes necessitated by the modifications listed below

Further information on modification titles, classification categories and Mark applicabilities is given in Topic 2.

Mod No	Brief details	Class
Jag 738	To reposition starboard harness strap stowage	B/2
ES 3700	Intro of a new negative-g strap and seat pan firing handle	B/2
PA 571	Intro of Parachute assembly Part No MBEU 10031PA	B/2
SE 108	Intro of PSP Type ZJ Mk 2 Part No 4240DP	B/2
PA 605	Intro of Harness assembly Part No MBEU 12211PA	B/2
PA 613	Intro of Backpad assembly Part No MBEU 11985PA	C/3 (WOTSAC)
ESA 75	Intro of ejection seat Tpe 9B, 9B1 and 9B2 Mk 3 in lieu of and by conversion of Types 9B, 9B1 and 9B2 Mk 2	B/2
SE 124	PSP Type ZJ Mk 2; intro of PSP lowering line MBEU 5004DP	B/2
PA 629	Intro of parachute assembly Type H4 Mk 1 Part No MBEU 12021PA in lieu of and by conversion of MBEU 10031PA	B/2
ES 3826	Intro of sticker clip for operation of PLB	B/2
▶ ES 7183	Intro of MOR handle assembly Part No MBEU 44664 in lieu of MOR handle assembly MBEU 44177 and blanking plug Part No MBEU 44665 in lieu of safety pin housing Part No MBEU 44175	C/3 NCP





This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.