



AP116Z-0426-12

April 1981

**NBC INTERCOMMUNICATION UNIT
5831-99-658-0607
(UEL TYPE 706)**

**GENERAL AND TECHNICAL INFORMATION
AND
GENERAL ORDERS AND MODIFICATIONS**

BY COMMAND OF THE DEFENCE COUNCIL

Ministry of Defence

Sponsored for use in the
ROYAL NAVY by DGA(N)
ARMY by DEME(A)
ROYAL AIR FORCE by D.Air Eng (RAF)

Prepared by Ultra Electronic Communications Ltd., Greenford
Publications authority: ATP/MOD (PE)

AEROSPACE LOGISTICS LTD

Technical library





AMENDMENT RECORD

Amdt	Incorporated by	Date
1		
2		
3		
4		
5	<i>A/Hus</i>	9-7-87
6	<i>[Signature]</i>	16/11/89
7	<i>[Signature]</i>	10-1-90
8	<i>[Signature]</i>	23/4/90
9	<i>[Signature]</i>	9/2/92
10	REINCORPORATED	8/6/01
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		
28		
29		
30		
31		
32		
33		
34		

Amdt	Incorporated by	Date
35		
36		
37		
38		
39		
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		
55		
56		
57		
58		
59		
60		
61		
62		
63		
64		
65		
66		
67		
68		



C O N T E N T S

PRELIMINARY MATERIAL

Title page
Amendment record
Contents (this list)
Preface
Leading particulars
Modification record

GENERAL AND TECHNICAL INFORMATION (-1)

Chapters


- 1 Introduction and technical description
- 2 Operating instructions
- 3 Test equipment
- 4 Servicing, fault diagnosis and repair

GENERAL ORDERS AND MODIFICATIONS (-2)

Preface
General orders (separator leaf followed by leaflets in numerical order)
Modification leaflets (separator leaf)
Equipment modification list
Modification leaflets (in numerical order)

NOTE TO READERS

This publication is also available in microfiche format. The microfiche version has been distributed to authorized users.



P R E F A C E

1 This publication contains Topic 1 and 2 information on the NBC intercom. unit. Topic 3 is issued separately. Because the intercom. unit is a simple, low-cost device, servicing is restricted to second line and there is no requirement for a Topic 4, 5 or 6. The bay servicing schedules normally contained in Topic 4 have been included in the present Topic 1.

► 2 The initial issue of Topic 1 described the NBC intercom. unit as originally introduced into service. Subsequently, a number of minor production changes were made by the manufacturer and Topic 1 has been amended to reflect these changes. Details of the variations between early and current units are given in Topic 2, GO leaflet No. 1. ◀

3 The subject matter of this publication may be affected by Defence Council Instructions or Special Technical Instructions. When this occurs, an amendment will normally be issued as soon as possible, but if discrepancies appear, the instruction is to be taken as the overriding authority.

4 Each page published with the initial issue bears the date of issue. Subsequent new or replacement leaves will be issued under the cover of an amendment instruction sheet, and will bear the number and date of that amendment. On all replacement pages, changes of technical import will be enclosed by indicator triangles, thus ►.....◀, positioned outside the type area. When the content of a chapter, or of a table within a chapter, has been so changed as to make the use of indicator triangles impracticable, the amended chapter, or table, will carry the note "(Completely revised)" beneath the title.

14B/007/1

MODIFICATION RECORD

The following record confirms that this publication incorporates all technical changes necessitated by the modifications listed below. Detailed information on each modification will be found in Topic 2.

- ▶ Mod. No. 1 (MOD Mod. No. B0219), Topic 2, Leaflet No. 1.
- ▶ Mod. No. 2 (MOD Mod. No. B1472), Topic 2, Leaflet No. 2 ◀

14B/007/2

M O D I F I C A T I O N R E C O R D

At the date of issue of this publication, no modifications have been made to the NBC intercommunication unit 5831-99-658-0607. Details of any future modifications will be incorporated in this topic and noted on this sheet as soon as possible following their introduction.

