

CHAP. 3 AIRFRAME
S.P. 300 A.L. 1
SHEET 1 OF 1

SERVICING PROCEDURE

F53

T55

BAC F53 & T55 (SA)

5A3A Section 1
2nd Edition


Main Undercarriage

AFSC


TIME EST

Safety and Servicing Notes are to be complied with
throughout the work detailed on this card.

43151
42152



- 1 SHOCK-ABSORBER STRUT PIVOT
- 2 FORWARD FLAP-ACTUATING LINK
- 3 UNDERCARRIAGE JACK
- 4 DOOR-JACK ATTACHMENT
- 5 DOOR-LATCH LEVER
- 6 DOOR-LATCH LEVER
- 7 DOOR-LATCH HOOK
- 8 DOOR-LATCH MICROSWITCH MECHANISM
- 9 DOOR-LATCH HOOK
- 10 DOOR MASTER-LATCH MECHANISM
- 11 DOOR ROLLERS
- 12 DOOR HINGES
- 13 RADIUS-ROD PIVOT SHAFT
- 14 RADIUS-ROD ATTACHMENT SHACKLE
- 15 RADIUS-ROD LOCK
- 16 RADIUS-ROD KNUCKLE JOINT
- 17 RADIUS-ROD BEARING
- 18 RADIUS-ROD TRUNNION ASSEMBLY
- 19 TORQUE-LINK PIVOTS
- 20 SHOCK-ABSORBER STRUT
- 21 AFT FLAP-ACTUATING LINK
- 22 FORWARD FLAP HINGES



KEY TO LUBRICANTS	
SYMBOL NOMENCLATURE	
<input type="checkbox"/>	XG-287
<input type="circle"/>	OX-14
<input type="square"/>	XG-277
<input checked="" type="checkbox"/>	P PRE-PACKED

MAIN UNDERCARRIAGE LUBRICATION POINTS

FIGURE 1

SERVICING PROCEDURE INSPECTION STAGES DO NOT EXCLUDE ADDITIONAL INSPECTION STAGES
INCORPORATED AS NECESSARY IN MAINTENANCE CERTIFICATION DOCUMENTS

This file was downloaded
from the RTFM Library.
Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

