

CHAP. 3 AIRFRAME
S.P. 302A A.L. 1
SHEET 1 OF 1

SERVICING PROCEDURE

F53

BAC F53 & T55 (SA)

5A3A Section 1
2nd Edition

Canopy and Seat Jettison

AFSC

43151


Safety and Servicing Notes are to be complied with
throughout the work detailed on this card.

42252

TIME EST

ASSOCIATED
PROCEDURES

NOTE: NO LUBRICANT TO BE APPLIED
TO CANOPY HINGE ARM HOOK
AND CATCH MATING SURFACES
OR TO ECCENTRIC ADJUSTMENTS.



KEY TO LUBRICANTS
SYMBOL NOMENCLATURE

◆ LUBRICATED ON ASSEMBLY

□ XG-287

▲ XG-273

□ P PRE PACKED

ALL PIN POINTS TO BE LIGHTLY
OILED WITH OIL OX-14.

LUBRICATION POINTS

FIGURE 1

SERVICING PROCEDURE INSPECTION STAGES DO NOT EXCLUDE ADDITIONAL INSPECTION STAGES
INCORPORATED AS NECESSARY IN MAINTENANCE CERTIFICATION DOCUMENTS

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

