

SERVICES							Page MZ1
INSTALLATION OF AIR TURBINE GEARBOX							
Ref. No.	Part No.	Description	No. off	Matl. Spec.	Cl. of Equip. M.R. L.M.	Plate No.	
		1 2 3 4 5 6					
	—	INSTALLATION OF AIR TURBINE GEARBOX (E.F3.61.53) Consisting of:—	—	—	—	161/2	
5UA/8783	E.B2.61.81	. ADAPTOR, turbine gear box exhaust	1	L35	—	161/3	
	E.E. CO. LTD.	. ALTERNATOR	1	—	A	161/26	
	BRADFORD						
	AE.2071						
2950	E.B2.61.65	. BOLT, special, air turbine gear box mounting	1	S95	C	161/5	
5UA/8387	AED.2054036	. COVER, and air pipe, assembly	1	—	C	161/6	
2951	E.B2.61.75	. EYE-BOLT, special, air turbine and steady arm anchor	1	S95	C	161/7	
5UA/8784	E.E. CO. LTD.	. GENERATOR (Pre-Mod. 9039)	1	—	A	161/27	
	AE.2519						
5UA/1098481	E.E. CO. LTD.	. GENERATOR (Mod. 9039)	1	—	A	161/27	
	AE.2519 Mk. 2						
28F/8011896	AGS.1142/C	. NIPPLE, gear box breather pipe	1	—	C	161/9	
28M/1011476	A27/JS	. NUT, 3/8" BSF, slotted, for air turbine gear box attachment bolts	2	—	C	161/10	
2952	E.B2.61.125	. PIPE, assembly, oil breather, 3/8" o/d x 24 SWG	1	L56	C	161/11	
28P/9527619	SP90/C7	. PIN, split, 1/16" dia. x 1" long, for nuts on air turbine attachment bolts	2	—	C	161/12	
2953	E.B2.61.83	. RING, piston, turbine exhaust pipe sealing	1	DTD719	C	161/13	
7852	EEAS.28/26/6A	. SHIM, laminated	1	Alum.	C	161/14	
12568	E.B2.61.73	. STRUT, air turbine gear box	1	—	C	161/15	
		Attachments:—					
2956	E.B1.61.31	. Bolt, special, 1/4" BSF	2	S95	C	161/16	
28M/7002430	AGS.2002/E/1	. Nut, stiff, 1/4" BSF	2	—	C	161/17	
28W/9419487	SP16/E	. Washer, 1/4" BSF plain	1	—	C	161/18	
28W/9419405	SP15/E	. Washer, 1/4" BSF plain	1	—	C	161/19	
2958	E.B2.61.85	. STRUT, air turbine gear box steady	1	—	C	161/20	
		Attachments:—					
2956	E.B1.61.31	. Bolt, special, 1/4" BSF	2	S95	C	161/16	
28M/7002430	AGS.2002/E/1	. Nut, stiff, 1/4" BSF	2	—	C	161/17	
28W/9419487	SP16/E	. Washer, 1/4" BSF plain	1	—	C	161/18	
28W/9419405	SP15/E	. Washer, 1/4" BSF plain	2	—	C	161/19	
2957	E.B2.61.95	. STRUT, air turbine gear box steady	1	—	C	161/21	
		Attachments:—					
2956	E.B1.61.31	. Bolt, special, 1/4" BSF	2	S95	C	161/16	
28M/7002430	AGS.2002/E/1	. Nut, stiff, 1/4" BSF	2	—	C	161/17	
28W/9419487	SP16/E	. Washer, 1/4" BSF plain	1	—	C	161/18	
28W/9419405	SP15/E	. Washer, 1/4" BSF plain	1	—	C	161/19	
37L/	ROTOL	. UNIT, accessory drive	1	—	A	161/28	
	ADE.383						
7853	EEAS.28/26/CU	. WASHER, special, for eye-bolt	1	S515	C	161/23	
28W/9419466	SP13/J	. WASHER, 3/8" BSF, for turbine gear box attachment bolts	2	—	C	161/24	
30A/2296	†	. WIRE, locking, 20 SWG	QR	DTD189	C	161/25	

Restricted

Page MZ2

SERVICES

INSTALLATION OF AIR TURBINE GEARBOX

Ref. No.	Part No.	Description	No. off	Matl. Spec.	Cl. of Equip.	Plate No.
					M.R. L.M.	
		1 2 3 4 5 6				

Restricted

ABCD