

SERVICES — RAIN REPELLENT SYSTEM  
(SWISS SUPPLY — SWISS FIT)

Ref. No.	Part No.	Description	No. Off	Material Specification	M.R. Class of Store	Plate No.
	E.320631	RAIN REPELLENT SYSTEM	—			
	Field A/C Services					
	B76 - P20	Adaptor, can valve	1			
	A.313444	Angle, mounting	1			
	Field A/C Services					
	B76 - P31	Bottle (Boeing Pt.No. 65-38196-2)	1			
	Field A/C Services					
	D76 - P200	Bracket, doubler	2			
	A.313445	Bracket, mounting, for time delay relay	1			
	B.313443	Bracket, support	1			
	F.313633	Bracket, switch	1			
3	B.315666	Cable, assy., F.216 (See section FA)	REF			
3	B.315675	Cable, assy., F.217 (See cable chart)	1			
3	B.315676	Cable, assy., F.219 (See cable chart)	1			
	A.306697	Clamp, for bottle	1			
11208	Std.2045/15/26	Clip	3			
	Field A/C Services					
	B76 - P115	Connection, bulkhead	1			
	Field A/C Services					
	B76 - P101	Gasket (AHO: 72460)	1			
	Field A/C Services					
	D76 - P43/1	Fitting, skin	2			
	A.313449	Hose, FR.6 to Starboard solenoid valve	1			
	A.313450	Hose, solenoid valve to solenoid valve	1			
	A.313448	Hose, visual reservoir to FR.6	1			
	Field A/C Services					
	B76 - P42	Locknut, rebated	2			
4242	Std.1231/7	Lug, locking	1			
	B.315674	Mounting, for connector bracket	1			
3	B.315651	Bracket, connector (Mod.2583)	1	743 F5		
	Field A/C Services					
	B76 - P160 SHT5	Nozzle, jet (idented D, R/H)	1			
	Field A/C Services					
	B76 - P160 SHT5	Nozzle, jet (idented D, L/H)	1			
	AN.924-4D	Nut	1			
	Std.2115 LT	Nut	1			
	Field A/C Services					
	B76 - P19	Nut, can valve adaptor	1			
	Field A/C Services					
	D76 - P43/5	Nut, retaining	2			
	F.306698	Plate, support	1			
	Field A/C Services					
	C76 - P28 SH1	Relay, time delay, type 503	2			
	Field A/C Services					
	D76 - P97/2	Reservoir, visual, assy.	1			
	MS.28777-4	Ring, back-up	3			
	AN.6227-5	Ring, '0'	2			
	AN.6227-7	Ring, '0'	5			
	GD.1772-11	Ring, sealing (Alt. to AGS.1186/11)	2			
5246	Std.1606/44/A12	Screw	4			
5F/9434857	NY.18007A	Strapping	A/R			
5F/9138822	NY.3342	Stud	A/R			
3	A.260946	Switch, push, modified (Mod.2583)	1			
	MC.21909-4C	Tee-piece	1			
	Field A/C Services					
	B76 - P34	Tube, connector	1			
	Std.1509/13/030	Tube, distance	1			
	Field A/C Services					
	D76 - P33/5	Valve, solenoid	2			
	AN.936-A1016	Washer, lock	2			



This file was downloaded  
from the RTFM Library.

Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.

