Accessories





ACCESSORIES

FIXING NUTS AND BUSHES FOR MODEL \$110G RESISTANCE THERMOMETERS

SIZE	NUT	BUSH
1/4 in B.S.P.	Part No. 173577	Part No. 165443
3/8 in B.S.P.	Part No. 165469	Part No. 165470
18 U.N.F.	Part No. 181448	Part No. 165443

COPPER GASKETS FOR RESISTANCE THERMOMETERS

Part No. 177016 Part No. 158777

ACCESSORIES FOR PRESSURE TRANSMITTERS AND SWITCHES

PART NO.	DESCRIPTION	WEIGHT		F.D.
169500	Quick Release Mounting Plate	2 oz (57 g)	For use with Model S195 and S122 Forms 4, 6, 10 & 11.	890
171818 170711 150404 150164	A.V. Mount Assembly (3 per set) Comprising: A.V. Mount Bush No.4BA Washer No.4BA Nut	3/4 oz per set (21 g)	For use with Quick Release Mounting Plates	890



ADJUSTMENT SPOOLS FOR THERMOCOUPLE CIRCUITS

This type of adjustment spool is supplied unadjusted and is capable of being adjusted on site to build out the thermocouple circuit to a given resistance value.

Manganin wire is employed and is wound on the bobbins to the approximate values listed in the table. Electrical connections and fixing are made via Plessey type tags or ring tags to fit No. 4BA size studs.

Adjustment spools are identified by the following code numbers:

Code No.	RESISTANCE (Approx.)	Connections and Fixings	F.D.
R.10.33 R.10.97 R.10.98 R.10.99 R.10.100 R.10.101	7 ohms 10 ohms 20 ohms 7 ohms 10 ohms 20 ohms	Plessey Tags Plessey Tags Plessey Tags No.4BA Ring Tags No.4BA Ring Tags No.4BA Ring Tags	871 871 871 1253 1253 1253

SMALL S.A.E. FLANGE ADAPTOR FOR 2 IN. DIA. INDICATORS

An adaptor kit is available for converting 2 in dia. indicators into small S.A.E. fixing. The kit consists of:

Flange (No.4BA fixing nuts)		168411
Gasket		168414
Locking Ring		168413
Flange (No.6. UNC fixing nut)		174323
Alternative to flange above		

ASTRALUX CLAMP FOR 2 IN. DIA. INDICATORS 171928

For use with 2 in indicators

This clamp (IN.21875) is manufactured by:

Astralux Ltd., Brightlingsea, Nr. Colchester, Essex.

