

Internal Checks (T5) -- *continued*

Front Right

AWP	Day/night as required. All lights on except TTC and ICE. Test, all lights on
LF sight	As required
◀ Pure air pressure	4200 PSI minimum ▶
E/F-band homer	OFF
Master armament selector	OFF
Missile telemetry	Light out
GW arming switch	SAFE
Pair/single	As required
Camera master	As required
Camera iris	As required
Weapons event panel	Test. Dimmer as required
AI recorder	Off (in)
Cabin temp selector	AUTO, as required
Cabin altimeter	Condition
Flap indicator	Condition
Flap selector	Mid position
Brake parachute selector	Fully in
Oxygen pressure gauges	60 to 100 PSI
Undercarriage indicator	Three green lights. Test alternative bulbs. Day/night as required

Right Side

AI changeover switch	As required
Mute switch	Unmuted
Airmix control	Pulled out. light on; pushed in, light out
Frequency card lighting	Test at night
Throttles	Check full range including reheat. Check synchronisation with pupil's throttles. Set at HP COCKS OFF

Oxygen:

Contents	Sufficient
Flow switches	Check 100%. Set AIRMIX
Flow indicators	Annunciating
Trigger safety catches	SAFE

This file was downloaded
from the RTFM Library.

Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

