

FAILURE TO START**Unsustained Starter Combustion**

Throttle HP COCK OFF

◆ Starter isolation ISOLATE ◆

Wait one minute

Repeat starting checks

Ensure engine not rotating

◆ Starter isolation START ◆

Starter button Press for 2 seconds and release
A maximum of 3 attempts to start may be made**WARNING:** After pressing the starter button, even if there is no apparent effect, a further attempt to start must not be made until one minute has elapsed in order to allow excess Avpin to drain**Engine Rotates but Fails to Light**

Before RPM reduce to 10%:

Throttle... .. HP COCK OFF

◆ Starter isolation ISOLATE ◆

Repeat starting checks

Ensure engine not rotating

◆ Starter isolation START ◆

As close as possible to one minute after first attempt:

Starter button Press for 2 seconds and release

If the second attempt is unsuccessful, wait 60 minutes before making a further attempt

Normal Starter Combustion but Engine Does Not Rotate

Throttle HP COCK OFF

◆ Starter isolation ISOLATE ◆

Do not attempt a further start

WARNING: A cooling period of 60 minutes must elapse before examination or investigation takes place

This file was downloaded
from the RTFM Library.
Link: www.scottbouch.com/rtfm

Please see site for usage terms,
and more aircraft documents.

