


<u>Ref No.</u>	<u>Sec</u>	<u>Chap</u>	<u>Make</u>	<u>Type</u>
5W/3	14	2	Rotax	AO107
5W23	14	18	Plessey	CZ 54043
5W/294	14	25	Rotax	A 0216
5W/352	14	30	Western	EJ 50 Mk 35 & 35A
5W/390	14	29	Western	EJ 50 Mk 26
5W/408	14	10	Western	EJ 25 MK9A
5W/411	14	64	Western	EOJ 600 MK1
5W/691	14	9	Western	EJ 25 Mk1B
5W/879	14	69	Western	EJ 25 Mk 1A
5W/1347	14	70	Western	EJ 25 MK 17 & 17A
5W/2401	14	61	Western	EJ 25 MK6A
5W/2613	14	63	Western	Ua 2342/B
5W/2614	14	62	Western	UA 2253
5W/2828	14	93	Plessey	1CZ 80383/1
5W/2850	14	69	Western	EJ 25 MKIE



SECTION 14

ACTUATORS, LINEAR, 12/24-VOLT

LIST OF CHAPTERS

Note 1.- A list of contents appears at the beginning of each chapter.

Note 2.- The chapter numbers below are arranged to correspond with those in Vol. 1. The only titles included are those of items for which repair information is required.

Actuator:-

- 1
- 2 Rotax, Type A0107
- 3
- ◀ 4 Rotax, A2700 series (Cancelled: now AP 113E-0157-16)▶
- ◀ 5 Rotax, Type A2102 (Cancelled: now AP 113E-0156-16)▶
- 6
- 7
- 8
- 9 Western Type EJ25, Mk.1B
- 10 Western, Type EJ25, Mk.9A
- 11
- ◀ 12 Plessey, Type CZ82360/B/1 (Cancelled: now AP 113E-0162-16)▶
- 13
- 14 Western, Type EJ50, Mk.24
- 15
- 16
- 17
- 18 Plessey, Type CZ54043
- 19
- 20
- 21
- 22

RESTRICTED

LIST OF CHAPTERS - (Continued)

Actuator:-

- 23 Western, Type EJ25, Mk.1C
- 24
- 25 Rotax, Type A0216
- 26
- 27
- 28
- 29 Western, Type EJ50, Mk.26
- 30 Western, Type EJ50, Mk.35 and 35A
- ◀ 31 Plessey, Type CZ53681/12 (Cancelled: now AP 113E-0115-16) ▶
- 32
- 33
- 34
- 35
- 36
- 37
- 38 B.T.H., Type EA2
- 39
- 40
- 41
- 42
- 43
- 44
- 45 Plessey, Type CZ80730/3/A
- 46
- 47
- 48
- 49
- 50
- ◀ 51 Plessey, Stoot (twin motor) series (Cancelled: now AP 113E-0124-13A6) ▶

RESTRICTED

LIST OF CHAPTERS - (Continued)

Actuator:-

- 52
- ◀ 53 Rotax, A0900 series (Cancelled: now AP 113E-0150-16) ▶
- 54
- 55
- 56
- ◀ 57 Plessey, Cub-Jaguar series (Cancelled: now AP 113E-0134-16) ▶
- 58
- 59
- 60
- 61 Western, Type EJ25, Mk.6A
- 62 Western, Type UA 2253
- 63 Western, Type UA 2342/B
- 64 Western, Type EOJ 600, Mk.1
- ◀ 65 Rotax, A1500 series (Cancelled: now AP 113E-0151-16) ▶
- ◀ 66 Rotax, Type A2001 (Cancelled: now AP 113E-0140-16) ▶
- ◀ 67 Rotax, Type A2201 (Cancelled: now AP 113E-0138-16) ▶
- 68
- 69 Western, Type EJ25, Mk.1A and 1E
- 70 Western, Type EJ25, Mk.17 and 17A
- 71
- ◀ 72 Rotax, Type A1803 (Cancelled: now AP 113E-0149-16) ▶
- 73
- 74
- 75 Plessey, Type 1CZ 80360/A (Cancelled: now AP 113E-0108-16)
- ◀ 76 Rotax, Type A1902 (Cancelled: now AP 113E-0139-16) ▶
- 77 to 92
- 93 Plessey, Type 1CZ 80383/1

