


## TESTMETER, TYPE Q



Ref. No. ... .. 10S/509  
 Dimension ... ..  $4\frac{1}{2}$  in.  $\times$   $3\frac{1}{2}$  in.  $\times$   $2\frac{1}{4}$  in.  
 Weight ... ..  $14\frac{1}{2}$  oz.  
 Associated publication A.P.1186E, Vol. 1, Sect. 9, Chap. 3

### BRIEF DESCRIPTION

The testmeter, Type Q, is a small multi-range testmeter for the measurement of a.c. and d.c. voltages, direct current and resistance. Range selection sockets at the top of the instrument and a selector switch on the front panel enable the ranges to be used. The meter is contained in a black moulded plastic case which is housed in a leatherette box having a hinged lid together with a pair of test leads fitted with plugs and crocodile clips. The movement consumes 1mA. for full-scale deflection.

### Ranges

D.C.	Voltage		Current D.C.(m.A.)	Resistance (ohms)
	D.C.	A.C.		
0-30	0-15		0-7.5	0-25,000
0-15	0-30		0-30	
0-30	0-150		0-150	
0-150	0-600		0-750	
0-600				

**RESTRICTED**

This file was downloaded  
from the RTFM Library.  
Link: [www.scottbouch.com/rtfm](http://www.scottbouch.com/rtfm)

Please see site for usage terms,  
and more aircraft documents.

